

Phase One Environmental Site Assessment (ESA)

97 Bower Street, Acton, Ontario

Project #

2402401

Prepared For

759509 Ontario Inc.

September 27, 2024

September 27, 2024

Rob Bucci
759509 Ontario Inc.
211 West Creek Drive, Suite 200
Woodbridge, ON L4L 9T7

Dear Rob Bucci:

Re: Phase One Environmental Site Assessment, 97 Bower Street, Acton, ON
Project #: 2402401

We are pleased to present our Phase One Environmental Site Assessment (ESA) report for the above-noted property. The scope of this Phase One ESA conforms to the requirements outlined in Ontario Regulation 153/04 and 407/19. This Phase One ESA does not include sampling or testing and is based solely on visual observations and a review of available or supplied factual data. The purpose of this Phase One ESA is to support a development approval application with the Town of Halton Hills.

The report provides information from Palmer's site reconnaissance, historical record review, interviews with knowledgeable individuals, and our conclusions for your consideration.

We trust that this report will be satisfactory for your current needs. If you have any questions or require further information, please contact our office at your convenience.

Yours truly,

PalmerTM | PART OF  **SLR**



Sarah Vlantis, B.Sc., P.Geo. (limited), QP_{ESA}
Team Lead, Land Quality and Remediation

Executive Summary

Palmer is pleased to provide this Phase One Environmental Site Assessment (ESA) report to 759509 Ontario Inc. The Phase One ESA was prepared for the parcel of land located at 97 Bower Street, Acton, ON (hereafter collectively referred to as the "Phase One Property").

It is Palmer's understanding that the purpose of this Phase One ESA is to support a development approval application with the Town of Halton Hills. The Phase One Property (also referred to as the "Subject Property" or "Site") is contemplated for residential redevelopment with a mid-rise building (5 stories) with underground parking (1-level). The Phase One ESA Report has been prepared in accordance with Schedule D of Ontario Regulation 153/04 under the Environmental Protection Act (EPA). The Phase One ESA includes an assessment of adjacent and neighbouring lands within a 250-metre (m) radius of the Phase One Property (hereafter referred to as the "Phase One Study Area").

The Phase One Property is a 0.92-hectare, irregular shaped, parcel of land located on the north side of Bower Street, west of the intersection with Wilbur Street North in Acton, Ontario. No building structures are present on the Phase One Property, which comprises asphalt-paved and grass areas, as well as a woodlot.

The Phase One Study Area ("surrounding area") covers land uses within a 250 metre (m) radius of the Phase One Property. The Phase One Study Area is partly developed with commercial, residential, institutional, and industrial land uses, including a railway track that exists adjacent to the north boundary of the Phase One Property.

A tributary of Black Creek intersects the northwestern portion of the Phase One Property and exists within the Phase One Study Area. In addition, a provincially significant evaluated wetland is located approximately 230 m north of the Property within the Phase One Study Area.

Historically, the Phase One Property was first developed since at least the late 1940s with a 2-storey building on the central portion. Since at least 1980, a 2-storey residential building and a garage was constructed on the southern portion of the Phase One Property. The buildings were all observed to be demolished prior to 2013. The buildings have been occupied by various residential tenants.

Based on the findings of the historical records review, Site reconnaissance, and personal interviews, it was concluded that seventeen (17) potentially contaminating activities (PCAs) were identified either on the Phase One Property or within the Phase One Study Area. These PCAs were deemed to be contributing to five (5) areas of potential environmental concern (APECs) on the Phase One Property. The identified PCAs and APECs are as follows:

Table A. Summary of APECs and PCAs

APEC	Location of APEC on the Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
APEC#1: Historic Fuel Oil Tank	Central Portion of the Phase One Property	#28: Gasoline and Associated Products Storage in Fixed Tanks	On-site – Prior environmental reports revealed the presence of a former on-site heating oil underground storage tank (UST) located on east side of the former northern two-storey building with fill and vent pipes along the west exterior wall.	Petroleum Hydrocarbons (PHCs), Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX)	Soil and Ground water
APEC#2: Fill Material of Unknown Quality and Historic Waste Disposal	Entirety of Phase One Property	#30: Importation of Fill Material of Unknown Quality #58: Waste Disposal and Waste Management including Thermal Treatment, Landfilling and Transfer of Waste, Other than use of Biosols as Soil Conditioners	On-site - Prior environmental reports revealed historic waste disposal at the Phase One Property which ceased in the early 1980s. The upper fill materials were observed to contain solid waste and debris during subsequent subsurface investigations. In addition, exceedances of PHCs, Metals, and PAHs were identified in soil and/or ground water.	PHC, BTEX, Volatile Organic Compounds (VOCs), Polycyclic Aromatic Hydrocarbons (PAHs), Metals, Arsenic (As), Antimony (Sb), Selenium (Se), Sodium (Na), Boron-Hot Water Soluble (B-HWS), Chloride (Cl-), Chromium VI (Cr VI), Mercury (Hg), Cyanide (CN-), low or high pH, Electrical Conductivity (EC) and Sodium Adsorption Ratio (SAR)	Soil and Ground water
APEC#3: Existing Railway Corridor	Northern Portion of the Phase One Property	#46: Rail Yards, Tracks and Spurs	Off-Site - Existing Railway corridor located adjacent to the northern property boundary of the Phase One Property.	PAHs, Metals, As, Sb, Se	Soil and Ground water
APEC#4: Existing Hydro Facility	Western Portion of the Phase One Property	#52: Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems #18: Electricity Generation, Transformation and Power Stations #28: Gasoline and Associated Products Storage in Fixed Tanks	Off-Site – Existing Hydro Facility at 43-45 Alice Street adjacent to the western property boundary of the Phase One Property with transformers and equipment in operation since the 1960s. In addition, vehicle maintenance and repairs are conducted in the maintenance area of the building. One 10,000-L gasoline and one 10,000-L diesel fuel USTs were installed in 1989.	PHC, BTEX, VOC, Polychlorinated Biphenyls (PCBs), Metals, As, Sb, Se	Soil and Ground water

APEC	Location of APEC on the Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
APEC#5: Historic Manufacturing Facility	Northwestern Portion of the Phase One Property	#12: Concrete, Cement, and Lime Manufacturing #34: Metal Fabrication #43: Plastics (including Fiberglass) Manufacturing And Processing #8: Chemical Manufacturing, Processing, and Bulk Storage #46: Rail Yards, Tracks and Spurs #51: Solvent Manufacturing, Processing, and Bulk Storage #54: Textile Manufacturing and Processing #31 Ink Manufacturing, Processing, and Bulk Storage #39: Paints Manufacturing, Processing, and Bulk Storage #28: Gasoline and Associated Products Storage in Fixed Tanks	Off-site - Former industrial facility at 125 McDonald Boulevard was operated between the late 1950s to the early 2020s as a manufacturer of various types of saws, metal equipment and parts, electrical vinyl insulating tape, radiator hoses and refractory products by H.K. Porter (Canada), Shurly-Dietrich Aikens Co. Ltd., Sandvik Canada Corp.; Frank Heller & Company Limited and Blackhawk Leather conducted leather processing, cutting, stretching and application of lacquers; Tri-El Limited conducted design and manufacturing of tarps and sand box covers for residential and commercial playground equipment; Tall People Furniture conducted furniture design and manufacturing; Mikia Printing conducted design and printing. Available environmental reports indicate the presence of chemical storage areas, a solvent dip tank, former waste oil UST, former spray paint booth and a railway spur.	PHCs, BTEX, VOCs, PAHs, Metals, As, Sb, Se, B-HWS, Cr VI, Hg, CN-, Na, Cl-	Ground water

A Phase Two ESA is recommended to assess subsurface impacts as a result of the aforementioned PCAs and APECs. The scope of the Phase Two ESA should entail the analysis of representative soil and ground water samples from the Phase One Property for the contaminants of potential concern identified; including PHCs, BTEX, VOCs, PAHs, Metals, As, Sb, Se, B-HWS, Cr VI, Hg, CN-, pH, Na, Cl-, EC, SAR, and PCBs.

The statements made in this Executive Summary are subject to the same limitations as contained in the report and should be read in conjunction with the entire report.

Table of Contents

Letter	
Executive Summary	1
1. Introduction	3
1.1 Phase One Property Information	3
1.2 Scope of Investigation	4
2. Records Review	5
2.1 General Records	5
2.1.1 Phase One ESA Study Area Determination	5
2.1.2 First Developed Use Determination	5
2.1.3 Fire Insurance Plans	5
2.1.4 City Directory Search	6
2.1.5 Chain of Title	6
2.1.6 Previous Environmental Reports	7
2.2 Environmental Source Information	8
2.2.1 Municipal Records Database	9
2.2.2 Provincial Records Database	9
2.2.3 Federal Records Database	12
2.2.4 Private Records Database	13
2.3 Physical Setting Sources	14
2.3.1 Aerial Photographs	14
2.3.2 Topography, Hydrology, Geology	15
2.3.3 Fill Materials	16
2.3.4 Water Bodies, Areas of Natural Significance & Ground Water Information	16
2.3.5 Well Records	16
2.4 Site Operating Records	18
3. Interviews	18
4. Phase One Property Reconnaissance	20
4.1 Written Description of Investigation	20
4.1 General Property Description	21
4.2 Specific Property Observations	21
4.2.1 Structures and Other Improvements	21
4.2.2 Underground Utilities and Service Corridors	22
4.2.3 Interiors of Structures and Buildings	22
4.2.4 Exterior Portions of the Phase One Property	22
4.2.5 Parts of the Phase One Property Not Covered by Structures	22
4.2.6 Enhanced Investigation of the Property	22
4.3 Written Description of Investigation	22
5. Review and Evaluation of Information	23
5.1 Current and Past Uses	23
5.2 Potentially Contaminating Activities (PCAs)	25

5.2.1	Phase One Property	25
5.2.2	Phase One Study Area	26
5.3	Areas of Actual or Potential Environmental Concern	29
5.3.1	Evaluation of Information	29
5.3.2	Identified Areas of Potential Environmental Concern	29
5.3.3	Contaminants of Potential Concern	29
5.3.4	Information Gaps in Phase One Investigation	30
5.4	Phase One Conceptual Site Model	30
6.	Conclusions	36
6.1	Whether a Phase Two ESA is Required	36
6.2	Phase One ESA Alone	36
6.3	Signatures and Certification	36
7.	Limitations of Report	38
8.	References	39

List of Tables

Table 1.	Fire Insurance Plan Summary	5
Table 2.	Aerial Photograph Review Summary	14
Table 3.	Well Water Records Review	16
Table 4.	Photograph Summary	20
Table 5.	Land Use Summary	23
Table 6.	Summary of PCAs on the Phase One Property	26
Table 7.	Summary of PCAs in the Phase One Study Area	26
Table 8.	Summary of Identified APECs	29
Table 9.	Summary of COPC	29

List of Figures

Figure 1	Site Location Map
Figure 2	Topographic Map
Figure 3	Phase One Property
Figure 4	Detailed Site Plan
Figure 5	On-Site and Off-Site Areas of Potential Environmental Concern

List of Appendices

Appendix A	Photographic Documentation
Appendix B	Aerial Photographs
Appendix C	Legal Plan of Survey
Appendix D	Land Registry Documents
Appendix E	EcoLog ERIS Database Report
Appendix F	Municipal FOI Correspondence
Appendix G	MECP FOI Correspondence
Appendix H	TSSA Correspondence
Appendix I	List of PCAs (Schedule D (Table 2), O.Reg. 153/04)

1. Introduction

Palmer was retained by 759509 Ontario Inc. (the 'Client') to conduct a Phase One Environmental Site Assessment (ESA) for the parcel of land located at 97 Bower Street, Acton, ON (hereinafter referred to as the 'Phase One Property').

It is Palmer's understanding that the purpose of this Phase One ESA is to support a development approval application with the Town of Halton Hills. The Phase One Property (also referred to as the "Subject Property" or "Site") is contemplated for residential redevelopment with a mid-rise building (5 stories) with underground parking (1-level). The Phase One ESA Report has been prepared in accordance with Schedule D of Ontario Regulation 407/19 (amending Ontario Regulation 153/04) under the Environmental Protection Act (EPA). The Phase One ESA includes an assessment of adjacent and neighbouring lands within a 250-metre (m) radius of the Phase One Property (hereafter referred to as the "Phase One Study Area").

At the time of the investigation, the Phase One Property was owned by 759509 Ontario Inc. The authorization for Palmer to proceed with the Phase One ESA was given by Rob Bucci (Owner/Director) of 759509 Ontario Inc. The contact information for the proponent is provided below:

<u>Company Name:</u>	759509 Ontario Inc.
<u>Company Address:</u>	211 West Creek Drive, Suite 200, Woodbridge, ON L4L 9T7
<u>Contact Name:</u>	Rob Bucci

1.1 Phase One Property Information

The Phase One Property is a 0.92-hectare, irregular shaped, parcel of land located on the north side of Bower Street, west of the intersection with Wilbur Street North in Acton, Ontario. No building structures are present on the Phase One Property, which comprises asphalt-paved and grass areas, as well as a woodlot.

The subject property is located north of Bower Street, and east of Alice Street, as shown in **Figure 1** and the photographs in **Appendix A** and **Appendix B**. The municipal address is 97 Bower Street, Acton with Property Identification Number (PIN) 25002-0325 (LT).

The legal description of the Phase One Property is Lot 272 & Part of Lot 268, MUP 1098, Part 1, 20R12317, in the Town of Halton Hills, Province of Ontario.

A legal plan of survey for the Phase One Property is presented in **Appendix C**.

The center of the combined area of the Phase One Property is located in UTM Zone 17, with approximate coordinates of Easting 577439 m and Northing 4831638 m.

1.2 Scope of Investigation

The Phase One ESA was completed in accordance with Schedule D of Ontario Regulation 407/19 (amending Ontario Regulation 153/04) under the EPA. The purpose of the Phase One ESA is to establish if potential environmental impacts are likely to be present on the Phase One Property as a result of previous or current land use on or in the vicinity of the Phase One Property. The following key components were completed as part of the assessment:

- Review of historical information (i.e. previous reports, site operating records, fire insurance plans, aerial photographs, occupancy search, etc.);
- Request and review of applicable documents (i.e. maps, provincial and federal archives, etc.);
- Review of applicable federal and provincial databases;
- Site reconnaissance and interviews with knowledgeable site representatives;
- Collections of photographs showing the current and past uses of the Site and surrounding area, as well as potentially contaminating activities (PCAs) and areas of potential environmental contamination (APECs);
- Tables and maps summarizing and providing the location of each PCA and APEC;
- Evaluation of information from records review, interviews and site reconnaissance; and
- Completion of a conceptual site model (CSM).

The Phase One ESA report was prepared for use by 759509 Ontario Inc. based on information collected by qualified Palmer staff members in April 2024. The Phase One ESA was prepared by Bailey Fleet, B.Sc.(Env.), EPT and Kalina Naydenova, M.Sc., under direct supervision by Sarah Vlantis, B.Sc., P.Geo. (limited), a “Qualified Person” (QP_{ESA}) as defined by Ontario Regulation 153/04. The qualifications of these Palmer members are summarized in Section 8.0.

2. Records Review

2.1 General Records

2.1.1 Phase One ESA Study Area Determination

The qualified person (QP), Sarah Vlantis, P. Geo. (limited), overseeing this Phase One ESA determined that the conventional distance of 250 m from the Site boundaries was adequate for defining the Phase One Study Area for all records reviewed. The limits of the Phase One Study Area are depicted on **Figure 1**.

2.1.2 First Developed Use Determination

The first developed use of the Phase One Property was determined through the records review as detailed throughout **Section 2** of the Phase One ESA report and summarized below.

An illustrated atlas from 1877 revealed that the Phase One Property was a vacant portion of a much larger block of land with no dwellings present.

An aerial photograph taken in 1946 showed the Phase One Property to comprise a residential building located on the southern portion of the Phase One Property with the remaining area comprised of grassed and/or wooded areas.

Aerial photographs taken between 1969 and 2002 showed the Phase One Property to essentially remain unchanged.

An aerial photograph taken in 2013 showed all structures on the Phase One Property to be demolished. Aerial photographs are shown in **Appendix B**.

2.1.3 Fire Insurance Plans

Fire insurance plans (FIPs) were produced between the late 1880's until the 1970s for urban communities throughout Canada. FIPs provided an illustrated resource that detailed the materials, occupancies, and potential fire hazards of existing buildings. The locations of above and below ground fuel storage tanks (ASTs/USTs) were also depicted on these plans.

Environmental Risk Information Services (ERIS) was retained to conduct a search for available FIPs or inspection report related documents pertaining to the Phase One Property or Study Area in order to provide additional information regarding historic usage and development at the site. The results of this search are summarized in **Table 1**.

Table 1. Fire Insurance Plan Summary

250 m Study Area Boundary		
Address	Map Description	PCA
Northern Portion of Study Area	1934: Railway	46
638 Willow Street (now 57 Willow St N)	1934: Acton Public Utilities Communications (Transformers)	18
	1934: Mason Knitting Co.	54

720 Bower Street (now 53 Bower Street)	1934: Glove Factory – W. H. Storey & Son	54
428 Mill Street (now 145 Mill St E)	1934: Garage Repair Facility with four associated USTs	28 & 52
439 Mill Street (now 130 Mill St E)	1934: Garage Repair Facility with two associated USTs	28 & 52
808 Mill Street (now 41 Mill St E)	1934: Auto Service Station with one associated UST	28 & 52
317 Bower Street (now 159 Perth Street)	1934: Acton Machine Co.	34
323 Bower Street (now 153 Perth Street)	1934: Acton Machine Shops	34

2.1.4 City Directory Search

Palmer retained ERIS to conduct a search of available directories (from the Digital Business Directory, Polk's Halton/Peel Region, and Mights) for the Phase One Property and all adjacent properties located within the Study Area. Relevant information obtained from the directories search is summarized as follows:

Phase One Property

- 97 Bower Street: Street Not Listed (1958-1981), Residential (1985-1991), Address Not Listed (1996-2021)

Summary

The Phase One Property was used residentially for at least 6 years (between 1985 and 1991).

2.1.5 Chain of Title

There is one (1) Chain of Title for the Phase One Property (97 Bower Street). Palmer obtained the Chain of Title/Parcel Register records from ERIS, and pertinent information is summarized as follows:

97 Bower Street has the PIN number 25002-0325 (LT) and was created in 1997.

Year	Name of Owner
Prior to 1820	Crown
1820 to 1830	Abraham Gilles
1830 to 1843	George Tufford
1843 to 1852	Charles Cameron
1852 to 1852	Thomas Smith
1852 to 1855	Edward Smith
1855 to 1862	John Fleming & William Robinson
1862 to 1862	John Goldie
1862 to 1864	Samuel Smith
1864 to 1875	Alexander Brown
1875 to 1875	Joseph Lasby

Year	Name of Owner
1875 to 1883	Charles Sidney Smith
1883 to 1887	Donald Cameron
1887 to 1894	Thomas C. Moore
1894 to 1915	William Brown
1915 to 1918	Alexander Donald & Edward Lacey
1918 to 1922	Donald McIvor
1922 to 1939	Doniel H. Young
1939 to 1941	Bruce Cornock Robson
1941 to 1947	Hugh McCutcheon & Eva McCutcheon
1947 to 1957	John J. Stewart & Edna Stewart
1957 to 1961	Corporation of The Town of Acton
1961 to 1961	John Wesley Wolf
1961 to 1970	Alexander J. Orr & Hazel Irene Orr
1970 to 1973	Frank Pethick & Ronald Legault
1973 to 1975	Edward McMullen
1975 to 1982	Bank of Montreal
1982 to 1989	Alexander Rudolf Schrempf & Brenda Joyce Denny
1989 to Present	759509 Ontario Inc.

A copy of this record is provided in **Appendix D**.

2.1.6 Previous Environmental Reports

Two (2) reports relating to the environmental conditions at the Phase One Property were provided and reviewed. A summary of the description of relevant report data, analysis and findings relevant to the Phase One ESA, including the presence of a contaminant on, in or under the Phase One Property or the existence of an area of potential environmental concern, is as follows:

Report Title: An Electromagnetic Survey of the Caranci Residential Lots 268 & 272 (Acton) Town of Halton Hills

Date: December 1991

Prepared by: Geomar Geophysics Ltd.

Prepared for: R.E. Clipsham Limited

An electromagnetic survey was carried out at Lots 268 & 272 in Acton, Town of Halton Hills, on December 4, 1991. The soil electrical conductivity found at the site ranged from 5 mS/m to 30 mS/m. In the western part of the site there are anomalies that are associated with the presence of buried metallic objects.

A zone of increased soil conductivity was observed west of the pond, which may indicate higher concentration of total dissolved solids (TDS) in the ground water. There were numerous anomalies caused by buried metallic objects within the northern pond.

A number of zones indicated possible buried metallic objects, which may indicate the location of a suspected buried vehicle and tank.

Report Title: Phase II Environmental Site Assessment, 97 Bower Street, Acton, Ontario

Date: July 8, 2009

Prepared by: Inspec-Sol Inc.

Prepared for: 759509 Ontario Inc.

A Phase II ESA was conducted for 97 Bower Street on July 8, 2009 by Inspec-Sol Inc. (Inspec-Sol). In the related Phase One Environmental Site Assessment by carried out by Inspec-Sol in May 2008, potential environmental impairment issues were identified to be associated with the Property. These included historic waste disposal, potential fuel oil USTs, potential asbestos-containing materials, and gasoline and diesel fuel USTs and the storage of PCB-containing materials on the adjacent property. During the Phase Two Environmental Assessment sixteen (16) boreholes (BH1-6 and BH/MW2-11) were drilled between depths ranging from 3.6 to 6.1 mbgs. Eleven (11) boreholes were converted to monitoring wells (MW2-11). Eleven (11) test pits (TP1-11) were also excavated to an approximate depth of 2.6 mbgs. Groundwater flow direction was identified in the southern direction and depth to groundwater ranged from 1.12 to 3.37 mbgs.

Table 1, Full Depth Background Site Condition Standards (SCS), for coarse-textured soils for residential/parkland/institutional/industrial/commercial/community property uses were chosen for the subject site. Soil samples in five (5) locations exceeded Table 1 SCS for PHCs, Copper, Lead, Zinc, Beryllium and several PAHs. Additionally, groundwater exceeded Table 1 SCS at four (4) locations for PAHs and at eight (8) locations for Copper. These concentrations appear linked to the concentrations of PAHs measured in the soils. Measured Copper concentrations were noted to be naturally occurring. Numerous test pits also identified debris (concrete, rubble, wood, scrap metal, tires, etc.) intermixed within the surficial fill layer across the Site.

The recommended remedial work to be carried out in the area of the soil exceedances should consist of sub excavation to remove the impacted soil, removal of the miscellaneous debris that is encountered through a sorting process, and analytical confirmation testing of any fill materials that are intended for reuse on Site. It was also recommended that another round of ground water sampling be carried out after the completion of the proposed Site remediation.

2.2 Environmental Source Information

The EcoLog ERIS (ERIS) system provides information from federal, provincial and private source databases and was searched for information relating to the Phase One Property. The EcoLog report is presented in **Appendix E**.

Each database is divided into records that present information such as company name, addresses, descriptions, status and other pertinent information. Records that fell within 250 m from the Phase One Property (Phase One Study Area) were extracted from the database for review.

2.2.1 *Municipal Records Database*

A written request was filed on April 1, 2024 for information concerning control orders, violation notices, and other environmental concerns for the Phase One Property with the Town of Halton Hills Records and Freedom of Information Department. No information has been received to date. Any forthcoming documentation from the aforementioned regulatory agency will be reviewed, and if the response specifies any environmental concerns, it will be addressed and forwarded to the Client. A copy of this correspondence is presented in **Appendix F**.

2.2.2 *Provincial Records Database*

A Freedom of Information request was filed on April 24, 2024 for information relating to any control orders, violation notices, or other environmental concerns with the MECP. No information has been received to date. Any forthcoming documentation from the aforementioned regulatory agency will be reviewed, and if the response specifies any environmental concerns, it will be addressed and forwarded to the Client. A copy of the MECP response is presented in **Appendix G**.

A total of one (1) provincial record was available for the Phase One Property and two hundred and twenty-three (223) records for the 250 m search radius from ERIS. The records are summarized as follows, with identification of existence of a PCA:

- i. **Certificates of Approval** – Eleven (11) records exist for the 250 m search radius. These records relate to municipal water and sewage approvals, with the exception of the following:
 1. Two (2) records relate to industrial air approvals for Halton Hills Hydro-Electric Commission at 43 Alice Street for one mobile emergency diesel powered electrical generator.
 2. Five (5) records relate to industrial air approvals for Blackhawk Leather Limited at 125 McDonald Blvd for an exhaust fan, roller coater, dryer, scrubbers, and blowers which used various contaminants.Records relating to 43 Alice Street (APEC #4) and 125 McDonald Blvd (APEC #5) are considered to pose a potential environmental concern to the Phase One Property.
- ii. **Delisted Fuel Tanks** – Two (2) records exist for the 250 m search radius. These records relate to a propane tank and propane refill centre located at 130 Mill Street East by Ciavone Investments Ltd. These records are considered to pose a **low** environmental concern to the Phase One Property, as the property is inferred to be located hydraulically cross-gradient from the Phase One Property.
- iii. **Environmental Activity and Sector Registry** – Two (2) records exist for the 250 m search radius. These records relate to air emissions located at 159 Perth Street by Harbison Walker International Corp and for water taking (construction dewatering) located at 125 McDonald Blvd by Drexler Construction Limited. These records are considered to pose a **low** environmental concern to the Phase One Property, as the property is inferred to be located hydraulically cross-gradient from the Phase One Property.

- iv. **Environmental Registry** – One (1) record exists for the 250 m search radius. This record relates to an approval for discharge into the natural environment other than water (i.e. air) by Mikia Printing Ltd. at 125 McDonald Blvd. This record is not considered to pose an environmental concern to the Phase One Property.
- v. **Environmental Compliance Approval** – Fourteen (14) records exist for the 250 m search radius. These records relate to municipal and private sewage works, municipal drinking water systems, and air approvals. These records are not considered to pose a potential environmental concern to the Phase One Property.
- vi. **Fuel Storage Tank** – Two (2) records exist for the 250 m search radius. These records relate to two (2) active underground liquid fuel tanks located at 43 Alice Street by Halton Hills Hydro Electric Commission. These records are considered to pose a potential environmental concern to the Phase One Property (APEC #4).
- vii. **Fuel Storage Tanks – Historic** – Two (2) records exist for the 250 m search radius. These records relate to a gasoline and diesel fuel UST used at a private fuel outlet station at 43 Alice Street for Halton Hills Hydro Electric Commission. These records are considered to pose a potential environmental concern to the Phase One Property (APEC #4).
- viii. **Ontario Regulation 347 Waste Generators Summary** – Ninety-three (93) records exist for the 250 m search radius. These records relate to the following:
 - 1. Pharmaceuticals and pathological wastes generated in 2001 at 93 Mill Street East by Medical Pharmacy.
 - 2. Acid solutions, miscellaneous wastes and organic/inorganic chemicals, alkaline solutions, aliphatic solvents and residues, organic acids and other inorganic acid wastes generated in 2019 at 76 Bower Street by Mark Dills.
 - 3. Emulsified oils and waste oils/sludges generated in 2001 and 2021-2022 at 153 Perth Street by Formtech Plastics Ontario Inc. and Vector Injection Ltd.
 - 4. Alkaline wastes, petroleum distillates, PCBs, light fuels, emulsified oils, oil skimmings and sludges, and waste oils and lubricants generated from 1992-2022 at 43 Alice Street by Halton Hills Hydro.
 - 5. Waste oils and lubricants, petroleum distillates and other specified inorganics generated from 2001-2022 at 159 Perth Street by RHI Refractories of America, Global-GIX Canada Inc., ANH Refractories Canada Inc., and HarbisonWalker International Corp.
 - 6. Light fuels generated from 2016-2017 at 137 Mill Street East by Sotirios Investments Inc. and Danosh Construction.
 - 7. PCBs generated in 2006 at 53 Bower Street by Brookfield LePage Johnson Controls.
 - 8. Pathological wastes generated from 1988-2022 at 55 Mill Street East by Shoemaker Funeral Home and Mackinnon Family Funeral Home Inc.
 - 9. Alkaline wastes generated in 2015 at 59 Willow Street North by Compressed Air & Filtration.
 - 10. Waste oils and sludges generated from 2018-2022 at 41 School Lane by Halton District School Board.

11. Paint/pigment/coating residues generated from 1994-1998 at 12 Wallace Street by Peter Zions Construction.
12. Pharmaceuticals and pathological wastes generated from 2014-2022 at 10 Eastern Avenue by Acton Medical and Urgent Care and Dr Jones Chan Dentistry Professional Corporation.
13. Waste oils and lubricants generated in 2021 at 57 Willow Street North by Halton Hills Hydro Inc.
14. Paint/pigment/coating residues, waste oils and lubricants, and organic tannery wastes, and PCBs generated from 1986-2004 and 2017 at 125 McDonald Blvd by Frank Heller & Company Ltd., Eagle Ottawa Canada, Ltd, Blackhawk Leather Ltd., and Permair Leathers Ltd.
15. Paint/pigment/coating residues, waste oils and lubricants, and graphic art wastes generated from 2004-2016 at 125 McDonald Blvd, Unit 3, by Mikia Printing Ltd.
16. Acid, alkaline, and neutralized wastes generated from 2006-2015 at 125 McDonald Blvd, Unit 1, by Zuraw Technologies Inc.

These records are considered to pose a **low** environmental concern to the Phase One Property, as these locations are inferred to be located hydraulically cross-gradient and/or down-gradient from the Phase One Property, with the exception of records #4 and #14-16, which are considered to pose a potential environmental concern to the Phase One Property (referred to as APEC #4 and 5).

- ix. **TSSA Historic Incidents** – One (1) record exists for the 250 m search radius. This record relates to the discovery of a petroleum product at a private fuel outlet in 2008, located at 43 Alice Street. This record is considered to pose a potential environmental concern to the Phase One Property (APEC #4).
- x. **Fuel Oil Spills and Leaks** – One (1) record exists for the 250 m search radius. This record relates to an unknown quantity of fuel oil leaked from an AST located on a construction site at 10 Eastern Avenue. This record is considered to pose a **low** environmental concern to the Phase One Property, as the location is inferred to be located hydraulically down-gradient from the Phase One Property.
- xi. **Inventory of PCB Storage Sites** – Eight (8) records exist for the 250 m search radius. These records relate to fifteen (15) PCB-containing transformers, seventeen (17) PCB-containing drums of soil, and eighteen (18) PCB-containing drums of other material from Halton Hills Hydro at 43 Alice Street. These records are considered to pose a potential environmental concern to the Phase One Property (APEC #4).
- xii. **Pesticide Register** – Two (2) records exist for the 250 m search radius. These records relate to retail pesticide vendors at Canadian Tire and Acton Home Hardware located at 130 Mill Street East and 43 Mill Street, respectively. These records are not considered to pose a potential environmental concern to the Phase One Property.
- xiii. **Pipeline Incidents** – Three (3) records exist for the 250 m search radius. These records relate to pipeline strikes located at 50 and 61 Bower Street, and 64 Church Street. These records are not considered to pose a potential environmental concern to the Phase One Property.

xiv. Private and Retail Fuel Storage Tanks – Two (2) records exist for the 250 m search radius. These records relate to a private fuel storage tank from Halton Hills Hydro Electric at 43 Alice Street and a retail fuel storage tank from R & R Honour Enterprises Inc. at 130 Mill Street East. Records relating to 43 Alice Street (APEC #4) are considered to pose a potential environmental concern to the Phase One Property. Records relating to 130 Mill Street East are considered to pose a **low** environmental concern to the Phase One Property, as the property is inferred to be located hydraulically cross-gradient from the Phase One Property.

xv. Record of Site Condition – Four (4) records exist for the 250 m search radius. These records relate to the following:

1. RSC filed based on Phase One and Two ESAs with RA conducted at 94-96 Mill Street for 2467766 Ontario Inc.
2. RSC filed based on Phase One and Two ESAs conducted at 125 McDonald Blvd for Frank Heller & Co. Ltd.

These records are not considered to pose a potential environmental concern to the Phase One Property.

xvi. Ontario Spills – Five (5) records exist for the 250 m search radius. These records relate to natural gas being released to the atmosphere between 2013 and 2019 with the exception of the following:

1. An unknown volume of oil and gas spilled to creek behind the Halton Hills Hydro building at 43 Alice Street in 2004.
2. A non-compliance action noted during an inspection at 159 Perth Street by HarbisonWalker International Corp. in 2019
3. 600 L of diesel spilled to ground in 2010 at 10 Eastern Avenue by Maple Reinders Construction Ltd.

These records are considered to pose a **low** environmental concern to the Phase One Property as the properties are inferred to be located hydraulically cross-gradient and/or down-gradient from the Phase One Property, with the exception of record #1, which is considered to pose a potential environmental concern to the Phase One Property (referred to as APEC #4).

xvii. Water Well Information System – One (1) record exists for the Phase One Property and seventy (70) records exist for the 250 m search radius. The record for the Phase One Property indicates the installation of a test hole to a maximum depth of 6 m below the ground surface in 2008. The records for Phase One Study Area relate to observation, test holes, and abandoned wells advanced to a maximum depth of 12.19 m below the ground surface in the vicinity of the Phase One Property. These records are not considered to pose an environmental concern to the Phase One Property.

2.2.3 Federal Records Database

No Federal Records were found for the Phase One Property and nine (9) were found within a 250 m search radius. The records are summarized as follows, with identification of existence of an area of potential environmental concern:

- i. **National PCB Inventory** – Eight (8) records exist for the 250 m search radius. These records relate to PCB containing transformers located at 43 Alice Street by Halton Hills Hydro and PCB containing ballasts located at 45 Bower Street by Canada Post. Records relating to 43 Alice Street (APEC #4) are considered to pose a potential environmental concern to the Phase One Property. The remaining records are considered to pose a **low** environmental concern to the Phase One Property, as these locations are inferred to be located hydraulically cross-gradient and/or down-gradient from the Phase One Property.
- ii. **National Pollutant Release Inventory 1993-2020** – One (1) record exists for the 250 m search radius. This record relates to the release of Toluene from leather and allied product manufacturing from 1997 to 2017 by Blackhawk Leather Limited and Eagle Ottawa Canada Ltd. at 125 McDonald Blvd. This record is considered to pose a potential environmental concern to the Phase One Property (APEC #5).

2.2.4 Private Records Database

A written request was made with a Customer Service Advisor with the Technical Standards and Safety Authority (TSSA) on April 1, 2024 for additional information regarding any storage tanks associated with the Phase One Property and/or Phase One Study Area. A response dated April 2, 2024 revealed the following:

- Two (2) liquid fuel tanks and a private fuel self-serve outlet located at 43 Alice Street (APEC #4); and,
- One (1) FS appliance located at 159 Perth Street. This property is inferred to be located hydraulically cross-gradient from the Phase One Property and is not considered to pose an environmental concern.

A copy of the TSSA correspondence and records are presented in **Appendix H**.

A total of one (1) private record was available for the Phase One Property and forty-four (44) records for the 250 m search radius from EcoLog. The records are summarized as follows, with identification of existence of an area of potential environmental concern:

- i. **ERIS Historical Searches** – One (1) record exists for the Phase One Property and thirty (30) records exist for the 250 m search radius. These records relate to record searches conducted from 2000 to 2022. These records are not considered to pose an environmental concern to the Phase One Property.
- ii. **Scott's Manufacturing Directory** – Fourteen (14) records exist for the 250 m search radius. These records relate to the following:
 1. Triple V Plastics Ltd. and Formtech Plastics Ontario Inc. operating as a plastic products manufacturing facility located at 153 Perth Street.
 2. ANH Refractories Canada Inc., Global-GIX Canada Inc., Harbison-Walker Refractories, A.P. Green Refractories (CDA), and RHI America Refractories operating as a clay building material and refractory manufacturing facility located at 159 Perth Street.
 3. Acton Denture Clinic operating as a medical equipment and supplies manufacturer located at 130 Mill Street East, Suite 103.

4. Plastics Eighty Ltd. operating as a plastics products manufacturing facility located at 12 Wallace Street.
5. Eagle Ottawa Canada Ltd., Permair Leathers Ltd., and Beardmore Leathers operating as a leather tanning, finishing, and goods manufacturing facility located at 125 McDonald Blvd.
6. Whiteclay Enterprises Inc. operating as an ornamental and architectural metal products manufacturing facility located at 125 McDonald Blvd, Unit 5.

These records are considered to pose a **low** environmental concern to the Phase One Property, as these locations are inferred to be located hydraulically cross-gradient and/or down-gradient from the Phase One Property, with the exception of records #5 and 6, which are considered to pose a potential environmental concern to the Phase One Property (referred to as APEC #5).

2.3 Physical Setting Sources

2.3.1 Aerial Photographs

Aerial photographs for select years between 1946 and 2023 were reviewed to assist in the determination of historic land uses and development of the Phase One Property and Study Area. Aerial photographs were obtained from ERIS, Town of Halton Hills and Esri Basemap Services.

Copies of reviewed aerial photographs are provided in **Appendix B**, and are summarized in **Table 2**, below.

Table 2. Aerial Photograph Review Summary

Date	Phase One Property	Adjacent Properties within Study Area
1946	The Property appears to have a residential dwelling in the central portion of the Site with grassed/wooded areas in the surrounding area of the property.	- Residential areas are present surrounding the property. - Farmsteads are present to the north. - Rail lines are present running east-west across the Study Area. - The remainder of the Study Area appears as developed residential, commercial and industrial lands. - Roadways appear in their current configurations.
1969	No significant changes evident.	- Industrial developments evident at 153 and 159 Perth Street. - New industrial facility built at 125 McDonald Blvd. - Institutional facility built at 21 School Lane. - The remainder of the Study Area appears unchanged.
1974	No significant changes evident.	No significant changes evident.
1980	An additional building and garage were constructed on the southern portion of the property.	No significant changes evident.
1990	No significant changes evident.	No significant changes evident.
2002	No significant changes evident.	No significant changes evident.

Date	Phase One Property	Adjacent Properties within Study Area
2013	All buildings on the property appear to have been demolished.	Building developed at 10 Eastern Avenue.
2023	No significant changes evident.	Removal of industrial facility located at 125 McDonald Blvd.

Summary:

The Phase One Property was used for residential purposes from 1946 to 2013. In 2013 the buildings on the Site were demolished and has remained vacant. The surrounding Study Area has primarily consisted of residential, commercial, and industrial land since 1946. A railway has been present since 1946 running from east to west within the Study Area. An industrial building structure was developed in 1969 and was demolished in 2023.

2.3.2 Topography, Hydrology, Geology

The Phase One Property is located at a topographic elevation of approximately 351 m above mean sea level. Topography at and in the general vicinity of the Site is relatively flat with a drop in elevation to the southeast, as shown in **Figure 2**.

The Phase One Property is located within the broad physiographic region known as the Horseshoe Marines (Chapman and Putnam, 1984). This region consists of two (2) landform components: (a) the irregular, stony knobs and ridges which are composed mostly of till and with some sand and gravel deposits; and (b) the more or less pitted sand and gravel terraces and swampy valley floors. This region forms the core of a horseshoe-shaped region flanking the upland that lies to the west of the highest part of the Niagara cuesta.

Local surficial geologic mapping (The Ontario Geological Survey, 2003) of the Acton area indicates that sand and gravel, minor silt, clay and till derived from ice-contact stratified deposits, underlie the Phase One Property.

Bedrock geologic mapping of Ontario (The Ontario Geological Survey, 1990) indicates that the glacially derived overburden soil at the Phase One Property is underlain by Lower Silurian Age sandstone, shale, dolostone, and siltstone of the Amabel Formation.

A Radon Potential Map of Ontario revealed that the subject property is located within Zone 3 (Radon Potential Map Ontario, 2013). This Zone is designated as a guarded relative radon hazard. Therefore, emissions of radon in the vicinity of the Site is of a potential environmental concern.

A tributary of Black Creek intersects the northwestern portion of the Phase One Property and exists within the Phase One Study Area. In addition, a provincially significant evaluated wetland is located approximately 230 m north of the Property within the Phase One Study Area. The local hydrogeology is controlled by this waterbody, the underlying geology, and the topography and is surmised to be directed southeastward.

Regional ground water flow is expected to be southeastward towards Lake Ontario. The static ground water level in the vicinity of the Phase One Property is noted to be between 0.9 and 5.0 m below existing grade based on well records in the vicinity of the Phase One Property.

2.3.3 Fill Materials

As previously discussed in Section 2.1.6., prior environmental reports revealed historic waste disposal at the Phase One Property which ceased in the early 1980s. The upper fill materials were observed to contain solid waste and debris during subsequent subsurface investigations. Therefore, fill material has been identified as a PCA on the Phase One Property (APEC #2).

2.3.4 Water Bodies, Areas of Natural Significance & Ground Water Information

A tributary of Black Creek intersects the northwestern portion of the Phase One Property and exists within the Phase One Study Area, which flows southeastward to Lake Ontario. Lake Ontario is located approximately 37 km southeast of the Phase One Property.

There are no areas of natural significance on the Phase One Property. A provincially significant evaluated wetland within the Phase One Study Area is located approximately 230 m north of the Phase One Property.

Local source water protection mapping (Source Protection Information Atlas, 2020) of the Acton area indicates there is a well-head protection area in the vicinity of the Phase One Property. A significant ground water recharge area is located throughout the Phase One Property as well as the Phase One Study Area. In addition, a highly vulnerable aquifer was noted to be present throughout the Phase One Property and Phase One Study Area.

The Phase One Property is not serviced by a municipal drinking water system. However, there is one (1) well record for the Phase One Property and seventy (70) well records within a 250 m search radius. The record for the Phase One Property indicates the installation of a test hole and the records for the Phase One Study Area relate to observation, test holes, and abandoned wells.

2.3.5 Well Records

As previously discussed in Section 2.2.2, there is one (1) well record for the Phase One Property and seventy (70) well records within a 250 m search radius. These records relate to observation, test holes, and abandoned wells on the Phase One Property and in the Phase One Study Area.

A review of these records does not provide detailed information however; available data is summarized as follows:

Table 3. Well Water Records Review

Well ID	Location	Depth (m)	Water Level (m)	Installation Date	Well Use	Status
7120007	97 Bower Street	6.0	4.7	August 6, 2008	Test Hole	Test Hole
7378700	Lot 28, Con 3	6.0	-	November 30, 2020	Monitoring	Observation
2809690	Lot 28, Con 3	-	-	January 17, 2003	-	Abandoned
7269004	137 Mill Street East	6.6	-	July 6, 2016	Monitoring	Observation
7221211	Metro Linx	5.4	-	April 2, 2014	Monitoring	Test Hole
7362200	125 McDonald Blvd	9.1	2.4	June 17, 2020	Monitoring	Observation
7361995	125 McDonald Blvd	10.0	2.4	June 17, 2020	Monitoring	Observation

Well ID	Location	Depth (m)	Water Level (m)	Installation Date	Well Use	Status
7269005	137 Mill Street East	6.6	-	July 6, 2016	Monitoring	Observation
7350907	125 McDonald Blvd	7.7	-	December 9, 2019	Monitoring	Observation
7360685	125 McDonald Blvd	8.1	2.7	June 5, 2020	Monitoring	Observation
7337156	125 McDonald Blvd	8.5	5.0	July 9, 2019	Monitoring	Observation
7360715	125 McDonald Blvd	7.8	2.7	June 5, 2020	Monitoring	Observation
7285175	-	-	-	March 29, 2017	-	-
7350987	125 McDonald Blvd	9.4	4.6	December 9, 2019	Monitoring	Observation
7388615	125 McDonald Blvd	5.9	3.0	May 26, 2021	Monitoring	Observation
7350991	125 McDonald Blvd	6.9	-	December 9, 2019	Monitoring	Observation
7362146	125 McDonald Blvd	5.4	-	June 26, 2020	Monitoring	Observation
7346699	151 Mill Street	6.0	-	-	Monitoring	Observation
7350957	125 McDonald Blvd	6.0	-	December 12, 2019	Monitoring	Observation
7388626	125 McDonald Blvd	7.3	3.0	May 28, 2021	Monitoring	Observation
7375865	125 McDonald Blvd	7.0	-	November 11, 2020	Monitoring	Observation
7362157	125 McDonald Blvd	4.5	-	June 26, 2020	Monitoring	Observation
7388625	125 McDonald Blvd	6.7	3.0	May 27, 2021	Monitoring	Observation
7360720	125 McDonald Blvd	9.3	3.5	June 5, 2020	Monitoring	Observation
7376265	125 McDonald Blvd	9.1	-	December 11, 2020	Monitoring	Observation
7375845	125 McDonald Blvd	7.0	-	November 11, 2020	Monitoring	Observation
7375851	125 McDonald Blvd	5.6	-	November 11, 2020	Monitoring	Observation
7350954	125 McDonald Blvd	6.0	-	December 13, 2019	Monitoring	Observation
7388622	125 McDonald Blvd	6.7	3.0	May 26, 2021	Monitoring	Observation
7306391	-	-	-	February 7, 2018	-	-
7376268	125 McDonald Blvd	6.1	-	December 11, 2020	Monitoring	Observation
7345190	-	-	-	September 27, 2019	-	-
7350958	125 McDonald Blvd	5.6	-	December 10, 2019	Monitoring	Observation
7375864	125 McDonald Blvd	4.8	-	November 11, 2020	Monitoring	Observation
7406702	125 McDonald Blvd	4.2	0.9	November 24, 2021	Monitoring	Observation
7388624	125 McDonald Blvd	5.7	3.0	May 28, 2021	Monitoring	Observation
7388614	125 McDonald Blvd	5.1	3.0	May 28, 2021	Monitoring	Observation
7352056	125 McDonald Blvd	10.2	-	January 7, 2020	Monitoring	Observation
7350972	125 McDonald Blvd	2.7	-	December 10, 2019	Monitoring	Observation
7360681	125 McDonald Blvd	9.1	2.7	June 5, 2020	Monitoring	Observation
7311615	-	-	-	May 3, 2018	-	-

Well ID	Location	Depth (m)	Water Level (m)	Installation Date	Well Use	Status
7351992	125 McDonald Blvd	8.9	-	January 6, 2020	Monitoring	Observation
7350911	125 McDonald Blvd	1.6	-	December 10, 2019	Monitoring	Observation
7171098	-	-	-	September 14, 2011	-	-
7406731	125 McDonald Blvd	8.2	-	November 24, 2021	Monitoring	Observation
7378699	Lot 29, Con 3	4.1	-	November 30, 2020	Monitoring	Observation
7337187	125 McDonald Blvd	6.0	3.5	July 9, 2019	Monitoring	Observation
7375866	125 McDonald Blvd	6.4	-	November 10, 2020	Monitoring	Observation
7315547	-	-	-	May 25, 2018	-	-
7388627	125 McDonald Blvd	8.0	3.0	May 27, 2021	Monitoring	Observation
7352094	125 McDonald Blvd	12.1	-	January 8, 2020	Monitoring	Observation
7388621	125 McDonald Blvd	7.0	3.0	May 26, 2021	Monitoring	Observation
7418964	125 McDonald Blvd	-	-	May 9, 2022	Monitoring	Observation
7418925	125 McDonald Blvd	-	-	May 9, 2022	Monitoring	Observation
7418931	125 McDonald Blvd	-	-	May 10, 2022	Monitoring	Observation
7418932	125 McDonald Blvd	-	-	May 12, 2022	Monitoring	Observation
7418934	125 McDonald Blvd	-	-	May 10, 2022	Monitoring	Observation
7418940	125 McDonald Blvd	-	-	May 9, 2022	Monitoring	Observation
7375843	125 McDonald Blvd	7.0	-	November 10, 2020	Monitoring	Observation
7142326	163 Church Street	-	-	February 12, 2010	-	-
7352091	125 McDonald Blvd	3.8	-	January 8, 2020	Monitoring	Observation
7310917	-	-	-	March 29, 2018	-	-
7388623	125 McDonald Blvd	7.4	3.0	May 27, 2021	Monitoring	Observation
7375863	125 McDonald Blvd	3.9	-	November 10, 2020	Monitoring	Observation
7337180	125 McDonald Blvd	6.0	3.5	July 9, 2019	Monitoring	Observation
7352065	125 McDonald Blvd	7.4	-	January 6, 2020	Monitoring	Observation
7350956	125 McDonald Blvd	3.5	-	December 13, 2019	Monitoring	Observation
7388618	125 McDonald Blvd	7.0	3.0	May 27, 2021	Monitoring	Observation
7406694	125 McDonald Blvd	6.4	-	November 24, 2021	Monitoring	Observation
7188674	-	-	-	May 28, 2012	-	-
7221212	Metro Linx	5.4	-	April 2, 2014	Monitoring	Test Hole

2.4 Site Operating Records

The Phase One Property does not require an enhanced investigation, as it has been used for residential purposes and thus, does not meet the requirements necessary for an enhanced property investigation to be carried out.

3. Interviews

An interview was conducted by Palmer with Robert Bucci on April 18, 2024. Pertinent information provided by Robert Bucci for 97 Bower Street is summarized as follows:

- Robert is employed with Maple Drywall.
- The property has been his family-owned land for 30+ years.
- The site is currently unoccupied and not in use.
- Robert mentioned he was not aware of any individuals who may have additional knowledge regarding current or past uses/activities related to the Phase One Property.
- It is understood that the property contains buried tires and a bus.
- According to Robert, the Phase One Property has not historically been used for industrial operations, dry-cleaning operations, gasoline service station or fuel storage, or automotive repair operations.
- Robert provided the following information regarding 97 Bower Street:
 - No storage and/or use of environmentally sensitive or hazardous products;
 - No products manufactured;
 - No by-products or wastes created;
 - No raw materials handling and storage locations;
 - No drums, totes, or bins stored;
 - No vehicle and maintenance areas;
 - No use of herbicides, pesticides, other agricultural chemicals;
 - No presence of underground structures, including in-ground hoists, pits, oil/water separators;
 - No records of spills;
 - No on-site wells or septic systems; and,
 - No storage tanks.
- A previous environmental investigation was conducted for 97 Bower Street and a copy of the report was provided for our review.
- The property is proposed for residential redevelopment.

4. Phase One Property Reconnaissance

4.1 Written Description of Investigation

The purpose of the Site reconnaissance was to determine if APECs exist, through observations about current and past uses and PCAs on, in or under the Phase One Property and within the Phase One Study Area, as well as to identify potential contaminant pathways. Exterior observations of the Phase One Property and surrounding properties were conducted. The exterior observations were recorded by walking over the grounds. Adjoining properties and properties within the Phase One Study Area were observed from within the grounds of the Phase One Property and public roadways.

An investigation of the Phase One Property was completed by Bailey Fleet, B.Sc.(Env.), EPt of Palmer on March 28, 2024. Weather conditions during the inspection were sunny with an ambient temperature at approximately 7 degrees Celsius, and slight winds. The inspection involved visual observations of the Phase One Property to confirm current conditions, as well as observations of adjacent properties from the Phase One Property limits and publicly accessible locations (i.e. municipal roads). Palmer was not accompanied during their inspection of 97 Bower Street. Photographs taken during the Phase One Property inspection are provided in **Appendix A**.

Photographs in **Appendix A** depict the following aspects of the Phase One Property and are noted in **Table 4**:

Table 4. Photograph Summary

Photograph #	Description
Photograph 1	Photo depicts the northwest facing view of the Phase One Property.
Photograph 2	Photo depicts the northeast facing view of the Phase One Property.
Photograph 3	Photo depicts the southwest facing view of the Phase One Property.
Photograph 4	Photo depicts the southeast facing view of the Phase One Property.
Photograph 5	Photo depicts location of previously installed BH1/MW1 on the asphalt-paved driveway on the southern portion of the property.
Photograph 6	Photo depicts view of 43 Alice Street, adjacent to the Phase One Property to the southwest.
Photograph 7	Photo depicts location of previously installed MW7 on the southwest portion of the property.
Photograph 8	Photo depicts underground pipe found in the vicinity of the former building on the central portion of the property.
Photograph 9	Photo depicts location of previously installed MW8 on the west portion of the property.
Photograph 10	Photo depicts tributary of Black Creek located north of the Phase One Property.
Photograph 11	Photo depicts concrete/metal debris found in the vicinity of the former building on the central portion of the property.
Photograph 12	Photo depicts the view of the railway to the north of the Phase One Property.
Photograph 13	Photo depicts location of previously installed MW9 on the northwest portion of the property.

Photograph #	Description
Photograph 14	Photo depicts location of previously installed MW10 on the north portion of the property.
Photograph 15	Photo depicts location of previously installed MW11 on the north portion of the property.
Photograph 16	Photo depicts location of previously installed MW5 on the north portion of the property.
Photograph 17	Photo depicts location of previously installed MW4 on the east portion of the property.
Photograph 18	Photo depicts the northeast view of the Phase One Study Area.
Photograph 19	Photo depicts the southwest view of the Phase One Study Area.
Photograph 20	Photo depicts the southeast view of the Phase One Study Area.
Photograph 21	Photo depicts the northwest view of the Phase One Study Area.

4.1 General Property Description

The Phase One Property is located adjacent to the northwest of the Bower Street and Frederick Street North intersection and comprises a total area of approximately 0.92 hectares. It is located in an area with predominantly residential, commercial and industrial land uses. Residential properties exist within the southern portion of the Study Area.

At the time of Palmer's investigation on March 28, 2024, the Phase One Property was vacant and not occupied. The Phase One Property has no building structures present. The driveway material at this lot was asphalt. Vegetation throughout this lot comprised a mix of manicured lawns, planted trees, and overgrown garden beds.

The Phase One Study Area, as depicted in **Figure 1**, was surveyed within a 250 m radius and all occupants of neighboring properties were noted. The Phase One Study Area is developed with residential, commercial, industrial, and institutional land uses, including a railway track that exists adjacent to the north property boundary of the Phase One Property, as shown in **Figure 3**.

A tributary of Black Creek intersects the northwestern portion of the Phase One Property and exists within the Phase One Study Area. In addition, a provincially significant evaluated wetland is located approximately 230 m north of the Property within the Phase One Study Area.

4.2 Specific Property Observations

4.2.1 Structures and Other Improvements

The Phase One Property is currently a vacant, undeveloped parcel of land with no structures.

Historically, the Phase One Property was first developed since at least the late 1940s with a 2-storey building on the central portion. Since at least 1980, a 2-storey residential building and a garage was constructed on the southern portion of the Phase One Property. The buildings were all observed to be demolished prior to 2013. The buildings have been occupied by various residential tenants.

An underground pipe was observed in the vicinity of the former 2-storey building in the central portion of the property. However, in previous investigations, it was reported that a heating oil UST formerly existed at the west side of the former northern 2-storey building on the Phase One Property.

4.2.2 Underground Utilities and Service Corridors

Underground utilities are not anticipated to be present at the Phase One Property.

4.2.3 Interiors of Structures and Buildings

The Phase One Property is a vacant, undeveloped parcel of land with no structures or buildings.

4.2.4 Exterior Portions of the Phase One Property

The exterior portion of the Phase One Property has grass covered areas, an asphalt-paved area in the southern area leading to Bower Street, and a woodlot located in the northern portion of the property, as shown in **Figure 4**.

Surface water from the property drains overland in a southeastern direction or towards the municipal stormwater sewer system along Bower Street.

There is no evidence to suggest the presence of abandoned or existing potable wells or septic tanks on the Site. However, eight (8) previously installed monitoring wells were identified on the property.

4.2.5 Parts of the Phase One Property Not Covered by Structures

There was no evidence of stressed vegetation or surficial staining identified on the Phase One Property during our Site reconnaissance on March 28, 2024. However, various debris including concrete and metal remnants (likely associated with building demolition activities) were observed in the vicinity of the former 2-storey building on the central portion of the property.

4.2.6 Enhanced Investigation of the Property

As per O.Reg. 153/04, a Phase One ESA will require the completion of an “Enhanced Property Investigation” should records indicate that a site has historically had any of the following land uses associated with it:

- Any industrial use;
- Operation of dry-cleaning equipment;
- Garage works; or
- Dispensing of bulk liquid (including gasoline, i.e. gas station).

The Phase One Property was not previously used for any of these purposes; thus, an enhanced property investigation is not required.

4.3 Written Description of Investigation

The investigations conducted for this ESA are described in Sections 2 through 4.

5. Review and Evaluation of Information

5.1 Current and Past Uses

The current and past land uses on the Phase One Property, as determined through the Phase One ESA records review, are summarized in **Table 5**, below.

Table 5. Land Use Summary

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
Prior to 1820	Crown	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1820 to 1830	Abraham Gilles	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1830 to 1843	George Tufford	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1843 to 1852	Charles Cameron	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1852 to 1852	Thomas Smith	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1852 to 1855	Edward Smith	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1855 to 1862	John Fleming & William Robinson	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1862 to 1862	John Goldie	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1862 to 1864	Samuel Smith	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1864 to 1875	Alexander Brown	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1875 to 1875	Joseph Lasby	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1875 to 1883	Charles Sidney Smith	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1883 to 1887	Donald Cameron	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1887 to 1894	Thomas C. Moore	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1894 to 1915	William Brown	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1915 to 1918	Alexander Donald & Edward Lacey	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
1918 to 1922	Donald McIvor	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1922 to 1939	Doniel H. Young	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1939 to 1941	Bruce Cornock Robson	Vacant, undeveloped land	Agriculture or Other Use	Chain of title revealed the aforementioned property owner
1941 to 1947	Hugh McCutcheon & Eva McCutcheon	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.
1947 to 1957	John J. Stewart & Edna Stewart	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.
1957 to 1961	Corporation of The Town of Acton	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.
1961 to 1961	John Wesley Wolf	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.
1961 to 1970	Alexander J. Orr & Hazel Irene Orr	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.
1970 to 1973	Frank Pethick & Ronald Legault	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.
1973 to 1975	Edward McMullen	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial photographs depicted building within the Phase One Property.

Year	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
1975 to 1982	Bank of Montreal	Residential building addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. The 1980 aerial photograph depicted a residential building and garage within the southern portion of Phase One Property.
1982 to 1989	Alexander Rudolf Schrempp & Brenda Joyce Denny	Residential building and free-standing structure addressed as 97 Bower Street	Residential Use	Chain of title revealed the aforementioned property owner. Aerial Photographs and City Directories revealed the Phase One Property Use. Aerial photographs depicted a residential building and garage within the southern portion of Phase One Property.
1989 to Present	759509 Ontario Inc.	Residential building addressed as 97 Bower Street. Buildings have been demolished since at least 2013 and Phase One Property has remained vacant since.	Residential Use	Chain of title revealed the aforementioned property owner. Aerial Photographs, Interviews, On-site Reconnaissance, and City Directories revealed the Phase One Property Use. Aerial photographs from 1980-2002 depicted a residential building and garage within the southern portion of Phase One Property. Aerial photographs from 2013-Present indicate that these buildings have been demolished and the Site is currently vacant.

5.2 Potentially Contaminating Activities (PCAs)

Potentially Contaminating Activities (PCAs) under the Environmental Protection Act are defined in in Schedule D (Table 2) of O.Reg. 153/04. A copy of this list is also provided in **Appendix I**. The PCAs identified within the Phase One ESA Study Area are illustrated on **Figure 5** and summarized in **Table 6** to **Table 9**, below.

5.2.1 Phase One Property

Based on the findings of the historical record review, site reconnaissance, and personal interviews; the following PCAs were identified in association with the Phase One Property:

Table 6. Summary of PCAs on the Phase One Property

Address	PCA	Location of APEC on Phase One Property
Phase One Property (97 Bower Street)	(1) #28. Gasoline and Associated Products Storage in Fixed Tanks. Prior environmental reports revealed the presence of former on-site heating oil underground storage tank (UST) located on west side of the former northern two-storey building.	Central Portion of Phase One Property
	(2) #30. Importation of Fill Material of Unknown Quality. The upper fill materials were observed to contain solid waste and debris during subsequent subsurface investigations. In addition, exceedances of PHCs, Metals, and PAHs were identified in soil and/or ground water.	Entirety of Phase One Property
	(3) #58. Waste Disposal and Waste Management including Thermal Treatment, Landfilling and Transfer of Waste, Other than use of Biosols as Soil Conditioners. Prior environmental reports revealed historic waste disposal at the Phase One Property which ceased in the early 1980s.	

5.2.2 Phase One Study Area

Based on the findings of the historical record review, site reconnaissance, and personal interviews; the following PCAs were identified in association with the Phase One Study Area:

Table 7. Summary of PCAs in the Phase One Study Area

Address	Potentially Contaminating Activity	Location of PCA			Location of APEC on Phase One Property
		On-Site/ Off-Site	Up-gradient (Y/N)	Proximity to Phase One Property	
Railway Adjacent to North Phase One Property Boundary	(1) #46. Rail Yards, Tracks and Spurs. Existing Railway corridor located adjacent to the northern property boundary of the Phase One Property.	Off-Site	Y	Adjacent	Northern Portion of Phase One Property
43-45 Alice Street	(1) #52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems. Vehicle maintenance and repairs are conducted in the maintenance area of the building. (2) #18. Electricity Generation, Transformation and Power Stations. Existing Hydro Facility adjacent to the western property boundary of the Phase One Property. (3) #28. Gasoline and Associated Products Storage in Fixed Tanks. One 10,000-L gasoline and one 10,000-L diesel fuel USTs were installed in 1989.	Off-Site	Y	Adjacent	Western Portion of Phase One Property
125 McDonald Boulevard	(1) #12. Concrete, Cement, and Lime Manufacturing. (2) #34. Metal Fabrication. Former industrial facility was operated between the late 1950s to the early 2020s as a manufacturer of various types of saws, metal equipment and parts, electrical vinyl insulating tape, radiator hoses and refractory products by H.K. Porter (Canada), Shurly-Dietrich Aikens Co. Ltd., Sandvik Canada Corp. (3) #43. Plastics (including Fiberglass) Manufacturing and Processing. Tri-El Limited conducted design and manufacturing of tarps and sand box covers for residential and commercial playground equipment. (4) #8. Chemical Manufacturing, Processing, and Bulk Storage. Available environmental	Off-Site	Y	160 m NW	Northwestern Portion of the Phase One Property

Address	Potentially Contaminating Activity	Location of PCA			Location of APEC on Phase One Property
		On-Site/ Off-Site	Up- gradient (Y/N)	Proximity to Phase One Property	
	reports indicate the presence of chemical storage areas. (5) #46. Rail Yards, Tracks and Spurs. Former railway spur. (6) #51. Solvent Manufacturing, Processing, and Bulk Storage. Presence of a solvent dip tank. (7) #54. Textile Manufacturing and Processing. Frank Heller & Company Limited and Blackhawk Leather conducted leather processing, cutting, stretching and application of lacquers. Tall People Furniture conducted furniture design and manufacturing. (8) #31. Ink Manufacturing, Processing, and Bulk Storage. Mikia Printing conducted design and printing. (9) #39. Paints Manufacturing, Processing, and Bulk Storage. Former spray paint booth. (10) #28. Gasoline and Associated Products Storage in Fixed Tanks. Former waste oil UST.				
19 Frederick Street N	(11) #28. Gasoline and Associated Products Storage in Fixed Tanks. Fill and Vent pipes observed for a heating oil UST.	Off-Site	N	60 m SE	N/A, property inferred to be located hydraulically down-gradient from the Phase One Property.
57 Willow Street North	(12) #18. Electricity Generation, Transformation and Power Stations. Acton Public Utilities Communications with associated transformers present in 1934. (13) #54. Textile Manufacturing and Processing. Mason Knitting Co. present in 1934. (14) #NA. Waste Generation. Waste oils and lubricants generated in 2021 by Halton Hills Hydro Inc.	Off-Site	N	245 m SW	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
53 Bower Street	(15) #54. Textile Manufacturing and Processing. Glove Factory (W.H. Storey & Son) present in 1934. (16) #NA. Waste Generation. PCBs generated in 2006 by Brookfield LePage Johnson Controls.	Off-Site	N	150 m SW	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
145 Mill Street East	(17) #52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems. Garage Repair Facility present in 1934. (18) #28. Gasoline and Associated Products Storage in Fixed Tanks. Four (4) associated USTs present in 1934.	Off-Site	N	140 m E	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
130 Mill Street East	(19) #52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems. Garage Repair Facility present in 1934. (20) #28. Gasoline and Associated Products Storage in Fixed Tanks. Two (2) associated USTs present in 1934. A propane tank and propane refill centre by Ciavone Investments Ltd. A retail fuel storage tank from R & R Honour enterprises Inc.	Off-Site	N	150 m E	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
41 Mill Street East	(21) #52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems. Auto Service Station present in 1934. (22) #28. Gasoline and Associated Products Storage in Fixed Tanks. One (1) associated UST present in 1934.	Off-Site	N	225 m SW	N/A, property inferred to be located hydraulically down-gradient from the Phase One Property.

Address	Potentially Contaminating Activity	Location of PCA			Location of APEC on Phase One Property
		On-Site/ Off-Site	Up- gradient (Y/N)	Proximity to Phase One Property	
153 Perth Street	(23) #34. Metal Fabrication. Acton Machine Shops present in 1934. (24) #NA. Waste Generation. Emulsified oils and waste oils/sludges generated in 2001 and 2021-2022 by Formtech Plastics Ontario Inc. and Vector Injection Ltd. (25) #43. Plastics (including Fiberglass) Manufacturing and Processing. Triple V Plastics Ltd. and Formtech Plastics Ontario Inc. operating as a plastic products manufacturing facility.	Off-Site	N	100 m NE	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
159 Perth Street	(26) #34. Metal Fabrication. Acton Machine Co. present in 1934. (27) #33. Metal Treatment, Coating, Plating, and Finishing. ANH Refractories Canada Inc., Global-GIX Canada Inc., HarbisonWalker Refractories, A.P. Green Refractories (CDA), and RHI America Refractories operating as a clay building material and refractory manufacturing facility. (28) #NA. Waste Generation. Waste oils and lubricants, petroleum distillates, and other specified inorganics generated from 2001-2022 by RHI Refractories of America, Global-GIX Canada Inc., ANH Refractories Canada Inc., and HarbisonWalker International Corp. (29) #28. Gasoline and Associated Products Storage in Fixed Tanks. One (1) FS appliance present.	Off-Site	N	140 m NE	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
76 Bower Street	(30) #NA. Waste Generation. Acid solutions, miscellaneous wastes and organic/inorganic chemicals, alkaline solutions, aliphatic solvents and residues, organic acids and other inorganic acid wastes generated in 2019 by Mark Dills.	Off-Site	N	70 m SW	N/A, property inferred to be located hydraulically down-gradient from the Phase One Property.
137 Mill Street East	(31) #NA. Waste Generation. Light fuels generated from 2016-2017 by Sotirios Investments Inc. and Danosh Construction.	Off-Site	N	143 m E	N/A, property inferred to be located hydraulically down-gradient from the Phase One Property.
59 Willow Street North	(32) #NA. Waste Generation. Alkaline wastes generated in 2015 by Compressed Air & Filtration.	Off-Site	N	190 m SW	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
12 Wallace Street	(33) #NA. Waste Generation. Paint/pigment/coating residues generated from 1994-1998 by Peter Zions Construction. (34) #43. Plastics (including Fiberglass) Manufacturing and Processing. Plastics Eighty Ltd. operating as a plastics products manufacturing facility.	Off-Site	N	155 m NE	N/A, property inferred to be located hydraulically cross-gradient from the Phase One Property.
10 Eastern Avenue	(35) #28. Gasoline and Associated Products Storage in Fixed Tanks. Previous AST present on construction site. (36) #NA. Spill. 600-L of diesel spilled to ground in 2010 by Maple Reinders Construction Ltd.	Off-Site	N	250 m E	N/A, property inferred to be located hydraulically down-gradient from the Phase One Property.

5.3 Areas of Actual or Potential Environmental Concern

5.3.1 Evaluation of Information

The purpose of this Phase One ESA was to document and identify any actual or potential environmental contamination associated with the property. A Phase One ESA is a preliminary study in which it is sufficient only to assess those liabilities which can be documented from a visual inspection of the property or available sources of public information.

The Phase One ESA does not include sampling or testing of soil or ground water. These analyses would be conducted in a Phase Two ESA, if warranted.

5.3.2 Identified Areas of Potential Environmental Concern

The current and historical PCAs on the Phase One Property and within the Phase One Study Area have the potential to contaminate the Phase One Property. The APECs are as follows:

Table 8. Summary of Identified APECs

Address	Location of APEC on Phase One Property	Rationale	Source of Information
97 Bower Street	Central Portion of Phase One Property	Historic Fuel Oil Tank, Potential Environmental Impacts	• Previous Studies (2.1.6)
97 Bower Street	Entirety of Phase One Property	Fill Material of Unknown Quality and Historic Waste Disposal, Potential Environmental Impacts	• Previous Studies (2.1.6)
Railway 10 m North of Property	Northern Portion of Phase One Property	Existing Railway Corridor, Potential Environmental Impacts	• Aerial Photographs (2.3.1) • Study Area Observations (4.5)
43-45 Alice Street	Western Portion of Phase One Property	Existing Hydro Facility, Potential Environmental Impacts	• Aerial Photographs (2.3.1) • Study Area Observations (4.5) • ERIS Database Report (2.2)
125 McDonald Boulevard	Northwestern Portion of Phase One Property	Historic Manufacturing Facility, Potential Environmental Impacts	• Aerial Photographs (2.3.1) • Study Area Observations (4.5) • ERIS Database Report (2.2)

5.3.3 Contaminants of Potential Concern

The contaminants of potential concern (COPC) identified with respect to each APEC identified in Section 5.3.2 are as follows:

Table 9. Summary of COPC

Address	Location of APEC on Phase One Property	COPC
97 Bower Street	Central Portion of Phase One Property	Petroleum Hydrocarbons (PHCs), Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX)
97 Bower Street	Entirety of Phase One Property	PHC, BTEX, Volatile Organic Compounds (VOCs), Polycyclic Aromatic Hydrocarbons (PAHs), Metals, Arsenic (As), Antimony (Sb), Selenium (Se), Sodium (Na), Boron-Hot Water Soluble (B-HWS), Chloride (Cl-), Chromium VI (Cr VI), Mercury (Hg), Cyanide (CN-), low or high pH, Electrical Conductivity (EC) and Sodium Adsorption Ratio (SAR)
Railway 10 m North of Property	Northern Portion of Phase One Property	PAHs, Metals, As, Sb, Se
43-45 Alice Street	Western Portion of Phase One Property	PHC, BTEX, VOC, Polychlorinated Biphenyls (PCBs), Metals, As, Sb, Se
125 McDonald Boulevard	Northwestern Portion of Phase One Property	PHCs, BTEX, VOCs, PAHs, Metals, As, Sb, Se, B-HWS, Cr VI, Hg, CN-, Na, Cl-

5.3.4 Information Gaps in Phase One Investigation

Full access to the Phase One Property was provided during the Site reconnaissance. All records were reviewed and no information gaps were encountered during the completion of the Phase One Investigation. Any outstanding responses that pose environmental concern will be forwarded to the Client upon receipt.

5.4 Phase One Conceptual Site Model

Site Description

The Phase One Property is a 0.92-hectare, irregular shaped, parcel of land located on the north side of Bower Street, west of the intersection with Wilbur Street North in Acton, Ontario. No building structures are present on the Phase One Property, which comprises asphalt-paved and grass areas, as well as a woodlot.

Historically, the Phase One Property was first developed since at least the late 1940s with a 2-storey building on the central portion. Since at least 1980, a 2-storey residential building and a garage was constructed on the southern portion of the Phase One Property. The buildings were all observed to be demolished prior to 2013. The buildings have been occupied by various residential tenants.

Water Bodies / Areas of Natural Significance

A tributary of Black Creek intersects the northwestern portion of the Phase One Property and exists within the Phase One Study Area. In addition, a provincially significant evaluated wetland is located approximately 230 m north of the Property within the Phase One Study Area.

Drinking Water Wells

There are no drinking water well records for the Phase One Property; however there is one (1) well record within the Phase One Property and seventy (70) well records within a 250 m search radius. These records relate to observation, test holes, and abandoned wells in the vicinity of the Phase One Property.

Neighboring Land Use

The Phase One Study Area is partly developed with commercial, residential, institutional, and industrial land uses, including a railway track that exists adjacent to the north boundary of the Phase One Property, as shown in **Figure 3**.

Areas of Potential Environmental Concerns (APECs)

Based on the findings of the historical record review, Site reconnaissance, and interviews, any APECs located on the Phase One Property and within the Phase One Study Area are labeled and located, as shown in **Figure 5**.

The following Potentially Contaminating Activities (PCAs) were found to be associated with the current or historical land uses of the Phase One Property and/or Phase One Study Area:

APEC	Location of APEC on the Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
APEC#1: Historic Fuel Oil Tank	Central Portion of the Phase One Property	#28: Gasoline and Associated Products Storage in Fixed Tanks	On-site – Prior environmental reports revealed the presence of a former on-site heating oil underground storage tank (UST) located on east side of the former northern two-storey building with fill and vent pipes along the west exterior wall.	Petroleum Hydrocarbons (PHCs), Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX)	Soil and Ground water
APEC#2: Fill Material of Unknown Quality and Historic Waste Disposal	Entirety of Phase One Property	#30: Importation of Fill Material of Unknown Quality #58: Waste Disposal and Waste Management including Thermal Treatment, Landfilling and Transfer of Waste, Other than use of Biosoils as Soil Conditioners	On-site - Prior environmental reports revealed historic waste disposal at the Phase One Property which ceased in the early 1980s. The upper fill materials were observed to contain solid waste and debris during subsequent subsurface investigations. In addition, exceedances of PHCs, Metals, and PAHs were identified in soil and/or ground water.	PHC, BTEX, Volatile Organic Compounds (VOCs), Polycyclic Aromatic Hydrocarbons (PAHs), Metals, Arsenic (As), Antimony (Sb), Selenium (Se), Sodium (Na), Boron-Hot Water Soluble (B-HWS), Chloride (Cl-), Chromium VI (Cr VI), Mercury (Hg), Cyanide (CN-), low or high pH, Electrical Conductivity (EC) and Sodium Adsorption Ratio (SAR)	Soil and Ground water
APEC#3: Existing Railway Corridor	Northern Portion of the Phase One Property	#46: Rail Yards, Tracks and Spurs	Off-Site - Existing Railway corridor located adjacent to the northern property boundary of the Phase One Property.	PAHs, Metals, As, Sb, Se	Soil and Ground water
APEC#4: Existing Hydro Facility	Western Portion of the Phase One Property	#52: Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems #18: Electricity Generation, Transformation and Power Stations #28: Gasoline and Associated Products Storage in Fixed Tanks	Off-Site – Existing Hydro Facility at 43-45 Alice Street adjacent to the western property boundary of the Phase One Property with transformers and equipment in operation since the 1960s. In addition, vehicle maintenance and repairs are conducted in the maintenance area of the building. One 10,000-L gasoline and one 10,000-L diesel fuel USTs were installed in 1989.	PHC, BTEX, VOC, Polychlorinated Biphenyls (PCBs), Metals, As, Sb, Se	Soil and Ground water
APEC#5: Historic Manufacturing Facility	Northwestern Portion of the Phase One Property	#12: Concrete, Cement, and Lime Manufacturing	Off-site - Former industrial facility at 125 McDonald Boulevard was operated between the late 1950s to	PHCs, BTEX, VOCs, PAHs, Metals, As, Sb, Se, B-HWS, Cr VI, Hg, CN-, Na, Cl-	Ground water

APEC	Location of APEC on the Phase One Property	PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
		#34: Metal Fabrication #43: Plastics (including Fiberglass) Manufacturing And Processing #8: Chemical Manufacturing, Processing, and Bulk Storage #46: Rail Yards, Tracks and Spurs #51: Solvent Manufacturing, Processing, and Bulk Storage #54: Textile Manufacturing and Processing #31 Ink Manufacturing, Processing, and Bulk Storage #39: Paints Manufacturing, Processing, and Bulk Storage #28: Gasoline and Associated Products Storage in Fixed Tanks	the early 2020s as a manufacturer of various types of saws, metal equipment and parts, electrical vinyl insulating tape, radiator hoses and refractory products by H.K. Porter (Canada), Shurly-Dietrich Aikens Co. Ltd., Sandvik Canada Corp.; Frank Heller & Company Limited and Blackhawk Leather conducted leather processing, cutting, stretching and application of lacquers; Tri-El Limited conducted design and manufacturing of tarps and sand box covers for residential and commercial playground equipment; Tall People Furniture conducted furniture design and manufacturing; Mikia Printing conducted design and printing. Available environmental reports indicate the presence of chemical storage areas, a solvent dip tank, former waste oil UST, former spray paint booth and a railway spur.		

Additional PCAs that were identified in association with the Phase One Study Area that are **not** considered to pose an APEC on the Phase One Property include:

PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
#18. Electricity Generation, Transformation and Power Stations	Off-Site	PHCs, VOCs, PCBs, Metals, As, Sb, Se	N/A

PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
#54. Textile Manufacturing and Processing	Off-Site	PHCs, VOCs, Metals, As, Sb, Se	N/A
#NA. Waste Generation	Off-Site	PHCs, BTEX	N/A
#54. Textile Manufacturing and Processing	Off-Site	PHCs, VOCs, Metals, As, Sb, Se	N/A
#NA. Waste Generation.	Off-Site	PCBs	N/A
#52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems	Off-Site	PHCs, BTEX, Metals, As, Sb, Se	N/A
#28. Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs, BTEX	N/A
#52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems	Off-Site	PHCs, BTEX, Metals, As, Sb, Se	N/A
#28. Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs, BTEX	N/A
#52. Storage, Maintenance, Fueling, and Repair of Equipment, Vehicles, and Material, Used to Maintain Transportation Systems	Off-Site	PHCs, BTEX, Metals, As, Sb, Se	N/A
#28. Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs, BTEX	N/A
#34. Metal Fabrication	Off-Site	Metals, As, Sb, Se	N/A
#NA. Waste Generation	Off-Site	PHCs, BTEX	N/A
#43. Plastics (including Fiberglass) Manufacturing and Processing	Off-Site	VOCs, Metals, As, Sb, Se	N/A
#34. Metal Fabrication	Off-Site	Metals, As, Sb, Se	N/A
#33. Metal Treatment, Coating, Plating, and Finishing	Off-Site	Metals, As, Sb, Se	N/A
#NA. Waste Generation	Off-Site	PHCs, BTEX	N/A
#28. Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs, BTEX	N/A
#NA. Waste Generation	Off-Site	PHCs, VOCs, Metals, As, Sb, Se, PAHs	N/A
#NA. Waste Generation	Off-Site	PHCs, BTEX	N/A
#NA. Waste Generation	Off-Site	PHCs, BTEX	N/A
#NA. Waste Generation	Off-Site	VOCs, Metals, As, Sb, Se, PAHs	N/A

PCA	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern (COPC)	Media Potentially Impacted (Ground water, Soil and/or Sediment)
#43. Plastics (including Fiberglass) Manufacturing and Processing	Off-Site	VOCs, Metals, As, Sb, Se	N/A
#28. Gasoline and Associated Products Storage in Fixed Tanks	Off-Site	PHCs, BTEX	N/A
#NA. Spill	Off-Site	PHCs, BTEX	N/A

Description of Assessment

PCAs with known or potential to affect the Phase One Property are as follows:

PCA Location	Location of APEC on the Phase One Property	Contaminants of Concern	Impact to Phase One Property (Known or Potential)
Phase One Property	Central Portion of Phase One Property	Petroleum Hydrocarbons (PHCs), Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX)	Potential
	Entirety of Phase One Property	PHC, BTEX, Volatile Organic Compounds (VOCs), Polycyclic Aromatic Hydrocarbons (PAHs), Metals, Arsenic (As), Antimony (Sb), Selenium (Se), Sodium (Na), Boron-Hot Water Soluble (B-HWS), Chloride (Cl-), Chromium VI (Cr VI), Mercury (Hg), Cyanide (CN-), low or high pH, Electrical Conductivity (EC) and Sodium Adsorption Ratio (SAR)	Potential
Railway Adjacent to North Phase One Property Boundary	Northern Portion of Phase One Property	PAHs, Metals, As, Sb, Se	Potential
43-45 Alice Street	Western Portion of Phase One Property	PHC, BTEX, VOC, Polychlorinated Biphenyls (PCBs), Metals, As, Sb, Se	Potential
125 McDonald Boulevard	Northwestern Portion of Phase One Property	PHCs, BTEX, VOCs, PAHs, Metals, As, Sb, Se, B-HWS, Cr VI, Hg, CN-, Na, Cl-	Potential

Additional PCAs that are **not** considered to pose an APEC to the Phase One Property are as follows:

PCA Location	Location of APEC on the Phase One Property	Contaminants of Concern	Impact to Phase One Property (Known or Potential)
57 Willow Street North	N/A Properties are inferred to be located hydraulically cross-	PHCs, VOCs, PCBs, Metals, As, Sb, Se	N/A Properties are inferred to be located hydraulically cross-gradient and/or down-
53 Bower Street		PHCs, VOCs, Metals, As, Sb, Se, PCBs	
145 Mill Street East		PHCs, BTEX, Metals, As, Sb, Se	

PCA Location	Location of APEC on the Phase One Property	Contaminants of Concern	Impact to Phase One Property (Known or Potential)
130 Mill Street East	gradient and/or down-gradient from the Phase One Property	PHCs, BTEX, Metals, As, Sb, Se	gradient from the Phase One Property
41 Mill Street East		PHCs, BTEX, Metals, As, Sb, Se	
153 Perth Street		PHCs, VOCs, Metals, As, Sb, Se	
159 Perth Street		PHCs, BTEX, Metals, As, Sb, Se	
76 Bower Street		PHCs, VOCs, Metals, As, Sb, Se, PAHs	
137 Mill Street East		PHCs, BTEX	
59 Willow Street North		PHCs, BTEX	
12 Wallace Street		VOCs, Metals, As, Sb, Se, PAHs	
10 Eastern Avenue		PHCs, BTEX	

Underground utilities are not expected to be present on the subject property.

Local surficial geologic mapping of the Acton area indicates sand and gravel, minor silt, clay and till derived from ice-contact stratified deposits, underlie the Phase One Property.

A tributary of Black Creek intersects the northwestern portion of the Phase One Property and exists within the Phase One Study Area. In addition, a provincially significant evaluated wetland is located approximately 230 m north of the Property within the Phase One Study Area. The local hydrogeology is controlled by this waterbody, the underlying geology, and the topography, and local ground water flow is expected to be southeastward. The regional ground water flow is also expected to be southeastward towards Lake Ontario.

It is not expected that any uncertainty or absence of information would affect the validity of the Conceptual Site Model (CSM).

6. Conclusions

6.1 Whether a Phase Two ESA is Required

The scope of this Phase One ESA conforms to the general requirements outlined in O.Reg. 153/04. The objectives of the Phase One ESA were to identify the likelihood of the presence or absence of PCAs and their associated APECs and COPC, in support of a development approval application with the Town of Halton Hills. The results of the Phase One ESA are documented in this report and reflect site conditions observed at the time of the site reconnaissance.

Based on the information obtained as part of the Phase One ESA, it is concluded that seventeen (17) PCAs were identified either on the Phase One Property or within the Phase One Study Area. These PCAs were deemed to be contributing to five (5) APECs on the Phase One Property.

A Phase Two ESA is recommended to assess subsurface impacts as a result of the aforementioned PCAs and APECs. The scope of the Phase Two ESA should entail the analysis of representative soil and ground water samples from the Phase One Property for the contaminants of potential concern identified; including PHCs, BTEX, VOCs, PAHs, Metals, As, Sb, Se, B-HWS, Cr VI, Hg, CN-, pH, Na, Cl-, EC, SAR, and PCBs.

6.2 Phase One ESA Alone


It is concluded that seventeen (17) PCAs were identified either on the Phase One Property or within the Phase One Study Area. Therefore, five (5) APECs were identified on the Phase One Property and a Phase Two ESA is required.

6.3 Signatures and Certification

This report was prepared by Bailey Fleet, B.Sc.(Env.), EPT who is currently an Environmental Scientist with Palmer. She has experience in conducting Phase One and Two ESAs at various land use types, in accordance with Ontario Regulation 153/04 and 511/09 and the CSA Z768-01 environmental protocols.

This report was reviewed by Kalina Naydenova, M.Sc. who is an Environmental Scientist with Palmer. She has over fourteen years' experience conducting numerous Phase One and Two ESAs at various land use types, conducting soil and ground water sampling procedures in accordance with ASTM 1527-13 and ASTM E1903-19, as well as experience with Ontario Regulation 153/04 and 511/09 and the CSA Z768-01 and Z769-00 environmental protocols.

This report was reviewed by Sarah Vlantis, B.Sc., P.Geo. (limited), Team Lead of Palmer. She has over 14 years' experience conducting Phase One and Two ESAs, soil and ground water sampling, and site remediation in accordance with Ontario Regulation 153/04 and 511/09, the CSA Z768-01 and Z769-00 environmental protocols, the Consulting Engineers of Ontario's Generally Accepted Standards for Environmental Investigations, and the Canadian Mortgage and Housing Corporation (CMHC) environmental site investigation procedures for mortgage loan insurance. The aforementioned ESAs have covered all land use types across Canada. Sarah also has numerous years of experience in preparing and filing Record of Site Conditions (RSCs) with the Ministry of the Environment, Conservation and Parks (MECP). Sarah also has experience conducting Excess Soil Reuse Planning assessments in accordance with Ontario Regulation 406/19.



Prepared By:

Bailey Fleet, B.Sc.(Env.), EPT
Environmental Scientist



Kalina Naydenova, M.Sc.
Environmental Scientist



Reviewed By:

Sarah Vlantis, B.Sc. P.Geo. (limited), QP_{ESA}
Team Lead, Land Quality and Remediation

7. Limitations of Report

This report has been prepared by Palmer for 759509 Ontario Inc. (Client) in accordance with the scope of work and all other terms and conditions of the agreement between such parties. Palmer acknowledges and agrees that the Client may provide this report to government agencies, interest holders, and/or Indigenous communities as part of project planning or regulatory approval processes. Copying or distribution of this report, in whole or in part, for any other purpose other than as aforementioned is not permitted without the prior written consent of Palmer.

Any findings, conclusions, recommendations, or designs provided in this report are based on conditions and criteria that existed at the time work was completed and the assumptions and qualifications set forth herein.

This report may contain data or information provided by third party sources on which Palmer is entitled to rely without verification and Palmer does not warranty the accuracy of any such data or information.

Nothing in this report constitutes a legal opinion nor does Palmer make any representation as to compliance with any laws, rules, regulations, or policies established by federal, provincial territorial, or local government bodies, other than as specifically set forth in this report. Revisions to legislative or regulatory standards referred to in this report may be expected over time and, as a result, modifications to the findings, conclusions, or recommendations may be necessary.

8. References

- Atlas of Canada, Topographic Maps;
 - <http://atlas.nrcan.gc.ca/Site/english/toporama/index.html>
- Chapman and Putnam, The Physiography of Southern Ontario, 1984;
- EcoLog ERIS Database Report, 97 Bower Street, Acton, Ontario, 2024;
- Esri Basemap Service, 2023;
- Fire Insurance Plan, 1934;
- Geomap Geophysics Ltd., An Electromagnetic Survey of the Caranci Residential Lots 268 & 272 (Acton), Town of Halton Hills, 1991
- Google Earth, 2018;
- Inspec-Soil Phase II Environmental Site Assessment, 97 Bower Street, Acton, Ontario, 2009
- Ontario Ministry of the Environment, Conservation and Parks (MECP);
- Radon Potential Map Ontario, Radon Environmental, 2013;
- Source Protection Information Atlas, 2020;
- Technical Standards & Safety Authority;
- The Ontario Geological Survey, 1990; and,
- The Ontario Geological Survey, 2003.


Figures



LEGEND

- Phase One Property
- Phase One Study Area
- ~ Watercourse¹

1. LIO/MNRF



North American Datum 1983
Universal Transverse Mercator Projection Zone 17


Scale: 1:3,500
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery (2023, Halton Region) provided by Esri basemap service.
Contains information licensed under the Open Government Licence – Ontario.




CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Site Location Map
Palmer™ PART OF SLR	REF. NO. 2402401-MR-101-1 Figure 1



LEGEND

- Phase One Property
- Phase One Study Area
- ← Inferred Ground Water Flow Direction



North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: May 2, 2024

Basemap:
Toporama web map service



CLIENT	759509 Ontario Inc	
PROJECT	97 Bower St, Acton, ON	
TITLE	Topographic Map	
	Palmer™ PART OF SLR	REF. NO. 2402401-MR-102-1 Figure 2



LEGEND

- Phase One Property
- Phase One Study Area
- Property Boundary
- ← Inferred Ground Water Flow Direction
- ~ Watercourse¹

1. LIO/MNRF

0 10 20 40 60 80 100
METRE SCALE

North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:3,500
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: May 2, 2024

Source Notes:
Imagery (2023, Halton Region) provided by Esri basemap service.
Contains information licensed under the Open Government Licence – Ontario.


 NORTH

CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Phase One Property
Palmer™	PART OF SLR
REF. NO.	2402401-MR-103-1
Figure 3	



LEGEND Phase One Property ← Inferred Ground Water Flow Direction ~ Watercourse¹	
1. LIO/MNRF 0 5 10 20 30 40 50 METRE SCALE North American Datum 1983 Universal Transverse Mercator Projection Zone 17 Scale: 1:1,000 Page Size: Letter (8.5 x 11 inches) Drawn: CV Checked: BF Date: May 2, 2024 Source Notes: Imagery (2023, Halton Region) provided by Esri basemap service. Contains information licensed under the Open Government Licence – Ontario.  NORTH	
CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Detailed Site Plan
 PART OF SLR	REF. NO. 2402401-MR-104-1 Figure 4



LEGEND

Phase One Property

Phase One Study Area

Inferred Ground Water Flow Direction

Watercourse¹

MECP Well Record

PCA of Concern (On-site)

PCA of Concern (Off-site)

PCA Not of Concern

APEC 1: Historic Fuel Oil Tank

APEC 2: Fill Material of Unknown Quality and Historic Waste Disposal

APEC 3: Existing Railway Corridor

APEC 4: Existing Hydro Facility

APEC 5: Historic Manufacturing Facility

020406080100

METRE SCALE

North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:2,500
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: May 2, 2024

Source Notes:
Imagery (2023, Halton Region) provided by Esri basemap service.
Contains information licensed under the Open Government Licence – Ontario.

NORTH

CLIENT	759509 Ontario Inc	
PROJECT	97 Bower St, Acton, ON	
TITLE	On-Site and Off-Site Areas of Potential Environmental Concern	
Palmer SLR PART OF	REF. NO.	2402401-MR-105-1
	Figure 5	

Document Path: G:\Shared drives\Projects 2024\24024 - 759509 Ontario Inc\2402401 - 97 Bower St (Acton)\GIS\1_Worksplace\Task 3 - EC Figures\100-PhOne.aprx

Appendix A

Photographic Documentation

**Photograph Log
Phase One ESA
97 Bower Street, Acton, ON
Project No.: 2402401**



Photograph 1

Photo depicts the northwest facing view of the Phase One Property.



Photograph 2

Photo depicts the northeast facing view of the Phase One Property.



Photograph 3

Photo depicts the southwest facing view of the Phase One Property.



Photograph 4

Photo depicts the southeast facing view of the Phase One Property.

**Photograph Log
Phase One ESA
97 Bower Street, Acton, ON
Project No.: 2402401**



Photograph 5

Photo depicts location of previously installed BH1/MW1 on the asphalt-paved driveway on the southern portion of the property.



Photograph 6

Photo depicts view of 43 Alice Street, adjacent to the Phase One Property to the southwest.



Photograph 7

Photo depicts location of previously installed MW7 on the southwest portion of the property.



Photograph 8

Photo depicts underground pipe found in the vicinity of the former building on the central portion of the property.

**Photograph Log
Phase One ESA
97 Bower Street, Acton, ON
Project No.: 2402401**



Photograph 9

Photo depicts location of previously installed MW8 on the west portion of the property.



Photograph 10

Photo depicts tributary of Black Creek located north of the Phase One Property.



Photograph 11

Photo depicts concrete/metal debris found in the vicinity of the former building on the central portion of the property.



Photograph 12

Photo depicts the view of the railway to the north of the Phase One Property.

**Photograph Log
Phase One ESA
97 Bower Street, Acton, ON
Project No.: 2402401**



Photograph 13

Photo depicts location of previously installed MW9 on the northwest portion of the property.



Photograph 14

Photo depicts location of previously installed MW10 on the north portion of the property.



Photograph 15

Photo depicts location of previously installed MW11 on the north portion of the property.



Photograph 16

Photo depicts location of previously installed MW5 on the north portion of the property.

**Photograph Log
Phase One ESA
97 Bower Street, Acton, ON
Project No.: 2402401**



Photograph 17

Photo depicts location of previously installed MW4 on the east portion of the property.



Photograph 18

Photo depicts the northeast view of the Phase One Study Area.



Photograph 19

Photo depicts the southwest view of the Phase One Study Area.



Photograph 20

Photo depicts the southeast view of the Phase One Study Area.

**Photograph Log
Phase One ESA
97 Bower Street, Acton, ON
Project No.: 2402401**




Photograph 21

Photo depicts the northwest view of the Phase One Study Area.


Appendix B

Aerial Photographs



LEGEND

- Phase One Property
- Phase One Study Area



North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery provided by ERS



CLIENT	759509 Ontario Inc	
PROJECT	97 Bower St, Acton, ON	
TITLE	Aerial Imagery (1946)	
	Palmer™ PART OF SLR	REF. NO. 2402401-MR-100-1 Figure B1



LEGEND

Phase One Property

Phase One Study Area

0204080120160200

METRE SCALE

North American Datum 1983

Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000

Page Size: Letter (8.5 x 11 inches)

Drawn: CV

Checked: BF

Date: Apr 15, 2024


Source Notes:

Imagery provided by ERI5

NORTH

CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Aerial Imagery (1969)
Palmer PART OF SLR REF. NO. 2402401-MR-100-1	Figure B2

Document Path: G:\Shared drives\Projects 2024\24024 - 759509 Ontario Inc\2402401 - 97 Bower St (Acton)\GIS\1_Workspace\Task 3 - EC Figures\100-PhOne.aprx



LEGEND

- Phase One Property
- Phase One Study Area

0

20

40

80

120

160

200

METRE SCALE

North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery provided by ERS

NORTH

CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Aerial Imagery (1974)
Palmer™ PART OF SLR REF. NO. 2402401-MR-100-1 Figure B3	



LEGEND

Phase One Property

Phase One Study Area

0204080120160200

METRE SCALE

North American Datum 1983

Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000

Page Size: Letter (8.5 x 11 inches)

Drawn: CV

Checked: BF

Date: Apr 15, 2024

Source Notes:


Imagery provided by ERIS



NORTH

CLIENT	759509 Ontario Inc	
PROJECT	97 Bower St, Acton, ON	
TITLE	Aerial Imagery (1980)	
	Palmer™ PART OF  SLR	REF. NO. 2402401-MR-100-1 Figure B4

Document Path: G:\Shared drives\Projects 2024\24024 - 759509 Ontario Inc\2402401 - 97 Bower St (Acton)\GIS\1_Workspace\Task 3 - EC Figures\100-PhOne.aprx



LEGEND

 Phase One Property

 Phase One Study Area

0 20 40 80 120 160 200

METRE SCALE

North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)


Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery provided by ERIS



NORTH

CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Aerial Imagery (1990)
 PART OF 	REF. NO. 2402401-MR-100-1 Figure B5



LEGEND

- Phase One Property
- Phase One Study Area



North American Datum 1983
Universal Transverse Mercator Projection Zone 17


Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery provided by Halton Hills map service



CLIENT	759509 Ontario Inc
PROJECT	97 Bower St, Acton, ON
TITLE	Aerial Imagery (2002)
Palmer™ PART OF SLR	REF. NO. 2402401-MR-100-1 Figure B6



LEGEND

- Phase One Property
- Phase One Study Area



North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery provided by Halton Hills map service




CLIENT	759509 Ontario Inc	
PROJECT	97 Bower St, Acton, ON	
TITLE	Aerial Imagery (2013)	
 PART OF 		REF. NO. 2402401-MR-100-1 Figure B7



LEGEND

-  Phase One Property
-  Phase One Study Area



North American Datum 1983
Universal Transverse Mercator Projection Zone 17

Scale: 1:5,000
Page Size: Letter (8.5 x 11 inches)

Drawn: CV
Checked: BF
Date: Apr 15, 2024

Source Notes:
Imagery provided by Esri basemap service



CLIENT	759509 Ontario Inc	
PROJECT	97 Bower St, Acton, ON	
TITLE	Aerial Imagery (2023)	
 PART OF 		REF. NO. 2402401-MR-100-1 Figure B8

Appendix C

Legal Plan of Survey

VERTICAL
DISTANCES SHOWN ON THIS PLAN ARE IN
METERS AND CAN BE CONVERTED TO FEET
BY DIVIDING BY 3.048

CLIENT COPY


759509 ONTARIO INC
97 BOWER ST ACTON
Single Detached
Demolition

09 111125 00 DP

AUG 14 2009

REC'D BACG. DEPT.

TOWN OF HALTON HILLS



REVIEWED BY
ZONING SECTION

AUG 18 2009

M. CUTHBERTSON

(H) R3-1/(CH) 02-1

TO BE
REMOVED

SURVEY NOTES

BOUNDARY INFORMATION COPIED FROM PLAN
200-12317 PREPARED BY CLIPSHAM LIMITED, DATED
FEBRUARY 5, 1997.
TOPOGRAPHIC INFORMATION FROM FIELD SURVEYS BY
CLIPSHAM LIMITED COMPLETED JULY 14, 2008 AND
AUGUST 1, 2008.
GORENFIELD, TESTIFY AND MONITORING WELL INFORMATION
FROM FIELD SURVEY BY CLIPSHAM LIMITED COMPLETED
AUGUST 11, 2008.
BENCHMARK: 110M-47
ELEVATION: 351.28
BRASS CAP IN SOUTH END CONCRETE HEADWALL ON
THE EAST SIDE OF WALLACE STREET (10.8M EAST OF
CENTRELINE OF WALLACE STREET WEST OF EAST FACE
AND 0.15M BELOW TOP OF CONCRETE).
TEMPORARY BENCHMARK: TBM1
ELEVATION: 351.26
RAILROAD SPIKE IN SIDE OF HYDRO PILE NO. A000077
IN FRONT OF 97 BOWER STREET.

The location and extent of all existing utilities are not
necessarily shown on this plan, and where shown, are
to be considered approximately only. All Contractors
shall confirm the location of the exact location and
extent of all existing utilities prior to the start of
construction, and shall assume all liabilities for damage
to them or to the resulting from their failure to do so.


ENGINEERING NOTES

1. EXISTING SATURDAY AND STORM SEWER INFECTIONS AND
FIRE SIZES FROM MEASUREMENTS TAKEN BY
CLIPSHAM LIMITED ON JULY 14, 2008.

GENERAL NOTES

- UNLESS OTHERWISE NOTED ON THE CHAIRMAN'S, THE
STANDARD TOAL, REGIONAL, AND CROSS-SECTION ARE TO
CONSTITUTE PART OF THIS CONTRACT AND SITE PLAN
DRAWINGS.
- THE APPROVAL OF THIS PLAN DOES NOT EXEMPT THE
OWNER'S CONTRACTOR FROM OBTAINING AND PAYING
FOR, BUT NOT LIMITED TO, THE FOLLOWING PERMITS:
ROAD CUTS, SEWER PERMITS, RELOCATION OF SERVICES,
CONCURRENCE AGREEMENTS, APPROACH APPROVAL
PERMITS, ETC. ALL PERMITS AS PER TOWN
STANDARD.
- PRIOR TO CONSTRUCTION, THE ENGINEER IS TO BE
NOTIFIED BY THE OWNER AND THE CONTRACTOR AS TO THE
EXTENT OF THE CONSTRUCTION WORKS THEY PROPOSE.
THE TOWN IS TO BE NOTIFIED BY THE CONTRACTOR
PRIOR TO CONSTRUCTION.
- THE CONTRACTOR SHALL BE RESPONSIBLE FOR ALL
TRAFFIC CONTROL AND SAFETY MEASURES DURING THE
CONSTRUCTION PERIOD, INCLUDING THE SUPPLY,
INSTALLATION AND REMOVAL OF ALL NECESSARY
TRAFFIC CONTROL DEVICES, DELINEATORS, MARKERS, ALL
SIGN ETC. SHALL CONFORM TO THE STANDARDS AND
SPECIFICATIONS FOR THE TOWN AND WITH MINIMUM
UNIFORM TRAFFIC CONTROL DEVICES FOR CHAIRMAN.
- THE CONTRACTOR SHALL PROVIDE ALL DISPERSED AREAS
TO BE OPEN TO TRAFFIC AND TO THE
SATISFACTION OF THE TOWN.
- BUILDING WILL NOT BE ALLOWED UNLESS AUTHORIZED BY
THE TOWN.
- ANY UTILITY RELOCATIONS DUE TO THIS DEVELOPMENT TO
BE UNDERMINED AT THE EXPENSE OF THE
OWNER/DEVELOPER.
- DRIVEWAYS SHALL BE SETBACK A MINIMUM CLEARANCE
OF 1.5M FROM ALL EXISTING OR PROPOSED CURBS OR
CONSTRUCTION.
- ALL CONSTRUCTION WORK IS TO BE CARRIED OUT IN
ACCORDANCE WITH THE REQUIREMENTS OF THE
OCCUPATIONAL HEALTH AND SAFETY ACT AND
REGULATIONS FOR CONSTRUCTION PROJECTS.

KEY PLAN



LEGEND

EX. EXISTING	PR. PROPOSED
NORTH ARROW	EX. ELEVATION TO TOWN
TEMPORARY BENCHMARK	PR. ELEVATION
EX. CONCRETE PILE	PR. TOP OF 1.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 2.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 3.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 4.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 5.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 6.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 7.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 8.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 9.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 10.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 11.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 12.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 13.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 14.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 15.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 16.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 17.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 18.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 19.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 20.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 21.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 22.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 23.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 24.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 25.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 26.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 27.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 28.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 29.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 30.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 31.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 32.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 33.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 34.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 35.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 36.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 37.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 38.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 39.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 40.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 41.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 42.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 43.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 44.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 45.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 46.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 47.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 48.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 49.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 50.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 51.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 52.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 53.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 54.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 55.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 56.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 57.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 58.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 59.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 60.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 61.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 62.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 63.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 64.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 65.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 66.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 67.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 68.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 69.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 70.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 71.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 72.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 73.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 74.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 75.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 76.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 77.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 78.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 79.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 80.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 81.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 82.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 83.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 84.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 85.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 86.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 87.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 88.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 89.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 90.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 91.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 92.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 93.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 94.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 95.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 96.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 97.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 98.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 99.5M DIA.
EX. CONCRETE PILE	PR. TOP OF 100.5M DIA.

Clipsham Limited
Consulting Engineers + Surveyors

759509 ONTARIO INC. (CARANGI)
301 JEVAN DRIVE
WOODBRIDGE, ON

BASE & REMOVAL PLAN
CARANGI SUBDIVISION
97 BOWER STREET, ACTON
PART LOTS 268 & 278, PLAN 1098
TOWN OF HALTON HILLS
REGIONAL MUNICIPALITY OF HALTON

PROJECT NO.
CB-JES9

DATE
AUG 14 2009

Appendix D

Land Registry Documents

CHAIN OF TITLE REPORT

Project #: 24032800818
Address: 97 Bower Street, Acton
Legal Description: Part Lot 268 & Lot 272 Plan 1098
Part 1, 20R12317

Searched at: Milton
LRO #: 20

Page 1

PIN #: 25002-0325 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
	Patent (200 Acres)	18 05 1820	Crown	Abraham GILLES
155	Deed	30 01 1830	Abraham Gilles	George TUFFORD
68	Deed	06 09 1843	George Tufford	Charles CAMERON
13 B	Deed	02 01 1852	Charles Cameron	Thomas SMITH
14 B	Deed	02 01 1852	Thomas Smith	Edward SMITH
195	Deed	29 09 1855	Edward Smith	John FLEMING William ROBINSON
167	Deed	26 03 1862	John Fleming William Robinson	John GOLDIE
168	Deed	26 03 1862	John Goldie	Samuel SMITH
636	Mortgage	22 01 1864	Samuel Smith	Alexander BROWN (Mortgagee)

Cont'd on Page 2

CHAIN OF TITLE REPORT

Project #: 24032800818
Address: 97 Bower Street, Acton
Legal Description: Part Lot 268 & Lot 272 Plan 1098
Part 1, 20R12317

Searched at: Milton
LRO #: 20

Page 2

PIN #: 25002-0325 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
1717	Deed (Power of Sale)	19 02 1875	Alexander Brown (Samuel Smith defaulted in Mtg)	Joseph LASBY
1718	Deed	19 02 1875	Joseph Lasby	Charles Sidney SMITH
3900	Deed	05 03 1883	Charles Sidney Smith	Donald CAMERON
935	Deed	22 01 1887	Donald Cameron	Thomas C. MOORE
1565	Deed	09 05 1894	Thomas C. Moore	William BROWN
3366	Deed	03 03 1915	William Brown	Alexander DONALD Edward LACEY
3604	Deed	02 12 1918	Alexander Donald Edward Lacey	Donald McIVOR
3971	Deed	16 03 1922	Donald McIvor	Daniel H. YOUNG
15525	Deed	05 10 1939	Daniel H. Young - Estate	Bruce Cornock ROBSON

Cont'd on Page 3

CHAIN OF TITLE REPORT

Project #: 24032800818
 Address: 97 Bower Street, Acton
 Legal Description: Part Lot 268 & Lot 272 Plan 1098
Part 1, 20R12317

Searched at: Milton
 LRO #: 20

Page 3

PIN #: 25002-0325 (LT)

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
15763	Deed	31 05 1941	Bruce Cornock Robson	Hugh McCUTCHEON Eva McCUTCHEON
17102	Deed	09 04 1947	Eva McCutcheon (surviving Joint Tenant)	John J. STEWART Edna STEWART
67773	Deed	26 08 1957	John J. Stewart Edna Stewart	Corporation of The Town of Acton
1098	Plan	29 05 1961	Corporation of The Town of Acton	John Wesley WOLF
131255	Deed	15 11 1961	John Wesley Wolf - Estate	Alexander J. ORR Hazel Irene ORR
292715	Deed	04 05 1970	Hazel Irene Orr (Surviving Joint Tenant)	Frank PETHICK Ronald LEGAULT
362199	Deed	22 05 1973	Frank Pethick Ronald Legault	Edward McMULLEN
411271	Mortgage	15 05 1975	Edward McMullen	Bank of Montreal (Mortgagee)

Cont'd on Page 4



CHAIN OF TITLE REPORT

Project #: 24032800818
Address: 97 Bower Street, Acton
Legal: Part Lot 268 & Lot 272 Plan 1098
Description: Part 1, 20R12317

PIN #: 25002-0325 (LT)

Searched at: Milton
LRO #: 20

INSTR #	DOC. TYPE	REG. DATE	PARTY FROM	PARTY TO
556696	Deed (Power of Sale)	30 04 1982	Bank of Montreal (Edward McMullen defaulted in Mtg)	Alexander Rudolf SCHREMPF Brenda Joyce DENNY
729285	Deed (Present Owner)	29 09 1989	Alexander Rudolf Schrempf Brenda Joyce Schrempf (Denny)	759509 Ontario Inc.



PROPERTY INDEX MAP
HALTON(No. 20)

LEGEND

FREEHOLD PROPERTY	
LEASEHOLD PROPERTY	
LIMITED INTEREST PROPERTY	
CONDOMINIUM PROPERTY	
RETIRED PIN (MAP UPDATE PENDING)	
PROPERTY NUMBER	0449
BLOCK NUMBER	08050
GEOGRAPHIC FABRIC	
EASEMENT	

THIS IS NOT A PLAN OF SURVEY

NOTES

REVIEW THE TITLE RECORDS FOR COMPLETE
PROPERTY INFORMATION AS THIS MAP MAY
NOT REFLECT RECENT REGISTRATIONS

THIS MAP WAS COMPILED FROM PLANS AND
DOCUMENTS RECORDED IN THE LAND
REGISTRATION SYSTEM AND HAS BEEN PREPARED
FOR PROPERTY INDEXING PURPOSES ONLY

FOR DIMENSIONS OF PROPERTIES BOUNDARIES SEE
RECORDED PLANS AND DOCUMENTS

ONLY MAJOR EASEMENTS ARE SHOWN

REFERENCE PLANS UNDERLYING MORE RECENT
REFERENCE PLANS ARE NOT ILLUSTRATED



PROPERTY DESCRIPTION:LT 272 & PT LT 268, MUP 1098, PT 1, 20R12317; HALTON HILLS

PROPERTY REMARKS:SUBJECT TO SECT 44(1) OF THE LAND TITLES ACT, EXCEPT PAR. 3 AND PROVINCIAL SUCCESSION DUTIES.

ESTATE/QUALIFIER:RECENTLY:PIN CREATION DATE:

FEE SIMPLE
ABSOLUTE

DIVISION FROM 25002-0099

1997/03/03

OWNERS' NAMESCAPACITY SHARE

759509 ONTARIO INC.

BENO

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE	2000/07/29	THE NOTATION OF THE	"BLOCK IMPLEMENTATION DATE" OF 1996/08/26 ON THIS PIN			
WAS REPLACED WITH THE	"PIN CREATION DATE"	OF 1997/03/03				
** PRINTOUT	INCLUDES ALL	DOCUMENT TYPES AND	DELETED INSTRUMENTS	SINCE 1997/03/03 **		
140478	1962/07/26	BYLAW				C
729285	1989/09/29	TRANSFER	\$680,000		759509 ONTARIO INC.	C
20R12317	1997/03/03	PLAN REFERENCE				C
H666464	1997/03/03	APL (GENERAL)		759509 ONTARIO INC.		C
REMARKS: QUALIFIED TO ABSOLUTE- PT 1, 20R12317						

NOTE: ADJOINING PROPERTIES SHOULD BE INVESTIGATED TO ASCERTAIN DESCRIPTIVE INCONSISTENCIES, IF ANY, WITH DESCRIPTION REPRESENTED FOR THIS PROPERTY.

NOTE: ENSURE THAT YOUR PRINTOUT STATES THE TOTAL NUMBER OF PAGES AND THAT YOU HAVE PICKED THEM ALL UP.

Appendix E

EcoLog ERIS Database Report



DATABASE REPORT

Project Property:	<i>Phase One ESA 97 Bower Street Acton ON L6Z 1M4</i>
Project No:	<i>P24002</i>
Report Type:	<i>Quote - Custom-Build Your Own Report</i>
Order No:	<i>24010300716</i>
Requested by:	<i>Palmer Environmental Consulting Group Inc.</i>
Date Completed:	<i>March 26, 2024</i>

Table of Contents

Table of Contents.....	2
Executive Summary.....	3
Executive Summary: Report Summary.....	4
Executive Summary: Site Report Summary - Project Property.....	7
Executive Summary: Site Report Summary - Surrounding Properties.....	8
Executive Summary: Summary By Data Source.....	30
Map.....	58
Aerial.....	59
Topographic Map.....	60
Detail Report.....	61
Unplottable Summary.....	348
Unplottable Report.....	350
Appendix: Database Descriptions.....	371
Definitions.....	381

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property: *Phase One ESA
97 Bower Street Acton ON L6Z 1M4*

Project No: *P24002*

Order Information:

Order No: *24010300716*

Date Requested: *January 3, 2024*

Requested by: *Palmer Environmental Consulting Group Inc.*

Report Type: *Quote - Custom-Build Your Own Report*

Historical/Products:

ERIS Xplorer [*ERIS Xplorer*](#)

Executive Summary: Report Summary

<i>Database</i>	<i>Name</i>	<i>Searched</i>	<i>Project Property</i>	<i>Boundary to 0.25km</i>	<i>Total</i>
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	0	0
CA	Certificates of Approval	Y	0	11	11
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	2	2
EASR	Environmental Activity and Sector Registry	Y	0	2	2
EBR	Environmental Registry	Y	0	1	1
ECA	Environmental Compliance Approval	Y	0	14	14
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	1	30	31
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	2	2
FSTH	Fuel Storage Tank - Historic	Y	0	2	2
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	93	93
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	1	1

Database	Name	Searched	Project Property	Boundary to 0.25km	Total
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	1	1
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	8	8
NPR2	National Pollutant Release Inventory 1993-2020	Y	0	1	1
NPRI	National Pollutant Release Inventory - Historic	Y	0	0	0
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	8	8
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	2	2
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handlers from NPRI	Y	0	0	0
PINC	Pipeline Incidents	Y	0	3	3
PRT	Private and Retail Fuel Storage Tanks	Y	0	2	2
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	4	4
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directory	Y	0	14	14
SPL	Ontario Spills	Y	0	5	5
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	0	0
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	0	0	0
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	1	70	71

<i>Database</i>	<i>Name</i>	<i>Searched</i>	<i>Project Property</i>	<i>Boundary to 0.25km</i>	<i>Total</i>
		Total:	2	276	278

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	EHS		97 Bower Street Halton Hills (Acton) ON L7J 1E4	NE/0.0	-0.85	61
1	WWIS		97 BOWER ST. ACTON ON <i>Well ID:</i> 7120007	NE/0.0	-0.85	61

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>2</u>	CA	R.M. OF HALTON - (ACTON)	BOWER ST./FREDERICK ST./WILBUR HALTON HILLS TOWN ON	SE/6.9	1.17	<u>64</u>
<u>3</u>	WWIS		n/a n/a lot 28 con 3 Rockwood ON Well ID: 7378700	NW/23.3	-0.69	<u>65</u>
<u>4</u>	WWIS		lot 28 con 3 ON Well ID: 2809690	NW/74.8	2.11	<u>68</u>
<u>5</u>	GEN	MEDICAL PHARMACY	93 MILL STREET EAST PHARMACY ACTON ON L7J 1H5	SE/79.6	2.31	<u>69</u>
<u>6</u>	GEN	Mark Dills	76 Bower Avenue Acton ON L7J 2B2	S/83.5	1.24	<u>70</u>
<u>7</u>	SPL	Halton Hills Hydro	45 Alice Street, Acton Halton Hills ON	SW/88.8	-0.73	<u>70</u>
<u>8</u>	CA	R.M. OF HALTON - (ACTON)	BOWER ST./WILBUR ST./MILL ST. HALTON HILLS TOWN ON	ESE/100.3	2.34	<u>71</u>
<u>9</u>	SCT	TRIPLE V PLASTICS LTD.	153 PERTH ST ACTON ON L7J 1C9	ENE/106.6	0.36	<u>72</u>
<u>9</u>	GEN	FORMTECH PLASTICS ONTARIO INC.	153 PERTH STREET ACTON ON L7J 1C9	ENE/106.6	0.36	<u>72</u>
<u>9</u>	SCT	Formtech Plastics Ontario Inc.	153 Perth St Acton ON L7J 1C9	ENE/106.6	0.36	<u>72</u>
<u>9</u>	GEN	Vector Injection Ltd	153 Perth St Acton ON L7J1C9	ENE/106.6	0.36	<u>73</u>
<u>9</u>	GEN	Formtech Plastics Ontario Inc.	153 Perth St. Acton ON L7J 1C9	ENE/106.6	0.36	<u>73</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>9</u>	GEN	Vector Injection Ltd	153 Perth St Acton ON L7J1C9	ENE/106.6	0.36	<u>73</u>
<u>10</u>	WWIS		137 MILL ST. E. ACTON ON Well ID: 7269004	E/117.1	2.31	<u>74</u>
<u>11</u>	RSC	2467766 ONTARIO INC.	71 - 79 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 69 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 94 - 96 MILL STREET, GEORGETOWN, ON L7G 2C9 Halton Hills ON	SE/121.6	3.15	<u>77</u>
<u>11</u>	RSC	2467766 ONTARIO INC.	94 - 96 MILL STREET ON Halton Hills ON	SE/121.6	3.15	<u>77</u>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET GEORGETOWN ON L7J 2A9	SW/123.7	-0.73	<u>78</u>
<u>12</u>	NPCB	HALTON HILLS HYDRO	43 ALICE STREET GEORGETOWN ON L7J 2A9	SW/123.7	-0.73	<u>78</u>
<u>12</u>	PRT	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TR	43 ALICE ST ACT ON L7J 2A9	SW/123.7	-0.73	<u>78</u>
<u>12</u>	NPCB	HALTON HILLS HYDRO	43 ALICE STREET ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>78</u>
<u>12</u>	CA	HALTON HILLS HYDRO- ELECTRIC COMMISSION	43 ALICE STREET, ACTON HALTON HILLS TOWN ON L7J 2A9	SW/123.7	-0.73	<u>79</u>
<u>12</u>	CA		43 Alice Street Acton ON L7J 2A9	SW/123.7	-0.73	<u>79</u>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>79</u>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>80</u>

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Dir/Dist (m)</i>	<i>Elev Diff (m)</i>	<i>Page Number</i>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>81</u>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>81</u>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET GEORGETOWN ON L7J 2A9	SW/123.7	-0.73	<u>82</u>
<u>12</u>	GEN	HALTON HILLS HYDRO- ELECTRIC COMM.	43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	SW/123.7	-0.73	<u>82</u>
<u>12</u>	GEN	HALTON HILLS HYDRO	43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	SW/123.7	-0.73	<u>82</u>
<u>12</u>	GEN	HALTON HILLS HYDRO- ELECTRIC COMM. 19-094	43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	SW/123.7	-0.73	<u>83</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>83</u>
<u>12</u>	NPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>84</u>
<u>12</u>	OPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>84</u>
<u>12</u>	FSTH	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON L7J 2A9	SW/123.7	-0.73	<u>85</u>
<u>12</u>	FSTH	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON L7J 2A9	SW/123.7	-0.73	<u>85</u>
<u>12</u>	NPCB	HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>85</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>12</u>	HINC		43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>86</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>86</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>87</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>88</u>
<u>12</u>	FST	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON	SW/123.7	-0.73	<u>88</u>
<u>12</u>	FST	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON	SW/123.7	-0.73	<u>88</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>89</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON	SW/123.7	-0.73	<u>89</u>
<u>12</u>	OPCB	Halton Hills Hydro	43 Alice St. Acton ON L7J 2A9	SW/123.7	-0.73	<u>90</u>
<u>12</u>	ECA	Halton Hills Hydro	43 Alice Street Acton ON L7J 2A9	SW/123.7	-0.73	<u>90</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>90</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>91</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>92</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>92</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>93</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>93</u>
<u>12</u>	GEN	HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	SW/123.7	-0.73	<u>94</u>
<u>13</u>	WWIS		METRO LINX ACTON ON Well ID: 7221211	ENE/124.6	1.31	<u>94</u>
<u>14</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7362200	WNW/125.3	5.42	<u>98</u>
<u>15</u>	SPL		61 Bower St (Acton) Halton Hills ON	SSW/126.9	0.31	<u>101</u>
<u>15</u>	PINC	PIPELINE HIT - 1/2"	61 BOWER ST,,ACTON,ON,L7J 1E4,CA ON	SSW/126.9	0.31	<u>102</u>
<u>16</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7361995	WNW/127.2	5.31	<u>102</u>
<u>17</u>	WWIS		137 MILL ST. E. ACTON ON Well ID: 7269005	E/128.4	2.33	<u>106</u>
<u>18</u>	SCT	HARBISON-WALKER REFRACTORIES	159 PERTH ST ACTON ON L7J 1C9	ENE/134.6	0.33	<u>109</u>
<u>18</u>	SCT	A.P. GREEN REFRACTORIES (CDA)	159 PERTH ST ACTON ON L7J 1C9	ENE/134.6	0.33	<u>109</u>
<u>18</u>	SCT	RHI AMERCIA REFRACTORIES	159 Perth St Acton ON L7J 1C9	ENE/134.6	0.33	<u>109</u>

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Dir/Dist (m)</i>	<i>Elev Diff (m)</i>	<i>Page Number</i>
<u>18</u>	SCT	RHI Refractories America	159 Perth St Acton ON L7J 1C9	ENE/134.6	0.33	<u>110</u>
<u>18</u>	GEN	RHI REFRACTORIES OF AMERICA	159 PERTH STREET HALTON ON L7J 1C9	ENE/134.6	0.33	<u>110</u>
<u>18</u>	SCT	Global-GIX Canada Inc.	159 Perth St Acton ON L7J 1C9	ENE/134.6	0.33	<u>110</u>
<u>18</u>	GEN	Global-GIX Canada Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>110</u>
<u>18</u>	SCT	ANH Refractories Canada Inc.	159 Perth St Acton ON L7J 1C9	ENE/134.6	0.33	<u>111</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>111</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>111</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>112</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>112</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>113</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J1C9	ENE/134.6	0.33	<u>113</u>
<u>18</u>	EHS		159 Perth St Halton Hills ON L7J1C9	ENE/134.6	0.33	<u>113</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON	ENE/134.6	0.33	<u>113</u>

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Dir/Dist (m)</i>	<i>Elev Diff (m)</i>	<i>Page Number</i>
<u>18</u>	GEN	HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>114</u>
<u>18</u>	GEN	HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>114</u>
<u>18</u>	GEN	ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>114</u>
<u>18</u>	GEN	HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>115</u>
<u>18</u>	GEN	HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>115</u>
<u>18</u>	EASR	HARBISONWALKER INTERNATIONAL CORP.	159 Perth ST Acton ON L7J 1C9	ENE/134.6	0.33	<u>116</u>
<u>18</u>	SPL	HarbisonWalker International Corp.	159 Perth St Acton Halton Hills ON L7J 1C9	ENE/134.6	0.33	<u>116</u>
<u>18</u>	GEN	HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>117</u>
<u>18</u>	GEN	HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>117</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>117</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>118</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>118</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>118</u>

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Dir/Dist (m)</i>	<i>Elev Diff (m)</i>	<i>Page Number</i>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>118</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>118</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>119</u>
<u>18</u>	EHS		159 Perth Street Acton ON L7J 1C9	ENE/134.6	0.33	<u>119</u>
<u>19</u>	EHS		80 Mill Street East Acton ON L7J 1H6	SSE/138.8	2.34	<u>119</u>
<u>20</u>	GEN	Sotirios Investments Inc	137 Mill Street East Acton ON L7J1H9	E/141.2	2.61	<u>119</u>
<u>20</u>	GEN	Danosh Construction	137 mill street east Acton ON L7J 1H9	E/141.2	2.61	<u>120</u>
<u>20</u>	EHS		137 Mill Street East Acton ON L7J 1H9	E/141.2	2.61	<u>120</u>
<u>20</u>	EHS		137 Mill Street East Acton ON L7J 1H9	E/141.2	2.61	<u>120</u>
<u>20</u>	EHS		137 Mill Street East Acton ON L7J 1H9	E/141.2	2.61	<u>120</u>
<u>20</u>	EHS		137 Mill Street East Acton ON L7J 1H9	E/141.2	2.61	<u>120</u>
<u>20</u>	EHS		137 Mill Street East Acton ON L7J 1H9	E/141.2	2.61	<u>121</u>
<u>21</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350907	WNW/155.0	5.27	<u>121</u>
<u>22</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WNW/155.2	5.27	<u>124</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7360685			
23	GEN	Brookfield LePage Johnson Controls	53 Bower Street Acton ON L7J 1E1	SSW/160.9	0.36	127
24	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7337156	WNW/162.6	5.27	128
25	PRT	R & R HONOUR ENTERPRISES INC	130 MILL ST E ACTON ON L7J1J1	ESE/166.9	3.73	132
25	SCT	Acton Denture Clinic	130 Mill St E Suite 103 Acton ON L7J 1J1	ESE/166.9	3.73	132
25	EHS		130 Mill Street Acton ON	ESE/166.9	3.73	132
25	DTNK	CIAVONE INVESTMENTS LTD	130 MILL ST E ACTON ON	ESE/166.9	3.73	132
25	DTNK	CIAVONE INVESTMENTS LTD	130 MILL ST E ACTON ON	ESE/166.9	3.73	133
25	PES	CANADIAN TIRE STORE 183/R & R HONOUR ENTERPRISES INC	130 MILL STREET EAST ACTON ON L7J1J1	ESE/166.9	3.73	133
26	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7360715	WNW/168.7	6.00	134
27	WWIS		ON Well ID: 7285175	NW/170.7	6.00	137
27	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350987	NW/170.7	6.00	138
28	PINC	PIPELINE HIT 1/2"	50 BOWER ST,,ACTON,ON,L7J 1E3,CA ON	SSW/173.5	0.44	142
29	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON	WNW/173.7	6.02	142

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7388615			
30	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350991	WNW/176.2	5.30	145
31	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7362146	WNW/176.6	5.31	148
32	WWIS		151 MILL ST AT RAILWAY CROSSING ACTON ON Well ID: 7346699	E/176.9	2.31	151
33	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350957	NW/177.2	6.00	155
34	CA	R.M. OF HALTON	MILL ST./FELLOWS ST. HALTON HILLS TOWN ON	E/178.7	3.00	158
35	GEN	SHOEMAKER FUNERAL HOME	55 MILL STREET EAST ACTON ON L7J 1H4	S/179.1	1.31	158
35	GEN	SHOEMAKER FUNERAL HOME	55 MILL STREET EAST ACTON ON L7J 1H4	S/179.1	1.31	158
35	GEN	SHOEMAKER FUNERAL HOME 44-053	55 MILL STREET EAST ACTON ON L7J 1H4	S/179.1	1.31	159
35	GEN	MACKINNON FAMILY FUNERAL HOME INC.	55 MILL STREET EAST ACTON ON L7J 1H4	S/179.1	1.31	159
35	GEN	MACKINNON FAMILY FUNERAL HOME INC.	SHOEMAKER CHAPEL 55 MILL STREET EAST ACTON ON L7J 1H4	S/179.1	1.31	160
35	GEN	MACKINNON FAMILY FUNERAL HOME INC.	SHOEMAKER CHAPEL 55 MILL STREET EAST ACTON ON L7J 1H4	S/179.1	1.31	160
35	GEN	MacKinnon Family Funeral Home	55 Mill Street East Acton ON L7J 1H4	S/179.1	1.31	160

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>35</u>	GEN	Mackinnon Family Funeral Home	55 Mill Street East Acton ON L7J 1H4	S/179.1	1.31	<u>161</u>
<u>35</u>	EHS		55 mill street east Acton ON L7J 1H4	S/179.1	1.31	<u>161</u>
<u>35</u>	EHS		55 mill street east Acton ON L7J 1H4	S/179.1	1.31	<u>161</u>
<u>35</u>	EHS		55 mill street east Acton ON L7J 1H4	S/179.1	1.31	<u>161</u>
<u>35</u>	EHS		55 mill street east Acton ON L7J 1H4	S/179.1	1.31	<u>162</u>
<u>36</u>	GEN	Compressed Air & Filtration	59 Willow St. N. Unit #3 Acton ON L7J1Z8	WSW/181.6	-0.96	<u>162</u>
<u>37</u>	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388626	NW/183.9	6.31	<u>162</u>
<u>38</u>	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON Well ID: 7375865	NW/186.1	6.31	<u>165</u>
<u>39</u>	GEN	HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON	W/187.0	4.49	<u>168</u>
<u>39</u>	GEN	HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	W/187.0	4.49	<u>168</u>
<u>39</u>	GEN	HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	W/187.0	4.49	<u>168</u>
<u>39</u>	GEN	HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	W/187.0	4.49	<u>169</u>
<u>39</u>	GEN	HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	W/187.0	4.49	<u>169</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>40</u>	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7362157	WNW/187.8	5.31	<u>169</u>
<u>41</u>	ECA	The Corporation of the Town of Halton Hills	128 McDonald Blvd 12 Division Street Halton Hills ON L7G 5G2	N/188.1	2.31	<u>172</u>
<u>42</u>	NPCB	CANADA POST	C/O ROYAL LEPAGE MANAGEMENT; 45 BOWER STREET ACTON-HALTON HILLS POST OFFICE; 45 BOWER ST ACTON ON L7J 1E1	SSW/188.7	0.29	<u>173</u>
<u>42</u>	NPCB	CANADA POST	45 BOWER STREET ACTON-HALTON HILLS POST OFFICE; 45 BOWER ST ACTON ON L7J 1E1	SSW/188.7	0.29	<u>173</u>
<u>42</u>	NPCB	CANADA POST	45 BOWER STREET c/ o ROYAL LEPAGE MANAGEMENT Acton ON L7J 1E1	SSW/188.7	0.29	<u>173</u>
<u>42</u>	NPCB	CANADA POST	45 BOWER ST C/O ROYAL LEPAGE MANAGEMENT ACTON ON L7J 1E1	SSW/188.7	0.29	<u>174</u>
<u>43</u>	EHS		146 Mill St E Halton Hills ON L7J1J1	E/189.5	3.31	<u>174</u>
<u>44</u>	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388625	WNW/190.9	6.02	<u>174</u>
<u>45</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7360720	NW/191.2	6.34	<u>177</u>
<u>46</u>	SCT	PLASTICS EIGHTY LTD	12 WALLACE ST ACTON ON L7J 2V6	ENE/191.2	2.00	<u>180</u>
<u>46</u>	GEN	PETER ZIONS CONSTRUCTION	12 WALLACE STREET ACTON ON L7J 2V6	ENE/191.2	2.00	<u>180</u>
<u>47</u>	WWIS		125 McDonald Blvd lot 29 con 3 Acton ON Well ID: 7376265	NW/191.4	4.61	<u>180</u>
<u>48</u>	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON	NW/191.7	6.31	<u>184</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7375845			
49	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON Well ID: 7375851	WNW/192.3	5.46	187
50	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350954	WNW/192.9	6.02	189
51	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388622	NW/194.1	6.31	192
52	WWIS		ON Well ID: 7306391	WNW/197.0	6.31	195
53	WWIS		125 McDonald Blvd lot 29 con 3 Acton ON Well ID: 7376268	WNW/197.4	6.31	196
54	WWIS		ON Well ID: 7345190	NW/197.5	6.34	199
55	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350958	WNW/200.1	5.46	201
56	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON Well ID: 7375864	WNW/200.1	6.31	204
57	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7406702	WNW/202.0	6.31	206
58	CA	R.M. OF HALTON	MILL STREET/BOWER STREET HALTON HILLS TOWN ON	E/202.6	2.38	209
59	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388624	WNW/203.2	5.46	210
60	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388614	WNW/203.6	6.31	212
61	WWIS		125 McDONALD BLVD lot 29 con 3 ACTON ON	NW/206.9	5.28	215

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7352056			
62	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350972	WNW/208.4	6.31	219
63	EHS		52 Mill St East Acton ON L7J 1H3	S/208.5	1.31	222
64	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7360681	NW/208.9	6.34	222
65	WWIS		ON Well ID: 7311615	NW/213.5	6.34	225
66	SPL	Maple Reinders Construction Limited	10 Eastern Ave, Acton ON Halton Hills ON L7J 0A5	E/213.7	3.35	226
66	INC		10 EASTERN AVENUE, ACTON ON	E/213.7	3.35	227
66	GEN	Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	E/213.7	3.35	228
66	GEN	Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	E/213.7	3.35	228
66	GEN	Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	E/213.7	3.35	229
66	GEN	Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	E/213.7	3.35	229
66	GEN	Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	E/213.7	3.35	229
66	GEN	Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	E/213.7	3.35	230
66	GEN	Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	E/213.7	3.35	230

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>66</u>	GEN	Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	E/213.7	3.35	<u>231</u>
<u>66</u>	GEN	Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	E/213.7	3.35	<u>231</u>
<u>66</u>	GEN	Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	E/213.7	3.35	<u>231</u>
<u>66</u>	GEN	Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	E/213.7	3.35	<u>232</u>
<u>66</u>	GEN	Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	E/213.7	3.35	<u>232</u>
<u>67</u>	GEN	Halton Hills Hydro Inc. Halton Hills Hydro Inc.	57 Willow St. N Acton ON L7J 1Z8	WSW/216.2	-1.28	<u>232</u>
<u>68</u>	PES	ACTON HOME HARDWARE	43 MILL ST ACTON ON L7J 1E8	S/218.2	1.31	<u>233</u>
<u>69</u>	WWIS		125 McDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7351992	NW/218.8	5.61	<u>233</u>
<u>70</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350911	WNW/220.7	6.31	<u>237</u>
<u>71</u>	WWIS		ON Well ID: 7171098	WNW/222.0	6.31	<u>240</u>
<u>72</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7406731	NW/222.3	5.61	<u>241</u>
<u>73</u>	WWIS		n/a n/a lot 29 con 3 Guelph ON Well ID: 7378699	W/222.8	4.31	<u>244</u>
<u>74</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON	NW/223.7	5.61	<u>247</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7337187			
75	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON Well ID: 7375866	NW/223.7	5.61	250
76	WWIS		ON Well ID: 7315547	WNW/224.6	5.22	253
77	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388627	NW/226.6	5.61	254
78	WWIS		125 McDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7352094	NW/228.6	6.34	257
79	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388621	NW/230.1	6.34	261
80	CA	BLACKHAWK LEATHER LIMITED	125 MCDONALD BLVD. W., ACTON HALTON HILLS TOWN ON	NW/232.2	6.34	264
80	CA	EAGLE DOMINION INC.	125 MCDONALD BLVD., ACTON HALTON HILLS TOWN ON L7J 2V7	NW/232.2	6.34	264
80	CA	BLACKHAWK LEATHER LIMITED	125 MCDONALD BLVD. W., ACTON HALTON HILLS TOWN ON	NW/232.2	6.34	265
80	CA	EAGLE DOMINION INC.	125 MCDONALD BLVD., ACTON HALTON HILLS TOWN ON L7J 2V7	NW/232.2	6.34	265
80	CA	EAGLE OTTAWA CANADA LTD.	125 MCDONALD BOULEVARD, ACTON HALTON HILLS ON L7J 2V7	NW/232.2	6.34	265
80	SCT	EAGLE OTTAWA CANADA LTD.	125 MCDONALD BLVD ACTON ON L7J 2V7	NW/232.2	6.34	265
80	SCT	PERMAIR LEATHERS LIMITED	125 McDonald Blvd Acton ON L7J 2V7	NW/232.2	6.34	266
80	GEN	FRANK HELLER & COMPANY LTD.	125 MCDONALD BLVD. ACTON ON L7J 2V7	NW/232.2	6.34	266

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Dir/Dist (m)</i>	<i>Elev Diff (m)</i>	<i>Page Number</i>
80	GEN	EAGLE DOMINION INC.	125 MCDONALD BLVD.. ACTON ON L7J 2V7	NW/232.2	6.34	266
80	GEN	EAGLE OTTAWA CANADA, LTD. 15-268	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	NW/232.2	6.34	267
80	GEN	BLACKHAWK LEATHER LTD. 15-268	125 MCDONALD BLVD.. ACTON ON L7J 2V7	NW/232.2	6.34	267
80	GEN	EAGLE OTTAWA CANADA, LTD	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	NW/232.2	6.34	268
80	GEN	EAGLE OTTAWA CANADA, LTD.	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	NW/232.2	6.34	268
80	GEN	PERMAIR LEATHERS LIMITED	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	NW/232.2	6.34	269
80	SCT	Whiteclay Enterprises Inc.	125 McDonald Blvd Unit 5 Acton ON L7J 2V7	NW/232.2	6.34	269
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	269
80	EBR	Mikia Printing Ltd.	125 MacDonald Boulevard, Unit 3, Acton Halton Hills Ontario L7J 2M2 Halton Hills ON	NW/232.2	6.34	270
80	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	270
80	SCT	Beardmore Leathers	125 McDonald Blvd Acton ON L7J 2V7	NW/232.2	6.34	271
80	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	271
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	271

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Dir/Dist (m)</i>	<i>Elev Diff (m)</i>	<i>Page Number</i>
80	EHS		125 McDonald Blvd. Acton ON L7J 2V7	NW/232.2	6.34	272
80	EHS		125 McDonald Boulevard Acton ON L7J 2V7	NW/232.2	6.34	272
80	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	272
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	273
80	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	273
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	273
80	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	274
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	274
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON	NW/232.2	6.34	275
80	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON	NW/232.2	6.34	275
80	ECA	Frank Heller & Co. Limited	125 McDonald Blvd Halton Hills ON N1G 4X7	NW/232.2	6.34	276
80	ECA	Mikia Printing Ltd.	125 MacDonald Boulevard, Unit 3, Acton Halton Hills ON L7J 2M2	NW/232.2	6.34	276
80	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	276

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>80</u>	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	<u>277</u>
<u>80</u>	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	<u>277</u>
<u>80</u>	GEN	Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	NW/232.2	6.34	<u>278</u>
<u>80</u>	GEN	Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	NW/232.2	6.34	<u>278</u>
<u>80</u>	GEN	Frank Heller & Company Limited	125 McDonald Blvd Acton ON L7J2V7	NW/232.2	6.34	<u>278</u>
<u>80</u>	EASR	DREXLER CONSTRUCTION LIMITED	125 McDonald BLVD Acton ON L7J 2V7	NW/232.2	6.34	<u>279</u>
<u>80</u>	RSC	FRANK HELLER & CO LIMITED	125 MCDONALD BOULEVARD ON Halton Hills ON	NW/232.2	6.34	<u>279</u>
<u>80</u>	RSC	FRANK HELLER & CO LIMITED	125 MCDONALD BOULEVARD ON Halton Hills ON	NW/232.2	6.34	<u>280</u>
<u>80</u>	WWIS		125 McDonald Blvd. lot 29 con 3 ACTON ON Well ID: 7418964	NW/232.2	6.34	<u>280</u>
<u>80</u>	WWIS		125 McDonald Blvd. lot 29 con 3 ACTON ON Well ID: 7418925	NW/232.2	6.34	<u>283</u>
<u>80</u>	WWIS		125 McDonald Blvd. lot 29 con 3 ACTON ON Well ID: 7418931	NW/232.2	6.34	<u>285</u>
<u>80</u>	WWIS		125 McDonald Blvd. lot 29 con 3 ACTON ON Well ID: 7418932	NW/232.2	6.34	<u>288</u>
<u>80</u>	WWIS		125 McDonald Blvd. lot 29 con 3 ACTON ON	NW/232.2	6.34	<u>290</u>

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7418934			
80	WWIS		125 McDonald Blvd. lot 29 con 3 ACTON ON Well ID: 7418940	NW/232.2	6.34	293
80	NPR2		125 MCDONALD BLVD. ACTON ON L7J2V7	NW/232.2	6.34	295
81	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON Well ID: 7375843	NW/232.9	5.61	298
82	EHS		125 McDonald Boulevard Acton ON L7J	NW/233.1	5.00	301
82	EHS		125 McDonald Boulevard Acton ON L7J	NW/233.1	5.00	301
82	EHS		125 McDonald Boulevard Acton ON L7J	NW/233.1	5.00	301
82	EHS		125 McDonald Boulevard Acton ON L7J	NW/233.1	5.00	301
83	EHS		163 Church Street Acton ON	E/233.4	3.31	302
83	WWIS		163 CHURCH ST ACTON ON Well ID: 7142326	E/233.4	3.31	302
84	WWIS		125 McDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7352091	NW/234.8	6.30	312
85	WWIS		ON Well ID: 7310917	NW/235.0	6.34	315
86	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388623	NW/237.8	6.34	316
87	WWIS		125 MC DONALD BLVD lot 29 con 3 ACTON ON	NW/238.8	6.28	319

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7375863			
88	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7337180	NW/242.8	6.34	322
89	WWIS		125 McDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7352065	NW/244.2	6.34	325
90	ECA	The Regional Municipality of Halton	Eastern Avenue Halton Hills ON L6M 3L1	ENE/245.3	2.31	328
90	ECA	The Regional Municipality of Halton	Agnes Street, Willow Street, John Street, Elgin Street, Frederick Street Halton Hills ON L6M 3L1	ENE/245.3	2.31	329
90	ECA	The Regional Municipality of Halton	Fellows Street from Mill Street to Church St Acton Halton Hills ON L6M 3L1	ENE/245.3	2.31	329
90	ECA	The Regional Municipality of Halton	Arthur Street, Acton Halton Hills ON L6M 3L1	ENE/245.3	2.31	329
90	ECA	The Regional Municipality of Halton	Mill Street, Perth Street and Peel Street Halton Hills ON L6M 3L1	ENE/245.3	2.31	330
90	ECA	The Regional Municipality of Halton	Eastern Avenue Halton Hills ON L6M 3L1	ENE/245.3	2.31	330
90	ECA	The Regional Municipality of Halton	Mill Street, Perth Street and Peel Street Halton Hills ON L6M 3L1	ENE/245.3	2.31	330
90	ECA	The Regional Municipality of Halton	Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street Halton Hills ON L6M 3L1	ENE/245.3	2.31	331
90	ECA	The Regional Municipality of Halton	Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street Halton Hills ON L6M 3L1	ENE/245.3	2.31	331
90	ECA	The Regional Municipality of Halton	Agnes Street Halton Hills ON L6M 3L1	ENE/245.3	2.31	331

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
<u>91</u>	EHS		40 Mill St. East Acton ON L7J 1H2	S/245.6	0.22	<u>332</u>
<u>92</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7350956	NW/246.4	6.79	<u>332</u>
<u>93</u>	WWIS		125 MCDONALD BLVD lot 29 con 3 ACTON ON Well ID: 7388618	NW/247.0	6.34	<u>335</u>
<u>94</u>	WWIS		125 MCDONALD BLVD. lot 29 con 3 ACTON ON Well ID: 7406694	NW/247.0	6.34	<u>338</u>
<u>95</u>	SPL	Enbridge Energy Distribution Inc.	64 Church Street Halton Hills ON	SSE/247.5	1.34	<u>341</u>
<u>95</u>	PINC	ENBRIDGE GAS INC	64 CHURCH ST E,,HALTON HILLS,ON, L7J 1K7,CA ON	SSE/247.5	1.34	<u>342</u>
<u>96</u>	WWIS		ON Well ID: 7188674	SSW/247.8	0.31	<u>342</u>
<u>97</u>	WWIS		METRO LINX ACTON ON Well ID: 7221212	W/248.4	4.31	<u>343</u>

Executive Summary: Summary By Data Source

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 11 CA site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
R.M. OF HALTON - (ACTON)	BOWER ST./FREDERICK ST./WILBUR HALTON HILLS TOWN ON	6.9	<u>2</u>
R.M. OF HALTON - (ACTON)	BOWER ST./WILBUR ST./MILL ST. HALTON HILLS TOWN ON	100.3	<u>8</u>
HALTON HILLS HYDRO-ELECTRIC COMMISSION	43 ALICE STREET, ACTON HALTON HILLS TOWN ON L7J 2A9	123.7	<u>12</u>
	43 Alice Street Acton ON L7J 2A9	123.7	<u>12</u>
R.M. OF HALTON	MILL ST./FELLOWS ST. HALTON HILLS TOWN ON	178.7	<u>34</u>
R.M. OF HALTON	MILL STREET/BOWER STREET HALTON HILLS TOWN ON	202.6	<u>58</u>
BLACKHAWK LEATHER LIMITED	125 MCDONALD BLVD. W., ACTON HALTON HILLS TOWN ON	232.2	<u>80</u>
EAGLE DOMINION INC.	125 MCDONALD BLVD., ACTON HALTON HILLS TOWN ON L7J 2V7	232.2	<u>80</u>
BLACKHAWK LEATHER LIMITED	125 MCDONALD BLVD. W., ACTON HALTON HILLS TOWN ON	232.2	<u>80</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
EAGLE DOMINION INC.	125 MCDONALD BLVD., ACTON HALTON HILLS TOWN ON L7J 2V7	232.2	80
EAGLE OTTAWA CANADA LTD.	125 MCDONALD BOULEVARD, ACTON HALTON HILLS ON L7J 2V7	232.2	80

DTNK - Delisted Fuel Tanks

A search of the DTNK database, dated Oct 2023 has found that there are 2 DTNK site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
ClAVONE INVESTMENTS LTD	130 MILL ST E ACTON ON	166.9	25
ClAVONE INVESTMENTS LTD	130 MILL ST E ACTON ON	166.9	25

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011-Jan 31, 2024 has found that there are 2 EASR site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HARBISONWALKER INTERNATIONAL CORP.	159 Perth ST Acton ON L7J 1C9	134.6	18
DREXLER CONSTRUCTION LIMITED	125 McDonald BLVD Acton ON L7J 2V7	232.2	80

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Jan 31, 2024 has found that there are 1 EBR site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Mikia Printing Ltd.	125 MacDonald Boulevard, Unit 3, Acton Halton Hills Ontario L7J 2M2 Halton Hills ON	232.2	<u>80</u>

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011- Jan 31, 2024 has found that there are 14 ECA site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Halton Hills Hydro	43 Alice Street Acton ON L7J 2A9	123.7	<u>12</u>
The Corporation of the Town of Halton Hills	128 McDonald Blvd 12 Division Street Halton Hills ON L7G 5G2	188.1	<u>41</u>
Mikia Printing Ltd.	125 MacDonald Boulevard, Unit 3, Acton Halton Hills ON L7J 2M2	232.2	<u>80</u>
Frank Heller & Co. Limited	125 McDonald Blvd Halton Hills ON N1G 4X7	232.2	<u>80</u>
The Regional Municipality of Halton	Eastern Avenue Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Agnes Street Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Mill Street, Perth Street and Peel Street Halton Hills ON L6M 3L1	245.3	<u>90</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
The Regional Municipality of Halton	Eastern Avenue Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Mill Street, Perth Street and Peel Street Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Agnes Street, Willow Street, John Street, Elgin Street, Frederick Street Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Arthur Street, Acton Halton Hills ON L6M 3L1	245.3	<u>90</u>
The Regional Municipality of Halton	Fellows Street from Mill Street to Church St Acton Halton Hills ON L6M 3L1	245.3	<u>90</u>

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Dec 31, 2023 has found that there are 31 EHS site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	97 Bower Street Halton Hills (Acton) ON L7J 1E4	0.0	<u>1</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
	159 Perth St Halton Hills ON L7J1C9	134.6	<u>18</u>
	159 Perth Street Acton ON L7J1C9	134.6	<u>18</u>
	80 Mill Street East Acton ON L7J 1H6	138.8	<u>19</u>
	137 Mill Street East Acton ON L7J 1H9	141.2	<u>20</u>
	137 Mill Street East Acton ON L7J 1H9	141.2	<u>20</u>
	137 Mill Street East Acton ON L7J 1H9	141.2	<u>20</u>
	137 Mill Street East Acton ON L7J 1H9	141.2	<u>20</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	130 Mill Street Acton ON	166.9	<u>25</u>
	55 mill street east Acton ON L7J 1H4	179.1	<u>35</u>
	55 mill street east Acton ON L7J 1H4	179.1	<u>35</u>
	55 mill street east Acton ON L7J 1H4	179.1	<u>35</u>
	55 mill street east Acton ON L7J 1H4	179.1	<u>35</u>
	146 Mill St E Halton Hills ON L7J1J1	189.5	<u>43</u>
	52 Mill St East Acton ON L7J 1H3	208.5	<u>63</u>
	125 Mcdonald Boulevard Acton ON L7J 2V7	232.2	<u>80</u>
	125 McDonald Blvd. Acton ON L7J 2V7	232.2	<u>80</u>
	125 McDonald Boulevard Acton ON L7J	233.1	<u>82</u>
	125 McDonald Boulevard Acton ON L7J	233.1	<u>82</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	125 McDonald Boulevard Acton ON L7J	233.1	<u>82</u>
	125 McDonald Boulevard Acton ON L7J	233.1	<u>82</u>
	163 Church Street Acton ON	233.4	<u>83</u>
	40 Mill St. East Acton ON L7J 1H2	245.6	<u>91</u>

FST - Fuel Storage Tank

A search of the FST database, dated Oct 2023 has found that there are 2 FST site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON	123.7	<u>12</u>
HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON	123.7	<u>12</u>

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 2 FSTH site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL	43 ALICE ST ACTON ON L7J 2A9	123.7	<u>12</u>

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Oct 31, 2022 has found that there are 93 GEN site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
MEDICAL PHARMACY	93 MILL STREET EAST PHARMACY ACTON ON L7J 1H5	79.6	<u>5</u>
Mark Dills	76 Bower Avenue Acton ON L7J 2B2	83.5	<u>6</u>
FORMTECH PLASTICS ONTARIO INC.	153 PERTH STREET ACTON ON L7J 1C9	106.6	<u>9</u>
Vector Injection Ltd	153 Perth St Acton ON L7J1C9	106.6	<u>9</u>
Formtech Plastics Ontario Inc.	153 Perth St. Acton ON L7J 1C9	106.6	<u>9</u>
Vector Injection Ltd	153 Perth St Acton ON L7J1C9	106.6	<u>9</u>
HALTON HILLS HYDRO-ELECTRIC COMM.	43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO-ELECTRIC COMM. 19-094	43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO INC.	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
RHI REFRACTORIES OF AMERICA	159 PERTH STREET HALTON ON L7J 1C9	134.6	<u>18</u>
Global-GIX Canada Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON	134.6	<u>18</u>
HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
ANH REFRACTORIES CANADA Inc.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
HarbisonWalker International Corp.	159 Perth Street Acton ON L7J 1C9	134.6	<u>18</u>
Sotirios Investments Inc	137 Mill Street East Acton ON L7J1H9	141.2	<u>20</u>
Danosh Construction	137 mill street east Acton ON L7J 1H9	141.2	<u>20</u>
Brookfield LePage Johnson Controls	53 Bower Street Acton ON L7J 1E1	160.9	<u>23</u>
SHOEMAKER FUNERAL HOME	55 MILL STREET EAST ACTON ON L7J 1H4	179.1	<u>35</u>
SHOEMAKER FUNERAL HOME	55 MILL STREET EAST ACTON ON L7J 1H4	179.1	<u>35</u>
SHOEMAKER FUNERAL HOME 44-053	55 MILL STREET EAST ACTON ON L7J 1H4	179.1	<u>35</u>
MACKINNON FAMILY FUNERAL HOME INC.	55 MILL STREET EAST ACTON ON L7J 1H4	179.1	<u>35</u>
MACKINNON FAMILY FUNERAL HOME INC.	SHOEMAKER CHAPEL 55 MILL STREET EAST ACTON ON L7J 1H4	179.1	<u>35</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
MACKINNON FAMILY FUNERAL HOME INC.	SHOEMAKER CHAPEL 55 MILL STREET EAST ACTON ON L7J 1H4	179.1	<u>35</u>
MackInnon Family Funeral Home	55 Mill Street East Acton ON L7J 1H4	179.1	<u>35</u>
MackInnon Family Funeral Home	55 Mill Street East Acton ON L7J 1H4	179.1	<u>35</u>
Compressed Air & Filtration	59 Willow St. N. Unit #3 Acton ON L7J1Z8	181.6	<u>36</u>
HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON	187.0	<u>39</u>
HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	187.0	<u>39</u>
HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	187.0	<u>39</u>
HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	187.0	<u>39</u>
HALTON DISTRICT SCHOOL BOARD	41 SCHOOL LANE ACTON ON L7J1B9	187.0	<u>39</u>
PETER ZIONS CONSTRUCTION	12 WALLACE STREET ACTON ON L7J 2V6	191.2	<u>46</u>
Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	213.7	<u>66</u>
Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	213.7	<u>66</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	213.7	<u>66</u>
Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	213.7	<u>66</u>
Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	213.7	<u>66</u>
Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	213.7	<u>66</u>
Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	213.7	<u>66</u>
Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	213.7	<u>66</u>
Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	213.7	<u>66</u>
Acton Medical and Urgent Care	10 Eastern Avenue Acton ON L7J0A5	213.7	<u>66</u>
Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	213.7	<u>66</u>
Dr Jones Chan Dentistry Professional Corporation	10 Eastern Ave unit 104 Acton ON L7J 0A5	213.7	<u>66</u>
Halton Hills Hydro Inc. Halton Hills Hydro Inc.	57 Willow St. N Acton ON L7J 1Z8	216.2	<u>67</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
FRANK HELLER & COMPANY LTD.	125 MCDONALD BLVD. ACTON ON L7J 2V7	232.2	<u>80</u>
EAGLE DOMINION INC.	125 MCDONALD BLVD.. ACTON ON L7J 2V7	232.2	<u>80</u>
EAGLE OTTAWA CANADA, LTD. 15-268	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	232.2	<u>80</u>
BLACKHAWK LEATHER LTD. 15-268	125 MCDONALD BLVD.. ACTON ON L7J 2V7	232.2	<u>80</u>
EAGLE OTTAWA CANADA, LTD	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	232.2	<u>80</u>
EAGLE OTTAWA CANADA, LTD.	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	232.2	<u>80</u>
PERMAIR LEATHERS LIMITED	125 MCDONALD BOULEVARD ACTON ON L7J 2V7	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>
Zuraw Technologies Inc.	125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	232.2	<u>80</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Mikia Printing Ltd	125 McDonald Blvd #3 Acton ON L7J 2V7	232.2	80
Frank Heller & Company Limited	125 McDonald Blvd Acton ON L7J2V7	232.2	80

HINC - TSSA Historic Incidents

A search of the HINC database, dated 2006-June 2009* has found that there are 1 HINC site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	43 ALICE STREET ACTON ON L7J 2A9	123.7	12

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated 31 Oct, 2023 has found that there are 1 INC site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	10 EASTERN AVENUE, ACTON ON	213.7	66

NPCB - National PCB Inventory

A search of the NPCB database, dated 1988-2008* has found that there are 8 NPCB site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	12
HALTON HILLS HYDRO	43 ALICE STREET GEORGETOWN ON L7J 2A9	123.7	12

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO	43 ALICE STREET ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
CANADA POST	45 BOWER ST C/O ROYAL LEPAGE MANAGEMENT ACTON ON L7J 1E1	188.7	<u>42</u>
CANADA POST	C/O ROYAL LEPAGE MANAGEMENT; 45 BOWER STREET ACTON-HALTON HILLS POST OFFICE; 45 BOWER ST ACTON ON L7J 1E1	188.7	<u>42</u>
CANADA POST	45 BOWER STREET ACTON-HALTON HILLS POST OFFICE; 45 BOWER ST ACTON ON L7J 1E1	188.7	<u>42</u>
CANADA POST	45 BOWER STREET c/ o ROYAL LEPAGE MANAGEMENT Acton ON L7J 1E1	188.7	<u>42</u>

NPR2 - National Pollutant Release Inventory 1993-2020

A search of the NPR2 database, dated Sep 2020 has found that there are 1 NPR2 site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	125 MCDONALD BLVD. ACTON ON L7J2V7	232.2	<u>80</u>

OPCB - Inventory of PCB Storage Sites

A search of the OPCB database, dated 1987-Oct 2004; 2012-Dec 2013 has found that there are 8 OPCB site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO	43 ALICE STREET GEORGETOWN ON L7J 2A9	123.7	<u>12</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
Halton Hills Hydro	43 Alice St. Acton ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET GEORGETOWN ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>
HALTON HILLS HYDRO	43 ALICE STREET ACTON ON L7J 2A9	123.7	<u>12</u>

PES - Pesticide Register

A search of the PES database, dated Oct 2011- Jan 31, 2024 has found that there are 2 PES site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
CANADIAN TIRE STORE 183/R & R HONOUR ENTERPRISES INC	130 MILL STREET EAST ACTON ON L7J1J1	166.9	<u>25</u>
ACTON HOME HARDWARE	43 MILL ST ACTON ON L7J 1E8	218.2	<u>68</u>

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 3 PINC site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
PIPELINE HIT - 1/2"	61 BOWER ST,,ACTON,ON,L7J 1E4,CA ON	126.9	<u>15</u>
PIPELINE HIT 1/2"	50 BOWER ST,,ACTON,ON,L7J 1E3,CA ON	173.5	<u>28</u>
ENBRIDGE GAS INC	64 CHURCH ST E,,HALTON HILLS,ON,L7J 1K7,CA ON	247.5	<u>95</u>

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 2 PRT site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TR	43 ALICE ST ACT ON L7J 2A9	123.7	<u>12</u>
R & R HONOUR ENTERPRISES INC	130 MILL ST E ACTON ON L7J1J1	166.9	<u>25</u>

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Jan 2024 has found that there are 4 RSC site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
2467766 ONTARIO INC.	94 - 96 MILL STREET ON Halton Hills ON	121.6	<u>11</u>
2467766 ONTARIO INC.	71 - 79 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 69 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 94 - 96 MILL STREET, GEORGETOWN, ON L7G 2C9 Halton Hills ON	121.6	<u>11</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
FRANK HELLER & CO LIMITED	125 MCDONALD BOULEVARD ON Halton Hills ON	232.2	<u>80</u>
FRANK HELLER & CO LIMITED	125 MCDONALD BOULEVARD ON Halton Hills ON	232.2	<u>80</u>

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 14 SCT site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
TRIPLE V PLASTICS LTD.	153 PERTH ST ACTON ON L7J 1C9	106.6	<u>9</u>
Formtech Plastics Ontario Inc.	153 Perth St Acton ON L7J 1C9	106.6	<u>9</u>
ANH Refractories Canada Inc.	159 Perth St Acton ON L7J 1C9	134.6	<u>18</u>
Global-GIX Canada Inc.	159 Perth St Acton ON L7J 1C9	134.6	<u>18</u>
HARBISON-WALKER REFRACTORIES	159 PERTH ST ACTON ON L7J 1C9	134.6	<u>18</u>
A.P. GREEN REFRACTORIES (CDA)	159 PERTH ST ACTON ON L7J 1C9	134.6	<u>18</u>
RHI AMERCIA REFRACTORIES	159 Perth St Acton ON L7J 1C9	134.6	<u>18</u>
RHI Refractories America	159 Perth St Acton ON L7J 1C9	134.6	<u>18</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Acton Denture Clinic	130 Mill St E Suite 103 Acton ON L7J 1J1	166.9	<u>25</u>
PLASTICS EIGHTY LTD	12 WALLACE ST ACTON ON L7J 2V6	191.2	<u>46</u>
EAGLE OTTAWA CANADA LTD.	125 MCDONALD BLVD ACTON ON L7J 2V7	232.2	<u>80</u>
PERMAIR LEATHERS LIMITED	125 McDonald Blvd Acton ON L7J 2V7	232.2	<u>80</u>
Whiteclay Enterprises Inc.	125 McDonald Blvd Unit 5 Acton ON L7J 2V7	232.2	<u>80</u>
Beardmore Leathers	125 McDonald Blvd Acton ON L7J 2V7	232.2	<u>80</u>

SPL - Ontario Spills

A search of the SPL database, dated 1988-Jan 2023; May 2023-Dec 2023 has found that there are 5 SPL site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Halton Hills Hydro	45 Alice Street, Acton Halton Hills ON	88.8	<u>7</u>
	61 Bower St (Acton) Halton Hills ON	126.9	<u>15</u>
HarbisonWalker International Corp.	159 Perth St Acton Halton Hills ON L7J 1C9	134.6	<u>18</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
Maple Reinders Construction Limited	10 Eastern Ave, Acton ON Halton Hills ON L7J 0A5	213.7	<u>66</u>
Enbridge Energy Distribution Inc.	64 Church Street Halton Hills ON	247.5	<u>95</u>

WWIS - Water Well Information System

A search of the WWIS database, dated Mar 31 2023 has found that there are 71 WWIS site(s) within approximately 0.25 kilometers of the project property.

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	97 BOWER ST. ACTON ON <i>Well ID: 7120007</i>	0.0	<u>1</u>
	n/a n/a lot 28 con 3 Rockwood ON <i>Well ID: 7378700</i>	23.3	<u>3</u>
	lot 28 con 3 ON <i>Well ID: 2809690</i>	74.8	<u>4</u>
	137 MILL ST. E. ACTON ON <i>Well ID: 7269004</i>	117.1	<u>10</u>
	METRO LINX ACTON ON <i>Well ID: 7221211</i>	124.6	<u>13</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7362200</i>	125.3	<u>14</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7361995</i>	127.2	<u>16</u>
	137 MILL ST. E. ACTON ON	128.4	<u>17</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	Well ID: 7269005		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	155.0	<u>21</u>
	Well ID: 7350907		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	155.2	<u>22</u>
	Well ID: 7360685		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	162.6	<u>24</u>
	Well ID: 7337156		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	168.7	<u>26</u>
	Well ID: 7360715		
	ON	170.7	<u>27</u>
	Well ID: 7285175		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	170.7	<u>27</u>
	Well ID: 7350987		
	125 MCDONALD BLVD lot 29 con 3 ACTON ON	173.7	<u>29</u>
	Well ID: 7388615		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	176.2	<u>30</u>
	Well ID: 7350991		
	125 MCDONALD BLVD lot 29 con 3 ACTON ON	176.6	<u>31</u>
	Well ID: 7362146		
	151 MILL ST AT RAILWAY CROSSING ACTON ON	176.9	<u>32</u>
	Well ID: 7346699		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	177.2	<u>33</u>
	Well ID: 7350957		


<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7388626</i>	183.9	<u>37</u>
	125 MC DONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7375865</i>	186.1	<u>38</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7362157</i>	187.8	<u>40</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7388625</i>	190.9	<u>44</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7360720</i>	191.2	<u>45</u>
	125 McDonald Blvd lot 29 con 3 Acton ON <i>Well ID: 7376265</i>	191.4	<u>47</u>
	125 MC DONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7375845</i>	191.7	<u>48</u>
	125 MC DONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7375851</i>	192.3	<u>49</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7350954</i>	192.9	<u>50</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7388622</i>	194.1	<u>51</u>
	ON <i>Well ID: 7306391</i>	197.0	<u>52</u>
	125 McDonald Blvd lot 29 con 3 Acton ON	197.4	<u>53</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	Well ID: 7376268		
	ON	197.5	<u>54</u>
	Well ID: 7345190		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	200.1	<u>55</u>
	Well ID: 7350958		
	125 MC DONALD BLVD lot 29 con 3 ACTON ON	200.1	<u>56</u>
	Well ID: 7375864		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	202.0	<u>57</u>
	Well ID: 7406702		
	125 MCDONALD BLVD lot 29 con 3 ACTON ON	203.2	<u>59</u>
	Well ID: 7388624		
	125 MCDONALD BLVD lot 29 con 3 ACTON ON	203.6	<u>60</u>
	Well ID: 7388614		
	125 McDONALD BLVD lot 29 con 3 ACTON ON	206.9	<u>61</u>
	Well ID: 7352056		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	208.4	<u>62</u>
	Well ID: 7350972		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	208.9	<u>64</u>
	Well ID: 7360681		
	ON	213.5	<u>65</u>
	Well ID: 7311615		
	125 McDONALD BLVD lot 29 con 3 ACTON ON	218.8	<u>69</u>
	Well ID: 7351992		

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7350911</i>	220.7	<u>70</u>
	ON <i>Well ID: 7171098</i>	222.0	<u>71</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7406731</i>	222.3	<u>72</u>
	n/a n/a lot 29 con 3 Guelph ON <i>Well ID: 7378699</i>	222.8	<u>73</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7337187</i>	223.7	<u>74</u>
	125 MC DONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7375866</i>	223.7	<u>75</u>
	ON <i>Well ID: 7315547</i>	224.6	<u>76</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7388627</i>	226.6	<u>77</u>
	125 McDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7352094</i>	228.6	<u>78</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7388621</i>	230.1	<u>79</u>
	125 McDonald Blvd. lot 29 con 3 ACTON ON <i>Well ID: 7418964</i>	232.2	<u>80</u>
	125 McDonald Blvd. lot 29 con 3 ACTON ON	232.2	<u>80</u>

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	Well ID: 7418925		
	125 McDonald Blvd. lot 29 con 3 ACTON ON	232.2	<u>80</u>
	Well ID: 7418931		
	125 McDonald Blvd. lot 29 con 3 ACTON ON	232.2	<u>80</u>
	Well ID: 7418932		
	125 McDonald Blvd. lot 29 con 3 ACTON ON	232.2	<u>80</u>
	Well ID: 7418934		
	125 McDonald Blvd. lot 29 con 3 ACTON ON	232.2	<u>80</u>
	Well ID: 7418940		
	125 MC DONALD BLVD lot 29 con 3 ACTON ON	232.9	<u>81</u>
	Well ID: 7375843		
	163 CHURCH ST ACTON ON	233.4	<u>83</u>
	Well ID: 7142326		
	125 McDONALD BLVD lot 29 con 3 ACTON ON	234.8	<u>84</u>
	Well ID: 7352091		
	ON	235.0	<u>85</u>
	Well ID: 7310917		
	125 MCDONALD BLVD lot 29 con 3 ACTON ON	237.8	<u>86</u>
	Well ID: 7388623		
	125 MC DONALD BLVD lot 29 con 3 ACTON ON	238.8	<u>87</u>
	Well ID: 7375863		
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	242.8	<u>88</u>
	Well ID: 7337180		

<u>Site</u>	<u>Address</u>	<u>Distance (m)</u>	<u>Map Key</u>
	125 McDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7352065</i>	244.2	<u>89</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7350956</i>	246.4	<u>92</u>
	125 MCDONALD BLVD lot 29 con 3 ACTON ON <i>Well ID: 7388618</i>	247.0	<u>93</u>
	125 MCDONALD BLVD. lot 29 con 3 ACTON ON <i>Well ID: 7406694</i>	247.0	<u>94</u>
	ON <i>Well ID: 7188674</i>	247.8	<u>96</u>
	METRO LINX ACTON ON <i>Well ID: 7221212</i>	248.4	<u>97</u>



Map: 0.25 Kilometer Radius

Order Number: 24010300716

Address: 97 Bower Street, Acton, ON



Project Property	Freeways; Highways	Beach	Shopping & Sports Area
Buffer Outline	Traffic Circle; Ramp	Airport	University/College
Eris Sites with Higher Elevation	Major Arterial; Minor Arterial	Industrial Area	Cemetery; Golf Course
Eris Sites with Same Elevation	Local Road	Military Base	Parkt (National)
Eris Sites with Lower Elevation	Service Road; Traffic Circle; Ramp	Aircraft Roads	Park (City/County)
Eris Sites with Unknown Elevation	Rail	Native Reservation	Hospital

80°3'W

43°37'30"N

43°37'30"N



1:10000

Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community

Aerial

Year: 2023

Order Number: 24010300716

Address: 97 Bower Street, Acton, ON



Source: ESRI World Imagery

© ERIS Information Limited Partnership

80°3'W


80°1'30"W

43°37'30"N

43°39'N

43°37'30"N

43°37'30"N



Topographic Map

Address: 97 Bower Street, ON

Source: ESRI World Topographic Map

Order Number: 24010300716



© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 2	NE/0.0	349.7 / -0.85	97 Bower Street Halton Hills (Acton) ON L7J 1E4	EHS
Order No: 20080325009				Nearest Intersection: Bower Street and Frederick Street North	
Status: C				Municipality: Halton Hills (Acton)	
Report Type: Complete Report				Client Prov/State: ON	
Report Date: 4/3/2008				Search Radius (km): 0.25	
Date Received: 3/25/2008				X: -80.039789	
Previous Site Name:				Y: 43.63386	
Lot/Building Size:					
Additional Info Ordered:					
1	2 of 2	NE/0.0	349.7 / -0.85	97 BOWER ST. ACTON ON	WWIS
Well ID: 7120007				Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st: Test Hole				Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status: Test Hole				Date Received: 03/02/2009	
Water Type:				Selected Flag: TRUE	
Casing Material:				Abandonment Rec:	
Audit No: M02723				Contractor: 7230	
Tag: A073411				Form Version: 5	
Constructn Method:				Owner:	
Elevation (m):				County: HALTON	
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality: HALTON HILLS TOWN (ACTON)					
Site Info:					
PDF URL (Map):				https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/712\7120007.pdf	
<u>Additional Detail(s) (Map)</u>					
Well Completed Date: 08/06/2008					
Year Completed: 2008					
Depth (m): 6					
Latitude: 43.6332015276258					
Longitude: -80.0403707468437					
Path: 712\7120007.pdf					
<u>Bore Hole Information</u>					
Bore Hole ID: 1002026144				Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone: 17	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Code OB:				East83:	577410.00
Code OB Desc:				North83:	4831582.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	5
Date Completed:	08/06/2008			UTMRC Desc:	margin of error : 100 m - 300 m
Remarks:				Location Method:	digit
Loc Method Desc:					
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1002744715			
Layer:		1			
Color:					
General Color:					
Mat1:		02			
Most Common Material:		TOPSOIL			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		0.6100000143051147			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1002744717			
Layer:		3			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:					
Mat2 Desc:					
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		1.5199999809265137			
Formation End Depth:		4.820000171661377			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1002744716			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		01			
Most Common Material:		FILL			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		28			
Mat3 Desc:		SAND			
Formation Top Depth:		0.6100000143051147			
Formation End Depth:		1.5199999809265137			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1002744718			
Layer:		4			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:					
Mat2 Desc:					
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		4.820000171661377			
Formation End Depth:		6.0			
Formation End Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1002744724			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1002744713			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1002744721			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.8999999761581421			
Depth To:		6.0			
Casing Diameter:		5.0			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1002744722			
Layer:		1			
Slot:		10			
Screen Top Depth:					
Screen End Depth:					
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		5.0			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pump Test ID:		1002744714			
Pump Set At:					
Static Level:		4.699999809265137			
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:					
Water State After Test Code:		0			
Water State After Test:					
Pumping Test Method:		0			
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
 <u>Water Details</u>					
Water ID:		1002744720			
Layer:		1			
Kind Code:		5			
Kind:		Not stated			
Water Found Depth:		4.699999809265137			
Water Found Depth UOM:		m			
 <u>Hole Diameter</u>					
Hole ID:		1002744719			
Diameter:		15.0			
Depth From:		0.0			
Depth To:		6.0			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
 <u>Links</u>					
Bore Hole ID:	1002026144			Tag No:	A073411
Depth M:	6			Contractor:	7230
Year Completed:	2008			Latitude:	43.6332015276258
Well Completed Dt:	08/06/2008			Longitude:	-80.0403707468437
Audit No:	M02723			Y:	43.63320152650327
Path:	712\7120007.pdf			X:	-80.04037059746074

2

1 of 1

SE/6.9

351.7 / 1.17

R.M. OF HALTON - (ACTON)
BOWER ST./FREDERICK ST./WILBUR
HALTON HILLS TOWN ON

CA

Certificate #: 3-1647-91-
Application Year: 91
Issue Date: 10/25/1991
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
3	1 of 1	NW/23.3	349.9 / -0.69	n/a n/a lot 28 con 3 Rockwood ON	WWIS
Well ID: 7378700 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: BZGMO8TN Tag: A306007 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info: Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 01/21/2021 Selected Flag: TRUE Abandonment Rec: Contractor: 7282 Form Version: 9 Owner: County: HALTON Lot: 028 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
<u>Bore Hole Information</u>					
Bore Hole ID: 1008554561 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 11/30/2020 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment: Elevation: Elevrc: Zone: 17 East83: 577401.00 North83: 4831704.00 Org CS: UTM83 UTMRC: 4 UTMRC Desc: margin of error : 30 m - 100 m Location Method: wwr					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID: 1008554671 Layer: 1 Color: 8 General Color: BLACK Mat1: 34 Most Common Material: TILL Mat2: Mat2 Desc: Mat3: Mat3 Desc: Formation Top Depth: 0.0 Formation End Depth: 5.0 Formation End Depth UOM: ft					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation ID:		1008554672			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		5.0			
Formation End Depth:		10.0			
Formation End Depth UOM:		ft			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008554674			
Layer:		4			
Color:		7			
General Color:		RED			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		18.0			
Formation End Depth:		20.0			
Formation End Depth UOM:		ft			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008554673			
Layer:		3			
Color:		7			
General Color:		RED			
Mat1:		28			
Most Common Material:		SAND			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		10.0			
Formation End Depth:		18.0			
Formation End Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008554758			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008554775			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		2			
Plug From:		9.0			
Plug To:		20.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008554774			
Layer:		1			
Plug From:		0.0			
Plug To:		9.0			
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008554634			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008554605			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008554713			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		10.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1008554728			
Layer:		1			
Slot:		10			
Screen Top Depth:		10.0			
Screen End Depth:		20.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.299999952316284			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008554606			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM:ft Rate UOM:GPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
Hole Diameter					
Hole ID:1008554743 Diameter:6.0 Depth From:0.0 Depth To:20.0 Hole Depth UOM:ft Hole Diameter UOM:inch					
Links					
Bore Hole ID:1008554561 Depth M:6.096 Year Completed:2020 Well Completed Dt:11/30/2020 Audit No:BZGMO8TN Path:737\7378700.pdf Tag No:A306007 Contractor:7282 Latitude:43.6343008086376 Longitude:-80.0404648249501 Y:43.63430080758384 X:-80.04046467519693					
4	1 of 1	NW/74.8	352.7 / 2.11	lot 28 con 3 ON	WWIS
Well ID:2809690 Construction Date: Use 1st: Use 2nd: Final Well Status:Abandoned-Other Water Type: Casing Material: Audit No:249789 Tag: Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: Site Info: Flowing (Y/N): Flow Rate: Data Entry Status: Data Src:1 Date Received:02/19/2003 Selected Flag:TRUE Abandonment Rec: Contractor:2801 Form Version:1 Owner: County:HALTON Lot:028 Concession:03 Concession Name:CON Easting NAD83: Northing NAD83: Zone: UTM Reliability: https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/280\2809690.pdf					
Additional Detail(s) (Map)					
Well Completed Date:01/17/2003 Year Completed:2003 Depth (m): Latitude:43.6346198603991					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Longitude:		-80.040930831865			
Path:		280\2809690.pdf			
<u>Bore Hole Information</u>					
Bore Hole ID:	10538781			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577363.00
Code OB Desc:				North83:	4831739.00
Open Hole:				Org CS:	N83
Cluster Kind:				UTMRC:	3
Date Completed:	01/17/2003			UTMRC Desc:	margin of error : 10 - 30 m
Remarks:				Location Method:	gps
Loc Method Desc:		from gps			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Method of Construction & Well Use</u>					
<u>Use</u>					
Method Construction ID:	962809690				
Method Construction Code:	0				
Method Construction:	Not Known				
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:	11087351				
Casing No:	1				
Comment:					
Alt Name:					
<u>Links</u>					
Bore Hole ID:	10538781			Tag No:	
Depth M:				Contractor:	2801
Year Completed:	2003			Latitude:	43.6346198603991
Well Completed Dt:	01/17/2003			Longitude:	-80.040930831865
Audit No:	249789			Y:	43.63461985822293
Path:	280\2809690.pdf			X:	-80.04093068236213

5

1 of 1

SE/79.6

352.9 / 2.31

**MEDICAL PHARMACY
93 MILL STREET EAST PHARMACY
ACTON ON L7J 1H5**

GEN

Generator No: ON1538114
SIC Code: 6031
SIC Description: PHARMACIES
Approval Years: 01
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Detail(s)</u>					
Waste Class:		261			
Waste Class Name:		PHARMACEUTICALS			
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
<u>6</u>	1 of 1	S/83.5	351.8 / 1.24	Mark Dills 76 Bower Avenue Acton ON L7J 2B2	GEN
Generator No:		ON8975669			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2019			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		112 B			
Waste Class Name:		Acid solutions - containing heavy metals			
Waste Class:		148 T			
Waste Class Name:		Misc. wastes and inorganic chemicals			
Waste Class:		263 I			
Waste Class Name:		Misc. waste organic chemicals			
Waste Class:		148 I			
Waste Class Name:		Misc. wastes and inorganic chemicals			
Waste Class:		122 C			
Waste Class Name:		Alkaline slutions - containing other metals and non-metals (not cyanide)			
Waste Class:		212 I			
Waste Class Name:		Aliphatic solvents and residues			
Waste Class:		212 B			
Waste Class Name:		Aliphatic solvents and residues			
Waste Class:		212 L			
Waste Class Name:		Aliphatic solvents and residues			
Waste Class:		267 C			
Waste Class Name:		Organic acids			
Waste Class:		114 C			
Waste Class Name:		Other inorganic acid wastes			
<u>7</u>	1 of 1	SW/88.8	349.8 / -0.73	Halton Hills Hydro 45 Alice Street, Acton Halton Hills ON	SPL
Ref No:	5250-67HK27			Municipality No:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Year: Incident Dt: 12/9/2004 Dt MOE Arvl on Scn: MOE Reported Dt: 12/9/2004 Dt Document Closed: Site No: MOE Response: Site County/District: Site Geo Ref Meth: Site District Office: Halton-Peel Nearest Watercourse: Site Name: FROM IN BEHIND THE HYDRO BUILDING TO THE LIBRARY<UNOFFICIAL> Site Address: Site Region: Central Site Municipality: Halton Hills Site Lot: Site Conc: Site Geo Ref Accu: Site Map Datum: Northing: Easting: Incident Cause: Incident Event: Environment Impact: Possible Nature of Impact: Surface Water Pollution Contaminant Qty: System Facility Address: Client Name: Halton Hills Hydro Client Type: Source Type: Contaminant Code: Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED) Contaminant Limit 1: Contam Limit Freq 1: Contaminant UN No 1: Receiving Medium: Water Incident Reason: Incident Summary: Acton: Oil and gas in creek from unknown source. Activity Preceding Spill: Property 2nd Watershed: Property Tertiary Watershed: Sector Type: SAC Action Class: Spill to Inland Watercourses Call Report Locatn Geodata:					

[8](#)

1 of 1

ESE/100.3

352.9 / 2.34

R.M. OF HALTON - (ACTON)
BOWER ST./WILBUR ST./MILL ST.
HALTON HILLS TOWN ON

CA

Certificate #: 7-1340-91-
Application Year: 91
Issue Date: 10/25/1991
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	1 of 6	ENE/106.6	350.9 / 0.36	TRIPLE V PLASTICS LTD. 153 PERTH ST ACTON ON L7J 1C9	SCT
Established:		1981			
Plant Size (ft²):		15000			
Employment:		11			
--Details--					
Description:		UNSUPPORTED PLASTICS PROFILE SHAPES			
SIC/NAICS Code:		3082			
Description:		PLASTICS PRODUCTS, NOT ELSEWHERE CLASSIFIED			
SIC/NAICS Code:		3089			
9	2 of 6	ENE/106.6	350.9 / 0.36	FORMTECH PLASTICS ONTARIO INC. 153 PERTH STREET ACTON ON L7J 1C9	GEN
Generator No:		ON2667200			
SIC Code:		1699			
SIC Description:		OTHER PLASTIC PROD.			
Approval Years:		01			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
9	3 of 6	ENE/106.6	350.9 / 0.36	Formtech Plastics Ontario Inc. 153 Perth St Acton ON L7J 1C9	SCT
Established:		01-JAN-01			
Plant Size (ft²):		10000			
Employment:					
--Details--					
Description:		Sporting and Athletic Goods Manufacturing			
SIC/NAICS Code:		339920			
Description:		Motor Vehicle Plastic Parts Manufacturing			
SIC/NAICS Code:		326193			
Description:		All Other Miscellaneous Manufacturing			
SIC/NAICS Code:		339990			
Description:		Aerospace Product and Parts Manufacturing			
SIC/NAICS Code:		336410			
Description:		All Other Plastic Product Manufacturing			
SIC/NAICS Code:		326198			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
9	4 of 6	ENE/106.6	350.9 / 0.36	Vector Injection Ltd 153 Perth St Acton ON L7J1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON6375518			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		253 L Emulsified oils			
9	5 of 6	ENE/106.6	350.9 / 0.36	Formtech Plastics Ontario Inc. 153 Perth St. Acton ON L7J 1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON6887697			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		251 L Waste oils/sludges (petroleum based)			
9	6 of 6	ENE/106.6	350.9 / 0.36	Vector Injection Ltd 153 Perth St Acton ON L7J1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON6375518			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Detail(s)</u>					
Waste Class:		253 L			
Waste Class Name:		EMULSIFIED OILS			
10	1 of 1	E/117.1	352.9 / 2.31	137 MILL ST. E. ACTON ON	WWIS
Well ID:	7269004			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	08/17/2016
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	Z223956			Contractor:	6607
Tag:	A201598			Form Version:	7
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:	07/06/2016				
Year Completed:	2016				
Depth (m):	6.6				
Latitude:	43.6335759785367				
Longitude:	-80.0377862684605				
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1006215029			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577618.00
Code OB Desc:				North83:	4831626.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	07/06/2016			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation ID:		1006218488			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		0.5			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1006218489			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		85			
Mat3 Desc:		SOFT			
Formation Top Depth:		0.5			
Formation End Depth:		6.599999904632568			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1006218496			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1006218498			
Layer:		3			
Plug From:		3.299999952316284			
Plug To:		6.599999904632568			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1006218497			
Layer:		2			
Plug From:		0.30000001192092896			
Plug To:		3.299999952316284			
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction ID:		1006218495			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1006218487			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1006218492			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.5999999046325684			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1006218493			
Layer:		1			
Slot:		10			
Screen Top Depth:		3.5999999046325684			
Screen End Depth:		6.599999904632568			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Water Details</u>					
Water ID:		1006218491			
Layer:					
Kind Code:					
Kind:					
Water Found Depth:					
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1006218490			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		6.599999904632568			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:		1006215029		Tag No:	A201598
Depth M:		6.6		Contractor:	6607
Year Completed:		2016		Latitude:	43.6335759785367
Well Completed Dt:		07/06/2016		Longitude:	-80.0377862684605
Audit No:		Z223956		Y:	43.63357597745455

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Path:	726\7269004.pdf			X: -80.03778611822605	
11	1 of 2	SE/121.6	353.7 / 3.15	2467766 ONTARIO INC. 71 - 79 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 69 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 94 - 96 MILL STREET, GEORGETOWN, ON L7G 2C9 Halton Hills ON	RSC
RSC No:	226831			X:	
RA No:	RA1520-16b			Y:	
Status:				Latitude:	
Filing Date:	2020/06/26			Longitude:	
Date Ack:				UTM Coordinates:	
Date Returned:				Latitude Longitude:	
Approval Date:				Accuracy Estimate:	
Cert Date:				Measurement Method:	
Cert Prop Use No:				Mailing Address:	
Curr Property Use:	Commercial			Telephone:	
Intended Prop Use:	Residential			Fax:	
Restoration Type:				Email:	
Soil Type:				Postal Code:	
Criteria:				Ministry District:	Halton-Peel District Office
Stratified (Y/N):				MOE District:	
Audit (Y/N):				SWP Area Name:	
Entire Leg Prop. (Y/N):				Qual Person Name:	ROBERT HELIK
CPU Issued Sect 1686:				Consultant:	
Refresh Date:					
Business Name:					
Address:		71 - 79 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 69 MAIN STREET SOUTH, GEORGETOWN, ON L7G 3G2, 94 - 96 MILL STREET, GEORGETOWN, ON L7G 2C9			
Legal Desc:					
Site Pin:		25042-0155 (LT)			
Asmt Roll No:		241501000305300, 241501000352800, 241501000305400			
Project Type:					
Approval Type:		Phase 1 and 2 RSC with RA			
Applicable Standards:					
Pdf Link:		https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=128676&fileName=BROWNFIELDS-E.pdf			
11	2 of 2	SE/121.6	353.7 / 3.15	2467766 ONTARIO INC. 94 - 96 MILL STREET ON Halton Hills ON	RSC
RSC No:	226831			X:	-79.92604005369397
RA No:				Y:	43.649706300468544
Status:	FILED			Latitude:	43.6497063
Filing Date:				Longitude:	-79.92604005
Date Ack:				UTM Coordinates:	
Date Returned:				Latitude Longitude:	
Approval Date:	1593188233000			Accuracy Estimate:	
Cert Date:				Measurement Method:	
Cert Prop Use No:				Mailing Address:	
Curr Property Use:				Telephone:	
Intended Prop Use:				Fax:	
Restoration Type:				Email:	
Soil Type:				Postal Code:	L7G 2C9
Criteria:				Ministry District:	
Stratified (Y/N):				MOE District:	Halton-Peel
Audit (Y/N):				SWP Area Name:	Credit Valley

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Entire Leg Prop. (Y/N): CPU Issued Sect 1686: Refresh Date: Business Name: Address: Legal Desc: Site Pin: Asmt Roll No: Project Type: Approval Type: Applicable Standards: Pdf Link: 1707874378000 2467766 ONTARIO INC. 94 - 96 MILL STREET ON 25042-0155 (LT) POST2011 RSC based on Phase One and Two ESAs with RA https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=226831 Qual Person Name: ROBERT HELIK Consultant:					
12	1 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET GEORGETOWN ON L7J 2A9	OPCB
Year: Site Number: Name Owner: Additional Site Information: 1992 30288A210					
12	2 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET GEORGETOWN ON L7J 2A9	NPCB
Company Code: Industry: Site Status: Transaction Date: Inspection Date: F1092 1/29/1996					
--Details-- Label: Serial No.: PCB Type/Code: Location: Item/State: No. of Items: Manufacturer: Status: Contents: Askarel Stored for Disposal 1800.00 KG					
12	3 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TR 43 ALICE ST ACT ON L7J 2A9	PRT
Location ID: Type: Expiry Date: Capacity (L): Licence #: 19823 private 18184.00 0076356237					
12	4 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ALICE STREET ACTON ON L7J 2A9	NPCB

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Company Code: F0989 Industry: Site Status: Transaction Date: Inspection Date:					
--Details-- Label: Serial No.: PCB Type/Code: Location: Item/State: No. of Items: Manufacturer: Status: In-Storage Contents:					
12	5 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO-ELECTRIC COMMISSION 43 ALICE STREET, ACTON HALTON HILLS TOWN ON L7J 2A9	CA
Certificate #: 8-3708-95-000 Application Year: 95 Issue Date: 1/19/96 Approval Type: Industrial air Status: Application Cancelled Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: SELF CONTAINED STANDBY DIESEL GENERATORS Contaminants: Emission Control:					
12	6 of 37	SW/123.7	349.8 / -0.73	43 Alice Street Acton ON L7J 2A9	CA
Certificate #: 1734-4MCR4X Application Year: 00 Issue Date: 10/27/00 Approval Type: Industrial air Status: Approved Application Type: New Certificate of Approval Client Name: Halton Hills Hydro Client Address: 43 Alice Street Client City: Acton Client Postal Code: L7J 2A9 Project Description: This application is for an Air Certificate of Approval for emissions from one mobile emergency diesel powered electrical generator. This generator will primarily provide emergency power at the Halton Hills Hydro Facility. On occasion, the unit may also be temporarily relocated and used to provide mobile power at off-site locations. Contaminants: Emission Control:					
12	7 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	OPCB

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Year: 1998 Site Number: 30288A001 Name Owner: Additional Site Information:					
--Details--					
Quantity:	1.00				
Address Site:					
Description:	Number of Capacitors with High Level PCBs (>1000 ppm)				
Quantity:	2970.00				
Address Site:					
Description:	Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg				
Quantity:	3545.00				
Address Site:					
Description:	Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg				
Quantity:	12.00				
Address Site:					
Description:	Number of Transformers with Low Level PCBs (< 1000 ppm) kg				
Quantity:	17.00				
Address Site:					
Description:	Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg				
Quantity:	6800.00				
Address Site:					
Description:	Calculated Weight (Kg) of Drums of Soil with Low Level PCBs (< 1000 ppm) kg				
Quantity:	18.00				
Address Site:					
Description:	Number of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg				
Quantity:	2700.00				
Address Site:					
Description:	Calculated Weight of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg				
12	8 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	OPCB
Year: 1999 Site Number: 30288A001 Name Owner: Additional Site Information:					
--Details--					
Quantity:	1.00				
Address Site:					
Description:	Number of Capacitors with High Level PCBs (>1000 ppm)				
Quantity:	2970.00				
Address Site:					
Description:	Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg				
Quantity:	3545.00				
Address Site:					
Description:	Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg				
Quantity:	12.00				
Address Site:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:		Number of Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity:		17.00			
Address Site:					
Description:		Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg			
Quantity:		6800.00			
Address Site:					
Description:		Calculated Weight (Kg) of Drums of Soil with Low Level PCBs (< 1000 ppm) kg			
Quantity:		18.00			
Address Site:					
Description:		Number of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg			
Quantity:		2700.00			
Address Site:					
Description:		Calculated Weight of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg			
12	9 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	OPCB
Year:		2000			
Site Number:		30288A001			
Name Owner:					
Additional Site Information:					
<u>--Details--</u>					
Quantity:		3545.00			
Address Site:					
Description:		Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity:		15.00			
Address Site:					
Description:		Number of Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity:		1.00			
Address Site:					
Description:		Number of Capacitors with High Level PCBs (>1000 ppm)			
12	10 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	OPCB
Year:		2003			
Site Number:		30288A001			
Name Owner:					
Additional Site Information:					
<u>--Details--</u>					
Quantity:		13.00			
Address Site:					
Description:		Number of Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity:		3545.00			
Address Site:					
Description:		Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	11 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET GEORGETOWN ON L7J 2A9	OPCB
Year: 1995 Site Number: 30288A001 Name Owner: Additional Site Information:					
--Details--					
Quantity:		1.00			
Address Site:					
Description:		Number of Capacitors with High Level PCBs (>1000 ppm)			
Quantity:		2673.00			
Address Site:					
Description:		Weight of Bulk Liquid with Low Level PCBs (< 1000 ppm) kg			
Quantity:		3190.00			
Address Site:					
Description:		Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity:		12.00			
Address Site:					
Description:		Number of Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity:		17.00			
Address Site:					
Description:		Number of Drums of Soil with Low Level PCBs (< 1000 ppm) kg			
Quantity:		6800.00			
Address Site:					
Description:		Weight of Drums of Soil with Low Level PCBs (< 1000 ppm) kg			
Quantity:		18.00			
Address Site:					
Description:		Number of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg			
Quantity:		2700.00			
Address Site:					
Description:		Weight of Drums of Other Material with Low Level PCBs (< 1000 ppm) kg			
12	12 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO-ELECTRIC COMM. 43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	GEN
Generator No: ON0453500 SIC Code: 4911 SIC Description: ELECT. POWER SYS. Approval Years: 86,87,88,89,90 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
12	13 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Generator No: ON0453500 SIC Code: 4911 SIC Description: ELECT. POWER SYS. Approval Years: 92,93,95,96,97,98,99,00,01 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 122 Waste Class Name: ALKALINE WASTES - OTHER METALS Waste Class: 213 Waste Class Name: PETROLEUM DISTILLATES Waste Class: 243 Waste Class Name: PCB'S Waste Class: 251 Waste Class Name: OIL SKIMMINGS & SLUDGES Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS					
12	14 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO-ELECTRIC COMM. 19-094 43 ALICE STREET TOWN OF HALTON HILLS (ACTON) ON L7J 2A9	GEN
Generator No: ON0453500 SIC Code: 4911 SIC Description: ELECT. POWER SYS. Approval Years: 94 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 243 Waste Class Name: PCB'S					
12	15 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No: ON0453500 SIC Code: SIC Description: Approval Years: 02,03,04,05,06,07,08 PO Box No: Country:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
Waste Class:		243			
Waste Class Name:		PCB'S			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
12	16 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	NPCB
Company Code:		F1010			
Industry:		Undefined			
Site Status:		Stored for Disposal			
Transaction Date:		12/30/1995			
Inspection Date:					
<u>--Details--</u>					
Label:					
Serial No.:					
PCB Type/Code:		Mineral Oil/Unknown			
Location:					
Item/State:					
No. of Items:					
Manufacturer:					
Status:		Stored for disposal			
Contents:					
12	17 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	OPCB
Year:		2004			
Site Number:		30288A001			
Name Owner:					
Additional Site Information:					
<u>--Details--</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Quantity: Address Site: Description:		600			
Quantity: Address Site: Description:		Weight of Liquid in Transformers with Low Level PCBs (< 1000 ppm) kg			
Quantity: Address Site: Description:		13			
Quantity: Address Site: Description:		Number of Transformers with Low Level PCBs (< 1000 ppm) kg			
12	18 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL 43 ALICE ST ACTON ON L7J 2A9	FSTH
License Issue Date: Tank Status: Tank Status As Of: Operation Type: Facility Type:		2/13/1992 Licensed August 2007 Private Fuel Outlet Gasoline Station - Self Serve			
--Details--					
Status: Year of Installation: Corrosion Protection: Capacity: Tank Fuel Type:		Active 1989 10000 Liquid Fuel Single Wall UST - Gasoline			
Status: Year of Installation: Corrosion Protection: Capacity: Tank Fuel Type:		Active 1989 10000 Liquid Fuel Single Wall UST - Diesel			
12	19 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL 43 ALICE ST ACTON ON L7J 2A9	FSTH
License Issue Date: Tank Status: Tank Status As Of: Operation Type: Facility Type:		2/13/1992 Licensed December 2008 Private Fuel Outlet Gasoline Station - Self Serve			
--Details--					
Status: Year of Installation: Corrosion Protection: Capacity: Tank Fuel Type:		Active 1989 10000 Liquid Fuel Single Wall UST - Gasoline			
Status: Year of Installation: Corrosion Protection: Capacity: Tank Fuel Type:		Active 1989 10000 Liquid Fuel Single Wall UST - Diesel			
12	20 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO 43 ALICE STREET ACTON ON L7J 2A9	NPCB

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Company Code: F1010 Industry: UNDEFINED Site Status: Transaction Date: Inspection Date:					
--Details--					
Label: F101000 Serial No.: PCB Type/Code: MINERAL OIL/UNKNOWN Location: Item/State: TRANSFORMER/FULL No. of Items: 15 Manufacturer: Status: STORED FOR DISPOSAL Contents: 3545 KG					
12	21 of 37	SW/123.7	349.8 / -0.73	43 ALICE STREET ACTON ON L7J 2A9	HINC
External File Num: FS INC 0809-05399 Fuel Occurrence Type: Discovery of a Petroleum Product Date of Occurrence: 9/17/2008 Fuel Type Involved: Gasoline Status Desc: Completed - Level 2 Root Cause Not Established(End) Job Type Desc: Incident/Near-Miss Occurrence (FS) Oper. Type Involved: Private Fuel Outlet (including agricultural farms) Service Interruptions: No Property Damage: No Fuel Life Cycle Stage: Storage and Dispensing Root Cause: Reported Details: Halton Hills Hydro Fuel Category: Liquid Fuel Occurrence Type: Incident Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.) County Name: Halton Approx. Quant. Rel: Nearby body of water: Enter Drainage Syst.: Approx. Quant. Unit: Environmental Impact:					
12	22 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No: ON0453500 SIC Code: 221122 SIC Description: Electric Power Distribution Approval Years: 2009 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		243			
Waste Class Name:		PCBS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
12	23 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:		ON0453500			
SIC Code:		221122			
SIC Description:		Electric Power Distribution			
Approval Years:		2010			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
 <u>Detail(s)</u>					
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		243			
Waste Class Name:		PCBS			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
12	24 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No: ON0453500 SIC Code: 221122 SIC Description: Electric Power Distribution Approval Years: 2011 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 213 Waste Class Name: PETROLEUM DISTILLATES					
Waste Class: 251 Waste Class Name: OIL SKIMMINGS & SLUDGES					
Waste Class: 221 Waste Class Name: LIGHT FUELS					
Waste Class: 122 Waste Class Name: ALKALINE WASTES - OTHER METALS					
Waste Class: 253 Waste Class Name: EMULSIFIED OILS					
Waste Class: 243 Waste Class Name: PCBS					
Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS					
12	25 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL 43 ALICE ST ACTON ON	FST
Inventory No: 11107756 Inventory Status: Active Installation Year: Capacity: Capacity Unit: Tank Type: Manufacturer: Model: Description: UNDERGROUND TANK					
Tank Material: Steel Corrosion Protect: Impressed Current Overfill Protection: Inventory Context: FS Liquid Fuel Tank Inventory Item: FS LIQUID FUEL TANK					
12	26 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO ELECTRIC COMMISSION ATTN G R TRUDELL 43 ALICE ST ACTON ON	FST
Inventory No: 11107720 Inventory Status: Active Installation Year:					
Tank Material: Steel Corrosion Protect: Impressed Current Overfill Protection:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Capacity: Capacity Unit: Tank Type: Manufacturer: Model: Description:				Inventory Context: Inventory Item:	FS Liquid Fuel Tank FS LIQUID FUEL TANK
		UNDERGROUND TANK			
12	27 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON0453500 221122 Electric Power Distribution 2012			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		251 OIL SKIMMINGS & SLUDGES			
Waste Class: Waste Class Name:		213 PETROLEUM DISTILLATES			
Waste Class: Waste Class Name:		243 PCBS			
Waste Class: Waste Class Name:		221 LIGHT FUELS			
Waste Class: Waste Class Name:		253 EMULSIFIED OILS			
Waste Class: Waste Class Name:		252 WASTE OILS & LUBRICANTS			
Waste Class: Waste Class Name:		122 ALKALINE WASTES - OTHER METALS			
12	28 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility:		ON0453500 221122 ELECTRIC POWER DISTRIBUTION 2013			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		243			
Waste Class Name:		PCBS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
<u>12</u>	29 of 37	SW/123.7	349.8 / -0.73	Halton Hills Hydro 43 Alice St. Acton ON L7J 2A9	OPCB
Year:		2012			
Site Number:		30288A001			
Name Owner:		Halton Hills Hydro			
Additional Site Information:					
<u>12</u>	30 of 37	SW/123.7	349.8 / -0.73	Halton Hills Hydro 43 Alice Street Acton ON L7J 2A9	ECA
Approval No:	1734-4MCR4X			MOE District:	Halton-Peel
Approval Date:	2000-10-27			City:	
Status:	Approved			Longitude:	-80.04103
Record Type:	ECA			Latitude:	43.633278
Link Source:	IDS			Geometry X:	
SWP Area Name:	Credit Valley			Geometry Y:	
Approval Type:	ECA-AIR				
Project Type:	AIR				
Business Name:	Halton Hills Hydro				
Address:	43 Alice Street				
Full Address:					
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4585-4L4PK7-14.pdf				
PDF Site Location:					
<u>12</u>	31 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:	ON0453500				
SIC Code:	221122				
SIC Description:	ELECTRIC POWER DISTRIBUTION				
Approval Years:	2016				
PO Box No:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		Canada DON MATTHEWS CO_OFFICIAL 519-853-3700 Ext.235 No No			
<u>Detail(s)</u>					
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		243			
Waste Class Name:		PCBS			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
12	32 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON0453500 221122 ELECTRIC POWER DISTRIBUTION 2015 Canada DON MATTHEWS CO_OFFICIAL 519-853-3700 Ext.235 No No			
<u>Detail(s)</u>					
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		243			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		PCBS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
12	33 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:		ON0453500			
SIC Code:		221122			
SIC Description:		ELECTRIC POWER DISTRIBUTION			
Approval Years:		2014			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:		DON MATTHEWS			
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:		519-853-3700 Ext.235			
Contaminated Facility:		No			
MHSW Facility:		No			
<u>Detail(s)</u>					
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
Waste Class:		243			
Waste Class Name:		PCBS			
Waste Class:		251			
Waste Class Name:		OIL SKIMMINGS & SLUDGES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
Waste Class:		253			
Waste Class Name:		EMULSIFIED OILS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
12	34 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:		ON0453500			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		252 L			
Waste Class Name:		Waste crankcase oils and lubricants			
Waste Class:		252 T			
Waste Class Name:		Waste crankcase oils and lubricants			
Waste Class:		253 L			
Waste Class Name:		Emulsified oils			
<u>12</u>	35 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:		ON0453500			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		253 L			
Waste Class Name:		Emulsified oils			
Waste Class:		252 L			
Waste Class Name:		Waste crankcase oils and lubricants			
Waste Class:		252 T			
Waste Class Name:		Waste crankcase oils and lubricants			
<u>12</u>	36 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:		ON0453500			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		252 T			
Waste Class Name:		Waste crankcase oils and lubricants			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		253 L			
Waste Class Name:		Emulsified oils			
Waste Class:		252 L			
Waste Class Name:		Waste crankcase oils and lubricants			
12	37 of 37	SW/123.7	349.8 / -0.73	HALTON HILLS HYDRO INC. 43 ALICE STREET ACTON ON L7J 2A9	GEN
Generator No:		ON0453500			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		252 T			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		252 L			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		253 L			
Waste Class Name:		EMULSIFIED OILS			
13	1 of 1	ENE/124.6	351.9 / 1.31	METRO LINX ACTON ON	WWIS
Well ID:		7221211		Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:		Monitoring and Test Hole		Data Entry Status:	
Use 2nd:		0		Data Src:	
Final Well Status:		Test Hole		Date Received:	05/30/2014
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:		Z183248		Contractor:	7241
Tag:		A160907		Form Version:	7
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ACTON)			
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Well Completed Date:		04/02/2014			
Year Completed:		2014			
Depth (m):		5.4864			
Latitude:		43.6343416353125			
Longitude:		-80.037823638579			
Path:					
 <u>Bore Hole Information</u>					
Bore Hole ID:	1004796167			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577614.00
Code OB Desc:				North83:	4831711.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	7
Date Completed:	04/02/2014			UTMRC Desc:	margin of error : 1 km - 3 km
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1005157327				
Layer:	2				
Color:	6				
General Color:	BROWN				
Mat1:	11				
Most Common Material:	GRAVEL				
Mat2:	28				
Mat2 Desc:	SAND				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	3.0				
Formation End Depth:	8.0				
Formation End Depth UOM:	ft				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1005157328				
Layer:	3				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:	28				
Mat2 Desc:	SAND				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	8.0				
Formation End Depth:	14.0				
Formation End Depth UOM:	ft				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation ID:		1005157329			
Layer:		4			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		91			
Mat3 Desc:		WATER-BEARING			
Formation Top Depth:		14.0			
Formation End Depth:		18.0			
Formation End Depth UOM:		ft			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1005157326			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		02			
Most Common Material:		TOPSOIL			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		3.0			
Formation End Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1005157340			
Layer:		3			
Plug From:		7.0			
Plug To:		18.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1005157338			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1005157339			
Layer:		2			
Plug From:		1.0			
Plug To:		7.0			
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction ID:		1005157337			
Method Construction Code:		D			
Method Construction:		Direct Push			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1005157325			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1005157333			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		8.0			
Casing Diameter:		1.25			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1005157334			
Layer:		1			
Slot:		10			
Screen Top Depth:		8.0			
Screen End Depth:		18.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		1.5			
 <u>Water Details</u>					
Water ID:		1005157332			
Layer:					
Kind Code:					
Kind:					
Water Found Depth:					
Water Found Depth UOM:		ft			
 <u>Hole Diameter</u>					
Hole ID:		1005157330			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		1.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
 <u>Hole Diameter</u>					
Hole ID:		1005157331			
Diameter:		3.25			
Depth From:		1.0			
Depth To:		18.0			
Hole Depth UOM:		ft			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1004796167			Tag No:	A160907
Depth M:	5.4864			Contractor:	7241
Year Completed:	2014			Latitude:	43.6343416353125
Well Completed Dt:	04/02/2014			Longitude:	-80.037823638579
Audit No:	Z183248			Y:	43.63434163315903
Path:				X:	-80.03782348985789

14	1 of 1	WNW/125.3	356.0 / 5.42	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7362200			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	07/01/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	TGLDCWHT			Contractor:	6607
Tag:	A293291			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Bore Hole Information

Bore Hole ID:	1008327359			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577294.00
Code OB Desc:				North83:	4831732.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	06/17/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					

Overburden and Bedrock

Materials Interval

Formation ID:	1008327466
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Most Common Material:		SILT			
Mat2:		05			
Mat2 Desc:		CLAY			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		3.700000047683716			
Formation End Depth:		7.5			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008327465			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		0.0			
Formation End Depth:		3.700000047683716			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008327467			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		11			
Most Common Material:		GRAVEL			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		7.5			
Formation End Depth:		9.100000381469727			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008327559			
Layer:		2			
Plug From:		0.30000001192092896			
Plug To:		5.099999904632568			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008327558			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Sealing Record</u>					
Plug ID:		1008327536			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008327415			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008327395			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008327495			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1008327508			
Layer:		1			
Slot:		10			
Screen Top Depth:		6.0			
Screen End Depth:		9.100000381469727			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008327396			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Water Details</u>					
Water ID:		1008327440			
Layer:		2			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		8.100000381469727			
Water Found Depth UOM:		m			
<u>Water Details</u>					
Water ID:		1008327439			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		2.4000000953674316			
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1008327521			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		9.100000381469727			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1008327359			Tag No:	A293291
Depth M:	9.1			Contractor:	6607
Year Completed:	2020			Latitude:	43.6345640133909
Well Completed Dt:	06/17/2020			Longitude:	-80.0417871084213
Audit No:	TGLDCWHT			Y:	43.6345640114433
Path:	736\7362200.pdf			X:	-80.04178695891898

<u>15</u>	1 of 2	SSW/126.9	350.9 / 0.31	61 Bower St (Acton) Halton Hills ON	SPL
Ref No:	6383-98HSTA			Municipality No:	
Year:				Nature of Damage:	
Incident Dt:	09-JUN-13			Discharger Report:	
Dt MOE Arvl on Scn:				Material Group:	
MOE Reported Dt:	09-JUN-13			Health/Env Conseq:	
Dt Document Closed:				Agency Involved:	
Site No:					
MOE Response:	Referral to others				
Site County/District:					
Site Geo Ref Meth:					
Site District Office:					
Nearest Watercourse:					
Site Name:	line strike<UNOFFICIAL>				
Site Address:	61 Bower St (Acton)				
Site Region:					
Site Municipality:	Halton Hills				
Site Lot:					
Site Conc:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Geo Ref Accu: Site Map Datum: Northing: Easting: Incident Cause: Operator/Human error Incident Event: Environment Impact: Confirmed Nature of Impact: Air Pollution; Human Health/Safety Contaminant Qty: 1 other - see incident description System Facility Address: Client Name: Client Type: Source Type: Contaminant Code: 35 Contaminant Name: METHANE GAS, COMPRESSED (NATURAL GAS) Contaminant Limit 1: Contam Limit Freq 1: Contaminant UN No 1: Receiving Medium: Incident Reason: Operator/Human Error Incident Summary: TSSA: line strike 61 Bower, Acton made safe Activity Preceding Spill: Property 2nd Watershed: Property Tertiary Watershed: Sector Type: Pipeline/Components SAC Action Class: Air Spills - Gases and Vapours Call Report Locatn Geodata:					
15	2 of 2	SSW/126.9	350.9 / 0.31	PIPELINE HIT - 1/2" 61 BOWER ST,,ACTON,ON,L7J 1E4,CA ON	PINC
Incident Id: Incident No: 1125406 Incident Reported Dt: 6/10/2013 Type: FS-Pipeline Incident Status Code: Tank Status: Home Owner Pipeline Strike Task No: Spills Action Centre: Fuel Type: Fuel Occurrence Tp: Date of Occurrence: Occurrence Start Dt: Depth: Customer Acct Name: PIPELINE HIT - 1/2" Incident Address: 61 BOWER ST,,ACTON,ON,L7J 1E4,CA Operation Type: Pipeline Type: Regulator Type: Summary: Reported By: Affiliation: Occurrence Desc: Damage Reason: Notes:					
Pipe Material: Fuel Category: Health Impact: Environment Impact: Property Damage: Service Interrupt: Enforce Policy: Public Relation: Pipeline System: PSIG: Attribute Category: Regulator Location: Method Details:					
16	1 of 1	WNW/127.2	355.9 / 5.31	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID: 7361995 Construction Date:					
Flowing (Y/N): Flow Rate:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	07/01/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	3JZBX9W7			Contractor:	6607
Tag:	A293286			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Bore Hole Information

Bore Hole ID:	1008323626	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577274.00
Code OB Desc:		North83:	4831709.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	06/17/2020	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1008323723
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Mat2 Desc:	CLAY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	3.700000047683716
Formation End Depth:	8.100000381469727
Formation End Depth UOM:	m

Overburden and Bedrock

Materials Interval

Formation ID:	1008323724
Layer:	3
Color:	2
General Color:	GREY
Mat1:	11

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Most Common Material:		GRAVEL			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		8.100000381469727			
Formation End Depth:		10.0			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008323722			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		0.0			
Formation End Depth:		3.700000047683716			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008323793			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008323812			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008323813			
Layer:		2			
Plug From:		0.30000001192092896			
Plug To:		6.0			
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008323692			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Pipe Information</u>					
Pipe ID:		1008323669			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008323749			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.900000095367432			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1008323765			
Layer:		1			
Slot:		10			
Screen Top Depth:		6.900000095367432			
Screen End Depth:		10.0			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008323670			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008323713			
Layer:		2			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		8.100000381469727			
Water Found Depth UOM:		m			
<u>Water Details</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Water ID:		1008323712			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		2.4000000953674316			
Water Found Depth UOM:		m			
 <u>Hole Diameter</u>					
Hole ID:		1008323777			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		10.0			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
 <u>Links</u>					
Bore Hole ID:	1008323626			Tag No:	A293286
Depth M:	10			Contractor:	6607
Year Completed:	2020			Latitude:	43.6343590262313
Well Completed Dt:	06/17/2020			Longitude:	-80.0420383035881
Audit No:	3JZBX9W7			Y:	43.63435902456673
Path:	736\7361995.pdf			X:	-80.0420381547605
17	1 of 1	E/128.4	352.9 / 2.33	137 MILL ST. E. ACTON ON	WWIS
Well ID:	7269005			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	08/17/2016
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	Z223957			Contractor:	6607
Tag:	A201594			Form Version:	7
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
 PDF URL (Map):					
 <u>Additional Detail(s) (Map)</u>					
Well Completed Date:	07/06/2016				
Year Completed:	2016				
Depth (m):	6.6				
Latitude:	43.633646644556				
Longitude:	-80.0376239832211				
Path:					
 <u>Bore Hole Information</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Bore Hole ID:	1006215380			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577631.00
Code OB Desc:				North83:	4831634.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	07/06/2016			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1006218501				
Layer:	2				
Color:	6				
General Color:	BROWN				
Mat1:	28				
Most Common Material:	SAND				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:	85				
Mat3 Desc:	SOFT				
Formation Top Depth:	0.5				
Formation End Depth:	6.599999904632568				
Formation End Depth UOM:	m				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1006218500				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	28				
Most Common Material:	SAND				
Mat2:	11				
Mat2 Desc:	GRAVEL				
Mat3:	01				
Mat3 Desc:	FILL				
Formation Top Depth:	0.0				
Formation End Depth:	0.5				
Formation End Depth UOM:	m				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1006218509				
Layer:	2				
Plug From:	0.30000001192092896				
Plug To:	3.299999952316284				
Plug Depth UOM:	m				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug ID:		1006218508			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1006218510			
Layer:		3			
Plug From:		3.299999952316284			
Plug To:		6.599999904632568			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1006218507			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1006218499			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1006218504			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.5999999046325684			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1006218505			
Layer:		1			
Slot:		10			
Screen Top Depth:		3.5999999046325684			
Screen End Depth:		6.599999904632568			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Water Details</u>					
Water ID:		1006218503			
Layer:					
Kind Code:					
Kind:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Water Found Depth:					
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1006218502			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		6.599999904632568			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:		1006215380		Tag No:	A201594
Depth M:		6.6		Contractor:	6607
Year Completed:		2016		Latitude:	43.633646644556
Well Completed Dt:		07/06/2016		Longitude:	-80.0376239832211
Audit No:		Z223957		Y:	43.63364664322378
Path:				X:	-80.03762383312359
<u>18</u>	1 of 33	ENE/134.6	350.9 / 0.33	HARBISON-WALKER REFRACTORIES 159 PERTH ST ACTON ON L7J 1C9	SCT
Established:		1950			
Plant Size (ft²):		20000			
Employment:		20			
<u>--Details--</u>					
Description:		Clay Building Material and Refractory Manufacturing			
SIC/NAICS Code:		327120			
<u>18</u>	2 of 33	ENE/134.6	350.9 / 0.33	A.P. GREEN REFRACTORIES (CDA) 159 PERTH ST ACTON ON L7J 1C9	SCT
Established:		1950			
Plant Size (ft²):		20000			
Employment:		20			
<u>--Details--</u>					
Description:		CERAMIC WALL AND FLOOR TILE			
SIC/NAICS Code:		3253			
Description:		CLAY REFRACTORIES			
SIC/NAICS Code:		3255			
<u>18</u>	3 of 33	ENE/134.6	350.9 / 0.33	RHI AMERCIA REFRACTORIES 159 Perth St Acton ON L7J 1C9	SCT
Established:		1950			
Plant Size (ft²):		20000			
Employment:		20			
<u>--Details--</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description: SIC/NAICS Code:		Clay Building Material and Refractory Manufacturing 327120			
18	4 of 33	ENE/134.6	350.9 / 0.33	RHI Refractories America 159 Perth St Acton ON L7J 1C9	SCT
Established: Plant Size (ft²): Employment:		1950 20000 20			
--Details-- Description: SIC/NAICS Code:		Clay Building Material and Refractory Manufacturing 327120			
18	5 of 33	ENE/134.6	350.9 / 0.33	RHI REFRACTORIES OF AMERICA 159 PERTH STREET HALTON ON L7J 1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON4150519 9999 OTHER SERVICES 01,02 			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		252 WASTE OILS & LUBRICANTS			
18	6 of 33	ENE/134.6	350.9 / 0.33	Global-GIX Canada Inc. 159 Perth St Acton ON L7J 1C9	SCT
Established: Plant Size (ft²): Employment:		1950 20000			
--Details-- Description: SIC/NAICS Code:		Clay Building Material and Refractory Manufacturing 327120			
18	7 of 33	ENE/134.6	350.9 / 0.33	Global-GIX Canada Inc. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years:		ON4150519 03,04,05,06			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
Detail(s)					
Waste Class:		146			
Waste Class Name:		OTHER SPECIFIED INORGANICS			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
18	8 of 33	ENE/134.6	350.9 / 0.33	ANH Refractories Canada Inc. 159 Perth St Acton ON L7J 1C9	SCT
Established:		01-JUL-50			
Plant Size (ft²):		20000			
Employment:					
--Details--					
Description:		Clay Building Material and Refractory Manufacturing			
SIC/NAICS Code:		327120			
Description:		Clay Building Material and Refractory Manufacturing			
SIC/NAICS Code:		327120			
18	9 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No:		ON4150519			
SIC Code:		327120			
SIC Description:		Clay Building Material and Refractory Manufacturing			
Approval Years:		07,08			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		146			
Waste Class Name:		OTHER SPECIFIED INORGANICS			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
18	10 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street Acton ON L7J 1C9	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Generator No: ON4150519 SIC Code: 327120 SIC Description: Clay Building Material and Refractory Manufacturing Approval Years: 2009 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS					
18	11 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: ON4150519 SIC Code: 327120 SIC Description: Clay Building Material and Refractory Manufacturing Approval Years: 2010 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS					
18	12 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: ON4150519 SIC Code: 327120 SIC Description: Clay Building Material and Refractory Manufacturing Approval Years: 2011 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
18	13 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No:		ON4150519			
SIC Code:		327120			
SIC Description:		Clay Building Material and Refractory Manufacturing			
Approval Years:		2012			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
18	14 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J1C9	EHS
Order No:		20130719024		Nearest Intersection:	
Status:		C		Municipality: Acton, Ontario	
Report Type:		Standard Report		Client Prov/State: VA	
Report Date:		30-JUL-13		Search Radius (km): .25	
Date Received:		19-JUL-13		X: -80.038003	
Previous Site Name:				Y: 43.634838	
Lot/Building Size:					
Additional Info Ordered:		Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos			
18	15 of 33	ENE/134.6	350.9 / 0.33	159 Perth St Halton Hills ON L7J1C9	EHS
Order No:		20130716004		Nearest Intersection:	
Status:		C		Municipality: Acton, Halton Hills, Halton Region	
Report Type:		Standard Report		Client Prov/State: ON	
Report Date:		24-JUL-13		Search Radius (km): .25	
Date Received:		16-JUL-13		X: -80.038907	
Previous Site Name:				Y: 43.635066	
Lot/Building Size:					
Additional Info Ordered:		Fire Insur. Maps and/or Site Plans			
18	16 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street Acton ON	GEN
Generator No:		ON4150519			
SIC Code:		327120			
SIC Description:		CLAY BUILDING MATERIAL AND REFRACTORARY MANUFACTURING			
Approval Years:		2013			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		252 WASTE OILS & LUBRICANTS			
18	17 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON4150519 327120 CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING 2016 Canada Steve Baker CO_OFFICIAL 519 241 2100 Ext. No No			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		252 WASTE OILS & LUBRICANTS			
Waste Class: Waste Class Name:		213 PETROLEUM DISTILLATES			
18	18 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON4150519 327120 CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING 2015 Canada Steve Baker CO_OFFICIAL 519 241 2100 Ext. No No			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		213 PETROLEUM DISTILLATES			
Waste Class: Waste Class Name:		252 WASTE OILS & LUBRICANTS			
18	19 of 33	ENE/134.6	350.9 / 0.33	ANH REFRACTORIES CANADA Inc. 159 Perth Street	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Acton ON L7J 1C9					
Generator No:		ON4150519			
SIC Code:		327120			
SIC Description:		CLAY BUILDING MATERIAL AND REFRACTORY MANUFACTURING			
Approval Years:		2014			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:		Steve Baker			
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:		519 241 2100 Ext.			
Contaminated Facility:		No			
MHSW Facility:		No			
Detail(s)					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		213			
Waste Class Name:		PETROLEUM DISTILLATES			
18	20 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No:		ON4150519			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		252 L			
Waste Class Name:		Waste crankcase oils and lubricants			
18	21 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No:		ON4150519			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Detail(s)</u>					
Waste Class:		252 L			
Waste Class Name:		Waste crankcase oils and lubricants			
18	22 of 33	ENE/134.6	350.9 / 0.33	HARBISONWALKER INTERNATIONAL CORP. 159 Perth ST Acton ON L7J 1C9	EASR
Approval No:		R-010-1111584513		MOE District:	Halton-Peel
Status:		REGISTERED		Municipality:	Acton
Date:		2019-09-30		Latitude:	43.63444444
Record Type:		EASR		Longitude:	-80.04083333
Link Source:		MOFA		Geometry X:	
Project Type:		Air Emissions		Geometry Y:	
Full Address:					
Approval Type:		EASR-Air Emissions			
SWP Area Name:		Credit Valley			
PDF URL:					
PDF Site Location:					
18	23 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth St Acton Halton Hills ON L7J 1C9	SPL
Ref No:		2481-BBRS34		Municipality No:	
Year:				Nature of Damage:	
Incident Dt:		4/12/2019		Discharger Report:	
Dt MOE Arvl on Scn:		4/12/2019		Material Group:	
MOE Reported Dt:		5/1/2019		Health/Env Conseq:	1 - Administrative
Dt Document Closed:				Agency Involved:	
Site No:		2394-BBKNCV			
MOE Response:		Yes			
Site County/District:		Regional Municipality of Halton			
Site Geo Ref Meth:		NA			
Site District Office:		Halton-Peel			
Nearest Watercourse:					
Site Name:		HarbisonWalker International			
Site Address:		159 Perth St Acton			
Site Region:		Central			
Site Municipality:		Halton Hills			
Site Lot:					
Site Conc:		NA			
Site Geo Ref Accu:		NA			
Site Map Datum:		NA			
Northing:		NA			
Easting:		NA			
Incident Cause:					
Incident Event:					
Environment Impact:					
Nature of Impact:					
Contaminant Qty:					
System Facility Address:					
Client Name:		HarbisonWalker International Corp.			
Client Type:		Corporation			
Source Type:					
Contaminant Code:					
Contaminant Name:					
Contaminant Limit 1:					
Contam Limit Freq 1:					
Contaminant UN No 1:					
Receiving Medium:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Incident Reason: Incident Summary: Inspection non-compliance, action items Activity Preceding Spill: Property 2nd Watershed: Property Tertiary Watershed: Sector Type: SAC Action Class: Call Report Locatn Geodata:					
18	24 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: ON4150519 SIC Code: SIC Description: Approval Years: As of Nov 2021 PO Box No: Country: Canada Status: Registered Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 252 L Waste Class Name: Waste crankcase oils and lubricants					
18	25 of 33	ENE/134.6	350.9 / 0.33	HarbisonWalker International Corp. 159 Perth Street Acton ON L7J 1C9	GEN
Generator No: ON4150519 SIC Code: SIC Description: Approval Years: As of Oct 2022 PO Box No: Country: Canada Status: Registered Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 252 L Waste Class Name: WASTE OILS & LUBRICANTS					
18	26 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: 22081700916 Status: C Report Type: Standard Report Report Date: 22-AUG-22 Date Received: 17-AUG-22					
Nearest Intersection: Municipality: Client Prov/State: OH Search Radius (km): .25 X: -80.0382105					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Previous Site Name: Lot/Building Size: Additional Info Ordered:				Y: 43.6348068 Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos	
18	27 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: 22101900672 Status: C Report Type: Standard Report Report Date: 24-OCT-22 Date Received: 19-OCT-22 Previous Site Name: Lot/Building Size: Additional Info Ordered:				Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): .25 X: -80.0382105 Y: 43.6348068 Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos	
18	28 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: 22101900672 Status: C Report Type: Standard Report Report Date: 24-OCT-22 Date Received: 19-OCT-22 Previous Site Name: Lot/Building Size: Additional Info Ordered:				Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): .25 X: -80.0382105 Y: 43.6348068 Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos	
18	29 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: 22081700916 Status: C Report Type: Standard Report Report Date: 22-AUG-22 Date Received: 17-AUG-22 Previous Site Name: Lot/Building Size: Additional Info Ordered:				Nearest Intersection: Municipality: Client Prov/State: OH Search Radius (km): .25 X: -80.0382105 Y: 43.6348068 Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos	
18	30 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: 22081700916 Status: C Report Type: Standard Report Report Date: 22-AUG-22 Date Received: 17-AUG-22 Previous Site Name: Lot/Building Size: Additional Info Ordered:				Nearest Intersection: Municipality: Client Prov/State: OH Search Radius (km): .25 X: -80.0382105 Y: 43.6348068 Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos	
18	31 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: 22101900672 Status: C 				Nearest Intersection: Municipality:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Report Type: Report Date: Date Received: Previous Site Name: Lot/Building Size: Additional Info Ordered:	Standard Report 24-OCT-22 19-OCT-22 Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos			Client Prov/State: Search Radius (km): X: Y:	ON .25 -80.0382105 43.6348068
18	32 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: Status: Report Type: Report Date: Date Received: Previous Site Name: Lot/Building Size: Additional Info Ordered:	22101900672 C Standard Report 24-OCT-22 19-OCT-22 Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos			Nearest Intersection: Municipality: Client Prov/State: Search Radius (km): X: Y:	 ON .25 -80.0382105 43.6348068
18	33 of 33	ENE/134.6	350.9 / 0.33	159 Perth Street Acton ON L7J 1C9	EHS
Order No: Status: Report Type: Report Date: Date Received: Previous Site Name: Lot/Building Size: Additional Info Ordered:	22081700916 C Standard Report 22-AUG-22 17-AUG-22 Fire Insur. Maps and/or Site Plans; Topographic Maps; City Directory; Aerial Photos			Nearest Intersection: Municipality: Client Prov/State: Search Radius (km): X: Y:	 OH .25 -80.0382105 43.6348068
19	1 of 1	SSE/138.8	352.9 / 2.34	80 Mill Street East Acton ON L7J 1H6	EHS
Order No: Status: Report Type: Report Date: Date Received: Previous Site Name: Lot/Building Size: Additional Info Ordered:	20120725012 C Custom Report 31-JUL-12 25-JUL-12 			Nearest Intersection: Municipality: Client Prov/State: Search Radius (km): X: Y:	 ON .25 -80.039044 43.631734
20	1 of 6	E/141.2	353.2 / 2.61	Sotirios Investments Inc 137 Mill Street East Acton ON L7J1H9	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:	ON5271741 445299 ALL OTHER SPECIALTY FOOD STORES 2016 Canada Jordan Stewart CO_ADMIN 5197323015 Ext. No No				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Detail(s)</u>					
Waste Class:		221			
Waste Class Name:		LIGHT FUELS			
20	2 of 6	E/141.2	353.2 / 2.61	Danosh Construction 137 mill street east Acton ON L7J 1H9	GEN
Generator No:		ON4696243			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2017			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		221 L			
Waste Class Name:		Light fuels			
20	3 of 6	E/141.2	353.2 / 2.61	137 Mill Street East Acton ON L7J 1H9	EHS
Order No:		22072100386		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Standard Report		Client Prov/State:	
Report Date:		26-JUL-22		Search Radius (km):	
Date Received:		21-JUL-22		X:	
Previous Site Name:				Y:	
Lot/Building Size:					
Additional Info Ordered:		Fire Insur. Maps and/or Site Plans; City Directory			
20	4 of 6	E/141.2	353.2 / 2.61	137 Mill Street East Acton ON L7J 1H9	EHS
Order No:		22072100386		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Standard Report		Client Prov/State:	
Report Date:		26-JUL-22		Search Radius (km):	
Date Received:		21-JUL-22		X:	
Previous Site Name:				Y:	
Lot/Building Size:					
Additional Info Ordered:		Fire Insur. Maps and/or Site Plans; City Directory			
20	5 of 6	E/141.2	353.2 / 2.61	137 Mill Street East Acton ON L7J 1H9	EHS
Order No:		22072100386		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Standard Report		Client Prov/State:	
Report Date:		26-JUL-22		Search Radius (km):	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Date Received:21-JUL-22X:-80.0375337 Previous Site Name:Y:43.6334292 Lot/Building Size: Additional Info Ordered:Fire Insur. Maps and/or Site Plans; City Directory					
20	6 of 6	E/141.2	353.2 / 2.61	137 Mill Street East Acton ON L7J 1H9	EHS
Order No:22072100386Nearest Intersection: Status:CMunicipality: Report Type:Standard ReportClient Prov/State:ON Report Date:26-JUL-22Search Radius (km):.25 Date Received:21-JUL-22X:-80.0375337 Previous Site Name:Y:43.6334292 Lot/Building Size: Additional Info Ordered:Fire Insur. Maps and/or Site Plans; City Directory					
21	1 of 1	WNW/155.0	355.8 / 5.27	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:7350907Flowing (Y/N): Construction Date:Flow Rate: Use 1st:Monitoring and Test HoleData Entry Status: Use 2nd:Data Src: Final Well Status:Observation WellsDate Received:12/20/2019 Water Type:Selected Flag:TRUE Casing Material:Abandonment Rec: Audit No:27W47DN6Contractor:6607 Tag:A286957Form Version:9 Constructn Method:Owner: Elevation (m):County:HALTON Elevatn Reliabilty:Lot:029 Depth to Bedrock:Concession:03 Well Depth:Concession Name:CON Overburden/Bedrock:Easting NAD83: Pump Rate:Northing NAD83: Static Water Level:Zone: Clear/Cloudy:UTM Reliability: Municipality:HALTON HILLS TOWN (ESQUESING) Site Info:MW 1420 PDF URL (Map):https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350907.pdf					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:12/09/2019 Year Completed:2019 Depth (m):7.74 Latitude:43.6346303575079 Longitude:-80.0421827564353 Path:735\7350907.pdf					
<u>Bore Hole Information</u>					
Bore Hole ID:1007854288Elevation: DP2BR:Elevrc: Spatial Status:Zone:17 Code OB:East83:577262.00 Code OB Desc:North83:4831739.00 Open Hole:Org CS:UTM83 Cluster Kind:UTMRC:4					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Date Completed:		12/09/2019		UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007854954			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		3.299999952316284			
Formation End Depth:		7.599999904632568			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007854953			
Layer:		2			
Color:		7			
General Color:		RED			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		3.299999952316284			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007854955			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		7.599999904632568			
Formation End Depth:		7.739999771118164			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Materials Interval</u>					
Formation ID:		1007854952			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855535			
Layer:		1			
Plug From:		0.0			
Plug To:		3.799999952316284			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855436			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854728			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007854565			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007855155			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		4.690000057220459			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Construction Record - Screen</u>					
Screen ID:		1007855252			
Layer:		1			
Slot:		10			
Screen Top Depth:		4.690000057220459			
Screen End Depth:		7.739999771118164			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007854566			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1007855333			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		7.739999771118164			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1007854288			Tag No:	A286957
Depth M:	7.74			Contractor:	6607
Year Completed:	2019			Latitude:	43.6346303575079
Well Completed Dt:	12/09/2019			Longitude:	-80.0421827564353
Audit No:	27W47DN6			Y:	43.63463035641494
Path:	735\7350907.pdf			X:	-80.04218260648291
22	1 of 1	WNW/155.2	355.8 / 5.27	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7360685			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/09/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	KCMCRXU7			Contractor:	6607
Tag:	A271808			Form Version:	9

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Constructn Method:			Owner:		
Elevation (m):			County: HALTON		
Elevatn Reliabilty:			Lot: 029		
Depth to Bedrock:			Concession: 03		
Well Depth:			Concession Name: CON		
Overburden/Bedrock:			Easting NAD83:		
Pump Rate:			Northing NAD83:		
Static Water Level:			Zone:		
Clear/Cloudy:			UTM Reliability:		
Municipality:			HALTON HILLS TOWN (ESQUESING)		
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:			06/05/2020		
Year Completed:			2020		
Depth (m):			8.1		
Latitude:			43.634657158259		
Longitude:			-80.0421575368253		
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:			1008307606		
DP2BR:			Elevation:		
Spatial Status:			Elevrc:		
Code OB:			Zone: 17		
Code OB Desc:			East83: 577264.00		
Open Hole:			North83: 4831742.00		
Cluster Kind:			Org CS: UTM83		
Date Completed:			UTMRC: 4		
Remarks:			UTMRC Desc: margin of error : 30 m - 100 m		
Loc Method Desc:			Location Method: wwr		
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:			1008308280		
Layer:			1		
Color:			6		
General Color:			BROWN		
Mat1:			28		
Most Common Material:			SAND		
Mat2:			06		
Mat2 Desc:			SILT		
Mat3:			01		
Mat3 Desc:			FILL		
Formation Top Depth:			0.0		
Formation End Depth:			8.100000381469727		
Formation End Depth UOM:			m		
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug ID:		1008308897			
Layer:		1			
Plug From:		0.0			
Plug To:		4.5			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008308898			
Layer:		2			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008308715			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008307962			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008307832			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008308434			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		5.099999904632568			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
 <u>Construction Record - Screen</u>					
Screen ID:		1008308519			
Layer:		1			
Slot:		10			
Screen Top Depth:		5.099999904632568			
Screen End Depth:		8.100000381469727			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008307833			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008308119			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		2.700000047683716			
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1008308608			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		8.100000381469727			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:		1008307606		Tag No: A271808	
Depth M:		8.1		Contractor: 6607	
Year Completed:		2020		Latitude: 43.634657158259	
Well Completed Dt:		06/05/2020		Longitude: -80.0421575368253	
Audit No:		KCMCRXU7		Y: 43.63465715664879	
Path:		736\7360685.pdf		X: -80.04215738718521	
23	1 of 1	SSW/160.9	350.9 / 0.36	Brookfield LePage Johnson Controls 53 Bower Street Acton ON L7J 1E1	GEN
Generator No:		ON3196891			
SIC Code:		811119			
SIC Description:		Other Automotive Mechanical and Electrical Repair			
Approval Years:		06			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Phone No Admin: Contaminated Facility: MHSW Facility:					
Detail(s)					
Waste Class:		243			
Waste Class Name:		PCB'S			
24	1 of 1	WNW/162.6	355.8 / 5.27	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:		7337156		Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:		Monitoring		Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:		Observation Wells		Date Received:	07/18/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:		5YTEVY6H		Contractor:	6607
Tag:		A245816		Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:		MW 3001			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7337156.pdf			
Additional Detail(s) (Map)					
Well Completed Date:		07/09/2019			
Year Completed:		2019			
Depth (m):		8.5			
Latitude:		43.6347205935056			
Longitude:		-80.0422061170396			
Path:		733\7337156.pdf			
Bore Hole Information					
Bore Hole ID:		1007507022		Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577260.00
Code OB Desc:				North83:	4831749.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:		07/09/2019		UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507667			
Layer:		3			
Color:		7			
General Color:		RED			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		05			
Mat2 Desc:		CLAY			
Mat3:		79			
Mat3 Desc:		PACKED			
Formation Top Depth:		2.700000047683716			
Formation End Depth:		6.0			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507669			
Layer:		5			
Color:		2			
General Color:		GREY			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		79			
Mat3 Desc:		PACKED			
Formation Top Depth:		7.599999904632568			
Formation End Depth:		8.5			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507666			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		05			
Mat2 Desc:		CLAY			
Mat3:		79			
Mat3 Desc:		PACKED			
Formation Top Depth:		0.4000000059604645			
Formation End Depth:		2.700000047683716			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507665			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat2 Desc:		GRAVEL			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		0.4000000059604645			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507668			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		05			
Mat2 Desc:		CLAY			
Mat3:		79			
Mat3 Desc:		PACKED			
Formation Top Depth:		6.0			
Formation End Depth:		7.599999904632568			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007508152			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007508245			
Layer:		1			
Plug From:		0.0			
Plug To:		4.9000000095367432			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007507427			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007507396			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007507877			
Layer:		1			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Material:					
Open Hole or Material:		5			
Depth From:		PLASTIC			
Depth To:		0.0			
Casing Diameter:		5.5			
Casing Diameter UOM:		5.099999904632568			
Casing Depth UOM:		cm			
Construction Record - Screen					
Screen ID:		1007507961			
Layer:		1			
Slot:		10			
Screen Top Depth:		5.5			
Screen End Depth:		8.5			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
Results of Well Yield Testing					
Pumping Test Method Desc:					
Pump Test ID:		1007507397			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
Water Details					
Water ID:		1007507608			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		5.099999904632568			
Water Found Depth UOM:		m			
Hole Diameter					
Hole ID:		1007508047			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		8.5			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
Links					
Bore Hole ID:		1007507022		Tag No:	
Depth M:		8.5		Contractor:	
				A245816	
				6607	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Year Completed: 2019 Well Completed Dt: 07/09/2019 Audit No: 5YTEVY6H Path: 733\7337156.pdf				Latitude: 43.6347205935056 Longitude: -80.0422061170396 Y: 43.634720592690236 X: -80.04220596715633	
25	1 of 6	ESE/166.9	354.3 / 3.73	R & R HONOUR ENTERPRISES INC 130 MILL ST E ACTON ON L7J1J1	PRT
Location ID: 663 Type: retail Expiry Date: 1995-04-30 Capacity (L): 2000 Licence #: 0076361211					
25	2 of 6	ESE/166.9	354.3 / 3.73	Acton Denture Clinic 130 Mill St E Suite 103 Acton ON L7J 1J1	SCT
Established: Plant Size (ft²): Employment:					
--Details--					
Description: Offices of All Other Health Practitioners SIC/NAICS Code: 621390					
Description: Medical Equipment and Supplies Manufacturing SIC/NAICS Code: 339110					
25	3 of 6	ESE/166.9	354.3 / 3.73	130 Mill Street Acton ON	EHS
Order No: 20051006020 Status: C Report Type: Basic Report Report Date: 10/18/2005 Date Received: 10/6/2005 Previous Site Name: Lot/Building Size: Additional Info Ordered: Fire Insur. Maps and/or Site Plans, Title Search, City Directory				Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): 0.25 X: -80.037064 Y: 43.632995	
25	4 of 6	ESE/166.9	354.3 / 3.73	CIAVONE INVESTMENTS LTD 130 MILL ST E ACTON ON	DTNK
<u>Delisted Expired Fuel Safety Facilities</u>					
Instance No: 9651355 Status: EXPIRED Instance ID: 392228 Instance Type: FS Facility Instance Creation Dt: Instance Install Dt: Item Description: Manufacturer:				Expired Date: Max Hazard Rank: Facility Location: Facility Type: Fuel Type 2: Fuel Type 3: Panam Related: Panam Venue Nm:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Model: Serial No: ULC Standard: Quantity: Unit of Measure: Overfill Prot Type: Creation Date: Next Periodic Str DT: TSSA Base Sched Cycle 2: TSSAMax Hazard Rank 1: TSSA Risk Based Periodic Yn: TSSA Volume of Directives: TSSA Periodic Exempt: TSSA Statutory Interval: TSSA Recd Insp Interva: TSSA Recd Tolerance: TSSA Program Area: TSSA Program Area 2: Description: Original Source: Record Date: External Identifier: Item: Piping Steel: Piping Galvanized: Tank Single Wall St: Piping Underground: Tank Underground: Source:					
25	5 of 6	ESE/166.9	354.3 / 3.73	CIAVONE INVESTMENTS LTD 130 MILL ST E ACTON ON	DTNK
<u>Delisted Expired Fuel Safety Facilities</u>					
Instance No: Status: Instance ID: Instance Type: Instance Creation Dt: Instance Install Dt: Item Description: Manufacturer: Model: Serial No: ULC Standard: Quantity: Unit of Measure: Overfill Prot Type: Creation Date: Next Periodic Str DT: TSSA Base Sched Cycle 2: TSSAMax Hazard Rank 1: TSSA Risk Based Periodic Yn: TSSA Volume of Directives: TSSA Periodic Exempt: TSSA Statutory Interval: TSSA Recd Insp Interva: TSSA Recd Tolerance: TSSA Program Area: TSSA Program Area 2: Description: Original Source: Record Date: 10524597 EXPIRED 27385 FS Propane Tank Expired Date: Max Hazard Rank: Facility Location: Facility Type: Fuel Type 2: Fuel Type 3: Panam Related: Panam Venue Nm: External Identifier: Item: Piping Steel: Piping Galvanized: Tank Single Wall St: Piping Underground: Tank Underground: Source:					
25	6 of 6	ESE/166.9	354.3 / 3.73	CANADIAN TIRE STORE 183/R & R HONOUR ENTERPRISES INC 130 MILL STREET EAST	PES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Code OB Desc:				North83:	4831772.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:		06/05/2020		UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008308348			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		7.800000190734863			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008308958			
Layer:		2			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008308769			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008308957			
Layer:		1			
Plug From:		0.0			
Plug To:		4.199999809265137			
Plug Depth UOM:		m			
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1008307995			
Method Construction Code:		6			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008307892			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008308461			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		4.800000190734863			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1008308543			
Layer:		1			
Slot:		10			
Screen Top Depth:		4.800000190734863			
Screen End Depth:		7.800000190734863			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008307893			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008308130			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		2.700000047683716			
Water Found Depth UOM:		m			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:		1008308647			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		7.800000190734863			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1008307696			Tag No:	A264559
Depth M:	7.8			Contractor:	6607
Year Completed:	2020			Latitude:	43.634926619837
Well Completed Dt:	06/05/2020			Longitude:	-80.0420788744722
Audit No:	VIIUQAAH			Y:	43.634926618590036
Path:	736\7360715.pdf			X:	-80.04207872441152
27	1 of 2	NW/170.7	356.6 / 6.00	ON	WWIS
Well ID:	7285175			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:				Data Entry Status:	Yes
Use 2nd:				Data Src:	
Final Well Status:				Date Received:	04/13/2017
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	C35279			Contractor:	7238
Tag:	A213579			Form Version:	8
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:	03/29/2017				
Year Completed:	2017				
Depth (m):					
Latitude:	43.6350964269255				
Longitude:	-80.0419274123994				
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1006381486			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577282.00
Code OB Desc:				North83:	4831791.00
Open Hole:				Org CS:	UTM83

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Cluster Kind: Date Completed: 03/29/2017 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:				UTMRC: UTMRC Desc: Location Method:	4 margin of error : 30 m - 100 m wwr
<u>Links</u>					
Bore Hole ID: 1006381486 Depth M: Year Completed: 2017 Well Completed Dt: 03/29/2017 Audit No: C35279 Path:				Tag No: A213579 Contractor: 7238 Latitude: 43.6350964269255 Longitude: -80.0419274123994 Y: 43.63509642561695 X: -80.04192726219927	
27	2 of 2	NW/170.7	356.6 / 6.00	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID: 7350987 Construction Date: Use 1st: Monitoring and Test Hole Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: ZSO9Q7LK Tag: A286983 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info: MW 1419				Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 12/20/2019 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:	
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350987.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date: 12/09/2019 Year Completed: 2019 Depth (m): 9.4 Latitude: 43.6350964269255 Longitude: -80.0419274123994 Path: 735\7350987.pdf					
<u>Bore Hole Information</u>					
Bore Hole ID: 1007854528 DP2BR: Spatial Status: Code OB: Code OB Desc:				Elevation: Elevrc: Zone: 17 East83: 577282.00 North83: 4831791.00	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	12/09/2019			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855137			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		8.350000381469727			
Formation End Depth:		9.399999618530273			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855136			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		4.690000057220459			
Formation End Depth:		8.350000381469727			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855134			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855135			
Layer:		2			
Color:		7			
General Color:		RED			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		4.690000057220459			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855516			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855727			
Layer:		1			
Plug From:		0.0			
Plug To:		5.789999961853027			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854810			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007854725			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007855234			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.300000190734863			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Construction Record - Screen</u>					
Screen ID:		1007855331			
Layer:		1			
Slot:		10			
Screen Top Depth:		6.300000190734863			
Screen End Depth:		9.399999618530273			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007854726			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1007854933			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		4.690000057220459			
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1007855418			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		9.399999618530273			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1007854528		Tag No:	A286983	
Depth M:	9.4		Contractor:	6607	
Year Completed:	2019		Latitude:	43.6350964269255	
Well Completed Dt:	12/09/2019		Longitude:	-80.0419274123994	
Audit No:	ZSO9Q7LK		Y:	43.63509642561695	
Path:	735\7350987.pdf		X:	-80.04192726219927	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	1 of 1	SSW/173.5	351.0 / 0.44	PIPELINE HIT 1/2" 50 BOWER ST,,ACTON,ON,L7J 1E3,CA ON	PINC
Incident Id:				Pipe Material:	
Incident No:		1021784		Fuel Category:	
Incident Reported Dt:		2/1/2013		Health Impact:	
Type:		FS-Pipeline Incident		Environment Impact:	
Status Code:				Property Damage:	
Tank Status:		Pipeline Damage Reason Est		Service Interrupt:	
Task No:				Enforce Policy:	
Spills Action Centre:				Public Relation:	
Fuel Type:				Pipeline System:	
Fuel Occurrence Tp:				PSIG:	
Date of Occurrence:				Attribute Category:	
Occurrence Start Dt:				Regulator Location:	
Depth:				Method Details:	
Customer Acct Name:		PIPELINE HIT 1/2"			
Incident Address:		50 BOWER ST,,ACTON,ON,L7J 1E3,CA			
Operation Type:					
Pipeline Type:					
Regulator Type:					
Summary:					
Reported By:					
Affiliation:					
Occurrence Desc:					
Damage Reason:					
Notes:					

29	1 of 1	WNW/173.7	356.6 / 6.02	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:		7388615		Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:		Monitoring		Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:		Observation Wells		Date Received:	06/01/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:		7Y6UB2MX		Contractor:	6607
Tag:		A313606		Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					

<u>Bore Hole Information</u>					
Bore Hole ID:		1008657864	Elevation:		
DP2BR:			Elevrc:		
Spatial Status:			Zone:		17
Code OB:			East83:		577253.00
Code OB Desc:			North83:		4831758.00
Open Hole:			Org CS:		UTM83
Cluster Kind:			UTMRC:		4
Date Completed:		05/26/2021	UTMRC Desc:		margin of error : 30 m - 100 m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Remarks:		Location Method:			WWF
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008657978			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		34			
Most Common Material:		TILL			
Mat2:		84			
Mat2 Desc:		SILTY			
Mat3:		81			
Mat3 Desc:		SANDY			
Formation Top Depth:		0.0			
Formation End Depth:		19.5			
Formation End Depth UOM:		ft			
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008658065			
Layer:		2			
Plug From:		1.0			
Plug To:		7.5			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008658046			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008658064			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
 <u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1008657935			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Pipe Information</u>					
Pipe ID:		1008657907			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008658000			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		9.5			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008658016			
Layer:		1			
Slot:		10			
Screen Top Depth:		9.5			
Screen End Depth:		19.5			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657908			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008657963			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Hole ID: Diameter: Depth From: Depth To: Hole Depth UOM: Hole Diameter UOM:		1008658029 8.0 0.0 19.5 ft inch			
Links					
Bore Hole ID: Depth M: Year Completed: Well Completed Dt: Audit No: Path:		1008657864 5.9436 2021 05/26/2021 7Y6UB2MX 738\7388615.pdf		Tag No: Contractor: Latitude: Longitude: Y: X:	A313606 6607 43.6348023459497 -80.0422915973661 43.63480234427126 -80.04229144721103

30	1 of 1	WNW/176.2	355.8 / 5.30	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID: Construction Date: Use 1st: Use 2nd: Final Well Status: Water Type: Casing Material: Audit No: Tag: Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: Site Info:		7350991 Monitoring and Test Hole Observation Wells VJT4438R A286956 HALTON HILLS TOWN (ESQUESING) MW 1421		Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: Selected Flag: Abandonment Rec: Contractor: Form Version: Owner: County: Lot: Concession: Concession Name: Easting NAD83: Northing NAD83: Zone: UTM Reliability:	12/20/2019 TRUE 6607 9 HALTON 029 03 CON margin of error : 30 m - 100 m wwr
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350991.pdf			

Additional Detail(s) (Map)

Well Completed Date: 12/09/2019
Year Completed: 2019
Depth (m): 6.9
Latitude: 43.6346420603434
Longitude: -80.0425048912028
Path: 735\7350991.pdf

Bore Hole Information

Bore Hole ID: DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: Remarks:	1007855749 12/09/2019 	Elevation: Elevrc: Zone: East83: North83: Org CS: UTMRC: UTMRC Desc: Location Method:	 17 577236.00 4831740.00 UTM83 4 margin of error : 30 m - 100 m wwr

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855773			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		0.8999999761581421			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855774			
Layer:		2			
Color:		7			
General Color:		RED			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.8999999761581421			
Formation End Depth:		2.700000047683716			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855775			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		2.700000047683716			
Formation End Depth:		6.900000095367432			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug ID:		1007855791			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855798			
Layer:		1			
Plug From:		0.0			
Plug To:		3.299999952316284			
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1007855763			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1007855758			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1007855779			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.9000000953674316			
Casing Diameter:		5.0999999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
 <u>Construction Record - Screen</u>					
Screen ID:		1007855783			
Layer:		1			
Slot:		10			
Screen Top Depth:		3.9000000953674316			
Screen End Depth:		6.900000095367432			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007855759			
Pump Set At:					
Static Level:					
Final Level After Pumping:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: m Rate UOM: LPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1007855787			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		6.900000095367432			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1007855749			Tag No:	A286956
Depth M:	6.9			Contractor:	6607
Year Completed:	2019			Latitude:	43.6346420603434
Well Completed Dt:	12/09/2019			Longitude:	-80.0425048912028
Audit No:	VJT4438R			Y:	43.63464205865701
Path:	735\7350991.pdf			X:	-80.04250474134213
31	1 of 1	WNW/176.6	355.9 / 5.31	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7362146			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	07/01/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	GPJNEQ8E			Contractor:	6607
Tag:	A293750			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008326234			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577215.00
Code OB Desc:				North83:	4831708.00

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	06/26/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008326371			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		73			
Mat3 Desc:		HARD			
Formation Top Depth:		0.0			
Formation End Depth:		10.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008326372			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		10.0			
Formation End Depth:		17.799999237060547			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008326500			
Layer:		2			
Plug From:		1.0			
Plug To:		5.800000190734863			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008326468			
Layer:		1			
Plug From:					
Plug To:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008326499			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008326311			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008326283			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008326412			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		7.800000190734863			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008326433			
Layer:		1			
Slot:		10			
Screen Top Depth:		7.800000190734863			
Screen End Depth:		17.799999237060547			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008326284			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008326448			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		17.799999237060547			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008326234			Tag No:	A293750
Depth M:	5.42544			Contractor:	6607
Year Completed:	2020			Latitude:	43.6343561499277
Well Completed Dt:	06/26/2020			Longitude:	-80.0427697657666
Audit No:	GPJNEQ8E			Y:	43.634356148280936
Path:	736\7362146.pdf			X:	-80.04276961673172

<u>32</u>	1 of 1	E/176.9	352.9 / 2.31	151 MILL ST AT RAILWAY CROSSING ACTON ON	WWIS
Well ID:		7346699		Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:		Monitoring		Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:		Observation Wells		Date Received:	11/07/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:		Z325672		Contractor:	6946
Tag:		A275686		Form Version:	7
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ACTON)			
Site Info:					
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/734\7346699.pdf			

Additional Detail(s) (Map)

Well Completed Date:
 Year Completed:
 Depth (m): 6.096
 Latitude: 43.6341821160534
 Longitude: -80.0370575790236
 Path: 734\7346699.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Bore Hole Information</u>					
Bore Hole ID:	1007703586			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577676.00
Code OB Desc:				North83:	4831694.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:				UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008101603				
Layer:	2				
Color:	6				
General Color:	BROWN				
Mat1:	10				
Most Common Material:	COARSE SAND				
Mat2:	11				
Mat2 Desc:	GRAVEL				
Mat3:	05				
Mat3 Desc:	CLAY				
Formation Top Depth:	5.0				
Formation End Depth:	10.0				
Formation End Depth UOM:	ft				
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008101602				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	11				
Most Common Material:	GRAVEL				
Mat2:	10				
Mat2 Desc:	COARSE SAND				
Mat3:	79				
Mat3 Desc:	PACKED				
Formation Top Depth:	0.0				
Formation End Depth:	5.0				
Formation End Depth UOM:	ft				
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008101605				
Layer:	4				
Color:	6				
General Color:	BROWN				
Mat1:	10				
Most Common Material:	COARSE SAND				
Mat2:	05				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat2 Desc:		CLAY			
Mat3:		85			
Mat3 Desc:		SOFT			
Formation Top Depth:		13.0			
Formation End Depth:		20.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008101604			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		05			
Mat2 Desc:		CLAY			
Mat3:		28			
Mat3 Desc:		SAND			
Formation Top Depth:		10.0			
Formation End Depth:		13.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008102332			
Layer:		1			
Plug From:		0.0			
Plug To:		14.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008102333			
Layer:		2			
Plug From:		14.0			
Plug To:		20.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008103107			
Method Construction Code:		B			
Method Construction:		Other Method			
Other Method Construction:		AUGERING			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008103106			
Method Construction Code:		2			
Method Construction:		Rotary (Convent.)			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008100409			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Casing No: Comment: Alt Name:		0			
<u>Construction Record - Casing</u>					
Casing ID:		1008103514			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		15.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		Inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008103753			
Layer:		1			
Slot:		.10			
Screen Top Depth:		15.0			
Screen End Depth:		20.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.375			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008104254			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:		0			
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008102726			
Diameter:		6.0			
Depth From:		0.0			
Depth To:		20.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		Inch			
<u>Links</u>					
Bore Hole ID:	1007703586		Tag No:	A275686	
Depth M:	6.096		Contractor:	6946	
Year Completed:			Latitude:	43.6341821160534	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Well Completed Dt:				Longitude:	-80.0370575790236
Audit No:	Z325672			Y:	43.63418211476433
Path:	734\7346699.pdf			X:	-80.03705742929908

33	1 of 1	NW/177.2	356.6 / 6.00	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7350957			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/20/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	CNDFJCZC			Contractor:	6607
Tag:	A286960			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW 1418				

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350957.pdf

Additional Detail(s) (Map)

Well Completed Date: 12/12/2019
Year Completed: 2019
Depth (m): 6
Latitude: 43.6352756522518
Longitude: -80.0418253881118
Path: 735\7350957.pdf

Bore Hole Information

Bore Hole ID:	1007854438	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577290.00
Code OB Desc:		North83:	4831811.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	12/12/2019	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	www
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID: 1007855054

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		2			
Color:		7			
General Color:		RED			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		4.690000057220459			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855053			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855055			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		4.690000057220459			
Formation End Depth:		6.0			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1007855486			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1007855666			
Layer:		1			
Plug From:		0.0			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug To:		2.4000000953674316			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854775			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007854665			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007855205			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1007855302			
Layer:		1			
Slot:		10			
Screen Top Depth:		3.0			
Screen End Depth:		6.0			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007854666			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:	1007855381				
Diameter:	21.0				
Depth From:	0.0				
Depth To:	6.0				
Hole Depth UOM:	m				
Hole Diameter UOM:	cm				
<u>Links</u>					
Bore Hole ID:	1007854438			Tag No:	A286960
Depth M:	6			Contractor:	6607
Year Completed:	2019			Latitude:	43.6352756522518
Well Completed Dt:	12/12/2019			Longitude:	-80.0418253881118
Audit No:	CNDFJCZC			Y:	43.63527565028215
Path:	735\7350957.pdf			X:	-80.04182523875212
34	1 of 1	E/178.7	353.6 / 3.00	R.M. OF HALTON MILL ST./FELLOWS ST. HALTON HILLS TOWN ON	CA
Certificate #:	3-1043-90-				
Application Year:	90				
Issue Date:	6/14/1990				
Approval Type:	Municipal sewage				
Status:	Approved				
Application Type:					
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:					
Contaminants:					
Emission Control:					
35	1 of 12	S/179.1	351.9 / 1.31	SHOEMAKER FUNERAL HOME 55 MILL STREET EAST ACTON ON L7J 1H4	GEN
Generator No:	ONF005300				
SIC Code:	9731				
SIC Description:	FUNERAL HOMES				
Approval Years:	88,89,90				
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:	312				
Waste Class Name:	PATHOLOGICAL WASTES				
35	2 of 12	S/179.1	351.9 / 1.31	SHOEMAKER FUNERAL HOME 55 MILL STREET EAST	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
ACTON ON L7J 1H4					
Generator No:		ONF005300			
SIC Code:		9731			
SIC Description:		FUNERAL HOMES			
Approval Years:		92,93,97,98			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	3 of 12	S/179.1	351.9 / 1.31	SHOEMAKER FUNERAL HOME 44-053 55 MILL STREET EAST ACTON ON L7J 1H4	GEN
Generator No:		ONF005300			
SIC Code:		9731			
SIC Description:		FUNERAL HOMES			
Approval Years:		94,95,96			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	4 of 12	S/179.1	351.9 / 1.31	MACKINNON FAMILY FUNERAL HOME INC. 55 MILL STREET EAST ACTON ON L7J 1H4	GEN
Generator No:		ONF005300			
SIC Code:		9731			
SIC Description:		FUNERAL HOMES			
Approval Years:		99,00,01,02,03,04			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
Detail(s)					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class: Waste Class Name:		312 PATHOLOGICAL WASTES			
35	5 of 12	S/179.1	351.9 / 1.31	MACKINNON FAMILY FUNERAL HOME INC. SHOEMAKER CHAPEL 55 MILL STREET EAST ACTON ON L7J 1H4	GEN
Generator No:		ONF005300			
SIC Code:		812210			
SIC Description:		Funeral Homes			
Approval Years:		06,07,08			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	6 of 12	S/179.1	351.9 / 1.31	MACKINNON FAMILY FUNERAL HOME INC. SHOEMAKER CHAPEL 55 MILL STREET EAST ACTON ON L7J 1H4	GEN
Generator No:		ONF005300			
SIC Code:		812210			
SIC Description:		Funeral Homes			
Approval Years:		2009			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
35	7 of 12	S/179.1	351.9 / 1.31	MacKinnon Family Funeral Home 55 Mill Street East Acton ON L7J 1H4	GEN
Generator No:		ON4868595			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
<u>35</u>	8 of 12	S/179.1	351.9 / 1.31	MacKinnon Family Funeral Home 55 Mill Street East Acton ON L7J 1H4	GEN
Generator No:		ON4868595			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
<u>35</u>	9 of 12	S/179.1	351.9 / 1.31	55 mill street east Acton ON L7J 1H4	EHS
Order No:		22062900051		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Custom Report		Client Prov/State:	ON
Report Date:		05-AUG-22		Search Radius (km):	.25
Date Received:		29-JUN-22		X:	-80.0400882
Previous Site Name:				Y:	43.6313694
Lot/Building Size:					
Additional Info Ordered:					
<u>35</u>	10 of 12	S/179.1	351.9 / 1.31	55 mill street east Acton ON L7J 1H4	EHS
Order No:		22062900051		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Custom Report		Client Prov/State:	ON
Report Date:		05-AUG-22		Search Radius (km):	.25
Date Received:		29-JUN-22		X:	-80.0400882
Previous Site Name:				Y:	43.6313694
Lot/Building Size:					
Additional Info Ordered:					
<u>35</u>	11 of 12	S/179.1	351.9 / 1.31	55 mill street east Acton ON L7J 1H4	EHS
Order No:		22062900051		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Custom Report		Client Prov/State:	ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Report Date: 05-AUG-22 Date Received: 29-JUN-22 Previous Site Name: Lot/Building Size: Additional Info Ordered:					
Search Radius (km): .25 X: -80.0400882 Y: 43.6313694					
35	12 of 12	S/179.1	351.9 / 1.31	55 mill street east Acton ON L7J 1H4	EHS
Order No: 22062900051 Status: C Report Type: Custom Report Report Date: 05-AUG-22 Date Received: 29-JUN-22 Previous Site Name: Lot/Building Size: Additional Info Ordered:					
Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): .25 X: -80.0400882 Y: 43.6313694					
36	1 of 1	WSW/181.6	349.6 / -0.96	Compressed Air & Filtration 59 Willow St. N. Unit #3 Acton ON L7J1Z8	GEN
Generator No: ON5280020 SIC Code: 811310 SIC Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE Approval Years: 2015 PO Box No: Country: Canada Status: Co Admin: Tony Ricciuto Choice of Contact: CO_ADMIN Phone No Admin: 9057921869 Ext. Contaminated Facility: No MHSW Facility: No					
Detail(s)					
Waste Class: 122 Waste Class Name: ALKALINE WASTES - OTHER METALS					
37	1 of 1	NW/183.9	356.9 / 6.31	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7388626 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: TSAVIFT7 Tag: A313610 Constructn Method: Elevation (m): Elevatn Reliability: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 06/01/2021 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
 <u>Bore Hole Information</u>					
Bore Hole ID:	1008657897			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577270.00
Code OB Desc:				North83:	4831797.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/28/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008657996				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:	61				
Mat2 Desc:	CLAYEY				
Mat3:	66				
Mat3 Desc:	DENSE				
Formation Top Depth:	0.0				
Formation End Depth:	24.0				
Formation End Depth UOM:	ft				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658086				
Layer:	1				
Plug From:	0.0				
Plug To:	1.0				
Plug Depth UOM:	ft				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658057				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658087				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		2			
Plug From:		1.0			
Plug To:		12.0			
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008657946			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008657929			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008658012			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		14.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1008658025			
Layer:		1			
Slot:		10			
Screen Top Depth:		14.0			
Screen End Depth:		24.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657930			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Flowing:					
<u>Water Details</u>					
Water ID:		1008657973			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					
Hole ID:		1008658042			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		24.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008657897		Tag No:	A313610	
Depth M:	7.3152		Contractor:	6607	
Year Completed:	2021		Latitude:	43.6351516904956	
Well Completed Dt:	05/28/2021		Longitude:	-80.0420752989724	
Audit No:	TSAVIFT7		Y:	43.635151688761	
Path:	738\7388626.pdf		X:	-80.0420751490976	

38	1 of 1	NW/186.1	356.9 / 6.31	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7375865		Flowing (Y/N):		
Construction Date:			Flow Rate:		
Use 1st:	Monitoring		Data Entry Status:		
Use 2nd:			Data Src:		
Final Well Status:	Observation Wells		Date Received:	12/15/2020	
Water Type:			Selected Flag:	TRUE	
Casing Material:			Abandonment Rec:		
Audit No:	T3JBWHAD		Contractor:	6607	
Tag:	A293615		Form Version:	9	
Constructn Method:			Owner:		
Elevation (m):			County:	HALTON	
Elevatn Reliabilty:			Lot:	029	
Depth to Bedrock:			Concession:	03	
Well Depth:			Concession Name:	CON	
Overburden/Bedrock:			Easting NAD83:		
Pump Rate:			Northing NAD83:		
Static Water Level:			Zone:		
Clear/Cloudy:			UTM Reliability:		
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008529394		Elevation:		
DP2BR:			Elevrc:		
Spatial Status:			Zone:	17	
Code OB:			East83:	577268.00	
Code OB Desc:			North83:	4831798.00	
Open Hole:			Org CS:	UTM83	
Cluster Kind:			UTMRC:	4	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Date Completed:		11/11/2020		UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008529491			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		23.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008529609			
Layer:		1			
Plug From:		0.0			
Plug To:		11.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008529559			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1008529452			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008529442			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Casing ID: 1008529511					
Layer: 1					
Material: 5					
Open Hole or Material: PLASTIC					
Depth From: 0.0					
Depth To: 13.0					
Casing Diameter: 2.0					
Casing Diameter UOM: inch					
Casing Depth UOM: ft					
<u>Construction Record - Screen</u>					
Screen ID: 1008529531					
Layer: 1					
Slot: 250					
Screen Top Depth: 13.0					
Screen End Depth: 23.0					
Screen Material: 5					
Screen Depth UOM: ft					
Screen Diameter UOM: inch					
Screen Diameter: 2.5					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID: 1008529443					
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM: ft					
Rate UOM: GPM					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID: 1008529536					
Diameter: 8.0					
Depth From: 0.0					
Depth To: 23.0					
Hole Depth UOM: ft					
Hole Diameter UOM: inch					
<u>Links</u>					
Bore Hole ID:	1008529394			Tag No:	A293615
Depth M:	7.0104			Contractor:	6607
Year Completed:	2020			Latitude:	43.6351609010722
Well Completed Dt:	11/11/2020			Longitude:	-80.0420999467611
Audit No:	T3JBWHAD			Y:	43.63516089949676
Path:	737\7375865.pdf			X:	-80.04209979796205

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	1 of 5	W/187.0	355.0 / 4.49	HALTON DISTRICT SCHOOL BOARD 41 SCHOOL LANE ACTON ON	GEN
Generator No:		ON7205564			
SIC Code:		611116			
SIC Description:					
Approval Years:		2012			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
39	2 of 5	W/187.0	355.0 / 4.49	HALTON DISTRICT SCHOOL BOARD 41 SCHOOL LANE ACTON ON L7J1B9	GEN
Generator No:		ON5977790			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		251 L			
Waste Class Name:		Waste oils/sludges (petroleum based)			
39	3 of 5	W/187.0	355.0 / 4.49	HALTON DISTRICT SCHOOL BOARD 41 SCHOOL LANE ACTON ON L7J1B9	GEN
Generator No:		ON5977790			
SIC Code:					
SIC Description:					
Approval Years:		As of Jul 2020			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		251 L			
Waste Class Name:		Waste oils/sludges (petroleum based)			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
39	4 of 5	W/187.0	355.0 / 4.49	HALTON DISTRICT SCHOOL BOARD 41 SCHOOL LANE ACTON ON L7J1B9	GEN
Generator No: ON5977790 SIC Code: SIC Description: Approval Years: As of Nov 2021 PO Box No: Country: Canada Status: Registered Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 251 L Waste Class Name: Waste oils/sludges (petroleum based)					
39	5 of 5	W/187.0	355.0 / 4.49	HALTON DISTRICT SCHOOL BOARD 41 SCHOOL LANE ACTON ON L7J1B9	GEN
Generator No: ON5977790 SIC Code: SIC Description: Approval Years: As of Oct 2022 PO Box No: Country: Canada Status: Registered Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 251 L Waste Class Name: OIL SKIMMINGS & SLUDGES					
40	1 of 1	WNW/187.8	355.9 / 5.31	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7362157 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: M5EQB2GQ Tag: A293751 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 07/01/2020 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Static Water Level: Clear/Cloudy: Municipality: Site Info:				Zone: UTM Reliability:	
HALTON HILLS TOWN (ESQUESING)					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008326650			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577207.00
Code OB Desc:				North83:	4831717.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	06/26/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:	1008326776				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:	28				
Mat2 Desc:	SAND				
Mat3:	73				
Mat3 Desc:	HARD				
Formation Top Depth:	0.0				
Formation End Depth:	5.0				
Formation End Depth UOM:	ft				
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:	1008326777				
Layer:	2				
Color:	2				
General Color:	GREY				
Mat1:	15				
Most Common Material:	LIMESTONE				
Mat2:	15				
Mat2 Desc:	LIMESTONE				
Mat3:	26				
Mat3 Desc:	ROCK				
Formation Top Depth:	5.0				
Formation End Depth:	15.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:	1008326868				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008326869			
Layer:		2			
Plug From:		1.0			
Plug To:		3.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008326846			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008326741			
Method Construction Code:		7			
Method Construction:		Diamond			
Other Method Construction:					
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008326740			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008326704			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008326804			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		5.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen ID:		1008326818			
Layer:		1			
Slot:		10			
Screen Top Depth:		5.0			
Screen End Depth:		15.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008326705			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008326832			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		5.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Hole Diameter</u>					
Hole ID:		1008326833			
Diameter:		4.0			
Depth From:		5.0			
Depth To:		15.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008326650			Tag No:	A293751
Depth M:	4.572			Contractor:	6607
Year Completed:	2020			Latitude:	43.6344380057476
Well Completed Dt:	06/26/2020			Longitude:	-80.0428676416158
Audit No:	M5EQB2GQ			Y:	43.63443800438422
Path:	736\7362157.pdf			X:	-80.04286749263507
41	1 of 1	N/188.1	352.9 / 2.31	The Corporation of the Town of Halton Hills 128 McDonald Blvd 12 Division Street Halton Hills ON L7G 5G2	ECA
Approval No:	3847-BH7K5P			MOE District:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Approval Date: 2019-10-28 Status: Approved Record Type: ECA Link Source: IDS SWP Area Name: Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS Business Name: The Corporation of the Town of Halton Hills Address: 128 McDonald Blvd 12 Division Street Full Address: Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/9552-BGRLAA-14.pdf PDF Site Location:					
42	1 of 4	SSW/188.7	350.8 / 0.29	CANADA POST C/O ROYAL LEPAGE MANAGEMENT; 45 BOWER STREET ACTON-HALTON HILLS POST OFFICE; 45 BOWER ST ACTON ON L7J 1E1	NPCB
Company Code: O4860 Industry: Canada Post Corp Site Status: Transaction Date: 9/18/1995 Inspection Date:					
42	2 of 4	SSW/188.7	350.8 / 0.29	CANADA POST 45 BOWER STREET ACTON-HALTON HILLS POST OFFICE; 45 BOWER ST ACTON ON L7J 1E1	NPCB
Company Code: O4860 Industry: Canada Post Corp Site Status: Transaction Date: 12/2/1994 Inspection Date:					
42	3 of 4	SSW/188.7	350.8 / 0.29	CANADA POST 45 BOWER STREET c/ o ROYAL LEPAGE MANAGEMENT Acton ON L7J 1E1	NPCB
Company Code: O4860 Industry: Canada Post Corp Site Status: In- Use Transaction Date: 2/12/1994 Inspection Date:					
--Details-- Label: Serial No.: PCB Type/Code: Askarel/Askarel Location: BALLASTS IN USE Item/State: No. of Items: Manufacturer: Status: In-Use Contents:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	4 of 4	SSW/188.7	350.8 / 0.29	CANADA POST 45 BOWER ST C/O ROYAL LEPAGE MANAGEMENT ACTON ON L7J 1E1	NPCB
Company Code:		O4860			
Industry:		CANADA POST CORP			
Site Status:		FEDERAL FACILITIES (IN USE)			
Transaction Date:		9/18/1995			
Inspection Date:					
--Details--					
Label:		DO03692			
Serial No.:					
PCB Type/Code:		ASKAREL/ASKAREL			
Location:					
Item/State:		LIGHT BALLAST/FULL			
No. of Items:		81			
Manufacturer:					
Status:		IN-USE			
Contents:		162 KG			
43	1 of 1	E/189.5	353.9 / 3.31	146 Mill St E Halton Hills ON L7J1J1	EHS
Order No:		20160418086		Nearest Intersection:	
Status:		C		Municipality:	
Report Type:		Standard Report		Client Prov/State: ON	
Report Date:		25-APR-16		Search Radius (km): .25	
Date Received:		18-APR-16		X: -80.0369	
Previous Site Name:				Y: 43.633466	
Lot/Building Size:					
Additional Info Ordered:					
44	1 of 1	WNW/190.9	356.6 / 6.02	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:		7388625		Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:		Monitoring		Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:		Observation Wells		Date Received: 06/01/2021	
Water Type:				Selected Flag: TRUE	
Casing Material:				Abandonment Rec:	
Audit No:		SH4ESTBT		Contractor: 6607	
Tag:		A313603		Form Version: 9	
Constructn Method:				Owner:	
Elevation (m):				County: HALTON	
Elevatn Reliabilty:				Lot: 029	
Depth to Bedrock:				Concession: 03	
Well Depth:				Concession Name: CON	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:		1008657894		Elevation:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577239.00
Code OB Desc:				North83:	4831768.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/27/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008657995			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		61			
Mat2 Desc:		CLAYEY			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		0.0			
Formation End Depth:		22.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008658056			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008658084			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008658085			
Layer:		2			
Plug From:		1.0			
Plug To:		10.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well</u>					
<u>Use</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction ID: 1008657945					
Method Construction Code: E					
Method Construction: Auger					
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID: 1008657927					
Casing No: 0					
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID: 1008658011					
Layer: 1					
Material: 5					
Open Hole or Material: PLASTIC					
Depth From: 0.0					
Depth To: 12.0					
Casing Diameter: 2.0					
Casing Diameter UOM: inch					
Casing Depth UOM: ft					
<u>Construction Record - Screen</u>					
Screen ID: 1008658024					
Layer: 1					
Slot: 10					
Screen Top Depth: 12.0					
Screen End Depth: 22.0					
Screen Material: 5					
Screen Depth UOM: ft					
Screen Diameter UOM: inch					
Screen Diameter: 2.5					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID: 1008657928					
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM: ft					
Rate UOM: GPM					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID: 1008657972					
Layer: 1					
Kind Code: 8					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					
Hole ID:		1008658041			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		22.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:		1008657894	Tag No:		A313603
Depth M:		6.7056	Contractor:		6607
Year Completed:		2021	Latitude:		43.6348938280287
Well Completed Dt:		05/27/2021	Longitude:		-80.0424637024066
Audit No:		SH4ESTBT	Y:		43.634893826646405
Path:		738\7388625.pdf	X:		-80.04246355267848
45	1 of 1	NW/191.2	356.9 / 6.34	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:		7360720	Flowing (Y/N):		
Construction Date:			Flow Rate:		
Use 1st:		Monitoring	Data Entry Status:		
Use 2nd:			Data Src:		
Final Well Status:		Observation Wells	Date Received:		06/09/2020
Water Type:			Selected Flag:		TRUE
Casing Material:			Abandonment Rec:		
Audit No:		Y3KOPOOH	Contractor:		6607
Tag:		A271809	Form Version:		9
Constructn Method:			Owner:		
Elevation (m):			County:		HALTON
Elevatn Reliabilty:			Lot:		029
Depth to Bedrock:			Concession:		03
Well Depth:			Concession Name:		CON
Overburden/Bedrock:			Easting NAD83:		
Pump Rate:			Northing NAD83:		
Static Water Level:			Zone:		
Clear/Cloudy:			UTM Reliability:		
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		06/05/2020			
Year Completed:		2020			
Depth (m):		9.3			
Latitude:		43.6353043230191			
Longitude:		-80.042023285872			
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:		1008307711	Elevation:		
DP2BR:			Elevrc:		
Spatial Status:			Zone:		17

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Code OB:				East83:	577274.00
Code OB Desc:				North83:	4831814.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	06/05/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008308368			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		9.300000190734863			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008308774			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008308970			
Layer:		2			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008308969			
Layer:		1			
Plug From:		0.0			
Plug To:		5.699999809265137			
Plug Depth UOM:		m			
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1008308001			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008307902			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008308467			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.300000190734863			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1008308548			
Layer:		1			
Slot:		10			
Screen Top Depth:		6.300000190734863			
Screen End Depth:		9.300000190734863			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008307903			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008308135			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		3.5999999046325684			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1008308654			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		9.300000190734863			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1008307711			Tag No:	A271809
Depth M:	9.3			Contractor:	6607
Year Completed:	2020			Latitude:	43.6353043230191
Well Completed Dt:	06/05/2020			Longitude:	-80.042023285872
Audit No:	Y3KOPOOH			Y:	43.63530432137801
Path:	736\7360720.pdf			X:	-80.0420231366455
<u>46</u>	1 of 2	ENE/191.2	352.6 / 2.00	PLASTICS EIGHTY LTD 12 WALLACE ST ACTON ON L7J 2V6	SCT
Established:	1980				
Plant Size (ft²):	26000				
Employment:	12				
<u>--Details--</u>					
Description:	PLASTICS PRODUCTS, NOT ELSEWHERE CLASSIFIED				
SIC/NAICS Code:	3089				
<u>46</u>	2 of 2	ENE/191.2	352.6 / 2.00	PETER ZIONS CONSTRUCTION 12 WALLACE STREET ACTON ON L7J 2V6	GEN
Generator No:	ON1839700				
SIC Code:	4011				
SIC Description:	SINGLE FAMILY HOUS.				
Approval Years:	94,95,96,97,98				
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:	145				
Waste Class Name:	PAINT/PIGMENT/COATING RESIDUES				
<u>47</u>	1 of 1	NW/191.4	355.2 / 4.61	125 McDonald Blvd lot 29 con 3 Acton ON	WWIS
Well ID:	7376265			Flowing (Y/N):	
Construction Date:				Flow Rate:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/18/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	HHXYJM2Q			Contractor:	7609
Tag:	A304642			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Bore Hole Information

Bore Hole ID:	1008533884	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577326.00
Code OB Desc:		North83:	4831858.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	12/11/2020	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1008534071
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Mat2 Desc:	
Mat3:	79
Mat3 Desc:	PACKED
Formation Top Depth:	1.5199999809265137
Formation End Depth:	3.049999952316284
Formation End Depth UOM:	m

Overburden and Bedrock

Materials Interval

Formation ID:	1008534070
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Most Common Material:					
Mat2:		FILL	06		
Mat2 Desc:		SILT	85		
Mat3:		SOFT	0.0		
Formation Top Depth:		1.5199999809265137			
Formation End Depth:		m			
Formation End Depth UOM:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008534072			
Layer:		3			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:					
Mat2 Desc:					
Mat3:		73			
Mat3 Desc:		HARD			
Formation Top Depth:		3.049999952316284			
Formation End Depth:		4.570000171661377			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008534073			
Layer:		4			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:					
Mat2 Desc:					
Mat3:		73			
Mat3 Desc:		HARD			
Formation Top Depth:		4.570000171661377			
Formation End Depth:		9.140000343322754			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534207			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534228			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Sealing Record</u>					
Plug ID:		1008534230			
Layer:		3			
Plug From:		5.489999771118164			
Plug To:		9.140000343322754			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534229			
Layer:		2			
Plug From:		0.30000001192092896			
Plug To:		5.489999771118164			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008533981			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008533942			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008534140			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.099999904632568			
Casing Diameter:		5.0			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1008534166			
Layer:		1			
Slot:		0.1			
Screen Top Depth:		6.099999904632568			
Screen End Depth:		9.140000343322754			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.0			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008533943			
Pump Set At:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Static Level: Final Level After Pumping: Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: m Rate UOM: LPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Hole Diameter</u>					
Hole ID: 1008534180 Diameter: 20.0 Depth From: 0.0 Depth To: 9.140000343322754 Hole Depth UOM: m Hole Diameter UOM: cm					
<u>Links</u>					
Bore Hole ID: 1008533884 Depth M: 9.14 Year Completed: 2020 Well Completed Dt: 12/11/2020 Audit No: HHXYJM2Q Path: 737\7376265.pdf					
Tag No: A304642 Contractor: 7609 Latitude: 43.63569504356 Longitude: -80.0413724258015 Y: 43.63569504228675 X: -80.04137227685104					
48	1 of 1	NW/191.7	356.9 / 6.31	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7375845 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: YPTOHGJP Tag: A293616 Constructn Method: Elevation (m): Elevatn Reliability: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 12/15/2020 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
<u>Bore Hole Information</u>					
Bore Hole ID: 1008528972 DP2BR: Spatial Status:					
Elevation: Elevrc: Zone: 17					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Code OB:				East83:	577267.00
Code OB Desc:				North83:	4831806.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/11/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008529113			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		23.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008529247			
Layer:		1			
Plug From:		0.0			
Plug To:		11.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008529207			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1008529044			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008529014			
Casing No:		0			
Comment:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008529134			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		13.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008529154			
Layer:		1			
Slot:		250			
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008529015			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008529187			
Diameter:		4.5			
Depth From:		0.0			
Depth To:		23.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008528972		Tag No:	A293616	
Depth M:	7.0104		Contractor:	6607	
Year Completed:	2020		Latitude:	43.635233027555	
Well Completed Dt:	11/11/2020		Longitude:	-80.0421111980412	
Audit No:	YPTOHGJP		Y:	43.63523302625562	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Path:	737\7375845.pdf			X:	-80.04211104845261
49	1 of 1	WNW/192.3	356.0 / 5.46	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7375851			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/15/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	AG4ZA72P			Contractor:	6607
Tag:	A293619			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008529352			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577228.00
Code OB Desc:				North83:	4831756.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/11/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008529477				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	05				
Most Common Material:	CLAY				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	0.0				
Formation End Depth:	18.5				
Formation End Depth UOM:	ft				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008529573			
Layer:		1			
Plug From:		0.0			
Plug To:		6.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008529545			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008529449			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008529414			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008529497			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		8.5			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008529517			
Layer:		1			
Slot:		250			
Screen Top Depth:		8.5			
Screen End Depth:		18.5			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008529415			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pump Set At: Static Level: Final Level After Pumping: Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: ft Rate UOM: GPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Hole Diameter</u>					
Hole ID: 1008529533 Diameter: 8.0 Depth From: 0.0 Depth To: 18.5 Hole Depth UOM: ft Hole Diameter UOM: inch					
<u>Links</u>					
Bore Hole ID: 1008529352 Depth M: 5.6388 Year Completed: 2020 Well Completed Dt: 11/11/2020 Audit No: AG4ZA72P Path: 737\7375851.pdf					
Tag No: A293619 Contractor: 6607 Latitude: 43.6347869361843 Longitude: -80.0426017665645 Y: 43.63478693423824 X: -80.04260161741523					

50	1 of 1	WNW/192.9	356.6 / 6.02	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID: 7350954 Construction Date: Use 1st: Monitoring and Test Hole Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: A7NTV44N Tag: A286959 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info: MW 1422					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 12/20/2019 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350954.pdf					

Additional Detail(s) (Map)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Well Completed Date:		12/13/2019			
Year Completed:		2019			
Depth (m):		6			
Latitude:		43.6349119375172			
Longitude:		-80.0424758118384			
Path:		735\7350954.pdf			
 <u>Bore Hole Information</u>					
Bore Hole ID:	1007854429			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577238.00
Code OB Desc:				North83:	4831770.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	12/13/2019			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1007855046				
Layer:	2				
Color:	7				
General Color:	RED				
Mat1:	28				
Most Common Material:	SAND				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	1.5				
Formation End Depth:	3.0				
Formation End Depth UOM:	m				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1007855045				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:	28				
Mat2 Desc:	SAND				
Mat3:	01				
Mat3 Desc:	FILL				
Formation Top Depth:	0.0				
Formation End Depth:	1.5				
Formation End Depth UOM:	m				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation ID:		1007855047			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		3.0			
Formation End Depth:		6.0			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855483			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855662			
Layer:		1			
Plug From:		0.0			
Plug To:		2.4000000953674316			
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854772			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1007854659			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1007855202			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
 <u>Construction Record - Screen</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen ID: 1007855299					
Layer: 1					
Slot: 10					
Screen Top Depth: 3.0					
Screen End Depth: 6.0					
Screen Material: 5					
Screen Depth UOM: m					
Screen Diameter UOM: cm					
Screen Diameter: 6.400000095367432					
Results of Well Yield Testing					
Pumping Test Method Desc:					
Pump Test ID: 1007854660					
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM: m					
Rate UOM: LPM					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
Hole Diameter					
Hole ID: 1007855378					
Diameter: 21.0					
Depth From: 0.0					
Depth To: 6.0					
Hole Depth UOM: m					
Hole Diameter UOM: cm					
Links					
Bore Hole ID: 1007854429					
Depth M: 6					
Year Completed: 2019					
Well Completed Dt: 12/13/2019					
Audit No: A7NTV44N					
Path: 735\7350954.pdf					
Tag No: A286959					
Contractor: 6607					
Latitude: 43.6349119375172					
Longitude: -80.0424758118384					
Y: 43.634911936768695					
X: -80.04247566286138					
51	1 of 1	NW/194.1	356.9 / 6.31	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7388622					
Construction Date:					
Use 1st: Monitoring					
Use 2nd:					
Final Well Status: Observation Wells					
Water Type:					
Casing Material:					
Audit No: KQHG7TWG					
Tag: A313643					
Constructn Method:					
Flowing (Y/N):					
Flow Rate:					
Data Entry Status:					
Data Src:					
Date Received: 06/01/2021					
Selected Flag: TRUE					
Abandonment Rec:					
Contractor: 6607					
Form Version: 9					
Owner:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug To:		1.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658053			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008657942			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008657921			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008658008			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		12.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1008658021			
Layer:		1			
Slot:		10			
Screen Top Depth:		12.0			
Screen End Depth:		22.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657922			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Recommended Pump Rate: Levels UOM: ft Rate UOM: GPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Water Details</u>					
Water ID:		1008657969			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					
Hole ID:		1008658038			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		22.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008657885			Tag No:	A313643
Depth M:	6.7056			Contractor:	6607
Year Completed:	2021			Latitude:	43.6352333391673
Well Completed Dt:	05/26/2021			Longitude:	-80.0421483843007
Audit No:	KQHG7TWG			Y:	43.63523333768083
Path:	738\7388622.pdf			X:	-80.04214823420196
52	1 of 1	WNW/197.0	356.9 / 6.31	ON	WWIS
Well ID:	7306391			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:				Data Entry Status:	Yes
Use 2nd:				Data Src:	
Final Well Status:				Date Received:	02/26/2018
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	C38499			Contractor:	7238
Tag:	A237309			Form Version:	8
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:	02/07/2018				
Year Completed:	2018				
Depth (m):					
Latitude:	43.6350552558916				
Longitude:	-80.0423867567816				
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1006991657			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577245.00
Code OB Desc:				North83:	4831786.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	02/07/2018			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Links</u>					
Bore Hole ID:	1006991657			Tag No:	A237309
Depth M:				Contractor:	7238
Year Completed:	2018			Latitude:	43.6350552558916
Well Completed Dt:	02/07/2018			Longitude:	-80.0423867567816
Audit No:	C38499			Y:	43.63505525456859
Path:				X:	-80.04238660749276
53	1 of 1	WNW/197.4	356.9 / 6.31	125 McDonald Blvd lot 29 con 3 Acton ON	WWIS
Well ID:	7376268			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/18/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	FSGU9YAW			Contractor:	7609
Tag:	A304648			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Bore Hole Information</u>					
Bore Hole ID:	1008533893			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577240.00
Code OB Desc:				North83:	4831780.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	12/11/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008534080				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:	85				
Mat3 Desc:	SOFT				
Formation Top Depth:	0.0				
Formation End Depth:	1.5199999809265137				
Formation End Depth UOM:	m				
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008534081				
Layer:	2				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:					
Mat2 Desc:					
Mat3:	79				
Mat3 Desc:	PACKED				
Formation Top Depth:	1.5199999809265137				
Formation End Depth:	3.049999952316284				
Formation End Depth UOM:	m				
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008534082				
Layer:	3				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat2 Desc:					
Mat3:		73			
Mat3 Desc:		HARD			
Formation Top Depth:		3.049999952316284			
Formation End Depth:		6.099999904632568			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534210			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534238			
Layer:		2			
Plug From:		0.30000001192092896			
Plug To:		2.440000057220459			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534239			
Layer:		3			
Plug From:		2.440000057220459			
Plug To:		6.099999904632568			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008534237			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008533984			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008533948			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Casing ID:		1008534143			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.049999952316284			
Casing Diameter:		5.0			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1008534169			
Layer:		1			
Slot:		0.1			
Screen Top Depth:		3.049999952316284			
Screen End Depth:		6.099999904632568			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.0			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008533949			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008534183			
Diameter:		20.0			
Depth From:		0.0			
Depth To:		6.099999904632568			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1008533893		Tag No:	A304648	
Depth M:	6.1		Contractor:	7609	
Year Completed:	2020		Latitude:	43.6350017581237	
Well Completed Dt:	12/11/2020		Longitude:	-80.0424495914898	
Audit No:	FSGU9YAW		Y:	43.63500175651907	
Path:	737\7376268.pdf		X:	-80.04244944193681	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
ON					
Well ID:	7345190			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:				Data Entry Status:	Yes
Use 2nd:				Data Src:	
Final Well Status:				Date Received:	10/17/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	C44200			Contractor:	7320
Tag:	A275314			Form Version:	8
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		09/27/2019			
Year Completed:		2019			
Depth (m):					
Latitude:		43.6353497526677			
Longitude:		-80.0420721524983			
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1007690334			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577270.00
Code OB Desc:				North83:	4831819.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	09/27/2019			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Links</u>					
Bore Hole ID:	1007690334			Tag No:	A275314
Depth M:				Contractor:	7320
Year Completed:	2019			Latitude:	43.6353497526677
Well Completed Dt:	09/27/2019			Longitude:	-80.0420721524983
Audit No:	C44200			Y:	43.63534975142644
Path:				X:	-80.0420720022824

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
55	1 of 1	WNW/200.1	356.0 / 5.46	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID: 7350958 Construction Date: Use 1st: Monitoring and Test Hole Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: EJ8QU6VJ Tag: A286982 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info: MW 1423 Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 12/20/2019 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability: PDF URL (Map):https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350958.pdf Well Completed Date: 12/10/2019 Year Completed: 2019 Depth (m): 5.68 Latitude: 43.6348325732141 Longitude: -80.0426754238973 Path: 735\7350958.pdf Bore Hole ID: 1007854441 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 12/10/2019 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment: Elevation: Elevrc: Zone: 17 East83: 577222.00 North83: 4831761.00 Org CS: UTM83 UTMRC: 4 UTMRC Desc: margin of error : 30 m - 100 m Location Method: wwr Overburden and Bedrock Materials Interval Formation ID: 1007855057 Layer: 2 Color: 7 General Color: RED Mat1: 28 Most Common Material: SAND					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		3.0			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855058			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		3.0			
Formation End Depth:		5.679999828338623			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007855056			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1007855487			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1007855667			
Layer:		1			
Plug From:		0.0			
Plug To:		2.0299999713897705			
Plug Depth UOM:		m			
<u>Method of Construction & Well</u>					
<u>Use</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction ID: 1007854776					
Method Construction Code: 6					
Method Construction: Boring					
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID: 1007854667					
Casing No: 0					
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID: 1007855206					
Layer: 1					
Material: 5					
Open Hole or Material: PLASTIC					
Depth From: 0.0					
Depth To: 2.640000104904175					
Casing Diameter: 5.099999904632568					
Casing Diameter UOM: cm					
Casing Depth UOM: m					
<u>Construction Record - Screen</u>					
Screen ID: 1007855303					
Layer: 1					
Slot: 10					
Screen Top Depth: 2.640000104904175					
Screen End Depth: 5.679999828338623					
Screen Material: 5					
Screen Depth UOM: m					
Screen Diameter UOM: cm					
Screen Diameter: 6.400000095367432					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID: 1007854668					
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM: m					
Rate UOM: LPM					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID: 1007855382					
Diameter: 21.0					
Depth From: 0.0					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Depth To:		5.679999828338623			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
Links					
Bore Hole ID:	1007854441			Tag No:	A286982
Depth M:	5.68			Contractor:	6607
Year Completed:	2019			Latitude:	43.6348325732141
Well Completed Dt:	12/10/2019			Longitude:	-80.0426754238973
Audit No:	EJ8QU6VJ			Y:	43.63483257142915
Path:	735\7350958.pdf			X:	-80.04267527474946

56	1 of 1	WNW/200.1	356.9 / 6.31	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7375864			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/15/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	PHOAMALU			Contractor:	6607
Tag:	A293617			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Bore Hole Information

Bore Hole ID:	1008529391	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577248.00
Code OB Desc:		North83:	4831795.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	11/11/2020	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008529490
Layer:	1
Color:	6

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
General Color:		BROWN			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		16.0			
Formation End Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008529608			
Layer:		1			
Plug From:		0.0			
Plug To:		4.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008529558			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008529451			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008529440			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008529510			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1008529530			
Layer:		1			
Slot:		250			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen Top Depth:		6.0			
Screen End Depth:		16.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:	1008529441				
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:	1008529535				
Diameter:	8.0				
Depth From:	0.0				
Depth To:	16.0				
Hole Depth UOM:	ft				
Hole Diameter UOM:	inch				
<u>Links</u>					
Bore Hole ID:	1008529391			Tag No:	A293617
Depth M:	4.8768			Contractor:	6607
Year Completed:	2020			Latitude:	43.6351359698005
Well Completed Dt:	11/11/2020			Longitude:	-80.0423482838121
Audit No:	PHOAMALU			Y:	43.63513596869212
Path:	737\7375864.pdf			X:	-80.04234813445078

57	1 of 1	WNW/202.0	356.9 / 6.31	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7406702			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/24/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	HYZBCZFZ			Contractor:	6607
Tag:	A313532			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: Site Info:				Easting NAD83: Northing NAD83: Zone: UTM Reliability:	
HALTON HILLS TOWN (ESQUESING)					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008898593			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577238.00
Code OB Desc:				North83:	4831785.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/24/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008898743				
Layer:	2				
Color:	6				
General Color:	BROWN				
Mat1:	28				
Most Common Material:	SAND				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:	77				
Mat3 Desc:	LOOSE				
Formation Top Depth:	10.0				
Formation End Depth:	14.0				
Formation End Depth UOM:	ft				
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008898742				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	28				
Most Common Material:	SAND				
Mat2:	11				
Mat2 Desc:	GRAVEL				
Mat3:	77				
Mat3 Desc:	LOOSE				
Formation Top Depth:	0.0				
Formation End Depth:	10.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug ID: 1008898835					
Layer: 1					
Plug From:					
Plug To:					
Plug Depth UOM: ft					
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID: 1008898864					
Layer: 1					
Plug From: 0.0					
Plug To: 2.0					
Plug Depth UOM: ft					
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID: 1008898865					
Layer: 2					
Plug From: 2.0					
Plug To: 4.0					
Plug Depth UOM: ft					
<u>Method of Construction & Well Use</u>					
Method Construction ID: 1008898676					
Method Construction Code: 6					
Method Construction: Boring					
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID: 1008898644					
Casing No: 0					
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID: 1008898775					
Layer: 1					
Material: 5					
Open Hole or Material: PLASTIC					
Depth From: 0.0					
Depth To: 4.0					
Casing Diameter: 5.099999904632568					
Casing Diameter UOM: inch					
Casing Depth UOM: ft					
<u>Construction Record - Screen</u>					
Screen ID: 1008898795					
Layer: 1					
Slot: 10					
Screen Top Depth: 4.0					
Screen End Depth: 14.0					
Screen Material: 5					
Screen Depth UOM: ft					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen Diameter UOM:		inch			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008898645			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008898712			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		3.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					
Hole ID:		1008898815			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		14.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:		1008898593		Tag No:	A313532
Depth M:		4.2672		Contractor:	6607
Year Completed:		2021		Latitude:	43.6350469799294
Well Completed Dt:		11/24/2021		Longitude:	-80.0424736674335
Audit No:		HYZBCZFZ		Y:	43.63504697874536
Path:		740\7406702.pdf		X:	-80.04247351767303
58	1 of 1	E/202.6	352.9 / 2.38	R.M. OF HALTON MILL STREET/BOWER STREET HALTON HILLS TOWN ON	CA

Certificate #: 7-0851-90-
 Application Year: 90
 Issue Date: 6/14/1990
 Approval Type: Municipal water
 Status: Approved
 Application Type:
 Client Name:
 Client Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Client City: Client Postal Code: Project Description: Contaminants: Emission Control:					
59	1 of 1	WNW/203.2	356.0 / 5.46	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7388624 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: NA6FZHSK Tag: A313609 Constructn Method: Elevation (m): Elevatn Reliability: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 06/01/2021 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
<u>Bore Hole Information</u>					
Bore Hole ID: 1008657891 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 05/28/2021 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:					
Elevation: Elevrc: Zone: 17 East83: 577225.00 North83: 4831770.00 Org CS: UTM83 UTMRC: 4 UTMRC Desc: margin of error : 30 m - 100 m Location Method: wwr					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID: 1008657994 Layer: 1 Color: 6 General Color: BROWN Mat1: 06 Most Common Material: SILT Mat2: 61 Mat2 Desc: CLAYEY Mat3: 66 Mat3 Desc: DENSE					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation Top Depth:		0.0			
Formation End Depth:		19.0			
Formation End Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658055			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658082			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658083			
Layer:		2			
Plug From:		1.0			
Plug To:		7.0			
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008657944			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008657925			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008658010			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		9.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen ID:		1008658023			
Layer:		1			
Slot:		10			
Screen Top Depth:		9.0			
Screen End Depth:		19.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657926			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008657971			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					
Hole ID:		1008658040			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		19.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008657891			Tag No:	A313609
Depth M:	5.7912			Contractor:	6607
Year Completed:	2021			Latitude:	43.6349132872282
Well Completed Dt:	05/28/2021			Longitude:	-80.0426369514598
Audit No:	NA6FZHSK			Y:	43.63491328520163
Path:	738\7388624.pdf			X:	-80.04263680170743

60

1 of 1

WNW/203.6

356.9 / 6.31

125 MCDONALD BLVD lot 29 con 3
ACTON ON

WWIS

Well ID: 7388614
Construction Date:Flowing (Y/N):
Flow Rate:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	6WDBBKIR			Contractor:	6607
Tag:	A313630			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Bore Hole Information

Bore Hole ID:	1008657861	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577236.00
Code OB Desc:		North83:	4831785.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	05/28/2021	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1008657977
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	61
Mat2 Desc:	CLAYEY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	0.0
Formation End Depth:	17.0
Formation End Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1008658045
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658063			
Layer:		2			
Plug From:		1.0			
Plug To:		5.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658062			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008657934			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008657905			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008657999			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		7.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008658015			
Layer:		1			
Slot:		10			
Screen Top Depth:		7.0			
Screen End Depth:		17.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pumping Test Method Desc:					
Pump Test ID:		1008657906			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
Water Details					
Water ID:		1008657962			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
Hole Diameter					
Hole ID:		1008658028			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		17.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
Links					
Bore Hole ID:	1008657861			Tag No:	A313630
Depth M:	5.1816			Contractor:	6607
Year Completed:	2021			Latitude:	43.6350471875931
Well Completed Dt:	05/28/2021			Longitude:	-80.0424984581992
Audit No:	6WDBBKIR			Y:	43.63504718679623
Path:	738\7388614.pdf			X:	-80.04249830847205
61	1 of 1	NW/206.9	355.8 / 5.28	125 McDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7352056			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	01/17/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	DSAUKP4F			Contractor:	6607
Tag:	A286922			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:					
Site Info:		HALTON HILLS TOWN (ESQUESING) MW-1431			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7352056.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		01/07/2020			
Year Completed:		2020			
Depth (m):		10.21			
Latitude:		43.6355825795006			
Longitude:		-80.0419196880011			
Path:		735\7352056.pdf			
<u>Bore Hole Information</u>					
Bore Hole ID:		1007987944		Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577282.00
Code OB Desc:				North83:	4831845.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:		01/07/2020		UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988838			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		3.809999942779541			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988840			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		05			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		5.329999923706055			
Formation End Depth:		10.210000038146973			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007988837			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		01			
Most Common Material:		FILL			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007988839			
Layer:		3			
Color:		7			
General Color:		RED			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		3.809999942779541			
Formation End Depth:		5.329999923706055			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989473			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989787			
Layer:		1			
Plug From:		0.0			
Plug To:		6.5			
Plug Depth UOM:		m			
 <u>Method of Construction & Well</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Use</u>					
Method Construction ID:		1007988454			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007988286			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007989076			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		7.159999847412109			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1007989211			
Layer:		1			
Slot:		10			
Screen Top Depth:		7.159999847412109			
Screen End Depth:		10.210000038146973			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007988287			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1007989325			
Diameter:		21.0			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Depth From:		0.0			
Depth To:		10.210000038146973			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
Links					
Bore Hole ID:	1007987944			Tag No:	A286922
Depth M:	10.21			Contractor:	6607
Year Completed:	2020			Latitude:	43.6355825795006
Well Completed Dt:	01/07/2020			Longitude:	-80.0419196880011
Audit No:	DSAUKP4F			Y:	43.6355825782411
Path:	735\7352056.pdf			X:	-80.04191953844328

62	1 of 1	WNW/208.4	356.9 / 6.31	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7350972			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/20/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	SDKD42IQ			Contractor:	6607
Tag:	A286955			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW 1424				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350972.pdf				

Additional Detail(s) (Map)

Well Completed Date: 12/10/2019
 Year Completed: 2019
 Depth (m): 2.7
 Latitude: 43.6351192102121
 Longitude: -80.0424973145401
 Path: 735\7350972.pdf

Bore Hole Information

Bore Hole ID:	1007854483	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577236.00
Code OB Desc:		North83:	4831793.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	12/10/2019	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855098			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.2000000476837158			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855100			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		2.0999999046325684			
Formation End Depth:		2.700000047683716			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855099			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.2000000476837158			
Formation End Depth:		2.0999999046325684			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855697			
Layer:		1			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug From:		0.0			
Plug To:		0.8999999761581421			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855501			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854791			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1007854695			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1007855220			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		1.5			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
 <u>Construction Record - Screen</u>					
Screen ID:		1007855317			
Layer:		1			
Slot:		10			
Screen Top Depth:		1.5			
Screen End Depth:		2.700000047683716			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007854696			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Flowing Rate: Recommended Pump Rate: Levels UOM: m Rate UOM: LPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
Hole Diameter					
Hole ID: 1007855400 Diameter: 21.0 Depth From: 0.0 Depth To: 2.700000047683716 Hole Depth UOM: m Hole Diameter UOM: cm					
Links					
Bore Hole ID: 1007854483 Depth M: 2.7 Year Completed: 2019 Well Completed Dt: 12/10/2019 Audit No: SDKD42IQ Path: 735\7350972.pdf					
Tag No: A286955 Contractor: 6607 Latitude: 43.6351192102121 Longitude: -80.0424973145401 Y: 43.635119208365936 X: -80.0424971658089					
63	1 of 1	S/208.5	351.9 / 1.31	52 Mill St East Acton ON L7J 1H3	EHS
Order No: 20020703003 Status: C Report Type: Custom Report Report Date: 7/10/02 Date Received: 7/3/02 Previous Site Name: Lot/Building Size: Additional Info Ordered:					
Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): 0.25 X: -80.039773 Y: 43.631062					
64	1 of 1	NW/208.9	356.9 / 6.34	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID: 7360681 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: I42FWHIB Tag: A267071 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 06/09/2020 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					
Additional Detail(s) (Map)					
Well Completed Date:		06/05/2020			
Year Completed:		2020			
Depth (m):		9.1			
Latitude:		43.6354939017563			
Longitude:		-80.0420822596066			
Path:					
Bore Hole Information					
Bore Hole ID:		1008307594		Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	
Code OB:				East83:	
Code OB Desc:				North83:	
Open Hole:				Org CS:	
Cluster Kind:				UTMRC:	
Date Completed:		06/05/2020		UTMRC Desc:	
Remarks:				Location Method:	
Loc Method Desc:		on Water Well Record		wwr	
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
Overburden and Bedrock					
Materials Interval					
Formation ID:		1008308271			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		9.100000381469727			
Formation End Depth UOM:		m			
Annular Space/Abandonment					
Sealing Record					
Plug ID:		1008308711			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
Annular Space/Abandonment					
Sealing Record					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug ID:		1008308890			
Layer:		2			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008308889			
Layer:		1			
Plug From:		0.0			
Plug To:		5.5			
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008307957			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008307824			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008308430			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		6.099999904632568			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
 <u>Construction Record - Screen</u>					
Screen ID:		1008308515			
Layer:		1			
Slot:		10			
Screen Top Depth:		6.099999904632568			
Screen End Depth:		9.100000381469727			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008307825			
Pump Set At:					
Static Level:					
Final Level After Pumping:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: m Rate UOM: LPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Water Details</u>					
Water ID:		1008308117			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		2.700000047683716			
Water Found Depth UOM:		m			
<u>Hole Diameter</u>					
Hole ID:		1008308603			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		9.100000381469727			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1008307594			Tag No:	A267071
Depth M:	9.1			Contractor:	6607
Year Completed:	2020			Latitude:	43.6354939017563
Well Completed Dt:	06/05/2020			Longitude:	-80.0420822596066
Audit No:	I42FHHIB			Y:	43.63549390037954
Path:	736\7360681.pdf			X:	-80.04208211010982
65	1 of 1	NW/213.5	356.9 / 6.34	ON	WWIS
Well ID:	7311615			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:				Data Entry Status:	Yes
Use 2nd:				Data Src:	
Final Well Status:				Date Received:	05/25/2018
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	C39585			Contractor:	7238
Tag:	A237225			Form Version:	8
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Info:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		05/03/2018			
Year Completed:		2018			
Depth (m):					
Latitude:		43.6354678281119			
Longitude:		-80.0421942478828			
Path:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1007060025			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577260.00
Code OB Desc:				North83:	4831832.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/03/2018			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Links</u>					
Bore Hole ID:	1007060025			Tag No:	A237225
Depth M:				Contractor:	7238
Year Completed:	2018			Latitude:	43.6354678281119
Well Completed Dt:	05/03/2018			Longitude:	-80.0421942478828
Audit No:	C39585			Y:	43.63546782674148
Path:				X:	-80.0421940985515
66	1 of 14	E/213.7	353.9 / 3.35	Maple Reinders Construction Limited 10 Eastern Ave, Acton ON Halton Hills ON L7J 0A5	SPL
Ref No:	0804-826J62			Municipality No:	
Year:				Nature of Damage:	
Incident Dt:				Discharger Report:	
Dt MOE Arvl on Scn:				Material Group:	
MOE Reported Dt:	1/29/2010			Health/Env Conseq:	
Dt Document Closed:				Agency Involved:	
Site No:					
MOE Response:					
Site County/District:					
Site Geo Ref Meth:					
Site District Office:					
Nearest Watercourse:					
Site Name:		Diesel Spill<UNOFFICIAL>			
Site Address:					
Site Region:					
Site Municipality:					
Site Lot:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Conc: Site Geo Ref Accu: Site Map Datum: Northing: Easting: Incident Cause: Pipe Or Hose Leak Incident Event: Environment Impact: Confirmed Nature of Impact: Soil Contamination Contaminant Qty: 600 L System Facility Address: Client Name: Maple Reinders Construction Limited Client Type: Source Type: Contaminant Code: 13 Contaminant Name: DIESEL FUEL Contaminant Limit 1: Contam Limit Freq 1: Contaminant UN No 1: Receiving Medium: Incident Reason: Spill Incident Summary: Maple Reinder Constructors- 600L diesel to ground Activity Preceding Spill: Property 2nd Watershed: Property Tertiary Watershed: Sector Type: Pipeline SAC Action Class: Land Spills Call Report Locatn Geodata:					

66	2 of 14	E/213.7	353.9 / 3.35	10 EASTERN AVENUE, ACTON ON	INC
Incident No: 317310 Incident ID: 2468734 Instance No: Status Code: Causal Analysis Complete Incident Status: Incident Severity: Task No: 2724454 Attribute Category: FS-Perform L1 Incident Insp Context: Date of Occurrence: 2010/01/29 00:00:00 Time of Occurrence: 12:00:00 Occr Insp Start Dt: 2010/01/29 00:00:00 Incident Creat On: Instance Creat Dt: Instance Install Dt: Approx Quant Rel: unknown Tank Capacity: Fuels Occur Type: Leak Occur Type Rpt: Occur Category: Fuel Type Involved: Fuel Oil Fuel Type Reported: Enforcement Policy: NULL Prc Escalation Req: NULL Item: Item Description: Device Installed Location: Venting Type: Vent Conn Mater: Vent Chimney Mater: Pipeline Type: Pipeline Involved:					
Any Health Impact: No Any Enviro Impact: Unknown Service Intrp: No Was Prop Damaged: No Reside App. Type: Commer App. Type: Indus App. Type: Institut App. Type: Depth Ground Cover: Operation Pressure: Equipment Type: Equipment Model: Serial No: Cylinder Capacity: Cylinder Cap Units: Cylinder Mat Type: Pump Flow Rate Cap: Contam. Migrated: Unknown Near Body of Water: No Drainage System: Unknown Sub Surface Contam: unknown Tank Material Type: Tank Storage Type: Tank Location Type:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pipe Material: Regulator Location: Regulator Type: Liquid Prop Make: Liquid Prop Model: Liquid Prop Serial No: Liquid Prop Notes: Inventory Address: 10 EASTERN AVENUE, ACTON - SPILL Invent Postal Code: Notes: Contact Natural Env: No Aff Prop Use Water: No Occurrence Narrative: Oil Leak from construction AST Operation Type Involved: Construction Site (including excavation)					
66	3 of 14	E/213.7	353.9 / 3.35	Acton Medical and Urgent Care 10 Eastern Avenue Acton ON L7J0A5	GEN
Generator No: ON5583345 SIC Code: 621110 SIC Description: OFFICES OF PHYSICIANS Approval Years: 2016 PO Box No: Country: Canada Status: Co Admin: Choice of Contact: CO_OFFICIAL Phone No Admin: Contaminated Facility: No MHSW Facility: No					
<u>Detail(s)</u>					
Waste Class: 261 Waste Class Name: PHARMACEUTICALS					
Waste Class: 312 Waste Class Name: PATHOLOGICAL WASTES					
66	4 of 14	E/213.7	353.9 / 3.35	Dr Jones Chan Dentistry Professional Corporation 10 Eastern Ave unit 104 Acton ON L7J 0A5	GEN
Generator No: ON7680926 SIC Code: 621210 SIC Description: OFFICES OF DENTISTS Approval Years: 2015 PO Box No: Country: Canada Status: Co Admin: Choice of Contact: CO_OFFICIAL Phone No Admin: Contaminated Facility: No MHSW Facility: No					
<u>Detail(s)</u>					
Waste Class: 312 Waste Class Name: PATHOLOGICAL WASTES					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	5 of 14	E/213.7	353.9 / 3.35	Acton Medical and Urgent Care 10 Eastern Avenue Acton ON L7J0A5	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON5583345 621110 OFFICES OF PHYSICIANS 2015 Canada CO_OFFICIAL No No			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		261 PHARMACEUTICALS			
Waste Class: Waste Class Name:		312 PATHOLOGICAL WASTES			
66	6 of 14	E/213.7	353.9 / 3.35	Dr Jones Chan Dentistry Professional Corporation 10 Eastern Ave unit 104 Acton ON L7J 0A5	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON7680926 621210 OFFICES OF DENTISTS 2016 Canada CO_OFFICIAL No No			
<u>Detail(s)</u>					
Waste Class: Waste Class Name:		312 PATHOLOGICAL WASTES			
66	7 of 14	E/213.7	353.9 / 3.35	Acton Medical and Urgent Care 10 Eastern Avenue Acton ON L7J0A5	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact:		ON5583345 621110 OFFICES OF PHYSICIANS 2014 Canada CO_OFFICIAL			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Phone No Admin:					
Contaminated Facility:		No			
MHSW Facility:		No			
<u>Detail(s)</u>					
Waste Class:		312			
Waste Class Name:		PATHOLOGICAL WASTES			
Waste Class:		261			
Waste Class Name:		PHARMACEUTICALS			
66	8 of 14	E/213.7	353.9 / 3.35	Acton Medical and Urgent Care 10 Eastern Avenue Acton ON L7J0A5	GEN
Generator No:		ON5583345			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
66	9 of 14	E/213.7	353.9 / 3.35	Dr Jones Chan Dentistry Professional Corporation 10 Eastern Ave unit 104 Acton ON L7J 0A5	GEN
Generator No:		ON7680926			
SIC Code:					
SIC Description:					
Approval Years:		As of Dec 2018			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
66	10 of 14	E/213.7	353.9 / 3.35	Dr Jones Chan Dentistry Professional Corporation 10 Eastern Ave unit 104 Acton ON L7J 0A5	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON7680926	As of Jul 2020	Canada Registered	
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
66	11 of 14	E/213.7	353.9 / 3.35	Acton Medical and Urgent Care 10 Eastern Avenue Acton ON L7J0A5	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON5583345	As of Jul 2020	Canada Registered	
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
66	12 of 14	E/213.7	353.9 / 3.35	Acton Medical and Urgent Care 10 Eastern Avenue Acton ON L7J0A5	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility:		ON5583345	As of Jan 2021	Canada Registered	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		261 A			
Waste Class Name:		Pharmaceuticals			
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
<u>66</u>	13 of 14	E/213.7	353.9 / 3.35	Dr Jones Chan Dentistry Professional Corporation 10 Eastern Ave unit 104 Acton ON L7J 0A5	GEN
Generator No:		ON7680926			
SIC Code:					
SIC Description:					
Approval Years:		As of Nov 2021			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		Pathological wastes			
<u>66</u>	14 of 14	E/213.7	353.9 / 3.35	Dr Jones Chan Dentistry Professional Corporation 10 Eastern Ave unit 104 Acton ON L7J 0A5	GEN
Generator No:		ON7680926			
SIC Code:					
SIC Description:					
Approval Years:		As of Oct 2022			
PO Box No:					
Country:		Canada			
Status:		Registered			
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		312 P			
Waste Class Name:		PATHOLOGICAL WASTES			
<u>67</u>	1 of 1	WSW/216.2	349.3 / -1.28	Halton Hills Hydro Inc. Halton Hills Hydro Inc. 57 Willow St. N Acton ON L7J 1Z8	GEN
Generator No:		ON5469628			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
SIC Code: SIC Description: Approval Years: As of Nov 2021 PO Box No: Country: Canada Status: Registered Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		252 L			
Waste Class Name:		Waste crankcase oils and lubricants			
68	1 of 1	S/218.2	351.9 / 1.31	ACTON HOME HARDWARE 43 MILL ST ACTON ON L7J 1E8	PES
Detail Licence No: Licence No: Status: Approval Date: Report Source: Licence Type: Vendor Licence Type Code: Licence Class: Licence Control: Latitude: Longitude: Lot: Concession: Region: District: County: Trade Name: PDF URL:		Operator Box: Operator Class: Operator No: Operator Type: Oper Area Code: Oper Phone No: Operator Ext: Operator Lot: Oper Concession: Operator Region: Operator District: Operator County: Op Municipality: Post Office Box: MOE District: SWP Area Name:			
69	1 of 1	NW/218.8	356.2 / 5.61	125 McDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7351992 Construction Date: Use 1st: Monitoring and Test Hole Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: 4LA8TKXI Tag: A286921 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING)		Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 01/17/2020 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Info:		MW-1430			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7351992.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		01/06/2020			
Year Completed:		2020			
Depth (m):		8.94			
Latitude:		43.6356466381531			
Longitude:		-80.0420426417179			
Path:		735\7351992.pdf			
<u>Bore Hole Information</u>					
Bore Hole ID:		1007987752		Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	
Code OB:				East83:	
Code OB Desc:				North83:	
Open Hole:				Org CS:	
Cluster Kind:				UTMRC:	
Date Completed:		01/06/2020		UTMRC Desc:	
Remarks:				Location Method:	
Loc Method Desc:		on Water Well Record		wwr	
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988700			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		01			
Most Common Material:		FILL			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988701			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation Top Depth:		1.5			
Formation End Depth:		3.809999942779541			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007988702			
Layer:		3			
Color:		7			
General Color:		RED			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		3.809999942779541			
Formation End Depth:		5.329999923706055			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007988703			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		5.329999923706055			
Formation End Depth:		8.9399995803833			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989408			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989569			
Layer:		1			
Plug From:		0.0			
Plug To:		5.28000020980835			
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1007988394			
Method Construction Code:		6			
Method Construction:		Boring			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007988158			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007989015			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		5.889999866485596			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1007989152			
Layer:		1			
Slot:		10			
Screen Top Depth:		5.889999866485596			
Screen End Depth:		8.9399995803833			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007988159			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1007989264			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		8.9399995803833			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Links</u>					
Bore Hole ID:	1007987752			Tag No:	A286921
Depth M:	8.94			Contractor:	6607
Year Completed:	2020			Latitude:	43.6356466381531
Well Completed Dt:	01/06/2020			Longitude:	-80.0420426417179
Audit No:	4LA8TKXI			Y:	43.63564663680196
Path:	735\7351992.pdf			X:	-80.04204249260803
<u>70</u>	1 of 1	WNW/220.7	356.9 / 6.31	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7350911			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/20/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	5XDTL39G			Contractor:	6607
Tag:	A286984			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW 1425				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350911.pdf				
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:	12/10/2019				
Year Completed:	2019				
Depth (m):	1.67				
Latitude:	43.6352189680964				
Longitude:	-80.0425825099302				
Path:	735\7350911.pdf				
<u>Bore Hole Information</u>					
Bore Hole ID:	1007854300			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577229.00
Code OB Desc:				North83:	4831804.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	12/10/2019			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007854961			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		0.8999999761581421			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007854962			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		0.8999999761581421			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007854963			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		26			
Most Common Material:		ROCK			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		1.6699999570846558			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855440			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Sealing Record</u>					
Plug ID:		1007855542			
Layer:		1			
Plug From:		0.0			
Plug To:		0.6000000238418579			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854734			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007854573			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007855159			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		0.8999999761581421			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1007855256			
Layer:		1			
Slot:		10			
Screen Top Depth:		0.8999999761581421			
Screen End Depth:		1.6699999570846558			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007854574			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
Hole Diameter					
Hole ID:		1007855339			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		1.6699999570846558			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
Links					
Bore Hole ID:	1007854300			Tag No:	A286984
Depth M:	1.67			Contractor:	6607
Year Completed:	2019			Latitude:	43.6352189680964
Well Completed Dt:	12/10/2019			Longitude:	-80.0425825099302
Audit No:	5XDTL39G			Y:	43.635218966709566
Path:	735\7350911.pdf			X:	-80.0425823601978

71	1 of 1	WNW/222.0	356.9 / 6.31	ON	WWIS
Well ID:	7171098			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:				Data Entry Status:	Yes
Use 2nd:				Data Src:	
Final Well Status:				Date Received:	11/03/2011
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	M07084			Contractor:	7238
Tag:	A115469			Form Version:	5
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/717\7171098.pdf			
Additional Detail(s) (Map)					
Well Completed Date:	09/14/2011				
Year Completed:	2011				
Depth (m):					
Latitude:	43.6350049763839				
Longitude:	-80.0428338480979				
Path:	717\7171098.pdf				
Bore Hole Information					
Bore Hole ID:	1003595924			Elevation:	
DP2BR:				Elevrc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Spatial Status:				Zone:	17
Code OB:				East83:	577209.00
Code OB Desc:				North83:	4831780.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	3
Date Completed:	09/14/2011			UTMRC Desc:	margin of error : 10 - 30 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Links</u>					
Bore Hole ID:	1003595924			Tag No:	A115469
Depth M:				Contractor:	7238
Year Completed:	2011			Latitude:	43.6350049763839
Well Completed Dt:	09/14/2011			Longitude:	-80.0428338480979
Audit No:	M07084			Y:	43.63500497415864
Path:	717\7171098.pdf			X:	-80.04283369887223

<u>72</u>	1 of 1	NW/222.3	356.2 / 5.61	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7406731			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/24/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	R9SPGP9N			Contractor:	6607
Tag:	A327752			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					

Bore Hole Information

Bore Hole ID:	1008899000			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577267.00
Code OB Desc:				North83:	4831852.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/24/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008899109			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		77			
Mat3 Desc:		LOOSE			
Formation Top Depth:		10.0			
Formation End Depth:		15.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008899108			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		77			
Mat3 Desc:		LOOSE			
Formation Top Depth:		0.0			
Formation End Depth:		10.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008899110			
Layer:		3			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		77			
Mat3 Desc:		LOOSE			
Formation Top Depth:		15.0			
Formation End Depth:		27.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008899207			
Layer:		1			
Plug From:		0.0			
Plug To:		2.0			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008899170			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008899208			
Layer:		2			
Plug From:		1.0			
Plug To:		14.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008899057			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008899042			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008899124			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		17.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008899137			
Layer:		1			
Slot:		10			
Screen Top Depth:		17.0			
Screen End Depth:		27.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		6.199999809265137			
<u>Results of Well Yield Testing</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Pumping Test Method Desc:

Pump Test ID: 1008899043
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1008899150
Diameter: 8.0
Depth From: 0.0
Depth To: 27.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

Links

Bore Hole ID:	1008899000	Tag No:	A327752
Depth M:	8.2296	Contractor:	6607
Year Completed:	2021	Latitude:	43.6356471575414
Well Completed Dt:	11/24/2021	Longitude:	-80.0421046192412
Audit No:	R9SPGP9N	Y:	43.63564715627389
Path:	740\7406731.pdf	X:	-80.04210446915638

<u>73</u>	1 of 1	W/222.8	354.9 / 4.31	n/a n/a lot 29 con 3 Guelph ON	WWIS

Well ID: 7378699 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: RODLBVZL Tag: A306008 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info:	Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 01/21/2021 Selected Flag: TRUE Abandonment Rec: Contractor: 7282 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:

Bore Hole Information

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Bore Hole ID:	1008554558			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577156.00
Code OB Desc:				North83:	4831680.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/30/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008554668				
Layer:	1				
Color:	8				
General Color:	BLACK				
Mat1:	02				
Most Common Material:	TOPSOIL				
Mat2:	01				
Mat2 Desc:	FILL				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	0.0				
Formation End Depth:	4.0				
Formation End Depth UOM:	ft				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008554670				
Layer:	3				
Color:	7				
General Color:	RED				
Mat1:	34				
Most Common Material:	TILL				
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:	9.0				
Formation End Depth:	13.5				
Formation End Depth UOM:	ft				
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008554669				
Layer:	2				
Color:	6				
General Color:	BROWN				
Mat1:	28				
Most Common Material:	SAND				
Mat2:					
Mat2 Desc:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat3:					
Mat3 Desc:					
Formation Top Depth:		4.0			
Formation End Depth:		9.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008554772			
Layer:		1			
Plug From:		0.0			
Plug To:		2.5			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008554757			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008554773			
Layer:		2			
Plug From:		2.5			
Plug To:		13.5			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008554633			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008554603			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008554712			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.5			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Construction Record - Screen</u>					
Screen ID:		1008554727			
Layer:		1			
Slot:		10			
Screen Top Depth:		3.5			
Screen End Depth:		13.5			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.299999952316284			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008554604			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008554742			
Diameter:		6.0			
Depth From:		0.0			
Depth To:		13.5			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008554558			Tag No:	A306008
Depth M:	4.1148			Contractor:	7282
Year Completed:	2020			Latitude:	43.6341101924955
Well Completed Dt:	11/30/2020			Longitude:	-80.0435050836403
Audit No:	RODLBVZL			Y:	43.63411019055181
Path:	737\7378699.pdf			X:	-80.04350493429274
74	1 of 1	NW/223.7	356.2 / 5.61	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7337187			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	07/18/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	JKYGRFAF			Contractor:	6607
Tag:	A245803			Form Version:	9

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Constructn Method:			Owner:		
Elevation (m):			County: HALTON		
Elevatn Reliabilty:			Lot: 029		
Depth to Bedrock:			Concession: 03		
Well Depth:			Concession Name: CON		
Overburden/Bedrock:			Easting NAD83:		
Pump Rate:			Northing NAD83:		
Static Water Level:			Zone:		
Clear/Cloudy:			UTM Reliability:		
Municipality:			HALTON HILLS TOWN (ESQUESING)		
Site Info:			MW 3002		
PDF URL (Map):			https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7337187.pdf		
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:			07/09/2019		
Year Completed:			2019		
Depth (m):			6		
Latitude:			43.6355939715382		
Longitude:			-80.0422046413056		
Path:			733\7337187.pdf		
<u>Bore Hole Information</u>					
Bore Hole ID:			1007507115		
DP2BR:			Elevation:		
Spatial Status:			Elevrc:		
Code OB:			Zone: 17		
Code OB Desc:			East83: 577259.00		
Open Hole:			North83: 4831846.00		
Cluster Kind:			Org CS: UTM83		
Date Completed:			UTMRC: 4		
Remarks:			UTMRC Desc: margin of error : 30 m - 100 m		
Loc Method Desc:			Location Method: wwr		
Elevrc Desc:			on Water Well Record		
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:			1007507756		
Layer:			2		
Color:			7		
General Color:			RED		
Mat1:			06		
Most Common Material:			SILT		
Mat2:			05		
Mat2 Desc:			CLAY		
Mat3:			79		
Mat3 Desc:			PACKED		
Formation Top Depth:			1.600000023841858		
Formation End Depth:			6.0		
Formation End Depth UOM:			m		
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation ID:		1007507755			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.600000023841858			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007508183			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007508305			
Layer:		1			
Plug From:		0.0			
Plug To:		2.4000000953674316			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007507464			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007507290			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007507908			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen ID: 1007507992					
Layer: 1					
Slot: 10					
Screen Top Depth: 3.0					
Screen End Depth: 6.0					
Screen Material: 5					
Screen Depth UOM: m					
Screen Diameter UOM: cm					
Screen Diameter: 6.400000095367432					
Results of Well Yield Testing					
Pumping Test Method Desc:					
Pump Test ID: 1007507291					
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM: m					
Rate UOM: LPM					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
Water Details					
Water ID: 1007507624					
Layer: 1					
Kind Code: 8					
Kind: Untested					
Water Found Depth: 3.5999999046325684					
Water Found Depth UOM: m					
Hole Diameter					
Hole ID: 1007508083					
Diameter: 21.0					
Depth From: 0.0					
Depth To: 6.0					
Hole Depth UOM: m					
Hole Diameter UOM: cm					
Links					
Bore Hole ID: 1007507115		Tag No: A245803			
Depth M: 6		Contractor: 6607			
Year Completed: 2019		Latitude: 43.6355939715382			
Well Completed Dt: 07/09/2019		Longitude: -80.0422046413056			
Audit No: JKYGRFAF		Y: 43.635593970174675			
Path: 733\7337187.pdf		X: -80.04220449114638			
75	1 of 1	NW/223.7	356.2 / 5.61	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7375866		Flowing (Y/N):			
Construction Date:		Flow Rate:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/15/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	T7YW9Q6Z			Contractor:	6607
Tag:	A293620			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					

Bore Hole Information

Bore Hole ID:	1008529397	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577267.00
Code OB Desc:		North83:	4831854.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	11/10/2020	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock

Materials Interval

Formation ID:	1008529492
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Mat2 Desc:	SILT
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	21.0
Formation End Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1008529610
Layer:	1
Plug From:	0.0
Plug To:	9.0
Plug Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008529560			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008529453			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008529444			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008529512			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		11.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008529532			
Layer:		1			
Slot:		250			
Screen Top Depth:		11.0			
Screen End Depth:		21.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008529445			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008529537			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		21.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:		1008529397		Tag No:	A293620
Depth M:		6.4008		Contractor:	6607
Year Completed:		2020		Latitude:	43.6356651631923
Well Completed Dt:		11/10/2020		Longitude:	-80.0421043332033
Audit No:		T7YW9Q6Z		Y:	43.63566516149463
Path:		737\7375866.pdf		X:	-80.0421041834906

76	1 of 1	WNW/224.6	355.8 / 5.22	ON	WWIS
Well ID:	7315547			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:				Data Entry Status:	Yes
Use 2nd:				Data Src:	
Final Well Status:				Date Received:	07/30/2018
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	C39592			Contractor:	7238
Tag:	A237251			Form Version:	8
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	
Depth to Bedrock:				Concession:	
Well Depth:				Concession Name:	
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					

Additional Detail(s) (Map)

Well Completed Date:	05/25/2018
Year Completed:	2018
Depth (m):	
Latitude:	43.6348803897632
Longitude:	-80.0430093836879
Path:	

Bore Hole Information

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Bore Hole ID: 1007229187 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 05/25/2018 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment: Elevation: Elevrc: Zone: 17 East83: 577195.00 North83: 4831766.00 Org CS: UTM83 UTMRC: 4 UTMRC Desc: margin of error : 30 m - 100 m Location Method: wwr					
Links Bore Hole ID: 1007229187 Depth M: Year Completed: 2018 Well Completed Dt: 05/25/2018 Audit No: C39592 Path: Tag No: A237251 Contractor: 7238 Latitude: 43.6348803897632 Longitude: -80.0430093836879 Y: 43.63488038857483 X: -80.04300923412575					
77	1 of 1	NW/226.6	356.2 / 5.61	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7388627 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: ZQIWJY9Y Tag: A313729 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ESQUESING) Site Info: Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 06/01/2021 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
Bore Hole Information					
Bore Hole ID: 1008657900 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 05/27/2021 Remarks: Loc Method Desc: on Water Well Record Elevation: Elevrc: Zone: 17 East83: 577266.00 North83: 4831857.00 Org CS: UTM83 UTMRC: 4 UTMRC Desc: margin of error : 30 m - 100 m Location Method: wwr					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1008657997			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		61			
Mat2 Desc:		CLAYEY			
Mat3:		66			
Mat3 Desc:		DENSE			
Formation Top Depth:		0.0			
Formation End Depth:		26.5			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658089			
Layer:		2			
Plug From:		1.0			
Plug To:		14.5			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658088			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658058			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008657947			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pipe ID:		1008657931			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008658013			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		16.5			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008658026			
Layer:		1			
Slot:		10			
Screen Top Depth:		16.5			
Screen End Depth:		26.5			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657932			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008657974			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
<u>Hole Diameter</u>					
Hole ID:		1008658043			
Diameter:		8.0			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Depth From:		0.0			
Depth To:		26.5			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
Links					
Bore Hole ID:	1008657900			Tag No:	A313729
Depth M:	8.0772			Contractor:	6607
Year Completed:	2021			Latitude:	43.6356922755423
Well Completed Dt:	05/27/2021			Longitude:	-80.04211629966
Audit No:	ZQIWJY9Y			Y:	43.635692274640284
Path:	738\7388627.pdf			X:	-80.04211615084057

78	1 of 1	NW/228.6	356.9 / 6.34	125 McDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7352094			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	01/17/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	SIHDRWYX			Contractor:	6607
Tag:	A286946			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW-1429				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7352094.pdf				

Additional Detail(s) (Map)

Well Completed Date: 01/08/2020
Year Completed: 2020
Depth (m): 12.19
Latitude: 43.6356391933913
Longitude: -80.0422287172933
Path: 735\7352094.pdf

Bore Hole Information

Bore Hole ID:	1007988058	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577257.00
Code OB Desc:		North83:	4831851.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	01/08/2020	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Overburden and Bedrock</u> <u>Materials Interval</u>					
Formation ID:		1007988954			
Layer:		5			
Color:		7			
General Color:		RED			
Mat1:		15			
Most Common Material:		LIMESTONE			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		7.920000076293945			
Formation End Depth:		12.1899995803833			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u> <u>Materials Interval</u>					
Formation ID:		1007988950			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		01			
Most Common Material:		FILL			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u> <u>Materials Interval</u>					
Formation ID:		1007988952			
Layer:		3			
Color:		7			
General Color:		RED			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		3.809999942779541			
Formation End Depth:		5.329999923706055			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u> <u>Materials Interval</u>					
Formation ID:		1007988951			
Layer:		2			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		3.809999942779541			
Formation End Depth UOM:		m			
 <u>Overburden and Bedrock</u> <u>Materials Interval</u>					
Formation ID:		1007988953			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		5.329999923706055			
Formation End Depth:		7.920000076293945			
Formation End Depth UOM:		m			
 <u>Annular Space/Abandonment</u> <u>Sealing Record</u>					
Plug ID:		1007989813			
Layer:		1			
Plug From:		0.0			
Plug To:		0.30000001192092896			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment</u> <u>Sealing Record</u>					
Plug ID:		1007989511			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment</u> <u>Sealing Record</u>					
Plug ID:		1007989814			
Layer:		2			
Plug From:		0.30000001192092896			
Plug To:		9.8999999618530273			
Plug Depth UOM:		m			
 <u>Method of Construction & Well</u> <u>Use</u>					
Method Construction ID:		1007988491			
Method Construction Code:		6			
Method Construction:		Boring			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Other Method Construction:					
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007988492			
Method Construction Code:		7			
Method Construction:		Diamond			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007988362			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007989113			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		10.050000190734863			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1007989248			
Layer:		1			
Slot:		10			
Screen Top Depth:		10.050000190734863			
Screen End Depth:		12.1899995803833			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007988363			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:		1007989365			
Diameter:		9.600000381469727			
Depth From:		9.100000381469727			
Depth To:		12.1899995803833			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Hole Diameter</u>					
Hole ID:		1007989363			
Diameter:		25.0			
Depth From:		0.0			
Depth To:		7.920000076293945			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Hole Diameter</u>					
Hole ID:		1007989364			
Diameter:		12.0			
Depth From:		7.920000076293945			
Depth To:		9.100000381469727			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
<u>Links</u>					
Bore Hole ID:	1007988058			Tag No:	A286946
Depth M:	12.19			Contractor:	6607
Year Completed:	2020			Latitude:	43.6356391933913
Well Completed Dt:	01/08/2020			Longitude:	-80.0422287172933
Audit No:	SIHDRWYX			Y:	43.63563919130511
Path:	735\7352094.pdf			X:	-80.04222856778092
79	1 of 1	NW/230.1	356.9 / 6.34	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7388621			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	KC9ZR6NV			Contractor:	6607
Tag:	A313616			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Bore Hole ID:	1008657882			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577254.00
Code OB Desc:				North83:	4831850.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/26/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008657991				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:	28				
Mat2 Desc:	SAND				
Mat3:	05				
Mat3 Desc:	CLAY				
Formation Top Depth:	0.0				
Formation End Depth:	23.0				
Formation End Depth UOM:	ft				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658052				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658077				
Layer:	2				
Plug From:	1.0				
Plug To:	11.0				
Plug Depth UOM:	ft				
 <u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658076				
Layer:	1				
Plug From:	0.0				
Plug To:	1.0				
Plug Depth UOM:	ft				
 <u>Method of Construction & Well</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Use</u>					
Method Construction ID:		1008657941			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008657919			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008658007			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		13.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008658020			
Layer:		1			
Slot:		10			
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657920			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008657968			
Layer:		1			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			
 <u>Hole Diameter</u>					
Hole ID:		1008658037			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		23.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
 <u>Links</u>					
Bore Hole ID:	1008657882			Tag No:	A313616
Depth M:	7.0104			Contractor:	6607
Year Completed:	2021			Latitude:	43.6356305021419
Well Completed Dt:	05/26/2021			Longitude:	-80.0422660467994
Audit No:	KC9ZR6NV			Y:	43.63563050076483
Path:	738\7388621.pdf			X:	-80.04226589726147
80	1 of 49	NW/232.2	356.9 / 6.34	BLACKHAWK LEATHER LIMITED 125 MCDONALD BLVD. W., ACTON HALTON HILLS TOWN ON	CA
Certificate #:		8-3220-94-			
Application Year:		94			
Issue Date:		7/26/1994			
Approval Type:		Industrial air			
Status:		Approved			
Application Type:					
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:		EXH. FAN. ROLLER COATER, CAT. DRYER			
Contaminants:		Propylene Glycolmonomethyl Ether Acetate,P.M.Ace., Ethylene Glycol Monomethyl Ether, Diethylene Glycol Monobutyl Ether, Triethanolamine, Formaldehyde, N-Butyl Acetate, Hexamethylene Di-Isocyanate Monomer			
Emission Control:		No Controls			
80	2 of 49	NW/232.2	356.9 / 6.34	EAGLE DOMINION INC. 125 MCDONALD BLVD., ACTON HALTON HILLS TOWN ON L7J 2V7	CA
Certificate #:		8-3316-91-			
Application Year:		91			
Issue Date:		2/11/1992			
Approval Type:		Industrial air			
Status:		Approved in 1992			
Application Type:					
Client Name:					
Client Address:					
Client City:					
Client Postal Code:					
Project Description:		USE WATER BASED ADHESIVE IN ENDURA PROC.			
Contaminants:		Hexamethylene Di-Isocyanate Monomer, Odour/Fumes			
Emission Control:		No Controls			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	3 of 49	NW/232.2	356.9 / 6.34	BLACKHAWK LEATHER LIMITED 125 MCDONALD BLVD. W., ACTON HALTON HILLS TOWN ON	CA
Certificate #: Application Year: Issue Date: Approval Type: Status: Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:		8-3299-93- 93 8/25/1993 Industrial air Approved EXHAUST FOR REVERSE ROLLERCOATER PROCESS Odour/Fumes, Other Organic Compounds No Controls			
80	4 of 49	NW/232.2	356.9 / 6.34	EAGLE DOMINION INC. 125 MCDONALD BLVD., ACTON HALTON HILLS TOWN ON L7J 2V7	CA
Certificate #: Application Year: Issue Date: Approval Type: Status: Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:		8-3018-92- 92 8/24/1993 Industrial air Underwent 2nd revision in 1993 INST. COUNTER-CURRENT WET SCRUBBER Cyclohexane, Ethyl Acetate Packed Tower,			
80	5 of 49	NW/232.2	356.9 / 6.34	EAGLE OTTAWA CANADA LTD. 125 MCDONALD BOULEVARD, ACTON HALTON HILLS ON L7J 2V7	CA
Certificate #: Application Year: Issue Date: Approval Type: Status: Application Type: Client Name: Client Address: Client City: Client Postal Code: Project Description: Contaminants: Emission Control:		8-3001-98- 98 3/10/1998 Industrial air Approved RETROFIT PLANT BLOWERS WITH SILENCERS			
80	6 of 49	NW/232.2	356.9 / 6.34	EAGLE OTTAWA CANADA LTD. 125 MCDONALD BLVD ACTON ON L7J 2V7	SCT
Established: Plant Size (ft²): Employment:		0000 104000 80			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
--Details--					
Description:		LEATHER TANNING AND FINISHING			
SIC/NAICS Code:		3111			
Description:		LEATHER GOODS, NOT ELSEWHERE CLASSIFIED			
SIC/NAICS Code:		3199			
80	7 of 49	NW/232.2	356.9 / 6.34	PERMAIR LEATHERS LIMITED 125 McDonald Blvd Acton ON L7J 2V7	SCT
Established:		2000			
Plant Size (ft²):		104000			
Employment:		30			
--Details--					
Description:		Leather and Hide Tanning and Finishing			
SIC/NAICS Code:		316110			
Description:		Other Leather and Allied Product Manufacturing			
SIC/NAICS Code:		316990			
80	8 of 49	NW/232.2	356.9 / 6.34	FRANK HELLER & COMPANY LTD. 125 MCDONALD BLVD. ACTON ON L7J 2V7	GEN
Generator No:		ON0082100			
SIC Code:		1719			
SIC Description:		OTHER LEATHER PROD.			
Approval Years:		86,87,88,89			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		311			
Waste Class Name:		ORGANIC TANNERY WASTES			
80	9 of 49	NW/232.2	356.9 / 6.34	EAGLE DOMINION INC. 125 MCDONALD BLVD.. ACTON ON L7J 2V7	GEN
Generator No:		ON0082100			
SIC Code:		1719			
SIC Description:		OTHER LEATHER PROD.			
Approval Years:		90			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		311			
Waste Class Name:		ORGANIC TANNERY WASTES			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
80	10 of 49	NW/232.2	356.9 / 6.34	EAGLE OTTAWA CANADA, LTD. 15-268 125 MCDONALD BOULEVARD ACTON ON L7J 2V7	GEN
Generator No: ON0082100 SIC Code: 1719 SIC Description: OTHER LEATHER PROD. Approval Years: 92,93,95,96 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		311			
Waste Class Name:		ORGANIC TANNERY WASTES			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
80	11 of 49	NW/232.2	356.9 / 6.34	BLACKHAWK LEATHER LTD. 15-268 125 MCDONALD BLVD.. ACTON ON L7J 2V7	GEN
Generator No: ON0082100 SIC Code: 1719 SIC Description: OTHER LEATHER PROD. Approval Years: 94 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		311			
Waste Class Name:		ORGANIC TANNERY WASTES			
<u>80</u>	12 of 49	NW/232.2	356.9 / 6.34	EAGLE OTTAWA CANADA, LTD 125 MCDONALD BOULEVARD ACTON ON L7J 2V7	GEN
Generator No:		ON0082100			
SIC Code:		1719			
SIC Description:		OTHER LEATHER PROD.			
Approval Years:		97			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		311			
Waste Class Name:		ORGANIC TANNERY WASTES			
<u>80</u>	13 of 49	NW/232.2	356.9 / 6.34	EAGLE OTTAWA CANADA, LTD. 125 MCDONALD BOULEVARD ACTON ON L7J 2V7	GEN
Generator No:		ON0082100			
SIC Code:		1719			
SIC Description:		OTHER LEATHER PROD.			
Approval Years:		98			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class: Waste Class Name:		252 WASTE OILS & LUBRICANTS			
Waste Class: Waste Class Name:		311 ORGANIC TANNERY WASTES			
80	14 of 49	NW/232.2	356.9 / 6.34	PERMAIR LEATHERS LIMITED 125 MCDONALD BOULEVARD ACTON ON L7J 2V7	GEN
Generator No:		ON0082100			
SIC Code:		1719			
SIC Description:		OTHER LEATHER PROD.			
Approval Years:		99,00,01,02,03,04			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		311			
Waste Class Name:		ORGANIC TANNERY WASTES			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
80	15 of 49	NW/232.2	356.9 / 6.34	Whiteclay Enterprises Inc. 125 McDonald Blvd Unit 5 Acton ON L7J 2V7	SCT
Established:		1987			
Plant Size (ft²):		3600			
Employment:		5			
<u>--Details--</u>					
Description:		Other Ornamental and Architectural Metal Products Manufacturing			
SIC/NAICS Code:		332329			
80	16 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		Other Printing			
Approval Years:		04,05,06,07,08			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		265			
Waste Class Name:		GRAPHIC ART WASTES			
80	17 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd. 125 MacDonald Boulevard, Unit 3, Acton Halton Hills Ontario L7J 2M2 Halton Hills ON	EBR
EBR Registry No:	IA05E1652			Decision Posted:	
Ministry Ref No:	4076-6H4KL5			Exception Posted:	
Notice Type:	Instrument Decision			Section:	
Notice Stage:				Act 1:	
Notice Date:	November 21, 2007			Act 2:	
Proposal Date:	October 25, 2005			Site Location Map:	
Year:	2005				
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)				
Off Instrument Name:					
Posted By:					
Company Name:	Mikia Printing Ltd.				
Site Address:					
Location Other:					
Proponent Name:					
Proponent Address:	125 MacDonald Boulevard, P.O. Box 84 , 3, Acton Ontario, L7J 2M2				
Comment Period:					
URL:					
Site Location Details:					
125 MacDonald Boulevard, Unit 3, Acton Halton Hills Ontario L7J 2M2 Halton Hills					
80	18 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No:	ON6399444				
SIC Code:	332810				
SIC Description:	Coating Engraving Heat Treating and Allied Activit				
Approval Years:	06,07,08				
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		112			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		ACID WASTE - HEAVY METALS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
80	19 of 49	NW/232.2	356.9 / 6.34	Beardmore Leathers 125 McDonald Blvd Acton ON L7J 2V7	SCT
Established:		01-SEP-98			
Plant Size (ft²):					
Employment:					
--Details--					
Description:		All Other Wholesaler-Distributors			
SIC/NAICS Code:		418990			
80	20 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No:		ON6399444			
SIC Code:		332810			
SIC Description:		Coating Engraving Heat Treating and Allied Activities			
Approval Years:		2009			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		112			
Waste Class Name:		ACID WASTE - HEAVY METALS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
80	21 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		Other Printing			
Approval Years:		2009			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class: 145 Waste Class Name: PAINT/PIGMENT/COATING RESIDUES Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS Waste Class: 265 Waste Class Name: GRAPHIC ART WASTES					
80	22 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. Acton ON L7J 2V7	EHS
Order No: 20111005038 Status: C Report Type: Custom Report Report Date: 10/17/2011 Date Received: 10/5/2011 7:36:39 PM Previous Site Name: Lot/Building Size: 11.93 acres Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory Nearest Intersection: Mcdonald and Wallace Municipality: Town of Halton Hills (Acton) Client Prov/State: ON Search Radius (km): 0.25 X: -80.042395 Y: 43.636177					
80	23 of 49	NW/232.2	356.9 / 6.34	125 Mcdonald Boulevard Acton ON L7J 2V7	EHS
Order No: 20120515027 Status: C Report Type: Custom Report Report Date: 25-MAY-12 Date Received: 15-MAY-12 Previous Site Name: Lot/Building Size: 11.39 acres Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos Nearest Intersection: Acton Municipality: ON Client Prov/State: ON Search Radius (km): .25 X: -80.041808 Y: 43.636177					
80	24 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No: ON6399444 SIC Code: 332810 SIC Description: Coating Engraving Heat Treating and Allied Activities Approval Years: 2010 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 112 Waste Class Name: ACID WASTE - HEAVY METALS Waste Class: 122 Waste Class Name: ALKALINE WASTES - OTHER METALS					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	25 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		Other Printing			
Approval Years:		2010			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		265			
Waste Class Name:		GRAPHIC ART WASTES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
80	26 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No:		ON6399444			
SIC Code:		332810			
SIC Description:		Coating Engraving Heat Treating and Allied Activities			
Approval Years:		2011			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		112			
Waste Class Name:		ACID WASTE - HEAVY METALS			
80	27 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		Other Printing			
Approval Years:		2011			
PO Box No:					
Country:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		265			
Waste Class Name:		GRAPHIC ART WASTES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
80	28 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No:		ON6399444			
SIC Code:		332810			
SIC Description:		Coating Engraving Heat Treating and Allied Activities			
Approval Years:		2012			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
Waste Class:		112			
Waste Class Name:		ACID WASTE - HEAVY METALS			
80	29 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		Other Printing			
Approval Years:		2012			
PO Box No:					
Country:					
Status:					
Co Admin:					
Choice of Contact:					
Phone No Admin:					
Contaminated Facility:					
MHSW Facility:					
<u>Detail(s)</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS Waste Class: 265 Waste Class Name: GRAPHIC ART WASTES Waste Class: 145 Waste Class Name: PAINT/PIGMENT/COATING RESIDUES					
80	30 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON	GEN
Generator No: ON8429412 SIC Code: 323119 SIC Description: OTHER PRINTING Approval Years: 2013 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 145 Waste Class Name: PAINT/PIGMENT/COATING RESIDUES Waste Class: 265 Waste Class Name: GRAPHIC ART WASTES Waste Class: 252 Waste Class Name: WASTE OILS & LUBRICANTS					
80	31 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON	GEN
Generator No: ON6399444 SIC Code: 332810 SIC Description: COATING, ENGRAVING, HEAT TREATING AND ALLIED ACTIVITIES Approval Years: 2013 PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 122 Waste Class Name: ALKALINE WASTES - OTHER METALS Waste Class: 131 Waste Class Name: NEUTRALIZED WASTES - HEAVY METALS Waste Class: 112					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		ACID WASTE - HEAVY METALS			
80	32 of 49	NW/232.2	356.9 / 6.34	Frank Heller & Co. Limited 125 McDonald Blvd Halton Hills ON N1G 4X7	ECA
Approval No:		1765-AJDQUK		MOE District:	
Approval Date:		2017-02-09		City:	
Status:		Approved		Longitude:	
Record Type:		ECA		Latitude:	
Link Source:		IDS		Geometry X:	
SWP Area Name:				Geometry Y:	
Approval Type:		ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS			
Project Type:		MUNICIPAL AND PRIVATE SEWAGE WORKS			
Business Name:		Frank Heller & Co. Limited			
Address:		125 McDonald Blvd			
Full Address:					
Full PDF Link:		https://www.accessenvironment.ene.gov.on.ca/instruments/9739-AJ5J56-14.pdf			
PDF Site Location:					
80	33 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd. 125 MacDonald Boulevard, Unit 3, Acton Halton Hills ON L7J 2M2	ECA
Approval No:		5392-78RTHG		MOE District: Halton-Peel	
Approval Date:		2007-11-11		City:	
Status:		Approved		Longitude: -80.042595	
Record Type:		ECA		Latitude: 43.63501	
Link Source:		IDS		Geometry X:	
SWP Area Name:		Credit Valley		Geometry Y:	
Approval Type:		ECA-AIR			
Project Type:		AIR			
Business Name:		Mikia Printing Ltd.			
Address:		125 MacDonald Boulevard, Unit 3, Acton			
Full Address:					
Full PDF Link:		https://www.accessenvironment.ene.gov.on.ca/instruments/4076-6H4KL5-14.pdf			
PDF Site Location:					
80	34 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		OTHER PRINTING			
Approval Years:		2016			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:					
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:					
Contaminated Facility:		No			
MHSW Facility:		No			
Detail(s)					
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		265			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class Name:		GRAPHIC ART WASTES			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
80	35 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No:		ON8429412			
SIC Code:		323119			
SIC Description:		OTHER PRINTING			
Approval Years:		2015			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:					
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:					
Contaminated Facility:		No			
MHSW Facility:		No			
<u>Detail(s)</u>					
Waste Class:		265			
Waste Class Name:		GRAPHIC ART WASTES			
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
80	36 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No:		ON6399444			
SIC Code:		332810			
SIC Description:		COATING, ENGRAVING, HEAT TREATING AND ALLIED ACTIVITIES			
Approval Years:		2015			
PO Box No:					
Country:		Canada			
Status:					
Co Admin:		Kim D Zuraw			
Choice of Contact:		CO_OFFICIAL			
Phone No Admin:		519-853-0249 Ext.			
Contaminated Facility:		No			
MHSW Facility:		No			
<u>Detail(s)</u>					
Waste Class:		112			
Waste Class Name:		ACID WASTE - HEAVY METALS			
Waste Class:		131			
Waste Class Name:		NEUTRALIZED WASTES - HEAVY METALS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	37 of 49	NW/232.2	356.9 / 6.34	Zuraw Technologies Inc. 125 McDonald Blvd. Unit 1 Acton ON L7J 2V7	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON6399444 332810 COATING, ENGRAVING, HEAT TREATING AND ALLIED ACTIVITIES 2014 Canada Kim D Zuraw CO_OFFICIAL 519-853-0249 Ext. No No			
<u>Detail(s)</u>					
Waste Class:		131			
Waste Class Name:		NEUTRALIZED WASTES - HEAVY METALS			
Waste Class:		112			
Waste Class Name:		ACID WASTE - HEAVY METALS			
Waste Class:		122			
Waste Class Name:		ALKALINE WASTES - OTHER METALS			
80	38 of 49	NW/232.2	356.9 / 6.34	Mikia Printing Ltd 125 McDonald Blvd #3 Acton ON L7J 2V7	GEN
Generator No: SIC Code: SIC Description: Approval Years: PO Box No: Country: Status: Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:		ON8429412 323119 OTHER PRINTING 2014 Canada CO_OFFICIAL No No			
<u>Detail(s)</u>					
Waste Class:		145			
Waste Class Name:		PAINT/PIGMENT/COATING RESIDUES			
Waste Class:		252			
Waste Class Name:		WASTE OILS & LUBRICANTS			
Waste Class:		265			
Waste Class Name:		GRAPHIC ART WASTES			
80	39 of 49	NW/232.2	356.9 / 6.34	Frank Heller & Company Limited 125 Mcdonald Blvd Acton ON L7J2V7	GEN
Generator No: SIC Code: SIC Description:		ON7243697 			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Approval Years: As of Dec 2017 PO Box No: Country: Canada Status: Registered Co Admin: Choice of Contact: Phone No Admin: Contaminated Facility: MHSW Facility:					
<u>Detail(s)</u>					
Waste Class: 251 L Waste Class Name: Waste oils/sludges (petroleum based) Waste Class: 243 D Waste Class Name: PCB					
80	40 of 49	NW/232.2	356.9 / 6.34	DREXLER CONSTRUCTION LIMITED 125 McDonald BLVD Acton ON L7J 2V7	EASR
Approval No: R-009-4111176370 Status: REGISTERED Date: 2020-01-09 Record Type: EASR Link Source: MOFA Project Type: Water Taking - Construction Dewatering Full Address: Approval Type: EASR-Water Taking - Construction Dewatering SWP Area Name: Credit Valley PDF URL: PDF Site Location:					
MOE District: Halton-Peel Municipality: Acton Latitude: 43.63555556 Longitude: -80.04222222 Geometry X: Geometry Y:					
80	41 of 49	NW/232.2	356.9 / 6.34	FRANK HELLER & CO LIMITED 125 MCDONALD BOULEVARD ON Halton Hills ON	RSC
RSC No: 229850 RA No: Status: FILED Filing Date: Date Ack: Date Returned: Approval Date: 1631289153000 Cert Date: Cert Prop Use No: Curr Property Use: Intended Prop Use: Restoration Type: Soil Type: Criteria: Stratified (Y/N): Audit (Y/N): Entire Leg Prop. (Y/N): CPU Issued Sect 1686: Refresh Date: 1707874378000 Business Name: FRANK HELLER & CO LIMITED Address: 125 MCDONALD BOULEVARD ON Legal Desc:					
X: -80.0416245754009 Y: 43.6362103866086 Latitude: 43.63621039 Longitude: -80.04162458 UTM Coordinates: Latitude Longitude: Accuracy Estimate: Measurement Method: Mailing Address: Telephone: Fax: Email: Postal Code: L7J 2V7 Ministry District: MOE District: Halton-Peel SWP Area Name: Credit Valley Qual Person Name: MATTHEW NELSON Consultant:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Pin: Asmt Roll No: Project Type: Approval Type: Applicable Standards: Pdf Link:		25002-0448 (LT) POST2011 RSC based on Phase One and Two ESAs https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=229850			
80	42 of 49	NW/232.2	356.9 / 6.34	FRANK HELLER & CO LIMITED 125 MCDONALD BOULEVARD ON Halton Hills ON	RSC
RSC No: RA No: Status: Filing Date: Date Ack: Date Returned: Approval Date: Cert Date: Cert Prop Use No: Curr Property Use: Intended Prop Use: Restoration Type: Soil Type: Criteria: Stratified (Y/N): Audit (Y/N): Entire Leg Prop. (Y/N): CPU Issued Sect 1686: Refresh Date: Business Name: Address: Legal Desc: Site Pin: Asmt Roll No: Project Type: Approval Type: Applicable Standards: Pdf Link:		229544 FILED 1631185032000 1707874378000 FRANK HELLER & CO LIMITED 125 MCDONALD BOULEVARD ON 25002-0448 (LT) POST2011 RSC based on Phase One and Two ESAs https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=229544			
X: Y: Latitude: Longitude: UTM Coordinates: Latitude Longitude: Accuracy Estimate: Measurement Method: Mailing Address: Telephone: Fax: Email: Postal Code: Ministry District: MOE District: SWP Area Name: Qual Person Name: Consultant:		-80.04243553760847 43.63666738404282 43.63666738 -80.04243554 L7J 2V7 Halton-Peel Credit Valley MATTHEW NELSON			
80	43 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. lot 29 con 3 ACTON ON	WWIS
Well ID: Construction Date: Use 1st: Use 2nd: Final Well Status: Water Type: Casing Material: Audit No: Tag: Constructn Method: Elevation (m): Elevatn Reliability: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality:		7418964 Monitoring Observation Wells ZAVR8JTU A327753 HALTON HILLS TOWN (ESQUESING)			
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: Selected Flag: Abandonment Rec: Contractor: Form Version: Owner: County: Lot: Concession: Concession Name: Easting NAD83: Northing NAD83: Zone: UTM Reliability:		06/01/2022 TRUE 6607 9 HALTON 029 03 CON			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1009050272			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577266.00
Code OB Desc:				North83:	4831858.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/09/2022			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1009050392				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:	05				
Mat3 Desc:	CLAY				
Formation Top Depth:	0.0				
Formation End Depth:	25.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050453				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050482				
Layer:	1				
Plug From:	0.0				
Plug To:	1.0				
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050483				
Layer:	2				
Plug From:	1.0				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug To:		18.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1009050325			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1009050313			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1009050402			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		15.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1009050412			
Layer:		1			
Slot:		10			
Screen Top Depth:		15.0			
Screen End Depth:		25.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1009050314			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:		1009050433			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		25.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>80</u>	44 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. lot 29 con 3 ACTON ON	WWIS
Well ID:	7418925			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2022
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	6SSRSGGM			Contractor:	6607
Tag:	A344234			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1009049858			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577280.00
Code OB Desc:				North83:	4831847.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/09/2022			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1009050001				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				
Mat2:	06				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat2 Desc:		SILT			
Mat3:		05			
Mat3 Desc:		CLAY			
Formation Top Depth:		0.0			
Formation End Depth:		30.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050123			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050124			
Layer:		2			
Plug From:		1.0			
Plug To:		18.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050103			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1009049958			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1009049918			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1009050049			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		20.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Construction Record - Screen</u>					
Screen ID:	1009050066				
Layer:	1				
Slot:	10				
Screen Top Depth:	20.0				
Screen End Depth:	30.0				
Screen Material:	5				
Screen Depth UOM:	ft				
Screen Diameter UOM:	inch				
Screen Diameter:	2.5				
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:	1009049919				
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:	ft				
Rate UOM:	GPM				
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:	1009050083				
Diameter:	8.0				
Depth From:	0.0				
Depth To:	30.0				
Hole Depth UOM:	ft				
Hole Diameter UOM:	inch				
<u>80</u>	45 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. lot 29 con 3 ACTON ON	WWIS
Well ID:	7418931			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2022
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	A74SH7JX			Contractor:	6607
Tag:	A344299			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1009049876			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577271.00
Code OB Desc:				North83:	4831840.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/10/2022			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1009050017				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:	05				
Mat3 Desc:	CLAY				
Formation Top Depth:	0.0				
Formation End Depth:	28.5				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050109				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050131				
Layer:	2				
Plug From:	1.0				
Plug To:	16.5				
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050130				
Laver:	1				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1009049964			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1009049930			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1009050055			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		18.5			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1009050072			
Layer:		1			
Slot:		10			
Screen Top Depth:		18.5			
Screen End Depth:		28.5			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1009049931			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:		1009050089			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		28.5			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>80</u>	46 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. lot 29 con 3 ACTON ON	WWIS
Well ID:	7418932			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2022
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	GIIFTXQD			Contractor:	6607
Tag:	A327525			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1009049879			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577251.00
Code OB Desc:				North83:	4831873.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/12/2022			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:	1009050018				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		05			
Mat3 Desc:		CLAY			
Formation Top Depth:		0.0			
Formation End Depth:		23.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050132			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050133			
Layer:		2			
Plug From:		1.0			
Plug To:		11.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050110			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1009049965			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1009049932			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1009050056			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		13.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Construction Record - Screen</u>					
Screen ID:		1009050073			
Layer:		1			
Slot:		10			
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1009049933			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1009050090			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		23.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			

80	47 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. lot 29 con 3 ACTON ON	WWIS
Well ID:	7418934			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2022
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	I5XFWY4I			Contractor:	6607
Tag:	A347578			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1009049885			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577258.00
Code OB Desc:				North83:	4831866.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/10/2022			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1009050020				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:	05				
Mat3 Desc:	CLAY				
Formation Top Depth:	0.0				
Formation End Depth:	23.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050135				
Layer:	1				
Plug From:	0.0				
Plug To:	1.0				
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050136				
Layer:	2				
Plug From:	1.0				
Plug To:	16.5				
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1009050112				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1009049966			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1009049936			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1009050057			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		13.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1009050074			
Layer:		1			
Slot:		10			
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1009049937			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1009050092			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		23.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
80	48 of 49	NW/232.2	356.9 / 6.34	125 McDonald Blvd. lot 29 con 3 ACTON ON	WWIS
Well ID:	7418940			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2022
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	QMUBT4A5			Contractor:	6607
Tag:	A347548			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1009049903			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577271.00
Code OB Desc:				North83:	4831857.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	05/09/2022			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1009050039				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Most Common Material:					
Mat2:		FILL	06		
Mat2 Desc:		SILT			
Mat3:		05			
Mat3 Desc:		CLAY			
Formation Top Depth:		0.0			
Formation End Depth:		25.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050118			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050147			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1009050148			
Layer:		2			
Plug From:		1.0			
Plug To:		13.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1009049972			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1009049948			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1009050063			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		15.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1009050080			
Layer:		1			
Slot:		10			
Screen Top Depth:		15.0			
Screen End Depth:		25.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1009049949			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1009050098			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		25.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			

80	49 of 49	NW/232.2	356.9 / 6.34	125 MCDONALD BLVD. ACTON ON L7J2V7	NPR2
NPRI ID:	666			Latitude:	43.6354
Facility ID:	222883			Longitude:	-80.0429
Note:	Substances included on NPRI reports for this NPRI ID are summarized below in the NPRI ID Substances Summary section. Substances listed in the Substances Summary are included on the basis of NPRI ID only. For entities (NPRI ID) with mobile plants and/or more than one facility location, substances listed above may or may not have been reported for specific facilities/mobile locations. The list of substances additionally includes those which have been included on the NPRI report with an unknown quantity or a quantity of 0. For specific details about substance quantities, years, release/transfer/disposal methods, the reader is referred the facility report: https://pollution-waste.canada.ca/national-release-inventory/?fromYear=1993&toYear=2022&name=666				

<u>NPRI ID Substances Summary</u>					
CAS No:	108-88-3		Is PAH?:	FALSE	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Is VOC?:	TRUE			NPRI:	TRUE
Is DF?:	FALSE				
Name English:		Toluene			
Name French:		Toluène			
Sort English:		Toluene			
Sort French:		Toluène			
<u>Geographic Location</u>					
DLS Description:				Datum:	1983.0
NTS Description:	A-064-H/040-P-9			Forward Sort Area:	L7J
Latitude:	43.6354			SOMA:	TRUE
Longitude:	-80.0429			ON PEMA:	TRUE
Census Subdiv ID:	3524015			QC PEMA:	FALSE
Ecozone ID:	8			Quebec Windsor Corr:	TRUE
Water Survey ID:	2			Province Code:	ON
<u>NPRI ID Facility ID</u>					
NPRI ID:		666			
Facility ID:		222883			
<u>Facility</u>					
Facility ID:	222883			IDM ID:	0
Portable:	FALSE			AB Approval ID:	0
NAICS Primary:	316990			GHGRP ID:	0
NAICS Secondary:	0			ON GHGRP ID:	0
NAICS Tertiary:	0				
Facility Name:					
Website:					
<u>Address</u>					
Address1:		125 McDonald Blvd.			
Address2:					
City:		ACTON			
Postal Zip:		L7J2V7			
Prov:					
<u>Primary NAICS Details</u>					
NAICS Code:	316990			Start Date:	1993
Record Year:	1997			End Date:	2001
Key Indus Sector En:		Other Manufacturing			
Key Indus Sector Fr:		Autres fabrication			
NAICS Title En:		Other Leather and Allied Product Manufacturing			
NAICS Title Fr:		Fabrication d'autres produits en cuir et produits analogues			
NAICS Description En:					
NAICS Description Fr:					
NAICS Code:	316990			Start Date:	1993
Record Year:	2002			End Date:	2006
Key Indus Sector En:		Other Manufacturing			
Key Indus Sector Fr:		Autres fabrication			
NAICS Title En:		Other Leather and Allied Product Manufacturing			
NAICS Title Fr:		Fabrication d'autres produits en cuir et produits analogues			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
NAICS Description En:					
NAICS Description Fr:					
NAICS Code:	316990			Start Date:	1993
Record Year:	2007			End Date:	2011
Key Indus Sector En:		Other Manufacturing			
Key Indus Sector Fr:		Autres fabrication			
NAICS Title En:		Other Leather and Allied Product Manufacturing			
NAICS Title Fr:		Fabrication d'autres produits en cuir et produits analogues			
NAICS Description En:					
NAICS Description Fr:					
NAICS Code:	316990			Start Date:	1993
Record Year:	2012			End Date:	2016
Key Indus Sector En:		Other Manufacturing			
Key Indus Sector Fr:		Autres fabrication			
NAICS Title En:		Other leather and allied product manufacturing			
NAICS Title Fr:		Fabrication d'autres produits en cuir et produits analogues			
NAICS Description En:					
This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing leather and allied products. Some important products of this industry are luggage, handbags, purses, and small articles normally carried on the person or in a handbag, such as billfolds, key cases and coin purses of leather or other materials, except precious metal.					
NAICS Description Fr:					
Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale consiste à fabriquer des produits en cuir et des produits analogues. Parmi les principaux produits de cette classe, notons les valises, les sacs à main et les petits articles qu'une personne transporte habituellement sur elle ou dans un sac à main comme les porte-billets, les porte-clés et les porte-monnaie en cuir ou en d'autres matériaux, sauf en métal précieux.					
NAICS Code:	316990			Start Date:	2017
Record Year:	2017			End Date:	2021
Key Indus Sector En:		Other Manufacturing			
Key Indus Sector Fr:		Autres fabrication			
NAICS Title En:		Other leather and allied product manufacturing			
NAICS Title Fr:		Fabrication d'autres produits en cuir et produits analogues			
NAICS Description En:					
This Canadian industry comprises establishments, not classified to any other Canadian industry, primarily engaged in manufacturing leather and allied products. Some important products of this industry are small articles normally carried on the person or in a handbag, such as billfolds, key cases and coin purses of leather or other materials, except precious metal.					
NAICS Description Fr:					
Cette classe canadienne comprend les établissements qui ne figurent dans aucune autre classe canadienne et dont l'activité principale consiste à fabriquer des produits en cuir et des produits analogues. Parmi les principaux produits de cette classe sont les petits articles qu'une personne transporte habituellement sur elle ou dans un sac à main comme les porte-billets, les porte-clés et les porte-monnaie en cuir ou en d'autres matériaux, sauf en métal précieux.					
NPRI Report					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Report ID:	3765			Repor Type ID:	1
Report Year:	1994			New Reporter:	FALSE
NPRI ID:	666			No of Employees:	105
Company ID:	100745			Is Compressor:	FALSE
Facility ID:	222883			Is NPRI Part 4:	FALSE
SWR Report ID:	19940000000666			Is Battery:	FALSE
<u>Company</u>					
Company Name:		Blackhawk Leather Limited			
Trade Name En:					
Trade Name Fr:					
DUNS No:	0				
Website:					
<u>NPRI Report</u>					
Report ID:	2773			Repor Type ID:	1
Report Year:	1995			New Reporter:	FALSE
NPRI ID:	666			No of Employees:	90
Company ID:	100924			Is Compressor:	FALSE
Facility ID:	222883			Is NPRI Part 4:	FALSE
SWR Report ID:	19950000000666			Is Battery:	FALSE
<u>Company</u>					
Company Name:		Eagle Ottawa Canada, Ltd.			
Trade Name En:					
Trade Name Fr:					
DUNS No:	0				
Website:					
<u>NPRI Report</u>					
Report ID:	6719			Repor Type ID:	1
Report Year:	1993			New Reporter:	FALSE
NPRI ID:	666			No of Employees:	0
Company ID:	100745			Is Compressor:	FALSE
Facility ID:	222883			Is NPRI Part 4:	FALSE
SWR Report ID:	19930000000666			Is Battery:	FALSE
<u>Company</u>					
Company Name:		Blackhawk Leather Limited			
Trade Name En:					
Trade Name Fr:					
DUNS No:	0				
Website:					

81	1 of 1	NW/232.9	356.2 / 5.61	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7375843			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/15/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	TG2F3HAU			Contractor:	6607
Tag:	A293612			Form Version:	9

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:					
Site Info:					
HALTON HILLS TOWN (ESQUESING)					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008528966			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577261.00
Code OB Desc:				North83:	4831861.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/10/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008529109				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	05				
Most Common Material:	CLAY				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	0.0				
Formation End Depth:	23.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008529205				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008529243				
Laver:	1				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug From:		0.0			
Plug To:		11.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008529041			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008529010			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008529132			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		13.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008529152			
Layer:		1			
Slot:		250			
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008529011			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:	1008529183				
Diameter:	8.0				
Depth From:	0.0				
Depth To:	23.0				
Hole Depth UOM:	ft				
Hole Diameter UOM:	inch				
<u>Links</u>					
Bore Hole ID:	1008528966			Tag No:	A293612
Depth M:	7.0104			Contractor:	6607
Year Completed:	2020			Latitude:	43.6357288061932
Well Completed Dt:	11/10/2020			Longitude:	-80.0421777051985
Audit No:	TG2F3HAU			Y:	43.635728804520525
Path:	737\7375843.pdf			X:	-80.04217755515904
82	1 of 4	NW/233.1	355.6 / 5.00	125 McDonald Boulevard Acton ON L7J	EHS
Order No:	20290900329			Nearest Intersection:	
Status:	C			Municipality:	
Report Type:	RSC Report - Quote			Client Prov/State:	ON
Report Date:	18-SEP-20			Search Radius (km):	.3
Date Received:	09-SEP-20			X:	-80.04186658
Previous Site Name:	Disston, Heller			Y:	43.63591271
Lot/Building Size:					
Additional Info Ordered:	Aerial Photos				
82	2 of 4	NW/233.1	355.6 / 5.00	125 McDonald Boulevard Acton ON L7J	EHS
Order No:	20290900329			Nearest Intersection:	
Status:	C			Municipality:	
Report Type:	RSC Report - Quote			Client Prov/State:	ON
Report Date:	18-SEP-20			Search Radius (km):	.3
Date Received:	09-SEP-20			X:	-80.04186658
Previous Site Name:	Disston, Heller			Y:	43.63591271
Lot/Building Size:					
Additional Info Ordered:	Aerial Photos				
82	3 of 4	NW/233.1	355.6 / 5.00	125 McDonald Boulevard Acton ON L7J	EHS
Order No:	20290900329			Nearest Intersection:	
Status:	C			Municipality:	
Report Type:	RSC Report - Quote			Client Prov/State:	ON
Report Date:	18-SEP-20			Search Radius (km):	.3
Date Received:	09-SEP-20			X:	-80.04186658
Previous Site Name:	Disston, Heller			Y:	43.63591271
Lot/Building Size:					
Additional Info Ordered:	Aerial Photos				
82	4 of 4	NW/233.1	355.6 / 5.00	125 McDonald Boulevard Acton ON L7J	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Order No: 20290900329 Status: C Report Type: RSC Report - Quote Report Date: 18-SEP-20 Date Received: 09-SEP-20 Previous Site Name: Disston, Heller Lot/Building Size: Additional Info Ordered: Aerial Photos					
Nearest Intersection: Municipality: Client Prov/State: ON Search Radius (km): .3 X: -80.04186658 Y: 43.63591271					
83	1 of 2	E/233.4	353.9 / 3.31	163 Church Street Acton ON	EHS
Order No: 20070223028 Status: C Report Type: CAN - Basic Report Report Date: 3/6/2007 Date Received: 2/23/2007 Previous Site Name: Lot/Building Size: Additional Info Ordered: City Directory					
Nearest Intersection: Municipality: Client Prov/State: Search Radius (km): 0.25 X: -80.036217 Y: 43.633582					
83	2 of 2	E/233.4	353.9 / 3.31	163 CHURCH ST ACTON ON	WWIS
Well ID: 7142326 Construction Date: Use 1st: Use 2nd: Final Well Status: 0 Water Type: Casing Material: Audit No: M06724 Tag: A097810 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ACTON) Site Info:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 03/24/2010 Selected Flag: TRUE Abandonment Rec: Contractor: 7241 Form Version: 5 Owner: County: HALTON Lot: Concession: Concession Name: Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7142326.pdf					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date: 02/12/2010 Year Completed: 2010 Depth (m): Latitude: 43.6335576842636 Longitude: -80.0366832518956 Path: 714\7142326.pdf					
PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7142326.pdf					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date: 02/12/2010					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Year Completed:		2010			
Depth (m):					
Latitude:		43.6335403053591			
Longitude:		-80.036757909844			
Path:		714\7142326.pdf			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7142326.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		02/12/2010			
Year Completed:		2010			
Depth (m):					
Latitude:		43.6335567440855			
Longitude:		-80.0365716963973			
Path:		714\7142326.pdf			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7142326.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		02/12/2010			
Year Completed:		2010			
Depth (m):					
Latitude:		43.6335660603046			
Longitude:		-80.0366087377338			
Path:		714\7142326.pdf			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7142326.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		03/15/2010			
Year Completed:		2010			
Depth (m):					
Latitude:		43.6336301246017			
Longitude:		-80.0367316816335			
Path:		714\7142326.pdf			
PDF URL (Map):		https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/714\7142326.pdf			
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:		02/12/2010			
Year Completed:		2010			
Depth (m):					
Latitude:		43.6336301246017			
Longitude:		-80.0367316816335			
Path:		714\7142326.pdf			
<u>Bore Hole Information</u>					
Bore Hole ID:	1003288152			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577703.00
Code OB Desc:				North83:	4831633.00
Open Hole:				Org CS:	UTM83
Cluster Kind:	This is a record from cluster log sheet			UTMRC:	4
Date Completed:	02/12/2010			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:	on Water Well Record				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1003288156			
Layer:					
Plug From:					
Plug To:					
Plug Depth UOM:					
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1003288155			
Method Construction Code:					
Method Construction:					
Other Method Construction:		DIRECT PUSH			
<u>Pipe Information</u>					
Pipe ID:		1003288157			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1003288159			
Layer:					
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:					
Depth To:		13.0			
Casing Diameter:					
Casing Diameter UOM:					
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1003288158			
Layer:					
Slot:					
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:					
Screen Depth UOM:		ft			
Screen Diameter UOM:					
Screen Diameter:					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1003288160			
Pump Set At:					
Static Level:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Final Level After Pumping: Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: Rate UOM: Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1003288154			
Diameter:		10.920000076293945			
Depth From:					
Depth To:		23.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Bore Hole Information</u>					
Bore Hole ID:	1003288161			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577701.00
Code OB Desc:				North83:	4831623.00
Open Hole:				Org CS:	UTM83
Cluster Kind:	This is a record from cluster log sheet			UTMRC:	4
Date Completed:	02/12/2010			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1003288165			
Layer:					
Plug From:					
Plug To:					
Plug Depth UOM:					
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1003288164			
Method Construction Code:					
Method Construction:					
Other Method Construction:		DIRECT PUSH			
<u>Pipe Information</u>					
Pipe ID:		1003288166			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Casing No: Comment: Alt Name:		0			
<u>Construction Record - Casing</u>					
Casing ID:		1003288168			
Layer:					
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:					
Depth To:		12.0			
Casing Diameter:					
Casing Diameter UOM:					
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1003288167			
Layer:					
Slot:					
Screen Top Depth:		12.0			
Screen End Depth:		22.0			
Screen Material:					
Screen Depth UOM:		ft			
Screen Diameter UOM:					
Screen Diameter:					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1003288169			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:					
Rate UOM:					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1003288163			
Diameter:		10.920000076293945			
Depth From:					
Depth To:		22.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Bore Hole Information</u>					
Bore Hole ID:	1003288179			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Code OB:				East83:	577713.00
Code OB Desc:				North83:	4831626.00
Open Hole:				Org CS:	UTM83
Cluster Kind:	This is a record from cluster log sheet			UTMRC:	4
Date Completed:	02/12/2010			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:	1003288183				
Layer:					
Plug From:					
Plug To:					
Plug Depth UOM:					
 <u>Method of Construction & Well Use</u>					
Method Construction ID:	1003288182				
Method Construction Code:					
Method Construction:					
Other Method Construction:	DIRECT PUSH				
 <u>Pipe Information</u>					
Pipe ID:	1003288184				
Casing No:	0				
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:	1003288186				
Layer:					
Material:	5				
Open Hole or Material:	PLASTIC				
Depth From:					
Depth To:	14.0				
Casing Diameter:					
Casing Diameter UOM:					
Casing Depth UOM:	ft				
 <u>Construction Record - Screen</u>					
Screen ID:	1003288185				
Layer:					
Slot:					
Screen Top Depth:	14.0				
Screen End Depth:	24.0				
Screen Material:					
Screen Depth UOM:	ft				
Screen Diameter UOM:					
Screen Diameter:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:	1003288187				
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:					
Rate UOM:					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:	1003288181				
Diameter:	10.920000076293945				
Depth From:					
Depth To:	24.0				
Hole Depth UOM:	ft				
Hole Diameter UOM:	inch				
<u>Bore Hole Information</u>					
Bore Hole ID:	1003288170			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577707.00
Code OB Desc:				North83:	4831625.00
Open Hole:				Org CS:	UTM83
Cluster Kind:	This is a record from cluster log sheet			UTMRC:	4
Date Completed:	02/12/2010			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:	1003288174				
Layer:					
Plug From:					
Plug To:					
Plug Depth UOM:					
<u>Method of Construction & Well Use</u>					
Method Construction ID:	1003288173				
Method Construction Code:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction:					
Other Method Construction:		DIRECT PUSH			
<u>Pipe Information</u>					
Pipe ID:		1003288175			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1003288177			
Layer:					
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:					
Depth To:		14.0			
Casing Diameter:					
Casing Diameter UOM:					
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1003288176			
Layer:					
Slot:					
Screen Top Depth:		14.0			
Screen End Depth:		24.0			
Screen Material:					
Screen Depth UOM:		ft			
Screen Diameter UOM:					
Screen Diameter:					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1003288178			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:					
Rate UOM:					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1003288172			
Diameter:		10.920000076293945			
Depth From:					
Depth To:		24.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Bore Hole Information</u>					
Bore Hole ID:	1003288188			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577716.00
Code OB Desc:				North83:	4831625.00
Open Hole:				Org CS:	UTM83
Cluster Kind:	This is a record from cluster log sheet			UTMRC:	4
Date Completed:	02/12/2010			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	www
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:	1003288192				
Layer:					
Plug From:					
Plug To:					
Plug Depth UOM:					
<u>Method of Construction & Well Use</u>					
Method Construction ID:	1003288191				
Method Construction Code:					
Method Construction:					
Other Method Construction:	DIRECT PUSH				
<u>Pipe Information</u>					
Pipe ID:	1003288193				
Casing No:	0				
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:	1003288195				
Layer:					
Material:	5				
Open Hole or Material:	PLASTIC				
Depth From:					
Depth To:	14.0				
Casing Diameter:					
Casing Diameter UOM:					
Casing Depth UOM:	ft				
<u>Construction Record - Screen</u>					
Screen ID:	1003288194				
Layer:					
Slot:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Screen Top Depth:		14.0			
Screen End Depth:		24.0			
Screen Material:					
Screen Depth UOM:		ft			
Screen Diameter UOM:					
Screen Diameter:					
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1003288196			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:					
Rate UOM:					
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1003288190			
Diameter:		10.920000076293945			
Depth From:					
Depth To:		24.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Bore Hole Information</u>					
Bore Hole ID:	1002954105			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577703.00
Code OB Desc:				North83:	4831633.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	03/15/2010			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Method of Construction & Well Use</u>					
Method Construction ID:	1003288197				
Method Construction Code:					
Method Construction:					
Other Method Construction:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Links</u>					
Bore Hole ID:	1003288179			Tag No:	A097810
Depth M:				Contractor:	7241
Year Completed:	2010			Latitude:	43.6335660603046
Well Completed Dt:	02/12/2010			Longitude:	-80.0366087377338
Audit No:	M06724			Y:	43.63356605838459
Path:	714\7142326.pdf			X:	-80.03660858896018
<u>Links</u>					
Bore Hole ID:	1003288170			Tag No:	A097810
Depth M:				Contractor:	7241
Year Completed:	2010			Latitude:	43.6335576842636
Well Completed Dt:	02/12/2010			Longitude:	-80.0366832518956
Audit No:	M06724			Y:	43.63355768222927
Path:	714\7142326.pdf			X:	-80.03668310239345
<u>Links</u>					
Bore Hole ID:	1003288152			Tag No:	A097810
Depth M:				Contractor:	7241
Year Completed:	2010			Latitude:	43.6336301246017
Well Completed Dt:	02/12/2010			Longitude:	-80.0367316816335
Audit No:	M06724			Y:	43.63363012364625
Path:	714\7142326.pdf			X:	-80.03673153234516
<u>Links</u>					
Bore Hole ID:	1003288161			Tag No:	A097810
Depth M:				Contractor:	7241
Year Completed:	2010			Latitude:	43.6335403053591
Well Completed Dt:	02/12/2010			Longitude:	-80.036757909844
Audit No:	M06724			Y:	43.63354030314608
Path:	714\7142326.pdf			X:	-80.03675776045624
<u>Links</u>					
Bore Hole ID:	1003288188			Tag No:	A097810
Depth M:				Contractor:	7241
Year Completed:	2010			Latitude:	43.6335567440855
Well Completed Dt:	02/12/2010			Longitude:	-80.0365716963973
Audit No:	M06724			Y:	43.63355674272619
Path:	714\7142326.pdf			X:	-80.03657154694204
<u>Links</u>					
Bore Hole ID:	1002954105			Tag No:	A097810
Depth M:				Contractor:	7241
Year Completed:	2010			Latitude:	43.6336301246017
Well Completed Dt:	03/15/2010			Longitude:	-80.0367316816335
Audit No:	M06724			Y:	43.63363012364625
Path:	714\7142326.pdf			X:	-80.03673153234516
84	1 of 1	NW/234.8	356.9 / 6.30	125 McDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7352091			Flowing (Y/N):	
Construction Date:				Flow Rate:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	01/17/2020
Water Type:				Selected Flag:	TRUE
Casing Material:	QMBDFKWF			Abandonment Rec:	
Audit No:				Contractor:	6607
Tag:	A286918			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:				HALTON HILLS TOWN (ESQUESING)	
Site Info:	MW-1432				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7352091.pdf				
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:	01/08/2020				
Year Completed:	2020				
Depth (m):	3.81				
Latitude:	43.6355420315774				
Longitude:	-80.0424534090033				
Path:	735\7352091.pdf				
<u>Bore Hole Information</u>					
Bore Hole ID:	1007988049			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577239.00
Code OB Desc:				North83:	4831840.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	01/08/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1007988942				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	01				
Most Common Material:	FILL				
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:	0.0				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Formation End Depth:		1.2000000476837158			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007988943			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.2000000476837158			
Formation End Depth:		3.809999942779541			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989508			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989748			
Layer:		1			
Plug From:		0.0			
Plug To:		1.6699999570846558			
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007988488			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007988356			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007989110			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		2.2799999713897705			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Casing Diameter: 5.099999904632568 Casing Diameter UOM: cm Casing Depth UOM: m					
Construction Record - Screen					
Screen ID: 1007989245 Layer: 1 Slot: 10 Screen Top Depth: 2.2799999713897705 Screen End Depth: 3.809999942779541 Screen Material: 5 Screen Depth UOM: m Screen Diameter UOM: cm Screen Diameter: 6.400000095367432					
Results of Well Yield Testing					
Pumping Test Method Desc: Pump Test ID: 1007988357 Pump Set At: Static Level: Final Level After Pumping: Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: m Rate UOM: LPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
Hole Diameter					
Hole ID: 1007989360 Diameter: 21.0 Depth From: 0.0 Depth To: 3.809999942779541 Hole Depth UOM: m Hole Diameter UOM: cm					
Links					
Bore Hole ID: 1007988049 Depth M: 3.81 Year Completed: 2020 Well Completed Dt: 01/08/2020 Audit No: QMBDFKWF Path: 735\7352091.pdf					
Tag No: A286918 Contractor: 6607 Latitude: 43.6355420315774 Longitude: -80.0424534090033 Y: 43.63554203037308 X: -80.04245325972704					
85	1 of 1	NW/235.0	356.9 / 6.34	ON	WWIS
Well ID: 7310917 Construction Date: Use 1st: Use 2nd: Final Well Status:					
Flowing (Y/N): Flow Rate: Data Entry Status: Yes Data Src: Date Received: 05/10/2018					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Water Type: Casing Material: Audit No: C38506 Tag: A237224 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: HALTON HILLS TOWN (ACTON) Site Info: Selected Flag: TRUE Abandonment Rec: Contractor: 7238 Form Version: 8 Owner: County: HALTON Lot: Concession: Concession Name: Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
PDF URL (Map):					
Additional Detail(s) (Map)					
Well Completed Date: 03/29/2018 Year Completed: 2018 Depth (m): Latitude: 43.6355777313682 Longitude: -80.0424156506621 Path:					
Bore Hole Information					
Bore Hole ID: 1007044758 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 03/29/2018 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment: Elevation: Elevrc: Zone: 17 East83: 577242.00 North83: 4831844.00 Org CS: UTM83 UTMRC: 4 UTMRC Desc: margin of error : 30 m - 100 m Location Method: wwr					
Links					
Bore Hole ID: 1007044758 Depth M: Year Completed: 2018 Well Completed Dt: 03/29/2018 Audit No: C38506 Path: Tag No: A237224 Contractor: 7238 Latitude: 43.6355777313682 Longitude: -80.0424156506621 Y: 43.63557772944876 X: -80.04241550174781					
86	1 of 1	NW/237.8	356.9 / 6.34	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7388623 Construction Date: Use 1st: Monitoring Use 2nd: Flowing (Y/N): Flow Rate: Data Entry Status: Data Src:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Final Well Status:	Observation Wells			Date Received:	06/01/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	LTPRR394			Contractor:	6607
Tag:	A313600			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					

Bore Hole Information

Bore Hole ID:	1008657888	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577255.00
Code OB Desc:		North83:	4831862.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	05/27/2021	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1008657993
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	61
Mat2 Desc:	CLAYEY
Mat3:	66
Mat3 Desc:	DENSE
Formation Top Depth:	0.0
Formation End Depth:	24.5
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1008658054
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658081			
Layer:		2			
Plug From:		1.0			
Plug To:		12.5			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008658080			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1008657943			
Method Construction Code:		E			
Method Construction:		Auger			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1008657923			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008658009			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		14.5			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008658022			
Layer:		1			
Slot:		10			
Screen Top Depth:		14.5			
Screen End Depth:		24.5			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657924			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pump Set At: Static Level: Final Level After Pumping: Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: ft Rate UOM: GPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Water Details</u>					
Water ID: 1008657970 Layer: 1 Kind Code: 8 Kind: Untested Water Found Depth: 10.0 Water Found Depth UOM: ft					
<u>Hole Diameter</u>					
Hole ID: 1008658039 Diameter: 8.0 Depth From: 0.0 Depth To: 24.5 Hole Depth UOM: ft Hole Diameter UOM: inch					
<u>Links</u>					
Bore Hole ID: 1008657888 Depth M: 7.4676 Year Completed: 2021 Well Completed Dt: 05/27/2021 Audit No: LTPRR394 Path: 738\7388623.pdf					
Tag No: A313600 Contractor: 6607 Latitude: 43.6357384321939 Longitude: -80.0422519353336 Y: 43.635738430614715 X: -80.04225178562147					

87	1 of 1	NW/238.8	356.8 / 6.28	125 MC DONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID: 7375863 Construction Date: Use 1st: Monitoring Use 2nd: Final Well Status: Observation Wells Water Type: Casing Material: Audit No: O5LOFI9M Tag: A293613 Constructn Method: Elevation (m): Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate:					
Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 12/15/2020 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 9 Owner: County: HALTON Lot: 029 Concession: 03 Concession Name: CON Easting NAD83: Northing NAD83:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Static Water Level: Clear/Cloudy: Municipality: Site Info:				Zone: UTM Reliability:	
HALTON HILLS TOWN (ESQUESING)					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008529388			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577233.00
Code OB Desc:				North83:	4831839.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/10/2020			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008529489				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	05				
Most Common Material:	CLAY				
Mat2:	06				
Mat2 Desc:	SILT				
Mat3:					
Mat3 Desc:					
Formation Top Depth:	0.0				
Formation End Depth:	13.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008529607				
Layer:	1				
Plug From:	0.0				
Plug To:	6.0				
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008529557				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
<u>Method of Construction & Well</u>					
<u>Use</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction ID:		1008529450			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008529438			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008529509			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		8.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1008529529			
Layer:		1			
Slot:		250			
Screen Top Depth:		8.0			
Screen End Depth:		13.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008529439			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
 <u>Hole Diameter</u>					
Hole ID:		1008529534			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		13.0			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
Links					
Bore Hole ID:	1008529388			Tag No:	A293613
Depth M:	3.9624			Contractor:	6607
Year Completed:	2020			Latitude:	43.6355336517442
Well Completed Dt:	11/10/2020			Longitude:	-80.0425279248667
Audit No:	O5LOFI9M			Y:	43.635533650592244
Path:	737\7375863.pdf			X:	-80.04252777585526

88	1 of 1	NW/242.8	356.9 / 6.34	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7337180			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	07/18/2019
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	H4VP3OGG			Contractor:	6607
Tag:	A245819			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW 3003				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/733\7337180.pdf				

Additional Detail(s) (Map)

Well Completed Date: 07/09/2019
Year Completed: 2019
Depth (m): 6
Latitude: 43.6357213612139
Longitude: -80.0423637810148
Path: 733\7337180.pdf

Bore Hole Information

Bore Hole ID:	1007507094	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	577246.00
Code OB Desc:		North83:	4831860.00
Open Hole:		Org CS:	UTM83
Cluster Kind:		UTMRC:	4
Date Completed:	07/09/2019	UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:		Location Method:	wwr
Loc Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507737			
Layer:		2			
Color:		7			
General Color:		RED			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		05			
Mat2 Desc:		CLAY			
Mat3:		79			
Mat3 Desc:		PACKED			
Formation Top Depth:		1.600000023841858			
Formation End Depth:		6.0			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007507736			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		1.600000023841858			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007508292			
Layer:		1			
Plug From:		0.0			
Plug To:		2.4000000953674316			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007508176			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007507454			
Method Construction Code:		6			
Method Construction:		Boring			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007507276			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007507901			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		3.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
<u>Construction Record - Screen</u>					
Screen ID:		1007507985			
Layer:		1			
Slot:		10			
Screen Top Depth:		3.0			
Screen End Depth:		6.0			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007507277			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		m			
Rate UOM:		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1007507619			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		3.5999999046325684			
Water Found Depth UOM:		m			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:	1007508074				
Diameter:	21.0				
Depth From:	0.0				
Depth To:	6.0				
Hole Depth UOM:	m				
Hole Diameter UOM:	cm				
<u>Links</u>					
Bore Hole ID:	1007507094			Tag No:	A245819
Depth M:	6			Contractor:	6607
Year Completed:	2019			Latitude:	43.6357213612139
Well Completed Dt:	07/09/2019			Longitude:	-80.0423637810148
Audit No:	H4VP3OGG			Y:	43.635721359684034
Path:	733\7337180.pdf			X:	-80.04236363123024
89	1 of 1	NW/244.2	356.9 / 6.34	125 McDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7352065			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring and Test Hole			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	01/17/2020
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	I33MCGBC			Contractor:	6607
Tag:	A286920			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW-1428				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7352065.pdf				
<u>Additional Detail(s) (Map)</u>					
Well Completed Date:	01/06/2020				
Year Completed:	2020				
Depth (m):	7.46				
Latitude:	43.6357927607178				
Longitude:	-80.0422882639542				
Path:	735\7352065.pdf				
<u>Bore Hole Information</u>					
Bore Hole ID:	1007987971			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577252.00
Code OB Desc:				North83:	4831868.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Date Completed:		01/06/2020		UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:		on Water Well Record			
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988863			
Layer:		4			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		5.329999923706055			
Formation End Depth:		7.460000038146973			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988861			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		1.5			
Formation End Depth:		3.809999942779541			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1007988860			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		01			
Most Common Material:		FILL			
Mat2:					
Mat2 Desc:					
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		1.5			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Materials Interval</u>					
Formation ID:		1007988862			
Layer:		3			
Color:		7			
General Color:		RED			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		3.809999942779541			
Formation End Depth:		5.329999923706055			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989808			
Layer:		1			
Plug From:		0.0			
Plug To:		3.809999942779541			
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989809			
Layer:		2			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007989482			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
<u>Method of Construction & Well Use</u>					
Method Construction ID:		1007988463			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:		1007988304			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1007989085			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:					
		1			
Material:					
		5			
Open Hole or Material:					
		PLASTIC			
Depth From:					
		0.0			
Depth To:					
		4.409999847412109			
Casing Diameter:					
		5.099999904632568			
Casing Diameter UOM:					
		cm			
Casing Depth UOM:					
		m			
<u>Construction Record - Screen</u>					
Screen ID:					
		1007989220			
Layer:					
		1			
Slot:					
		10			
Screen Top Depth:					
		4.409999847412109			
Screen End Depth:					
		7.460000038146973			
Screen Material:					
		5			
Screen Depth UOM:					
		m			
Screen Diameter UOM:					
		cm			
Screen Diameter:					
		6.400000095367432			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
		1007988305			
Pump Test ID:					
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:					
		m			
Rate UOM:					
		LPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Hole Diameter</u>					
Hole ID:					
		1007989334			
Diameter:					
		21.0			
Depth From:					
		0.0			
Depth To:					
		7.460000038146973			
Hole Depth UOM:					
		m			
Hole Diameter UOM:					
		cm			
<u>Links</u>					
Bore Hole ID:					
		1007987971		Tag No:	A286920
Depth M:					
		7.46		Contractor:	6607
Year Completed:					
		2020		Latitude:	43.6357927607178
Well Completed Dt:					
		01/06/2020		Longitude:	-80.0422882639542
Audit No:					
		I33MCGBC		Y:	43.63579275955153
Path:					
		735\7352065.pdf		X:	-80.04228811437345
90	1 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Eastern Avenue	ECA

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Halton Hills ON L6M 3L1					
Approval No:	3584-6MXLS3			MOE District:	Halton-Peel
Approval Date:	2006-03-28			City:	
Status:	Approved			Longitude:	-80.0363
Record Type:	ECA			Latitude:	43.6345
Link Source:	IDS			Geometry X:	
SWP Area Name:	Credit Valley			Geometry Y:	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS				
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS				
Business Name:	The Regional Municipality of Halton				
Address:	Eastern Avenue				
Full Address:					
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/9743-6MWRNL-14.pdf				
PDF Site Location:					
90	2 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Agnes Street, Willow Street, John Street, Elgin Street, Frederick Street Halton Hills ON L6M 3L1	ECA
Approval No:	4308-5B9HGQ			MOE District:	Halton-Peel
Approval Date:	2002-06-19			City:	
Status:	Approved			Longitude:	-80.0363
Record Type:	ECA			Latitude:	43.6345
Link Source:	IDS			Geometry X:	
SWP Area Name:	Credit Valley			Geometry Y:	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS				
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS				
Business Name:	The Regional Municipality of Halton				
Address:	Agnes Street, Willow Street, John Street, Elgin Street, Frederick Street				
Full Address:					
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3870-5B4H9U-14.pdf				
PDF Site Location:					
90	3 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Fellows Street from Mill Street to Church St Acton Halton Hills ON L6M 3L1	ECA
Approval No:	1543-889RQ9			MOE District:	Halton-Peel
Approval Date:	2010-08-31			City:	
Status:	Approved			Longitude:	-80.0363
Record Type:	ECA			Latitude:	43.6345
Link Source:	IDS			Geometry X:	
SWP Area Name:	Credit Valley			Geometry Y:	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS				
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS				
Business Name:	The Regional Municipality of Halton				
Address:	Fellows Street from Mill Street to Church St Acton				
Full Address:					
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/6364-887NN8-14.pdf				
PDF Site Location:					
90	4 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Arthur Street, Acton Halton Hills ON L6M 3L1	ECA
Approval No:	3085-5AYJSU			MOE District:	Halton-Peel
Approval Date:	2002-06-10			City:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Status: Approved Record Type: ECA Link Source: IDS SWP Area Name: Credit Valley Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS Business Name: The Regional Municipality of Halton Address: Arthur Street, Acton Full Address: Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7728-5ASPXW-14.pdf PDF Site Location:					
90	5 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Mill Street, Perth Street and Peel Street Halton Hills ON L6M 3L1	ECA
Approval No: 7657-7FZR3F Approval Date: 2008-07-03 Status: Approved Record Type: ECA Link Source: IDS SWP Area Name: Credit Valley Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS Business Name: The Regional Municipality of Halton Address: Mill Street, Perth Street and Peel Street Full Address: Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7560-7FZGSL-14.pdf PDF Site Location:					
90	6 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Eastern Avenue Halton Hills ON L6M 3L1	ECA
Approval No: 3631-6MXLP2 Approval Date: 2006-03-28 Status: Approved Record Type: ECA Link Source: IDS SWP Area Name: Credit Valley Approval Type: ECA-Municipal Drinking Water Systems Project Type: Municipal Drinking Water Systems Business Name: The Regional Municipality of Halton Address: Eastern Avenue Full Address: Full PDF Link: PDF Site Location:					
90	7 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Mill Street, Perth Street and Peel Street Halton Hills ON L6M 3L1	ECA
Approval No: 5076-7FZQDT Approval Date: 2008-07-03 Status: Approved Record Type: ECA Link Source: IDS SWP Area Name: Credit Valley Approval Type: ECA-Municipal Drinking Water Systems Project Type: Municipal Drinking Water Systems					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Business Name: Address: Full Address: Full PDF Link: PDF Site Location:		The Regional Municipality of Halton Mill Street, Perth Street and Peel Street			
90	8 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street Halton Hills ON L6M 3L1	ECA
Approval No: Approval Date: Status: Record Type: Link Source: SWP Area Name: Approval Type: Project Type: Business Name: Address: Full Address: Full PDF Link: PDF Site Location:		5272-659RTT 2004-10-29 Approved ECA IDS Credit Valley ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS MUNICIPAL AND PRIVATE SEWAGE WORKS The Regional Municipality of Halton Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street https://www.accessenvironment.ene.gov.on.ca/instruments/6675-655J4S-14.pdf			
90	9 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street Halton Hills ON L6M 3L1	ECA
Approval No: Approval Date: Status: Record Type: Link Source: SWP Area Name: Approval Type: Project Type: Business Name: Address: Full Address: Full PDF Link: PDF Site Location:		3145-659RYQ 2004-10-29 Approved ECA IDS Credit Valley ECA-Municipal Drinking Water Systems Municipal Drinking Water Systems The Regional Municipality of Halton Mill Street, John Street, Elgin Street, Frederick Street and Wilbur Street			
90	10 of 10	ENE/245.3	352.9 / 2.31	The Regional Municipality of Halton Agnes Street Halton Hills ON L6M 3L1	ECA
Approval No: Approval Date: Status: Record Type: Link Source: SWP Area Name: Approval Type: Project Type: Business Name: Address: Full Address: Full PDF Link:		0880-5B9H8L 2002-06-19 Approved ECA IDS Credit Valley ECA-Municipal and Private Water Works Municipal and Private Water Works The Regional Municipality of Halton Agnes Street			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
PDF Site Location:					
91	1 of 1	S/245.6	350.8 / 0.22	40 Mill St. East Acton ON L7J 1H2	EHS
Order No:	20000613001		Nearest Intersection:	Willow and Mill St. East	
Status:	C		Municipality:	Halton	
Report Type:	Complete Report		Client Prov/State:	ON	
Report Date:	6/16/00		Search Radius (km):	0.25	
Date Received:	6/13/00		X:	-80.040207	
Previous Site Name:			Y:	43.630593	
Lot/Building Size:					
Additional Info Ordered:					
92	1 of 1	NW/246.4	357.3 / 6.79	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7350956		Flowing (Y/N):		
Construction Date:			Flow Rate:		
Use 1st:	Monitoring and Test Hole		Data Entry Status:		
Use 2nd:			Data Src:		
Final Well Status:	Observation Wells		Date Received:	12/20/2019	
Water Type:			Selected Flag:	TRUE	
Casing Material:			Abandonment Rec:		
Audit No:	BIE8D9B2		Contractor:	6607	
Tag:	A286958		Form Version:	9	
Constructn Method:			Owner:		
Elevation (m):			County:	HALTON	
Elevatn Reliabilty:			Lot:	029	
Depth to Bedrock:			Concession:	03	
Well Depth:			Concession Name:	CON	
Overburden/Bedrock:			Easting NAD83:		
Pump Rate:			Northing NAD83:		
Static Water Level:			Zone:		
Clear/Cloudy:			UTM Reliability:		
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:	MW 1426				
PDF URL (Map):	https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/735\7350956.pdf				
Additional Detail(s) (Map)					
Well Completed Date:	12/13/2019				
Year Completed:	2019				
Depth (m):	3.58				
Latitude:	43.6356416856641				
Longitude:	-80.0425262094001				
Path:	735\7350956.pdf				
Bore Hole Information					
Bore Hole ID:	1007854435		Elevation:		
DP2BR:			Elevrc:		
Spatial Status:			Zone:	17	
Code OB:			East83:	577233.00	
Code OB Desc:			North83:	4831851.00	
Open Hole:			Org CS:	UTM83	
Cluster Kind:			UTMRC:	4	
Date Completed:	12/13/2019		UTMRC Desc:	margin of error : 30 m - 100 m	
Remarks:					
Loc Method Desc:	on Water Well Record				

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment:					
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855050			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		01			
Mat3 Desc:		FILL			
Formation Top Depth:		0.0			
Formation End Depth:		0.8999999761581421			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855051			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.8999999761581421			
Formation End Depth:		2.4000000953674316			
Formation End Depth UOM:		m			
<u>Overburden and Bedrock Materials Interval</u>					
Formation ID:		1007855052			
Layer:		3			
Color:		2			
General Color:		GREY			
Mat1:		05			
Most Common Material:		CLAY			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		34			
Mat3 Desc:		TILL			
Formation Top Depth:		2.4000000953674316			
Formation End Depth:		3.5799999237060547			
Formation End Depth UOM:		m			
<u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855665			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		1			
Plug From:		0.0			
Plug To:		1.440000057220459			
Plug Depth UOM:		m			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1007855485			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		m			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1007854774			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1007854663			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1007855204			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		2.0399999618530273			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		cm			
Casing Depth UOM:		m			
 <u>Construction Record - Screen</u>					
Screen ID:		1007855301			
Layer:		1			
Slot:		10			
Screen Top Depth:		2.0399999618530273			
Screen End Depth:		3.5799999237060547			
Screen Material:		5			
Screen Depth UOM:		m			
Screen Diameter UOM:		cm			
Screen Diameter:		6.400000095367432			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1007854664			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: m Rate UOM: LPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
Hole Diameter					
Hole ID:		1007855380			
Diameter:		21.0			
Depth From:		0.0			
Depth To:		3.5799999237060547			
Hole Depth UOM:		m			
Hole Diameter UOM:		cm			
Links					
Bore Hole ID:	1007854435			Tag No:	A286958
Depth M:	3.58			Contractor:	6607
Year Completed:	2019			Latitude:	43.6356416856641
Well Completed Dt:	12/13/2019			Longitude:	-80.0425262094001
Audit No:	BIE8D9B2			Y:	43.635641684640504
Path:	735\7350956.pdf			X:	-80.0425260591656
93	1 of 1	NW/247.0	356.9 / 6.34	125 MCDONALD BLVD lot 29 con 3 ACTON ON	WWIS
Well ID:	7388618			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	06/01/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	CB3NFQ3T			Contractor:	6607
Tag:	A313625			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliabilty:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
Bore Hole Information					
Bore Hole ID:	1008657873			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577247.00
Code OB Desc:				North83:	4831867.00
Open Hole:				Org CS:	UTM83

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Cluster Kind:				UTMRC:	4
Date Completed:	05/27/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:	1008657986				
Layer:	1				
Color:	6				
General Color:	BROWN				
Mat1:	06				
Most Common Material:	SILT				
Mat2:	61				
Mat2 Desc:	CLAYEY				
Mat3:	66				
Mat3 Desc:	DENSE				
Formation Top Depth:	0.0				
Formation End Depth:	23.0				
Formation End Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658049				
Layer:	1				
Plug From:					
Plug To:					
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658070				
Layer:	1				
Plug From:	0.0				
Plug To:	1.0				
Plug Depth UOM:	ft				
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:	1008658071				
Layer:	2				
Plug From:	1.0				
Plug To:	11.0				
Plug Depth UOM:	ft				
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:	1008657937				
Method Construction Code:	E				
Method Construction:	Auger				
Other Method Construction:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Pipe Information</u>					
Pipe ID:		1008657913			
Casing No:		0			
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:		1008658004			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		13.0			
Casing Diameter:		2.0			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
<u>Construction Record - Screen</u>					
Screen ID:		1008658017			
Layer:		1			
Slot:		10			
Screen Top Depth:		13.0			
Screen End Depth:		23.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		2.5			
<u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008657914			
Pump Set At:					
Static Level:					
Final Level After Pumping:					
Recommended Pump Depth:					
Pumping Rate:					
Flowing Rate:					
Recommended Pump Rate:					
Levels UOM:		ft			
Rate UOM:		GPM			
Water State After Test Code:					
Water State After Test:					
Pumping Test Method:					
Pumping Duration HR:					
Pumping Duration MIN:					
Flowing:					
<u>Water Details</u>					
Water ID:		1008657965			
Layer:		1			
Kind Code:		8			
Kind:		Untested			
Water Found Depth:		10.0			
Water Found Depth UOM:		ft			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Hole Diameter</u>					
Hole ID:		1008658033			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		23.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008657873			Tag No:	A313625
Depth M:	7.0104			Contractor:	6607
Year Completed:	2021			Latitude:	43.6357842771484
Well Completed Dt:	05/27/2021			Longitude:	-80.0423503846151
Audit No:	CB3NFQ3T			Y:	43.63578427578149
Path:	738\7388618.pdf			X:	-80.04235023555134
<u>94</u>	1 of 1	NW/247.0	356.9 / 6.34	125 MCDONALD BLVD. lot 29 con 3 ACTON ON	WWIS
Well ID:	7406694			Flowing (Y/N):	
Construction Date:				Flow Rate:	
Use 1st:	Monitoring			Data Entry Status:	
Use 2nd:				Data Src:	
Final Well Status:	Observation Wells			Date Received:	12/24/2021
Water Type:				Selected Flag:	TRUE
Casing Material:				Abandonment Rec:	
Audit No:	4BO8QGPGC			Contractor:	6607
Tag:	A327850			Form Version:	9
Constructn Method:				Owner:	
Elevation (m):				County:	HALTON
Elevatn Reliability:				Lot:	029
Depth to Bedrock:				Concession:	03
Well Depth:				Concession Name:	CON
Overburden/Bedrock:				Easting NAD83:	
Pump Rate:				Northing NAD83:	
Static Water Level:				Zone:	
Clear/Cloudy:				UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)				
Site Info:					
<u>Bore Hole Information</u>					
Bore Hole ID:	1008898569			Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	17
Code OB:				East83:	577249.00
Code OB Desc:				North83:	4831869.00
Open Hole:				Org CS:	UTM83
Cluster Kind:				UTMRC:	4
Date Completed:	11/24/2021			UTMRC Desc:	margin of error : 30 m - 100 m
Remarks:				Location Method:	wwr
Loc Method Desc:	on Water Well Record				
Elevrc Desc:					
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
<u>Overburden and Bedrock</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
<u>Materials Interval</u>					
Formation ID:		1008898721			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:		77			
Mat3 Desc:		LOOSE			
Formation Top Depth:		0.0			
Formation End Depth:		10.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008898722			
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		06			
Mat2 Desc:		SILT			
Mat3:		77			
Mat3 Desc:		LOOSE			
Formation Top Depth:		10.0			
Formation End Depth:		15.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1008898723			
Layer:		3			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		77			
Mat3 Desc:		LOOSE			
Formation Top Depth:		15.0			
Formation End Depth:		21.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1008898827			
Layer:		1			
Plug From:					
Plug To:					
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Plug ID:		1008898848			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
 <u>Annular Space/Abandonment Sealing Record</u>					
Plug ID:		1008898849			
Layer:		2			
Plug From:		1.0			
Plug To:		9.0			
Plug Depth UOM:		ft			
 <u>Method of Construction & Well Use</u>					
Method Construction ID:		1008898667			
Method Construction Code:		6			
Method Construction:		Boring			
Other Method Construction:					
 <u>Pipe Information</u>					
Pipe ID:		1008898628			
Casing No:		0			
Comment:					
Alt Name:					
 <u>Construction Record - Casing</u>					
Casing ID:		1008898767			
Layer:		1			
Material:		5			
Open Hole or Material:		PLASTIC			
Depth From:		0.0			
Depth To:		11.0			
Casing Diameter:		5.099999904632568			
Casing Diameter UOM:		inch			
Casing Depth UOM:		ft			
 <u>Construction Record - Screen</u>					
Screen ID:		1008898787			
Layer:		1			
Slot:		10			
Screen Top Depth:		11.0			
Screen End Depth:		21.0			
Screen Material:		5			
Screen Depth UOM:		ft			
Screen Diameter UOM:		inch			
Screen Diameter:		6.099999904632568			
 <u>Results of Well Yield Testing</u>					
Pumping Test Method Desc:					
Pump Test ID:		1008898629			
Pump Set At:					
Static Level:					
Final Level After Pumping:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Recommended Pump Depth: Pumping Rate: Flowing Rate: Recommended Pump Rate: Levels UOM: ft Rate UOM: GPM Water State After Test Code: Water State After Test: Pumping Test Method: Pumping Duration HR: Pumping Duration MIN: Flowing:					
<u>Hole Diameter</u>					
Hole ID:		1008898807			
Diameter:		8.0			
Depth From:		0.0			
Depth To:		21.0			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			
<u>Links</u>					
Bore Hole ID:	1008898569			Tag No:	A327850
Depth M:	6.4008			Contractor:	6607
Year Completed:	2021			Latitude:	43.6358020751016
Well Completed Dt:	11/24/2021			Longitude:	-80.0423253075741
Audit No:	4B08QGPC			Y:	43.635802073563056
Path:	740\7406694.pdf			X:	-80.04232515818823
95	1 of 2	SSE/247.5	351.9 / 1.34	Enbridge Energy Distribution Inc. 64 Church Street Halton Hills ON	SPL
Ref No:	5703-BJ6K6M			Municipality No:	
Year:				Nature of Damage:	
Incident Dt:	11/22/2019			Discharger Report:	
Dt MOE Arvl on Scn:				Material Group:	
MOE Reported Dt:	11/22/2019			Health/Env Conseq:	2 - Minor Environment
Dt Document Closed:				Agency Involved:	
Site No:	NA				
MOE Response:	No				
Site County/District:	Regional Municipality of Halton				
Site Geo Ref Meth:					
Site District Office:	Halton-Peel				
Nearest Watercourse:					
Site Name:	church<UNOFFICIAL>				
Site Address:	64 Church Street				
Site Region:	Central				
Site Municipality:	Halton Hills				
Site Lot:					
Site Conc:					
Site Geo Ref Accu:					
Site Map Datum:					
Northing:					
Easting:					
Incident Cause:					
Incident Event:	Leak/Break				
Environment Impact:					
Nature of Impact:					
Contaminant Qty:	1 other - see incident description				
System Facility Address:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Client Name: Enbridge Energy Distribution Inc. Client Type: Corporation Source Type: Pipeline/Components Contaminant Code: 35 Contaminant Name: NATURAL GAS (METHANE) Contaminant Limit 1: Contam Limit Freq 1: Contaminant UN No 1: 1075 Receiving Medium: Air Incident Reason: Operator/Human Error Incident Summary: TSSA FSB: 1.25" IP plastic line dmg; made safe Activity Preceding Spill: Property 2nd Watershed: Property Tertiary Watershed: Sector Type: Miscellaneous Communal SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill Call Report Locatn Geodata:					
95	2 of 2	SSE/247.5	351.9 / 1.34	ENBRIDGE GAS INC 64 CHURCH ST E,,HALTON HILLS,ON,L7J 1K7, CA ON	PINC
Incident Id: Incident No: 2726432 Incident Reported Dt: 11/22/2019 Type: FS-Pipeline Incident Status Code: Tank Status: Pipeline Damage Reason Est Task No: Spills Action Centre: Fuel Type: Fuel Occurrence Tp: Date of Occurrence: Occurrence Start Dt: Depth: Customer Acct Name: ENBRIDGE GAS INC Incident Address: 64 CHURCH ST E,,HALTON HILLS,ON,L7J 1K7,CA Operation Type: Pipeline Type: Regulator Type: Summary: Reported By: Affiliation: Occurrence Desc: Damage Reason: Notes:					
Pipe Material: Fuel Category: Health Impact: Environment Impact: Property Damage: Service Interrupt: Enforce Policy: Public Relation: Pipeline System: PSIG: Attribute Category: Regulator Location: Method Details:					
96	1 of 1	SSW/247.8	350.9 / 0.31	ON	WWIS
Well ID: 7188674 Construction Date: Use 1st: Use 2nd: Final Well Status: Water Type: Casing Material: Audit No: C17997 Tag: A126157 Constructn Method: Elevation (m):					
Flowing (Y/N): Flow Rate: Data Entry Status: Yes Data Src: Date Received: 06/18/2012 Selected Flag: TRUE Abandonment Rec: Contractor: 6607 Form Version: 8 Owner: County: HALTON					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Elevatn Reliabilty: Depth to Bedrock: Well Depth: Overburden/Bedrock: Pump Rate: Static Water Level: Clear/Cloudy: Municipality: Site Info: HALTON HILLS TOWN (ACTON) Lot: Concession: Concession Name: Easting NAD83: Northing NAD83: Zone: UTM Reliability:					
PDF URL (Map):					
<u>Additional Detail(s) (Map)</u>					
Well Completed Date: 05/28/2012 Year Completed: 2012 Depth (m): Latitude: 43.63114809615 Longitude: -80.0413827243313 Path:					
<u>Bore Hole Information</u>					
Bore Hole ID: 1004197509 DP2BR: Spatial Status: Code OB: Code OB Desc: Open Hole: Cluster Kind: Date Completed: 05/28/2012 Remarks: Loc Method Desc: on Water Well Record Elevrc Desc: Location Source Date: Improvement Location Source: Improvement Location Method: Source Revision Comment: Supplier Comment: Elevation: Elevrc: Zone: 17 East83: 577331.00 North83: 4831353.00 Org CS: UTM83 UTMRC: 3 UTMRC Desc: margin of error : 10 - 30 m Location Method: wwr					
<u>Links</u>					
Bore Hole ID: 1004197509 Depth M: Year Completed: 2012 Well Completed Dt: 05/28/2012 Audit No: C17997 Path: Tag No: A126157 Contractor: 6607 Latitude: 43.63114809615 Longitude: -80.0413827243313 Y: 43.63114809466708 X: -80.04138257464409					
97	1 of 1	W/248.4	354.9 / 4.31	METRO LINX ACTON ON	WWIS
Well ID: 7221212 Construction Date: Use 1st: Monitoring and Test Hole Use 2nd: 0 Final Well Status: Test Hole Water Type: Casing Material: Audit No: Z183246 Tag: A160906 Constructn Method: Flowing (Y/N): Flow Rate: Data Entry Status: Data Src: Date Received: 05/30/2014 Selected Flag: TRUE Abandonment Rec: Contractor: 7241 Form Version: 7 Owner:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Elevation (m):			County: HALTON		
Elevatn Reliabilty:			Lot:		
Depth to Bedrock:			Concession:		
Well Depth:			Concession Name:		
Overburden/Bedrock:			Easting NAD83:		
Pump Rate:			Northing NAD83:		
Static Water Level:			Zone:		
Clear/Cloudy:			UTM Reliability:		
Municipality:		HALTON HILLS TOWN (ESQUESING)			
Site Info:					
PDF URL (Map):					
Additional Detail(s) (Map)					
Well Completed Date:		04/02/2014			
Year Completed:		2014			
Depth (m):		5.4864			
Latitude:		43.6340769811037			
Longitude:		-80.0438403249107			
Path:					
Bore Hole Information					
Bore Hole ID:		1004796213		Elevation:	
DP2BR:				Elevrc:	
Spatial Status:				Zone:	
Code OB:				East83:	
Code OB Desc:				North83:	
Open Hole:				Org CS:	
Cluster Kind:				UTMRC:	
Date Completed:		04/02/2014		UTMRC Desc:	
Remarks:				Location Method:	
Loc Method Desc:		on Water Well Record		margin of error : 30 m - 100 m	
Elevrc Desc:				wwr	
Location Source Date:					
Improvement Location Source:					
Improvement Location Method:					
Source Revision Comment:					
Supplier Comment:					
Overburden and Bedrock					
Materials Interval					
Formation ID:		1005157344			
Layer:		3			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:		91			
Mat3 Desc:		WATER-BEARING			
Formation Top Depth:		13.0			
Formation End Depth:		18.0			
Formation End Depth UOM:		ft			
Overburden and Bedrock					
Materials Interval					
Formation ID:		1005157343			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Layer:		2			
Color:		6			
General Color:		BROWN			
Mat1:		06			
Most Common Material:		SILT			
Mat2:		28			
Mat2 Desc:		SAND			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		5.0			
Formation End Depth:		13.0			
Formation End Depth UOM:		ft			
<u>Overburden and Bedrock</u>					
<u>Materials Interval</u>					
Formation ID:		1005157342			
Layer:		1			
Color:		6			
General Color:		BROWN			
Mat1:		28			
Most Common Material:		SAND			
Mat2:		11			
Mat2 Desc:		GRAVEL			
Mat3:					
Mat3 Desc:					
Formation Top Depth:		0.0			
Formation End Depth:		5.0			
Formation End Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1005157355			
Layer:		3			
Plug From:		7.0			
Plug To:		18.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1005157353			
Layer:		1			
Plug From:		0.0			
Plug To:		1.0			
Plug Depth UOM:		ft			
<u>Annular Space/Abandonment</u>					
<u>Sealing Record</u>					
Plug ID:		1005157354			
Layer:		2			
Plug From:		1.0			
Plug To:		7.0			
Plug Depth UOM:		ft			
<u>Method of Construction & Well</u>					
<u>Use</u>					
Method Construction ID:		1005157352			
Method Construction Code:		D			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Method Construction:		Direct Push			
Other Method Construction:					
<u>Pipe Information</u>					
Pipe ID:	1005157341				
Casing No:	0				
Comment:					
Alt Name:					
<u>Construction Record - Casing</u>					
Casing ID:	1005157348				
Layer:	1				
Material:	5				
Open Hole or Material:	PLASTIC				
Depth From:	0.0				
Depth To:	8.0				
Casing Diameter:	1.25				
Casing Diameter UOM:	inch				
Casing Depth UOM:	ft				
<u>Construction Record - Screen</u>					
Screen ID:	1005157349				
Layer:	1				
Slot:	10				
Screen Top Depth:	8.0				
Screen End Depth:	18.0				
Screen Material:	5				
Screen Depth UOM:	ft				
Screen Diameter UOM:	inch				
Screen Diameter:	1.5				
<u>Water Details</u>					
Water ID:	1005157347				
Layer:					
Kind Code:					
Kind:					
Water Found Depth:					
Water Found Depth UOM:	ft				
<u>Hole Diameter</u>					
Hole ID:	1005157346				
Diameter:	3.25				
Depth From:	1.0				
Depth To:	18.0				
Hole Depth UOM:	ft				
Hole Diameter UOM:	inch				
<u>Hole Diameter</u>					
Hole ID:	1005157345				
Diameter:	8.0				
Depth From:	0.0				
Depth To:	1.0				
Hole Depth UOM:	ft				
Hole Diameter UOM:	inch				

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction/ Distance (m)</i>	<i>Elev/Diff (m)</i>	<i>Site</i>	<i>DB</i>
<u>Links</u>					
Bore Hole ID:	1004796213			Tag No:	A160906
Depth M:	5.4864			Contractor:	7241
Year Completed:	2014			Latitude:	43.6340769811037
Well Completed Dt:	04/02/2014			Longitude:	-80.0438403249107
Audit No:	Z183246			Y:	43.63407697945345
Path:				X:	-80.04384017557182

Unplottable Summary

Total: **37** Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	336560 ONTARIO LTD.	EASEMENT JOHN STREET	HALTON HILLS TOWN ON	
CA	ACTO-2 INVESTMENTS LIMITED	PT.LOT 29/CON.3, RCP 1098, SWM	HALTON HILLS TOWN ON	
CA	The Regional Municipality of Halton	Lots 26, 27, 28, Concession 3&4	Halton Hills ON	
CA	The Regional Municipality of Halton	Fellows Street from Mill Street to Church St Acton	Halton Hills ON	
CA	The Regional Municipality of Halton	Eastern Avenue	Halton Hills ON	
CA	Maple Leaf Foods Inc.	Lots 26 through 28, Concession 3, and Lot 26, Concession 4	Halton Hills ON	
CA	The Regional Municipality of Halton	Mill Street	Halton Hills ON	
CA	Maple Leaf Foods Inc.	Lots 26 through 28, Concession 3, and Lot 26, Concession 4	Halton Hills ON	
CA	The Regional Municipality of Halton	Mill Street, Perth Street and Peel Street	Halton Hills ON	
CA	TOWN	EASTERN AVE.	HALTON HILLS ON	
CA		Hillcrest Street and Maria Street	Halton Hills ON	
CA	MR. DAVID MANES	MILL ST.	HALTON HILLS TOWN ON	
CA	HALTON BUILDER & RENOVATOR LTD.	MILL STREET	HALTON HILLS TOWN ON	
DTNK	ERIC REID UNITED CO-OPERATIVES OF ONTARIO	TOWN OF HALTON HWY 7	HALTON HILLS ON	
DTNK	FPP CENTRAL TRANS LTD	HWY 7	ACTON ON	
DTNK	FPP CENTRAL TRANS LTD	HWY 7	ACTON ON	

EBR	Maple Leaf Foods Inc.	Elgin Street Halton Hills Ontario Halton Hills	ON	
EBR	Maple Leaf Foods Inc.	Elgin Street Halton Hills Ontario Halton Hills	ON	
EBR	Maple Leaf Foods Inc.	Elgin Street Halton Hills Ontario Halton Hills	ON	
ECA	The Regional Municipality of Halton	Willow St	Halton Hills ON	L6M 3L1
ECA	The Corporation of the Town of Halton Hills	Wallace Street, Acton, Halton Hills	Halton Hills ON	L7G 5G2
ECA	The Regional Municipality of Halton	Hillcrest Street and Maria Street	Halton Hills ON	L6M 3L1
GEN	CANADA PACKERS INC.	BEARDMORE TANNERIES PT. LOT 290 REG. PLAN 1098, ELGIN STREET,	ACTON, ON	L7R 3Z6
GEN	CANADA PACKERS INC	BEARDMORE TANNERIES PT. LOT 290 REG. PLAN 1098, ELGIN STREET,	ACTON, ON	L7J 2M5
GEN	DOUG CHALMERS INC. 12-649	HWY #7 EAST, HALTON HILLS C/O BOX 280	GEORGETOWN ON	L7G 4Y5
GEN	BEARDMORE	ELGIN ST.	ACTON ON	L7J 2M5
GEN	Metrolinx	Acton GO Station	Acton ON	L7J 2E6
PRT	ERIC REID UNITED CO-OPERATIVES OF ONTARIO	TOWN OF HALTON HWY 7	ON	
REC	BEARDMORE (SEE & USE 302-86A022)	ELGIN ST.	ACTON ON	L7J 2M5
SPL	HARMAC TRANSPORTATION	HWY 7, CANADIAN TIRE TANK TRUCK (CARGO)	HALTON HILLS TOWN ON	
SPL	VIA RAIL CANADA INC.	MILL STREET, ACTON GO TRAIN STATION	HALTON HILLS TOWN ON	
SPL	Zuraw Technologies<UNOFFICIAL>		Halton Hills ON	
SPL	UNKNOWN	WALLACE AVE., ACTON	HALTON HILLS TOWN ON	
SPL	UNKNOWN	JOHN ST. GEORGETOWN	HALTON HILLS TOWN ON	
SPL	CANADIAN PACIFIC BULK SYSTEMS	UNITED CO-OP YARD ON HWY #7 TANK TRUCK (CARGO)	HALTON HILLS TOWN ON	
SPL	Cavalier Transportation Services Inc.	Highway 7 (east of Acton)	Halton Hills ON	
WWIS		lot 28	ON	

Unplottable Report

Site: 336560 ONTARIO LTD.
EASEMENT JOHN STREET HALTON HILLS TOWN ON

Database:
CA

Certificate #: 3-1545-86-
Application Year: 86
Issue Date: 10/17/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ACTO-2 INVESTMENTS LIMITED
PT.LOT 29/CON.3, RCP 1098, SWM HALTON HILLS TOWN ON

Database:
CA

Certificate #: 3-1346-99-
Application Year: 99
Issue Date: 12/2/1999
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: The Regional Municipality of Halton
Lots 26, 27, 28, Concession 3&4 Halton Hills ON

Database:
CA

Certificate #: 1364-5KUJVG
Application Year: 2003
Issue Date: 3/24/2003
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: The Regional Municipality of Halton
Fellows Street from Mill Street to Church St Acton Halton Hills ON

Database:
CA

Certificate #: 1543-889RQ9

Application Year: 2010
Issue Date: 8/31/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *The Regional Municipality of Halton
Eastern Avenue Halton Hills ON*

Database:
[CA](#)

Certificate #: 3584-6MXLS3
Application Year: 2006
Issue Date: 3/28/2006
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *Maple Leaf Foods Inc.
Lots 26 through 28, Concession 3, and Lot 26, Concession 4 Halton Hills ON*

Database:
[CA](#)

Certificate #: 4343-5STQVF
Application Year: 2003
Issue Date: 11/4/2003
Approval Type: Industrial Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *The Regional Municipality of Halton
Mill Street Halton Hills ON*

Database:
[CA](#)

Certificate #: 5272-659RTT
Application Year: 2004
Issue Date: 10/29/2004
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *Maple Leaf Foods Inc.
Lots 26 through 28, Concession 3, and Lot 26, Concession 4 Halton Hills ON*

Database:
[CA](#)

Certificate #: 6102-5E5KK4
Application Year: 2002
Issue Date: 10/22/2002
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *The Regional Municipality of Halton
Mill Street, Perth Street and Peel Street Halton Hills ON*

Database:
[CA](#)

Certificate #: 7657-7FZR3F
Application Year: 2008
Issue Date: 7/3/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *TOWN
EASTERN AVE. HALTON HILLS ON*

Database:
[CA](#)

Certificate #: 7-0315-85-006
Application Year: 85
Issue Date: 5/27/85
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: *Hillcrest Street and Maria Street Halton Hills ON*

Database:
[CA](#)

Certificate #: 3146-4ZNX2
Application Year: 01
Issue Date: 8/17/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: The Corporation of the Regional Municipality of Halton
Client Address: 1151 Bronte Road

Client City: Oakville
Client Postal Code: L6M 3L1
Project Description: Construction of Sanitary Sewers on Hillcrest Street and Maria Street
Contaminants:
Emission Control:

Site: MR. DAVID MANES
MILL ST. HALTON HILLS TOWN ON

Database:
CA

Certificate #: 3-1845-87-
Application Year: 87
Issue Date: 10/7/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: HALTON BUILDER & RENOVATOR LTD.
MILL STREET HALTON HILLS TOWN ON

Database:
CA

Certificate #: 3-1543-87-
Application Year: 87
Issue Date: 9/15/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ERIC REID UNITED CO-OPERATIVES OF ONTARIO
TOWN OF HALTON HWY 7 HALTON HILLS ON

Database:
DTNK

**Delisted Expired Fuel Safety
Facilities**

Instance No: 9189408
Status: EXPIRED
Instance ID: 380245
Instance Type: FS Facility
Instance Creation Dt:
Instance Install Dt:
Item Description:
Manufacturer:
Model:
Serial No:
ULC Standard:
Quantity:
Unit of Measure:
Overfill Prot Type:
Creation Date:
Next Periodic Str DT:

Expired Date:
Max Hazard Rank:
Facility Location:
Facility Type:
Fuel Type 2:
Fuel Type 3:
Panam Related:
Panam Venue Nm:
External Identifier:
Item:
Piping Steel:
Piping Galvanized:
Tank Single Wall St:
Piping Underground:
Tank Underground:
Source:

TSSA Base Sched Cycle 2:
TSSAMax Hazard Rank 1:
TSSA Risk Based Periodic Yn:
TSSA Volume of Directives:
TSSA Periodic Exempt:
TSSA Statutory Interval:
TSSA Recd Insp Interva:
TSSA Recd Tolerance:
TSSA Program Area:
TSSA Program Area 2:
Description: FS Gasoline Station - Full Serve
Original Source: EXP
Record Date: Up to Mar 2012

Site: FPP CENTRAL TRANS LTD
HWY 7 ACTON ON

Database:
DTNK

Delisted Expired Fuel Safety
Facilities

Instance No:	10447674	Expired Date:	
Status:	EXPIRED	Max Hazard Rank:	
Instance ID:	17921	Facility Location:	
Instance Type:	FS Highway Tank - Gas/Diesel	Facility Type:	
Instance Creation Dt:		Fuel Type 2:	
Instance Install Dt:		Fuel Type 3:	
Item Description:		Panam Related:	
Manufacturer:		Panam Venue Nm:	
Model:		External Identifier:	
Serial No:		Item:	
ULC Standard:		Piping Steel:	
Quantity:		Piping Galvanized:	
Unit of Measure:		Tank Single Wall St:	
Overfill Prot Type:		Piping Underground:	
Creation Date:		Tank Underground:	
Next Periodic Str DT:		Source:	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: FPP CENTRAL TRANS LTD
HWY 7 ACTON ON

Database:
DTNK

Delisted Expired Fuel Safety
Facilities

Instance No:	10468837	Expired Date:	
Status:	EXPIRED	Max Hazard Rank:	
Instance ID:	22028	Facility Location:	
Instance Type:	FS Highway Tank - Gas/Diesel	Facility Type:	
Instance Creation Dt:		Fuel Type 2:	
Instance Install Dt:		Fuel Type 3:	
Item Description:		Panam Related:	
Manufacturer:		Panam Venue Nm:	

Model:		External Identifier:	
Serial No:		Item:	
ULC Standard:		Piping Steel:	
Quantity:		Piping Galvanized:	
Unit of Measure:		Tank Single Wall St:	
Overfill Prot Type:		Piping Underground:	
Creation Date:		Tank Underground:	
Next Periodic Str DT:		Source:	
TSSA Base Sched Cycle 2:			
TSSAMax Hazard Rank 1:			
TSSA Risk Based Periodic Yn:			
TSSA Volume of Directives:			
TSSA Periodic Exempt:			
TSSA Statutory Interval:			
TSSA Recd Insp Interva:			
TSSA Recd Tolerance:			
TSSA Program Area:			
TSSA Program Area 2:			
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL		
Original Source:	EXP		
Record Date:	Up to Mar 2012		

Site: **Maple Leaf Foods Inc.**
Elgin Street Halton Hills Ontario Halton Hills ON

Database:
EBR

EBR Registry No:	IA02E1509	Decision Posted:	
Ministry Ref No:	9921-5D9LMU	Exception Posted:	
Notice Type:	Instrument Decision	Section:	
Notice Stage:		Act 1:	
Notice Date:	October 20, 2006	Act 2:	
Proposal Date:	November 29, 2002	Site Location Map:	
Year:	2002		
Instrument Type:	(EPA s. 27) - Approval for a waste disposal site.		
Off Instrument Name:			
Posted By:			
Company Name:	Maple Leaf Foods Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	30 St. Clair Avenue West , 1500, Toronto Ontario, M4V 3A2		
Comment Period:			
URL:			

Site Location Details:

Elgin Street Halton Hills Ontario Halton Hills

Site: **Maple Leaf Foods Inc.**
Elgin Street Halton Hills Ontario Halton Hills ON

Database:
EBR

EBR Registry No:	IA02E1008	Decision Posted:	
Ministry Ref No:	7923-5D8TGV	Exception Posted:	
Notice Type:	Instrument Decision	Section:	
Notice Stage:		Act 1:	
Notice Date:	October 29, 2002	Act 2:	
Proposal Date:	August 28, 2002	Site Location Map:	
Year:	2002		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Maple Leaf Foods Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	30 St. Clair Avenue West , 1500, Toronto Ontario, M4V 3A2		
Comment Period:			

URL:

Site Location Details:

Elgin Street Halton Hills Ontario Halton Hills

Site: *Maple Leaf Foods Inc.*
Elgin Street Halton Hills Ontario Halton Hills ON

Database:
EBR

EBR Registry No: IA05E1791
Ministry Ref No: 2327-6JEQX8
Notice Type: Instrument Decision
Notice Stage:
Notice Date: June 15, 2006
Proposal Date: April 24, 2006
Year: 2006
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Maple Leaf Foods Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 30 St. Clair Avenue West , 1500, Toronto Ontario, M4V 3A2
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

Elgin Street Halton Hills Ontario Halton Hills

Site: *The Regional Municipality of Halton*
Willow St Halton Hills ON L6M 3L1

Database:
ECA

Approval No: 1964-9MPHDS
Approval Date: 2014-08-11
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Halton
Address: Willow St
Full Address:
Full PDF Link: <https://www.accessenvironment.ene.gov.on.ca/instruments/1931-9MJS6P-14.pdf>
PDF Site Location:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: *The Corporation of the Town of Halton Hills*
Wallace Street, Acton, Halton Hills Halton Hills ON L7G 5G2

Database:
ECA

Approval No: 1948-8EYJVP
Approval Date: 2011-03-31
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Corporation of the Town of Halton Hills
Address: Wallace Street, Acton, Halton Hills
Full Address:

MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: The Regional Municipality of Halton
Hillcrest Street and Maria Street Halton Hills ON L6M 3L1

Database:
ECA

Approval No:	3146-4ZNXJ2	MOE District:	Halton-Peel
Approval Date:	2001-08-17	City:	
Status:	Approved	Longitude:	-80.0308
Record Type:	ECA	Latitude:	43.6304
Link Source:	IDS	Geometry X:	
SWP Area Name:	Credit Valley	Geometry Y:	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Business Name:	The Regional Municipality of Halton		
Address:	Hillcrest Street and Maria Street		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/4092-4ZLJ58-14.pdf		
PDF Site Location:			

Site: CANADA PACKERS INC.
BEARDMORE TANNERIES PT. LOT 290 REG. PLAN 1098, ELGIN STREET, ACTON, ON L7R 3Z6

Database:
GEN

Generator No: ON0044219
SIC Code: 1711
SIC Description: LEATHER TANNERIES
Approval Years: 89
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class:	251
Waste Class Name:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Name:	WASTE OILS & LUBRICANTS
Waste Class:	144
Waste Class Name:	INORGANIC TANNERY WASTES
Waste Class:	212
Waste Class Name:	ALIPHATIC SOLVENTS
Waste Class:	213
Waste Class Name:	PETROLEUM DISTILLATES
Waste Class:	221
Waste Class Name:	LIGHT FUELS
Waste Class:	222
Waste Class Name:	HEAVY FUELS
Waste Class:	114
Waste Class Name:	OTHER INORGANIC ACID WASTES

Site: CANADA PACKERS INC
BEARDMORE TANNERIES PT. LOT 290 REG. PLAN 1098, ELGIN STREET, ACTON, ON L7J 2M5

Database:
GEN

Generator No: ON0044219
SIC Code: 1711
SIC Description: LEATHER TANNERIES
Approval Years: 86,87,88
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 212
Waste Class Name: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Name: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Name: WASTE OILS & LUBRICANTS

Site: DOUG CHALMERS INC. 12-649
HWY #7 EAST, HALTON HILLS C/O BOX 280 GEORGETOWN ON L7G 4Y5

Database:
GEN

Generator No: ON1498002
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
Approval Years: 92,93,94,95,96,97,98
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146
Waste Class Name: OTHER SPECIFIED INORGANICS

Waste Class: 221
Waste Class Name: LIGHT FUELS

Waste Class: 251
Waste Class Name: OIL SKIMMINGS & SLUDGES

Site: BEARDMORE
ELGIN ST. ACTON ON L7J 2M5

Database:
GEN

Generator No: RRPCB0230
SIC Code: 030
SIC Description:
Approval Years: 86
PO Box No:
Country:
Status:
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:

MHSW Facility:

Site: Metrolinx
Acton GO Station Acton ON L7J 2E6

Database:
GEN

Generator No: ON8827577
SIC Code:
SIC Description:
Approval Years: As of Aug 2021
PO Box No:
Country: Canada
Status: Registered
Co Admin:
Choice of Contact:
Phone No Admin:
Contaminated Facility:
MHSW Facility:

Detail(s)

Waste Class: 146 L
Waste Class Name: Other specified inorganic sludges, slurries or solids

Site: ERIC REID UNITED CO-OPERATIVES OF ONTARIO
TOWN OF HALTON HWY 7 ON

Database:
PRT

Location ID: 17826
Type: retail
Expiry Date: 1990-05-31
Capacity (L): 0
Licence #: 0000015300

Site: BEARDMORE (SEE & USE 302-86A022)
ELGIN ST. ACTON ON L7J 2M5

Database:
REC

ID:		Province In:	ONT
Company ID:		Province Out:	
Receiver No:	RRPCB0230	County Out:	
Co Admin:		Mail Addr:	
Choice of Contact:		Site PO Box:	
Rec Div:			
Rec Op Div:			
Rec Op Name:			
Site Bldg:			
Facility Type:			
Approval Yrs:	1986; 1987; 1988; 1989; 1990; 1992; 1994; 1995; 1996; 1997; 1998; 2006; 2007; 2008		

1986 Receiver Manifest Details

Gen Dist: 100
Gen District Office Name: LONDON, ONT
Gen Region Code: 01
Gen Region Office Name: SOUTHWESTERN REGION
Gen SIC: 9941
NAICS Desc: ELECTRIC MOTOR REPAIR
Wastecode: 243
Waste Class: PCB'S
Waste Chara:
Waste Count: 2
Qty Recvd: 819

Site: HARMAC TRANSPORTATION
HWY 7, CANADIAN TIRE TANK TRUCK (CARGO) HALTON HILLS TOWN ON

Database:
SPL

Ref No:	97479	Municipality No:	14401
Year:		Nature of Damage:	
Incident Dt:	3/18/1994	Discharger Report:	
Dt MOE Arvl on Scn:		Material Group:	
MOE Reported Dt:	3/18/1994	Health/Env Conseq:	
Dt Document Closed:		Agency Involved:	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	HALTON HILLS TOWN		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Incident Cause:	PIPE/HOSE LEAK		
Incident Event:			
Environment Impact:	NOT ANTICIPATED		
Nature of Impact:			
Contaminant Qty:			
System Facility Address:			
Client Name:			
Client Type:			
Source Type:			
Contaminant Code:			
Contaminant Name:			
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:	LAND		
Incident Reason:	ERROR		
Incident Summary:	HARMAC TRANSPORT: 3L GASOLINE LEAK FROM TANK TRUCK DURING DELIVERY		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:			
SAC Action Class:			
Call Report Locatn Geodata:			

Site: VIA RAIL CANADA INC.
MILL STREET, ACTON GO TRAIN STATION HALTON HILLS TOWN ON

Database:
SPL

Ref No:	78105	Municipality No:	14401
Year:		Nature of Damage:	
Incident Dt:	10/29/1992	Discharger Report:	
Dt MOE Arvl on Scn:		Material Group:	
MOE Reported Dt:	10/29/1992	Health/Env Conseq:	
Dt Document Closed:		Agency Involved:	CN-RAIL,F.D.WORKS DEPT
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	HALTON HILLS TOWN		
Site Lot:			
Site Conc:			

Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: OTHER CONTAINER LEAK
Incident Event:
Environment Impact: CONFIRMED
Nature of Impact: Soil contamination
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: OTHER
Incident Summary: VIA RAIL: 4050 L DIESEL FUEL OVER 2-3 KM RAIL BEDFROM RUPTURED ENGINE TANK
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: Zuraw Technologies<UNOFFICIAL>
 Halton Hills ON

Database:
 SPL

Ref No:	3501-8TTPYY	Municipality No:
Year:		Nature of Damage:
Incident Dt:	29-APR-12	Discharger Report:
Dt MOE Arvl on Scn:	30-APR-12	Material Group:
MOE Reported Dt:	29-APR-12	Health/Env Conseq:
Dt Document Closed:		Agency Involved:
Site No:		
MOE Response:	Priority Field Response (ERP Callout)	
Site County/District:		
Site Geo Ref Meth:		
Site District Office:		
Nearest Watercourse:		
Site Name:	swale between Dr. Moore Cres. and south to MacDonald Blvd to SWP<UNOFFICIAL>	
Site Address:		
Site Region:		
Site Municipality:	Halton Hills	
Site Lot:		
Site Conc:		
Site Geo Ref Accu:		
Site Map Datum:		
Northing:		
Easting:		
Incident Cause:	Unknown	
Incident Event:		
Environment Impact:	Possible	
Nature of Impact:	Surface Water Pollution	
Contaminant Qty:		
System Facility Address:		
Client Name:	Zuraw Technologies<UNOFFICIAL>	
Client Type:		
Source Type:		
Contaminant Code:		
Contaminant Name:		
Contaminant Limit 1:		
Contam Limit Freq 1:		
Contaminant UN No 1:		

Receiving Medium: Sewage - Municipal/Private and Commercial
Incident Reason: Unknown - Reason not determined
Incident Summary: TIPS: white solvent in swale; trib. of Black Creek
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Unknown
SAC Action Class: Pollution Incident Reports (PIRs) and ¿Other¿ calls
Call Report Locatn Geodata:

Site: UNKNOWN
WALLACE AVE., ACTON HALTON HILLS TOWN ON

Database:
SPL

Ref No: 88510 **Municipality No:** 14401
Year: **Nature of Damage:**
Incident Dt: 7/15/1993 **Discharger Report:**
Dt MOE Arvl on Scn: **Material Group:**
MOE Reported Dt: 7/15/1993 **Health/Env Conseq:**
Dt Document Closed: **Agency Involved:**
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: HALTON HILLS TOWN
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNKNOWN
Incident Event:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: UNKNOWN
Incident Summary: 10 L OF MOTOR OIL TO STREET FROM UNKNOWN SOURCE
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: UNKNOWN
JOHN ST. GEORGETOWN HALTON HILLS TOWN ON

Database:
SPL

Ref No: 157 **Municipality No:** 14401
Year: **Nature of Damage:**
Incident Dt: 1/6/1988 **Discharger Report:**
Dt MOE Arvl on Scn: **Material Group:**

MOE Reported Dt: 1/6/1988
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: HALTON HILLS TOWN
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Incident Cause: UNKNOWN
Incident Event:
Environment Impact: NOT ANTICIPATED
Nature of Impact: SOIL CONTAMINATION
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: UNKNOWN
Incident Summary: EST. 45 LITRES OF OIL TO ROADSIDE DITCH. FROM A TRUCK.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Health/Env Conseq:
Agency Involved:

Site: CANADIAN PACIFIC BULK SYSTEMS
 UNITED CO-OP YARD ON HWY #7 TANK TRUCK (CARGO) HALTON HILLS TOWN ON

Database:
 SPL

Ref No: 9566
Year:
Incident Dt: 9/19/1988
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/19/1988
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: HALTON HILLS TOWN
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:

Municipality No: 14401
Nature of Damage:
Discharger Report:
Material Group:
Health/Env Conseq:
Agency Involved:

Incident Cause: ABOVE-GROUND TANK LEAK
Incident Event:
Environment Impact:
Nature of Impact:
Contaminant Qty:
System Facility Address:
Client Name:
Client Type:
Source Type:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Incident Reason: EQUIPMENT FAILURE
Incident Summary: C.P.BULK SYSTEMS- 100 LITRES FURNACE OIL TOGROUND AT CO-OP YARD.
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:

Site: Cavalier Transportation Services Inc.
 Highway 7 (east of Acton) Halton Hills ON

Database:
 SPL

Ref No:	2358-8B8LJR	Municipality No:
Year:		Nature of Damage:
Incident Dt:		Discharger Report:
Dt MOE Arvl on Scn:		Material Group:
MOE Reported Dt:	11/15/2010	Health/Env Conseq:
Dt Document Closed:		Agency Involved:
Site No:		
MOE Response:	No Field Response	
Site County/District:		
Site Geo Ref Meth:		
Site District Office:		
Nearest Watercourse:		
Site Name:	MVA (Highway 7)<UNOFFICIAL>	
Site Address:		
Site Region:		
Site Municipality:		
Site Lot:		
Site Conc:		
Site Geo Ref Accu:		
Site Map Datum:		
Northing:		
Easting:		
Incident Cause:	Other Transport Accident	
Incident Event:		
Environment Impact:	Confirmed	
Nature of Impact:	Soil Contamination	
Contaminant Qty:	0 other - see incident description	
System Facility Address:		
Client Name:		
Client Type:		
Source Type:		
Contaminant Code:	13	
Contaminant Name:	DIESEL FUEL	
Contaminant Limit 1:		
Contam Limit Freq 1:		
Contaminant UN No 1:		
Receiving Medium:		
Incident Reason:	Spill	
Incident Summary:	MVA: Hwy 7, east of Acton. Fluids spilled. Unkwn qunties.	
Activity Preceding Spill:		

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Motor Vehicle
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:

Site:
lot 28 ON

Database:
WWIS

Well ID:	2807837	Flowing (Y/N):	
Construction Date:		Flow Rate:	
Use 1st:		Data Entry Status:	
Use 2nd:		Data Src:	1
Final Well Status:	Water Supply	Date Received:	09/20/1991
Water Type:		Selected Flag:	TRUE
Casing Material:		Abandonment Rec:	
Audit No:	104434	Contractor:	4552
Tag:		Form Version:	1
Constructn Method:		Owner:	
Elevation (m):		County:	HALTON
Elevatn Reliabilty:		Lot:	028
Depth to Bedrock:		Concession:	
Well Depth:		Concession Name:	CON
Overburden/Bedrock:		Easting NAD83:	
Pump Rate:		Northing NAD83:	
Static Water Level:		Zone:	
Clear/Cloudy:		UTM Reliability:	
Municipality:	HALTON HILLS TOWN (ESQUESING)		
Site Info:			

Bore Hole Information

Bore Hole ID:	10154094	Elevation:	
DP2BR:		Elevrc:	
Spatial Status:		Zone:	17
Code OB:		East83:	
Code OB Desc:		North83:	
Open Hole:		Org CS:	
Cluster Kind:		UTMRC:	9
Date Completed:	08/06/1991	UTMRC Desc:	unknown UTM
Remarks:		Location Method:	na
Loc Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

**Overburden and Bedrock
Materials Interval**

Formation ID:	931448997
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Mat2 Desc:	SAND
Mat3:	
Mat3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	15.0
Formation End Depth UOM:	ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449000
Layer: 4
Color: 6
General Color: BROWN
Mat1: 11
Most Common Material: GRAVEL
Mat2: 28
Mat2 Desc: SAND
Mat3:
Mat3 Desc:
Formation Top Depth: 50.0
Formation End Depth: 65.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931448999
Layer: 3
Color: 2
General Color: GREY
Mat1: 11
Most Common Material: GRAVEL
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 30.0
Formation End Depth: 50.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449003
Layer: 7
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 90.0
Formation End Depth: 100.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449005
Layer: 9
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:

Formation Top Depth: 105.0
Formation End Depth: 115.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449008
Layer: 12
Color: 2
General Color: GREY
Mat1: 15
Most Common Material: LIMESTONE
Mat2: 18
Mat2 Desc: SANDSTONE
Mat3:
Mat3 Desc:
Formation Top Depth: 130.0
Formation End Depth: 160.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449004
Layer: 8
Color: 2
General Color: GREY
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 100.0
Formation End Depth: 105.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449007
Layer: 11
Color: 2
General Color: GREY
Mat1: 17
Most Common Material: SHALE
Mat2: 18
Mat2 Desc: SANDSTONE
Mat3:
Mat3 Desc:
Formation Top Depth: 120.0
Formation End Depth: 130.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449001
Layer: 5
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 11

Mat2 Desc: GRAVEL
Mat3:
Mat3 Desc:
Formation Top Depth: 65.0
Formation End Depth: 75.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449009
Layer: 13
Color: 7
General Color: RED
Mat1: 17
Most Common Material: SHALE
Mat2:
Mat2 Desc:
Mat3:
Mat3 Desc:
Formation Top Depth: 160.0
Formation End Depth: 310.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931448998
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 05
Mat2 Desc: CLAY
Mat3:
Mat3 Desc:
Formation Top Depth: 15.0
Formation End Depth: 30.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449002
Layer: 6
Color: 2
General Color: GREY
Mat1: 28
Most Common Material: SAND
Mat2: 11
Mat2 Desc: GRAVEL
Mat3: 90
Mat3 Desc: VERY
Formation Top Depth: 75.0
Formation End Depth: 90.0
Formation End Depth UOM: ft

Overburden and Bedrock
Materials Interval

Formation ID: 931449006
Layer: 10
Color: 2
General Color: GREY

Mat1: 11
Most Common Material: GRAVEL
Mat2: 17
Mat2 Desc: SHALE
Mat3:
Mat3 Desc:
Formation Top Depth: 115.0
Formation End Depth: 120.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 962807837
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 10702664
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930262132
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 123.0
Casing Diameter: 7.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930262133
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 310.0
Casing Diameter: 6.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc: PUMP
Pump Test ID: 992807837
Pump Set At:
Static Level: 10.0
Final Level After Pumping: 250.0
Recommended Pump Depth: 295.0
Pumping Rate: 95.0
Flowing Rate:
Recommended Pump Rate: 15.0
Levels UOM: ft
Rate UOM: GPM
Water State After Test Code: 2
Water State After Test: CLOUDY
Pumping Test Method: 1

Pumping Duration HR: 3
Pumping Duration MIN: 0
Flowing: No

Draw Down & Recovery

Pump Test Detail ID: 934180102
Test Type: Draw Down
Test Duration: 15
Test Level: 100.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934712770
Test Type: Draw Down
Test Duration: 45
Test Level: 200.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934454042
Test Type: Draw Down
Test Duration: 30
Test Level: 150.0
Test Level UOM: ft

Draw Down & Recovery

Pump Test Detail ID: 934965425
Test Type: Draw Down
Test Duration: 60
Test Level: 250.0
Test Level UOM: ft

Water Details

Water ID: 933611478
Layer: 1
Kind Code: 3
Kind: SULPHUR
Water Found Depth: 220.0
Water Found Depth UOM: ft

Appendix: Database Descriptions

*Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. **Note:** Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory:

Provincial [AAGR](#)

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory:

Provincial [AGR](#)

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Nov 2023

Abandoned Mine Information System:

Provincial [AMIS](#)

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Mar 2022

Anderson's Waste Disposal Sites:

Private [ANDR](#)

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks:

Provincial [AST](#)

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies:

Private [AUWR](#)

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Oct 31, 2023

Borehole:

Provincial [BORE](#)

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval:

Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities:

Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2022

Commercial Fuel Oil Tanks:

Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.

Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors:

Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register:

Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Oct 31, 2023

Compressed Natural Gas Stations:

Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 -Nov 2023

Inventory of Coal Gasification Plants and Coal Tar Sites:

Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions:

Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Jan 2024

Certificates of Property Use:

Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Jan 31, 2024

Drill Hole Database:

Provincial

[DRL](#)

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Aug 2023

Delisted Fuel Tanks:

Provincial

[DTNK](#)

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry:

Provincial

[EASR](#)

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval). Please see our ECA database.

Government Publication Date: Oct 2011-Jan 31, 2024

Environmental Registry:

Provincial

[EBR](#)

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Jan 31, 2024

Environmental Compliance Approval:

Provincial

[ECA](#)

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011- Jan 31, 2024

Environmental Effects Monitoring:

Federal

[EEM](#)

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches:

Private

[EHS](#)

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Dec 31, 2023

Environmental Issues Inventory System:

Federal

[EIIS](#)

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event:

Provincial

EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022**Environmental Penalty Annual Report:**

Provincial

EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2022**List of Expired Fuels Safety Facilities:**

Provincial

EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.

Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023**Federal Convictions:**

Federal

FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007***Contaminated Sites on Federal Land:**

Federal

FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Oct 2023**Fisheries & Oceans Fuel Tanks:**

Federal

FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2019**Federal Identification Registry for Storage Tank Systems (FIRSTS):**

Federal

FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: Oct 31, 2021**Fuel Storage Tank:**

Provincial

FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.

Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic:

Provincial

FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary:

Provincial

GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Oct 31, 2022

Greenhouse Gas Emissions from Large Facilities:

Federal

GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO₂ eq).

Government Publication Date: 2013-Dec 2021

TSSA Historic Incidents:

Provincial

HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks:

Federal

IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks:

Provincial

INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing is a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: 31 Oct, 2023

Landfill Inventory Management Ontario:

Provincial

LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations:

Private

MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences:

Provincial

MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Feb 2024

National Analysis of Trends in Emergencies System (NATES):

Federal

NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports:

Provincial

NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2022

National Defense & Canadian Forces Fuel Tanks:

Federal

NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills:

Federal

NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites:

Federal

NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents:

Federal

NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2021

National Energy Board Wells:

Federal

NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES):

Federal

[NEES](#)

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003***National PCB Inventory:**

Federal

[NPCB](#)

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008***National Pollutant Release Inventory 1993-2020:**

Federal

[NPR2](#)

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Sep 2020**National Pollutant Release Inventory - Historic:**

Federal

[NPRI](#)

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017**Oil and Gas Wells:**

Private

[OGWE](#)

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Feb 29, 2024**Ontario Oil and Gas Wells:**

Provincial

[OOGW](#)

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Aug 2023**Inventory of PCB Storage Sites:**

Provincial

[OPCB](#)

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013**Orders:**

Provincial

[ORD](#)

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Jan 31, 2024

Canadian Pulp and Paper:

Private

[PAP](#)

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks:

Federal

[PCFT](#)

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register:

Provincial

[PES](#)

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011- Jan 31, 2024

NPRI Reporters - PFAS Substances:

Federal

[PFCH](#)

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per- and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Sep 2020

Potential PFAS Handlers from NPRI:

Federal

[PFHA](#)

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per- and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Sep 2020

Pipeline Incidents:

Provincial

[PINC](#)

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing is an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Private and Retail Fuel Storage Tanks:

Provincial

[PRT](#)

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water:

Provincial

[PTTW](#)

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Jan 31, 2024

Ontario Regulation 347 Waste Receivers Summary:

Provincial

[REC](#)

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition:

Provincial

[RSC](#)

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004-Jan 2024

Retail Fuel Storage Tanks:

Private

[RST](#)

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Oct 31, 2023

Scott's Manufacturing Directory:

Private

[SCT](#)

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills:

Provincial

[SPL](#)

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X. The Ministry of the Environment, Conservation and Parks cites the coronavirus pandemic as an explanation for delays in releasing data pursuant to requests.

Government Publication Date: 1988-Jan 2023; May 2023-Dec 2023

Wastewater Discharger Registration Database:

Provincial

[SRDS](#)

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2020

Anderson's Storage Tanks:

Private

[TANK](#)

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks:

Federal

[TCFT](#)

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2023

Variances for Abandonment of Underground Storage Tanks:

Provincial

[VAR](#)

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.

Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory:

Provincial

[WDS](#)

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Jan 31, 2024

Waste Disposal Sites - MOE 1991 Historical Approval Inventory:

Provincial

[WDSH](#)

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System:

Provincial

[WWIS](#)

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Mar 31 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Appendix F

Municipal FOI Correspondence



**Municipal Freedom of Information and
Protection of Privacy Act (MFIPPA)
Access or Correction Request**

This MFIPPA form and a \$5.00 application fee are required for all Access or Correction to personal information requests. See page 2 for submission of form and payment options. The Town is required to render a decision within 30 days of receipt of your completed form and fee.

REQUESTER INFORMATION

COMPLETE ALL FIELDS

Requester Name(s) Bailey Fleet
Address 1-871 Equestrain Court
City/Town Oakville Province ON Postal Code L6L 6L7
Phone No. (8:30am – 4:30pm, M-F) 905-708-7299
Email address bailey.fleet@pecg.ca

If you are the Agent for the Requester above, please provide your contact information here:

Agent Name _____ Company _____
Address _____
City/Town _____ Province _____ Postal Code _____
Phone No. (8:30am – 4:30pm, M-F) _____
Email Address _____

DESCRIBE RECORD(s) in detail and include information such as address, dates, names, etc.

Any environmental records, control order, or violation notices on file with the building, planning, enforcement, and/or environmental departments for the property located at 97 Bower Street, Acton, ON.

I hereby declare the information above is true, complete, and correct and that any documents submitted along with this form are genuine. I further understand that any false statements or deliberate omissions on this form, or within any documents submitted along with this form, or in any other communication related to this matter, may be considered as false pretences and upon conviction I may be liable to a fine pursuant to s.48 of MFIPPA.

Signature _____ Date Apr. 1, 2024

Personal information on this form is collected pursuant to MFIPPA and will be used to process your Access or Correction request. Questions? Please email: foi@haltonhills.ca



Municipal Freedom of Information and Protection of Privacy Act (MFIPPA) Access or Correction Request

SUBMISSION of MFIPPA FORM (page 1)

Email completed MFIPPA form to: foi@haltonhills.ca

AGENTS: If you are acting as an agent for the requester, please include their written consent along with your completed MFIPPA form.

PAYMENT of \$5.00 MFIPPA FEE

By credit card (Visa/MC)

Call 905-873-2600, press "0" (Monday - Friday, 8:30 am - 4:30 pm)

Provide your full name, phone number, email (for receipt) and credit card information to Service Halton Hills Staff.

DO NOT LEAVE CREDIT CARD INFORMATION ON TOWN VOICE MAIL AND DO NOT EMAIL

The Form and Fee can also be submitted at the Service Halton Hills counter located in Town Hall, 1 Halton Hills Drive, Halton Hills (Monday - Friday, 8:30 am - 4:30 pm)

FEES AUTHORIZED by SECTION 45(1) of the ACT

According to Section 6 of R.R.O. 1990, Regulation 823, the following fees can be charged as per subsection 45(1) of the Act:

- Photocopies and Computer Printouts (.20 per page).
- Preparing a record for disclosure, including redaction, \$7.50 for each 15 minutes spent by any person.
- Manually searching for a record, \$7.50 for each 15 minutes spent by any person.
- For developing a computer program or other method of producing a record from machine readable record, \$15 for each 15 minutes spent by any person.
- The costs, including computer costs, that the institution incurs in locating, retrieving, processing, and copying the record if those costs are specified in an invoice that the institution has received.

RATES and FEES (Refer to Report CS-2023-032 and By-Law 2023-0105)

- Drawings and Plans (\$6.00 each)
- Off-Site Storage Record(s) Retrieval of one box (\$43.00)
- Cost per additional box from off-site (\$3.00 each)

RELEASE of RECORDS

A decision letter will be prepared at the conclusion of the review of responsive records. Payment of additional applicable fees (see above) must be received prior to the release of record(s). The manner of release will be communicated to you the requester, and you will be advised if no records responsive to your request exist.

Appendix G

MECP FOI Correspondence

Ministry of the Environment, Conservation and Parks

Freedom of Information Request for Property Information

Instructions

Use this form to:

- submit and pay for a new FOI request for access to records/information about a property
- pay for a deposit or a final fee on an existing FOI request

Fields marked with an asterisk (*) are mandatory.

Are you: *

- ☒ Submitting a new FOI Request for Property Information
- ☐ Paying a deposit or final fee for an existing FOI Request for Property Information

Section 1 – Description of Records Requested

Time Period for Records Requested

From (yyyy/mm/dd) *

To (yyyy/mm/dd) *

1985/01/01

2024/04/24

Type of Record(s) *

- ☒ All environmental records relating to the identified property/site exclusive of Environmental Approvals and Registrations
- ☒ Environmental Approvals and Registrations (e.g. Environmental Compliance Approvals; Certificate of Approval; Renewable Energy Approvals; Environmental Activity and Sector Registry Registrations)

Select only if you are seeking access to an Approval or Registration that is not publicly available or if you are also seeking supporting documents relating to the Approval or Registration.

Operator and vendor Pesticide Licenses from September 4, 2018, final Approvals and Registrations are publicly available on the Access Environment website at:

<https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/GoSearch.action?search=basic&lang=en>.

Records of Site Condition (RSC) records are publicly available on the Brownfields Environmental Site Registry (BSER).

- RSC records between 2004 to June 30, 2011 are available at:
<https://www.lrcsde.lrc.gov.on.ca/besrWebPublic/generalSearch>
- RSC records filed after July 2011 are available at:
https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/earchFiledRsc_search?request_locale=en

☐ Other Specific Document(s)

Type of Approval/Registration *

- ☐ Drinking Water Licenses
- ☐ Pesticide Licenses

- ☐ Permits to Take Water
- ☐ Noise Vibrations Approvals/Registrations
- ☐ Air Emissions Approvals/Registrations
- ☐ Water Approvals/Registrations - Ontario Water Resources Commission, treatment, ground level, standpipes & elevated storage, pumping stations (local & booster), mains
- ☐ Sewage – Treatment, Stormwater, Storm, Leachate & Lieachate Treatment & Sewage pump stations, Sanitary
- ☐ Waste Water - Industrial discharge
- ☒ Waste Sites - Disposal, Landfill sites, Transfer stations, Processing sites, Incinerator sites
- ☐ No Supporting Documents ☒ All Supporting Documents ☐ Some Supporting Documents
- ☐ Waste Management Systems - haulers: sewage, non-hazardous & hazardous waste, mobile waste processing units, Polychlorinated Biphenyls (PCBs) storage, transfer or destruction, Waste Generator Systems)
- ☐ Waste Generator Registration - number/class

List any record(s) that should be excluded from the scope of your request (e.g. email correspondences; records originating from your organization/business; records already in your possession, prior year(s) annual reports for approvals)

n/a

Please provide any additional relevant information relating to your request. For example, does your request relate to any other ministry business? Please note that this information is being requested only in order to provide contextual information to the Access and Privacy Office and will not in any way affect or expedite the status of any related ministry business identified.

n/a

Section 2 – Requester Information

Last Name *

Fleet

First Name *

Bailey

Middle Initial

Business/Organization Name (if applicable or indicate "N/A") *

Palmer

Project/Reference Number (if applicable)

2402401

Are you submitting this request on behalf of a client? *

☐ Yes ☒ No

Mailing Address

Unit Number

1

Street Number *

871

Street Name *

Equestrian Court

PO Box

City/Town *

Oakville

Province *

ON

Postal Code *

L6L 6L7

Telephone Number *

Email Address *

905-708-7299

ext.

bailey.fleet@pecg.ca

Is there an alternate contact (e.g. office admin)? *

☐ Yes ☒ No

Section 3 – Current Property Address Information

Is the property a:

☐ Park ☐ Lake ☐ First Nation Band ☐ Wind Farm ☐ Federal Land ☐ Island ☐ Unsurveyed Land

Are you requesting information about multiple addresses? *

☐ Yes ☒ No

Property Address

Unit Number

Street Number

Street Name

97

Bower Street

Full Lot Number

Concession

Geographic Township

City/Town/Village *

Acton

Closest Intersection

Bower St and Frederick St N

Section 4 – Previous Property Address Information

Do you want the ministry to search all prior historical addresses for this property/site for the time period of the records requested? *

☐ Yes ☒ No

Section 5 – Owner Information

Please provide all present and previous property owner and/or tenant names for the search years requested.

Current Property Owner/Tenant

97 Bower Street

Acton

Owner Name

759509 ONTARIO INC.

Date of Ownership (yyyy/mm/dd)

Tenant Name

Section 6 – Supporting Documents

Please upload any documents (e.g. Maps) that are relevant to your FOI request.

The total size of all attachments must not be more than 8 MB.

1. File Name

bower st.JPG

Total File Size

0.05 MB

Payment confirmation number: 29107290

Appendix H

TSSA Correspondence and Records

Request - Acton

Public Information Services <publicinformationsservices@tssa.org>
To: Bailey Fleet <bailey.fleet@pecg.ca>

Tue, Apr 2, 2024 at 10:14 AM

Hello ,

RECORD FOUND IN CURRENT DATABASE:

- We confirm that there are **fuels records** in our database at the subject address(es).

Inventory Number	Address	City	Province	Postal Code	Reason Code	Asset Class / Inventory Context	Asset Type / Inventory Item
11107720	43 ALICE ST	ACTON	ON	L7J 2A9	Active	FS Liquid Fuel Tank	FS LIQUID FUEL TANK
11107756	43 ALICE ST	ACTON	ON	L7J 2A9	Active	FS Liquid Fuel Tank	FS LIQUID FUEL TANK
9913416	43 ALICE ST	ACTON	ON	L7J 2A9	Active	FS Facility	FS PRIVATE FUEL OUTLET - SELF SERVE

Inventory Number	Address	City	Province	Postal Code	Reason Code	Asset Class / Inventory Context	Asset Type / Inventory Item
64552030	159 PERTH ST	ACTON	ON	L7J 1C9	Active	FS Appliance	FS APPLIANCE

NO RECORDS FOUND IN CURRENT DATABASE:

- We confirm that there are NO **fuels records** in our database at the subject address(es).
- 97 Bower Street, Acton, ON
- 19 Frederick Street North, Acton, ON
- 153 Perth Street, Acton, ON
- 125 McDonald Blvd, Acton, ON

This is not a confirmation that there are no records in the archives. For a further search in our archives, please apply for release of public information (PI Form) through TSSA's new Service Prepayment Portal. The associated fee must be paid via credit card (Visa or MasterCard) through a secure site.

Please follow the steps below to access the applications and the Service Prepayment Portal:

Accessing the applications

- Click [Request a Public Record](#)
- Select the appropriate application, download it, complete it in full and save it (you will have to upload application)
- Proceed to page 3 of the application and click the "TSSA Service Prepayment Portal" link under payment options (the link will take you the secure site where you can pay for the request via credit card)

Accessing the Service Prepayment Portal

- Select new or existing customer (*if you are an existing customer, you will need your account number & postal code to access your account)
- Under "Program Area" select **Public Information** and click continue
- Enter application form number (found on the bottom left corner of the application form - **PI-095-v2**) and click continue
- Complete the primary contact information section
- Complete the fee section
- Upload your completed application
- Upload supporting documents (if required) and click continue

Once all steps have been successfully completed you will receive your payment receipt via email.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.

If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationsservices@tssa.org.

Kind regards,

Slavka Zahrebelny | Public Information & Records Agent

Public Information

345 Carlingview Drive

Toronto, Ontario M9W 6N9

Tel: +1 416-734-3585 | Fax: +1 416-734-6242 | E-Mail: szahrebelny@tssa.orgwww.tssa.org

Winner of 2023 5-Star Safety Cultures Award

From: Bailey Fleet <bailey.fleet@pecg.ca>
Sent: Monday, April 1, 2024 4:07 PM
To: Public Information Services <publicinformationsservices@tssa.org>
Subject: Request - Acton

[CAUTION]: This email originated outside the organisation.
Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Hello,

Please provide a search on the following locations and notify me of any records:

- 97 Bower Street, Acton, ON
- 19 Frederick Street North, Acton, ON
- 43 Alice Street, Acton, ON
- 153 Perth Street, Acton, ON
- 159 Perth Street, Acton, ON
- 125 McDonald Blvd, Acton, ON

Thank you,

Bailey Fleet
Environmental Scientist, B.Sc. (Env.), EPT

(she/her)



| c (905) 708 7299 | e bailey.fleet@pecg.ca

Learn More:

www.pecg.ca

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

Appendix I

List of PCAs (Schedule D (Table 2), O.Reg 153/04)

Ontario Regulation 153/04
Table 2
Potentially Contaminating Activities

Item	Activity
1	Acid and Alkali Manufacturing, Processing, and Bulk Storage
2	Adhesives and Resins Manufacturing, Processing, and Bulk Storage
3	Airstrips and Hangars Operation
4	Antifreeze and De-icing Manufacturing and Bulk Storage
5	Asphalt and Bitumen Manufacturing
6	Battery Manufacturing, Recycling, and Bulk Storage
7	Boat Manufacturing
8	Chemical Manufacturing, Processing, and Bulk Storage
9	Coal Gasification
10	Commercial Autobody Shops
11	Commercial Trucking and Container Terminals
12	Concrete, Cement, and Lime Manufacturing
13	Cosmetics Manufacturing, Processing and Bulk Storage
14	Crude Oil Refining, Processing, and Bulk Storage
15	Discharge of Brine Related to Oil and Gas Production
16	Drum and Barrel and Tank Reconditioning and Recycling
17	Dye Manufacturing, Processing, and Bulk Storage
18	Electricity Generation, Transformation, and Power Stations
19	Electronic and Computer Equipment Manufacturing
20	Explosives and Ammunition Manufacturing, Production, and Bulk Storage
21	Explosives and Firing Range
22	Fertilizer Manufacturing, Processing, and Bulk Storage
23	Fire Retardant Manufacturing, Processing, and Bulk Storage
24	Fire Training
25	Flocculants Manufacturing, Processing, and Bulk Storage
26	Foam and Expanded Foam Manufacturing and Processing
27	Garages and Maintenance and Repair of Railcars, Marine Vehicles, and Aviation Vehicles
28	Gasoline and Associated Products Storage in Fixed Tanks
29	Glass Manufacturing
30	Importation of Fill Material of Unknown Quality

Item	Activity
31	Ink Manufacturing, Processing, and Bulk Storage
32	Iron and Steel Manufacturing and Processing
33	Metal Treatment, Coating, Plating, and Finishing
34	Metal Fabrication
35	Mining, Smelting, and Refining; Ore Processing; Tailings Storage
36	Oil Production
37	Operation of Dry Cleaning Equipment (where chemicals used)
38	Ordnance Use
39	Paints Manufacturing, Processing, and Bulk Storage
40	Pesticides (including Herbicides, Fungicides, and Anti-Fouling Agents) Manufacturing, Processing, Bulk Storage, and Large-Scale Applications
41	Petroleum-derived Gas Refining, Manufacturing, Processing, and Bulk Storage
42	Pharmaceutical Manufacturing and Processing
43	Plastics (including Fibreglass) Manufacturing and Processing
44	Port Activities, including Operation and Maintenance of Wharves and Docks
45	Pulp, Paper and Paperboard Manufacturing and Processing
46	Rail yards, Tracks, and Spurs
47	Rubber Manufacturing and Processing
48	Salt Manufacturing, Processing, and Bulk Storage
49	Salvage Yard, including Automobile Wrecking
50	Soap and Detergent Manufacturing, Processing, and Bulk Storage
51	Solvent Manufacturing, Processing, and Bulk Storage
52	Storage, Maintenance, Fuelling, and Repair of Equipment, Vehicles, and Material Used to Maintain Transportation Systems
53	Tannery
54	Textile Manufacturing and Processing
55	Transformer Manufacturing, Processing, and Use
56	Treatment of Sewage Equal to or Greater than 10,000 Litres per Day
57	Vehicles and Associated Parts Manufacturing
58	Waste Disposal and Waste Management, including Thermal Treatment, Landfilling and Transfer of Waste, Other than use of Biosoils as Soil Conditioners
59	Wood Treating and Preservative Facility and Bulk Storage of Treated and Preserved Wood Products