

APPENDIX F

Photograph Log



Photo 1

Comments: Pavilion and Accessory buildings, looking south



Photo 2

Comments: Derelict Storage Building, looking West



Photo 3

Comments: View inside Derelict Storage Building



Photo 4

Comments: Small storage shed shed, looking West



Photo 5

Comments: View inside small storage shed



Photo 6

Comments: Concrete structure, looking North



Photo 7

Comments: View inside concrete structure



Photo 8

Comments: Adjacent property to the west behind trees, looking west



Photo 9

Comments: Adjacent properties to the northwest, looking northwest



Photo 10

Comments: Guelph street, and properties to the north, looking north



Photo 11

Comments: Credit River and forested land, looking east



Photo 12

Comments: adjacent vacant forested land to the South, looking South



Photo 13

Comments: Septic tank, south of Pavilion building



Photo 14

Comments: Derelict camping trailer south of Pavilion building



Photo 15

Comments: Former patio south of Pavilion building, looking north



Photo 16

Comments: Tire storage east of Accessory building, looking North



Photo 17

Comments: Trailer and storage south of Accessory building, looking northwest



Photo 18

Comments: Miscellaneous debris south of Pavilion building, looking south



Photo 19

Comments: Imported fill near south perimeter, looking west



Photo 20

Comments: Main room in Pavilion building



Photo 21

Comments: Pavilion building mezzanine



Photo 22

Comments: Pavilion building kitchen



Photo 23

Comments: Black stained granular material, south of Accessory Building, looking north



Photo 24

Comments: Fuel and chemical storage in Accessory Building



Photo 25

Comments: View of Accessory building maintenance area



Photo 26

Comments: Straining observed on floor of Accessory building maintenance area




Photo 27

Comments: Vehicle and storage area in Accessory building




Photo 28

Comments: Basement of Accessory building



Photo 29

Comments: Sump in basement of Accessory building



Photo 30

Comments: Open sump area in Accessory building basement